

QUOTATION

合合車廠私人有限公司 HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101
TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456
Business Regn. / GST Regn. No. 19-8004325-G

Date: 15/08/2018

M/s AXA INSURANCE PTE LTD

VEHICLE NO. SMA 8821K

MAKE Honda Integra

Our Ref: HHW/TP 2395/2018

Your Ref:

- | | | | |
|------|------------------------------|--|---------|
| 1 pc | Tail lamp LH | | 3440.60 |
| 1 pc | Tail lamp bracket lower LH | | 48.00 |
| 1 pc | End panel | | 453.70 |
| 1 pc | Rear bumper | | 718.70 |
| 1 pc | Rear bumper side retainer LH | | 36.70 |

Less 20%

- | | | | |
|-------|-------------------------|--|----------|
| 1 set | Reverse sensor & fixing | | 200.00SN |
|-------|-------------------------|--|----------|

Labour charge to cut, weld, replace rear end panel;
repair, straighten rear LH fender, rear LH fender
inner panel, tail lamp panel and dismantle, align,
adjust and replace parts.

Spray paint on rear end panel - inside/outside,
rear LH fender, tail lamp panel, rear bumper,
reverse sensor.

Spicker ?

3558.16

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HUP HUP WORKSHOP PTE. LTD.

Authorized Signatory

Office - 62563561

Tanjong 9749547

17/8/18 @ 1455

Resurvey after repair

05 days

sur@lkkauto.com

N.B.: Estimate does not include 7% GST