

## Prime Auto Claims Service Pte Ltd

GST Reg. No: 201606560M 5 Benoi Place Singapore 629926 Tel: 6861 0908 Fax: 6515 2948

Date: 14.08.2018

Lonpac Insurance Bhd 100 Beach Road #19-00 **Shaw Tower** Singapore 189702

Attn: Motor Claims Dept

## RE: ESTIMATE COST OF REPAIR TO VEHICLE SLQ1907X TOYOTA AXIO HYBRID 1.5 (2016)

	To Su	pply			
			Front bumper	Ś	le 1,370.00
	2)	1set	Front bumper clip	\$	NU 30.00
	3)	1pc	Front bumper right side retainer	\$	7 97.00
	4)	1pc	Right head lamp	\$	at 825.00
			Sub total Parts	\$	2,322.00
			Less: 25% discount	\$	(580.50)
				\$	1,741.50
	L/cha	rges			20:
	1)	To foc	us right head lamp.	\$	40.00
1	2)	front f	nove front bumper & right head lamp. Knock & repair right ender. Replace right head lamp & front bumper. Adjust bumper.	\$	200 400.00
	3)	To put To poli	ty, respray painting front bumper & right front fender. sh.	\$	259 500.00
			Sub total L/charges	\$	940.00

Estimated Grand Total \$ 2,681.50

## LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: