

Accident Photo



Accident Photo



Accident Photo



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



SCENE PHOTO



C L APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Tang Chiu Gek
C/o: Torque 5 Bodyworks Pte Ltd
8 Kaki Bukit Avenue 4 #01-49/54
Premier @ Kaki Bukit Singapore 415875

Invoice No: CL/17304

Ref No: TOQ/02/1701/TP

Date: 09 May 2017

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SKA 2464 X
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

SS 1,371.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

LCL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Hp: 90688689 Email: clappraiser@yahoo.com
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Tang Chiu Gek
C/o: Torque 5 Bodyworks Pte Ltd
8 Kaki Bukit Avenue 4 #01-49/54
Premier @ Kaki Bukit Singapore 415875

Date : 09 May 2017
Our ref : TOQ/02/1701/TP

Accident Date : 10 December 2016
Inspection Date : 22 February 2017
Repairer Name : Torque 5 Bodyworks Pte Ltd
8 Kaki Bukit Avenue 4
#01-49/50/51/52/53/54 Premier @ Kaki Bukit
Singapore 415875

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SKA 2464 X
Make / Model : Volkswagen Scirocco
Chassis No : WVWZZZ13ZBV021874
Engine No : CAV249229

Year / Capacity : 2011 / 1390 cc
Colour : White
Mileage : -

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	235/40 R18	5 mm	Sport
Front Offside	: Bridgestone	235/40 R18	5 mm	Sport
Rear Nearside	: Bridgestone	235/40 R18	5 mm	Sport
Rear Offside	: Bridgestone	235/40 R18	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear and front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 176 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 26,300.00** on a contractual basis.

Under normal circumstances, the repair period would be about 16 (**Sixteen**) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No: SKA 2464 X

Our Ref No: TOQ/02/1701/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front bonnet ✓	Damage	\$ 938.00	\$ 938.00 CRU ✓
2	Front bonnet hinges ✓	Damage	\$ 182.00	\$ 120.00 182.00 BT ✓
1	Front bonnet insulator ✓	Damage	\$ 395.00	\$ 265.30 395.00 CUT ✓
1	Front bonnet insulator clip (1 set) ✓	Necessary	\$ 50.00	\$ 30.00 50.00 NEC ✓
1	Front bonnet upper lock ✓	Damage	\$ 103.00	\$ 103.00 BT ✓
1	Front bonnet lower lock ✓	Damage	\$ 126.00	\$ 126.00 BT ✓
1	Front bonnet logo ✓	Necessary	\$ 98.00	\$ 98.00 NEC ✓
1	Front bonnet rubber ✓	Necessary	\$ 65.00	\$ 65.00 CUT ✓
2	Front headlamps ✓	Damage	\$ 1,438.00	\$ 1,438.00 BR ✓
2	Front headlamp top panels ✓	Damage	\$ 184.00	\$ 184.00 BT ✓
1	Front grille ✓	Damage	\$ 310.00	\$ 310.00 BR ✓
1	Front bumper ✓	Damage	\$ 1,088.00	\$ 1,088.00 BR ✓ 4765.3
2	Front bumper fog lamps ✓	Damage	\$ 360.00	\$ 360.00 BR ✓
2	Front bumper fog lamp external coverings ✓	Damage	\$ @105.00 350.00	\$ 210.00 350.00 BR ✓
1	Front bumper inner sponge ✓	Damage	\$ 210.00	\$ 210.00 BR ✓
1	Front bumper reinforcement ✓	Damage	\$ 554.00	\$ 554.00 BT ✓
2	Front bumper side retainers ✓	Necessary	\$ 70.00	\$ 70.00 NEC ✓
2	Front bumper signal lamps ✓	Damage	\$ 196.00	\$ 196.00 BR ✓
1	Front bumper centre mesh ✓	Damage	\$ 332.00	\$ 332.00 BR ✓
2	Front fenders ✓	N/S Damage	\$ 1,340.00	\$ 670.00 R X
2	Front fender inner shields ✓	Damage	\$ 378.00	\$ 378.00 NN X
1	Front support panel ✓	Damage	\$ 1,021.00	\$ 845.50 1,021.00 BT ✓
1	Front support panel top garnish ✓	Damage	\$ 108.00	\$ 108.00 BR ✓
1	Horn ✓	Damage	\$ 146.00	\$ 146.00 NN X
1	Air con condenser ✓	Damage	\$ 608.00	\$ 608.00 BR ✓
1	Air con discharge pipe ✓	Damage	\$ 286.00	\$ 150.00 286.00 BR ✓
1	Air con fan motor ✓	Damage	\$ 502.00	\$ 300.00 502.00 BR ✓
1	Air con suction pipe ✓	Damage	\$ 265.00	\$ 150.00 265.00 TN ✓
1	Radiator ✓	Damage	\$ 685.00	\$ 500.00 685.00 BR ✓ 9358.5
1	Radiator fan assy ✓	Damage	\$ 548.00	\$ 548.00 BR ✓
1	Air cleaner box ✓	Damage	\$ 486.00	\$ 281.35 486.00 BR ✓
1	Battery plate ✓	Damage	\$ 185.00	\$ 185.00 NN X
1	Alternator assy ✓	Damage	\$ 1,350.00	\$ 105.00 1,350.00 DD ✓
1	Front wiper tank ✓	Damage	\$ 126.00	\$ 126.00 BR ✓
1	Front wiper motor ✓	Damage	\$ 158.00	\$ -158.00 NN X
1	Front wiper garnish ✓	Damage	\$ 140.00	\$ 140.00 NN X
1	Exhaust manifold head shield ✓	Damage	\$ 145.00	\$ 145.00 DIS ✓
2	Front door pillar top garnishes ✓	Damage	\$ 1,388.00	\$ 1,388.00 DD ✓
			\$ 16,914.00	\$ 16,244.00 12902.00

SCL APPRAISER PTE LTD

Vehicle Registration No: SKA 2464 X

Our Ref No: TOQ/02/1701/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
List Items Sub Total c/f			\$ 16,914.00	\$ 16,244.00

12902.00

SPARE PARTS - LIST ITEMS

1	Rear tailgate	Repair	\$ 2,015.00	
1	Rear tailgate inner lock <i>NN X</i>	Damage	\$ 385.00	\$ 385.00 <i>NNX</i>
1	Rear tailgate rubber <i>NN X</i>	Intact	\$ 353.00	
2	Rear taillamps	Damage	\$ 964.00	\$ 964.00 <i>BR ✓</i>
1	Rear end panel	Damage	\$ 1,285.00	\$ 1,285.00 <i>DD ✓</i>
1	Rear end panel inner trim	Damage	\$ 386.00	\$ 386.00 <i>DIS ✓</i>
1	Rear bumper	Damage	\$ 1,355.00	\$1000.00 <i>1,355.00 DIS ✓</i>
1	Rear bumper centre bracket	Damage	\$ 95.00	\$ 95.00 <i>BR ✓</i>
2	Rear bumper side brackets	Damage	\$ 96.00	\$ 96.00 <i>BR ✓</i>
1	Rear bumper inner sponge	Damage	\$ 205.00	<i>\$100.00</i> 205.00 <i>BR ✓</i>
1	Rear bumper lower spoiler	Damage	\$ 985.00	\$ 985.00 <i>BR ✓</i>
2	Rear bumper reflectors	Damage	\$ 174.00	\$ 174.00 <i>CUT ✓</i>
1	Rear bumper reinforcement	Damage	\$ 515.00	\$360.00 <i>515.00 DD ✓</i>
2	Rear bumper side retainers	Damage	\$ 70.00	\$ 70.00 <i>BR ✓</i>
2	Rear number plate lamps	Damage	\$ 148.00	\$ 148.00 <i>BR ✓</i>
1	Rear spare tyre board	Damage	\$ 495.00	\$ 495.00 <i>NNX</i>
1	Rear spare tyre panel	Damage	\$ 2,250.00	\$ 2,250.00 <i>R X</i>
2	Rear exhaust mountings	Necessary	\$ 56.00	\$ 56.00 <i>CUT ✓</i>
1	Rear exhaust silencer head shield	Damage	\$ 145.00	\$ 145.00 <i>DD ✓</i>
			\$ 28,891.00	\$ 25,853.00 <i>18766.00</i>
			<i>Less 10%</i> \$ 2,889.10	<i>\$ 2,585.30</i> <i>1876.60</i>
Total Cost - List Items			\$ 26,001.90	\$ 23,267.70 <i>16889.40</i>

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	Necessary	\$ 45.00	\$ 45.00 <i>NEC ✓</i>
1	Rear bumper clip (1 set)	Necessary	\$ 45.00	\$ 45.00 <i>NEC ✓</i>
1	Rear number plate with holder	Damage	\$ 50.00	\$ 50.00 <i>BR ✓</i>
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 280.00 <i>CUT ✓</i>
1	Rear reverse camera	Damage	\$ 550.00	\$ 550.00 <i>NNX</i>
1	Rear spare tyre side board	Damage	\$ 180.00	\$ 180.00 <i>NNX</i>
1	Rear exhaust silencer - Sport	Damage	\$ 2,880.00	\$2000.00 <i>2,880.00 PUN ✓</i>
Total Cost - Special Nett items			\$ 4,100.00	\$ 4,030.00 <i>2420.00</i>

Total cost of parts

\$ 30,101.90 **\$ 27,297.70** *19,309.40*

SCL APPRAISER PTE LTD

Vehicle Registration No: SKA 2464 X

Our Ref No: TOQ/02/1701/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 30,101.90	\$ 27,297.70 19,309.40
<u>LABOUR</u>			
1	To tow accident vehicle to workshop.	\$ 150.00	\$ 150.00 ✓
2	To check wiring , lighting and resetting headlamps focussing.	\$ 80.00	\$ 50.00 ✓ 30
3	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 ✓ 30
4	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 ✓ 60 ✓ NN X
5	To remove and refit rear reverse sensor and camera.	\$ 150.00	\$ 120.00 ✓ 80.00 ✓
6	To remove and replace air-con condenser, vaccum, refill gas and conduct leakage test.	\$ 180.00	\$ 120.00 ✓ 100
7	To remove, refit and replace exhaust silencer and mountings.	\$ 150.00	\$ 120.00 ✓ 80.00
8	To apply undercoating on repaired and replaced panel.	\$ 250.00	\$ 180.00 ✓ 60.00 (20 ✓)
9	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 2,800.00	\$ 2,500.00 ✓ 1600.00 + 200 8 ✓
10	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 2,600.00	\$ 2,200.00 ✓ 1200.00 + 300 6 ✓
GRAND TOTAL		\$ 36,691.90	\$ 32,907.70 22,549.40

L/S 18,000.00
Repair days 14

C L APPRAISER PTE LTD

Vehicle Registration No: SKA 2464 X

Our Ref No: TOQ/02/1701/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 26,300.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K.H
Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		20 Aug 2018 12:25 Edit Adj Rpt	S\$18,000.00 Edit Estimates	S\$18,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	TANG CHIU GEK , ID: F0291807L		
Vehicle Reg. No.:	SKA2464X	Date of Loss:	10/12/2016 14:00 - :59 [71 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT16120443	Policy/Cover Note No.:	MCOM0016 (Third Party Only)
Vehicle Reg. No. (Insured):	SH6611E	Policy No. (Claimant):	5077302647
		Excess:	
Repairer:	Torque 5 Bodyworks Pte Ltd (HQ) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA2464X (MCT16120443)
[SH6611E]
TP
TANG CHIU GEK
Dec 10 2016 2:00PM
[COMFORT TRANSPORTATION PTE LTD]
Torque 5 Bodyworks Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser ▾	
Assessment Reports							1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)					Thumbnail	Print	
1	17/12/16 11:08	Accident Statement					Load HTM		
Documentation							1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail	Print	
1	20/08/18 10:40	Letter of Demand from Third PartyTORQUE 5					Load PDF		
2	20/08/18 10:43	EMAIL FROM III					Load PDF		
3	20/08/18 14:12	SH6611E IV GIA REP					Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	13/09/18 12:32	LETTER					Load PDF		

Linked Accident Report Documents

						View		View in Browser ▾	
Assessment Reports							1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)					Thumbnail	Print	
1	17/12/16 11:08	Accident Statement					Load HTM		
Photos/Images							3 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)					Thumbnail	Print	
1	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
2	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
3	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
4	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
5	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
6	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
7	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
8	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
9	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
10	17/12/16 11:05	Accident Photo					Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)					Thumbnail	Print	
1	17/12/16 11:07	Sketch Plan					Load TIF		
2	17/12/16 11:07	Sketch Plan #2					Load TIF		
3	17/12/16 11:07	Common Statement					Load TIF		
4	17/12/16 11:07	Common Statement					Load TIF		
5	17/12/16 11:07	Common Statement					Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS1/III18015103/GRBS2
Date: 13/09/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016
Claimant Vehicle No : SKA2464X **Insured Vehicle No :** SH6611E
 Date of Loss: 10/12/2016 Nature of Claim: TP Claim No: MCT16120443

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA2464X**
 Make & Model: VOLKSWAGEN SCIROCCO, 1.4 (A) Engine No: CAV249229
 Reg. Date: 01/01/2011 (Man. Year: 2011) Chassis No: WVVZZZ13ZBV021874
 Colour: White Odometer: 0 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18 Rear Tyre Size: 235/40 R18
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,101.90	19,309.53	10,792.37	35.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,590.00	3,880.00	2,710.00	41.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,691.90	23,189.53	13,502.37	36.80
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	36,691.90	18,000.00	18,691.90	50.94
+ GST 7.00/7.00% (S\$)	2,568.43	1,260.00	1,308.43	50.94
Nett Amount (S\$)	39,260.33	19,260.00	20,000.33	50.94

INSPECTION

Date of Assignment: 20/08/2018
 Date Inspected: 20/08/2018 Inspected At: Torque 5 Bodyworks Pte Ltd (HQ)
 8 Kaki Bukit Ave 4., #01-49/50/51/52/53/54 Premier @
 Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 14.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

9/13/2018

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2018)
Parts: M1-COUPE	VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKA2464X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Crushed	938.00 FL	*938.00 FL
2	2		*FRONT BONNET HINGES	Bent	182.00 FL	*120.00 FL
3	1		*FRONT BONNET INSULATOR	Cut	395.00 FL	*265.30 FL
4	1		*SET FRONT BUMPER INSULATOR CLIP	Necessary	50.00 FL	*30.00 FL
5	1		*FRONT BONNET UPPER LOCK	Bent	103.00 FL	*103.00 FL
6	1		*FRONT BONNET LOWER LOCK	Bent	126.00 FL	*126.00 FL
7	1		*FRONT BONNET LOGO	Necessary	98.00 FL	*98.00 FL
8	1		*FRONT BONNET RUBBER	Cut	65.00 FL	*65.00 FL
9	2		*FRONT HEADLAMPS	Broken	1,438.00 FL	*1,438.00 FL
10	2		*FRONT HEADLAMP TOP PANELS	Bent	184.00 FL	*184.00 FL
11	1		*FRONT GRILLE	Broken	310.00 FL	*310.00 FL
12	1		*FRONT BUMPER	Broken	1,088.00 FL	*1,088.00 FL
13	2		*FRONT BUMPER FOG LAMPS	Broken	360.00 FL	*360.00 FL
14	2		*FRONT BUMPER FOG LAMP EXTERNAL COVERINGS	Broken	350.00 FL	*210.00 FL
15	1		*FRONT BUMPER INNER SPONGE	Broken	210.00 FL	*210.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Bent	554.00 FL	*554.00 FL
17	2		*FRONT BUMPER SIDE RETAINERS	Necessary	70.00 FL	*70.00 FL
18	2		*FRONT BUMPER SIGNAL LAMPS	Broken	196.00 FL	*196.00 FL
19	1		*FRONT BUMPER CENTRE MESH	Broken	332.00 FL	*332.00 FL
20	2		*FRONT FENDERS	Repair	1,340.00 FL	*- FL
21	2		*FRONT FENDER INNER SHIELDS	Not Necessary	378.00 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Bent	1,021.00 FL	*845.50 FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	108.00 FL	*108.00 FL
24	1		*HORN	Not Necessary	146.00 FL	*- FL
25	1		*AIR CON CONDENSER	Broken	608.00 FL	*608.00 FL
26	1		*AIR CON DISCHARGE PIPE	Broken	286.00 FL	*150.00 FL
27	1		*AIR CON FAN MOTOR	Broken	502.00 FL	*300.00 FL
28	1		*AIR CON SUCTION PIPE	Torn	265.00 FL	*150.00 FL
29	1		*RADIATOR	Broken	685.00 FL	*500.00 FL
30	1		*RADIATOR FAN ASSY	Broken	548.00 FL	*548.00 FL
31	1		*AIR CLEANER BOX	Broken	486.00 FL	*281.35 FL
32	1		*BATTERY PLATE	Not Necessary	185.00 FL	*- FL
33	1		*ALTERNATOR ASSY	Dented	1,350.00 FL	*1,055.00 FL
34	1		*FRONT WIPER TANK	Broken	126.00 FL	*126.00 FL
35	1		*FRONT WIPER MOTOR	Not Necessary	158.00 FL	*- FL
36	1		*FRONT WIPER GARNISH	Not Necessary	140.00 FL	*- FL
37	1		*EXHAUST MANIFOLD HEAD SHIELD	Distorted	145.00 FL	*145.00 FL
38	2		*FRONT DOOR PILLAR TOP GARNISHES	Dented	1,388.00 FL	*1,388.00 FL
39	1		*REAR TAILGATE	Repair	2,015.00 FL	*- FL
40	1		*REAR TAILGATE INNER LOCK	Not Necessary	385.00 FL	*- FL
41	1		*REAR TAILGATE RUBBER	Not Necessary	353.00 FL	*- FL
42	2		*REAR TAILLAMPS	Broken	964.00 FL	*964.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR END PANEL	Dented	1,285.00 FL	*1,285.00 FL
44	1		*REAR END PANEL INNER TRIM	Distorted	386.00 FL	*386.00 FL
45	1		*REAR BUMPER	Distorted	1,355.00 FL	*1,000.00 FL
46	1		*REAR BUMPER CENTRE BRACKET	Broken	95.00 FL	*95.00 FL
47	2		*REAR BUMPER SIDE BRACKETS	Broken	96.00 FL	*96.00 FL
48	1		*REAR BUMPER INNER SPONGE	Broken	205.00 FL	*100.00 FL
49	1		*REAR BUMPER LOWER SPOILER	Broken	985.00 FL	*985.00 FL
50	2		*REAR BUMPER REFLECTORS	Cut	174.00 FL	*174.00 FL
51	1		*REAR BUMPER REINFORCEMENT	Dented	515.00 FL	*360.00 FL
52	2		*REAR BUMPER SIDE RETAINERS	Broken	70.00 FL	*70.00 FL
53	2		*REAR NUMBER PLATE LAMPS	Broken	148.00 FL	*148.00 FL
54	1		*REAR SPARE TYRE BOARD	Not Necessary	495.00 FL	*- FL
55	1		*REAR SPARE TYRE PANEL	Repair	2,250.00 FL	*- FL
56	2		*REAR EXHAUST MOUNTINGS	Cut	56.00 FL	*56.00 FL
57	1		*REAR EXHAUST SILENCER HEAD SHIELD	Dented	145.00 FL	*145.00 FL
58	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
59	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
60	1		*REAR NUMBER PLATE WITH HOLDER	Broken	50.00 FS	*50.00 FS
61	1		*SET REAR REVERSE SENSOR	Cut	350.00 FS	*280.00 FS
62	1		*REAR REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
63	1		*REAR SPARE TYRE SIDE BOARD	Not Necessary	180.00 FS	*- FS
64	1		*REAR EXHAUST SILENCER - SPORT	Punctured	2,880.00 FS	*2,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	32,991.00	21,186.15
- List Item Discount on L Items 10.00/10.00% (S\$)	2,889.10	1,876.62
Total Parts (S\$)	30,101.90	19,309.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP.	New	150.00	80.00
2	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING.	New	80.00	30.00
3	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.	New	80.00	30.00
4	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.	New	150.00	60.00
5	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA.	New	150.00	80.00
6	TO REMOVE AND REPLACE AIR-CON CONDENSER, VACUUM, REFILL GAS AND CONDUCT LEAKAGE TEST.	New	180.00	100.00
7	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	New	150.00	80.00
8	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	New	250.00	120.00
9	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	2,800.00	1,800.00
10	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.	New	2,600.00	1,500.00
Gross Labour Cost (S\$)			6,590.00	3,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >