

ASS. REC. BY:

REF: CS/FCI 180 15/44/T1/d3ⁿ² Special Instruction:

Surveyor:

CWS

Taufik

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

17/8/18 @ 4:48pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT 53312

Insured:

SHD 6716M

at Workshop m/s

Prime Auto

Tel:

68610908

of

6 Benoi place

Policy No:

Claim No:

D18006180 MFSTH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:59am @ 20/8/18

Person Contacted:

pei yee

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SGT 53312-x

SHD 6716M-CC31A1G16017770/Ghg3q2

DOA: 16/9/16

31/8 @ 2:12pm Revert prelude via email.

lump Sum \$1500/- (Red: 1045.11 : 41%)

Tanglin

RTU

FCI

Accident No. 36T5331Z

2022 April
207 April

From: _____ Date: _____

Estimated Date: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop No: _____

ed: _____

Insurance: _____

Policy No: _____

Claims No: _____

Car Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Mark of Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / RP Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val Yes or No

CA / REV / REP: / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Vehicle: 36T5331Z

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios

Colour: Black

Ap Reading: 293046

Engine: MRO53HY 42042 / 7263

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Goodride

Front	Rear
R/Bal: 6 mm	R/Bal: 6 mm
L/Bal: 6 mm	L/Bal: 6 mm

D.O.A: _____ D.O.I: 20/8/18 @ 5pm

Survey held at: Prime Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 26 SEP 2018

Date/Time: 25/8/18

Preli. Report ☐

Final Report ☒

Only Time / Life Return: _____

Report Format: TP

Lump Sum / LRT: 1500T

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Late Trip: 1\$

☐ Inflation: 1\$

☐ Day Trip: 1\$

☐ Night Trip: 1\$

Survey Fee

Inspection

110

50

50

26

236



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015144/T1td3	
36 ROBINSON ROAD #16-01 CITYLINK SINGAPORE 068877		Date : 20-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured	SHD 6716M	Veh. Inspected	SGT 5331Z
Policy		Coverage (\$)	0.00
Claim	SH8006180MFSH	Excess (\$)	0.00
Assign	CWS (KAREN TAN)	Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make		c.c	0
Eng	HIDDEN	Year of Reg.	
Cha		Colour	
Odo		Steering	
Bra		Modification	
Col			
3. Conditions of Tyres			
	Size	Make	Balance
R/R			mm
L/R			mm
R/R			mm
L/R			mm
4. Description of Damages			
5. General Information			
A	20/08/2018	Inspection Date	20/08/2018
S	TIME AUTO CLAIMS SERVICE PTE LTD		
	ENNOI PLACE		
	SINGAPORE 629927		
5a. Remarks			
App	TIC WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
En	NO TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D18006180MFSH

Date: 31/8/2018

Our Ref: CS/FCI18011631/T1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGT 5331Z

Please be informed that we had conducted the inspection of the abovementioned vehicle 20/8/2018 at the premises of M/s Prime Auto and have the following to report: -

Workshop Estimate Amount	: S\$ <u>2,545.11</u>
Revised Estimate Amount	: S\$ <u>1,931.63</u>
"Check" Items Amount	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the N/S portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-08-2018	Our Ref No. D18006180MFSH
Accident Date	15-08-2018	Claim Type. Third Party
Insured Vehicle	SHD6716M	Third Party Vehicle. SGT5331Z
Survey Location	6 Benoi Place	
Contact Person.	CHRISSY TEO	
Contact No.	68610908/ 0	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 31 August 2018 2:12 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006180MFSH/1
Attachments: PRELI ADVISED SGT 5331Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGT 5331Z**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 20 August 2018 11:27 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006180MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 17 August 2018 4:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006180MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 17.08.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SGT5331Z TOYOTA VIOS (2006)

To Supply

1)	1pc	Left side mirror assy.	\$	234.00	<i>bro ✓</i>
2)	1pc	Left side mirror outer cover	\$	61.30	<i>mis ✓</i>
3)	1pc	Left front door	\$	1,053.34	<i>bt ✓</i>
4)	1pc	Left front door window glass	\$	431.50	<i>x m ✓</i>

Sub total parts	\$	1,780.14
Less: 25% discount	\$	(445.03)
	\$	1,335.11

L/charges

1)	To tuff kote.	\$	50.00	<i>30</i>
2)	To transfer left front door handle, trim board & mechanism parts.	\$	60.00	<i>40</i>
3)	To remove left front door. Repair left rear door. Replace the above parts. Align & adjust left front door & left rear door.	\$	500.00	<i>400</i>

- 4) To putty, respray painting left front door inlet & outer, left rear door and left side mirror outer cover. To polish.

\$ 600.00

450

Sub total L/charges	\$	1,210.00
Estimated Grand Total	\$	2,545.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495249
 'wp'
 20/8/18 E Spr
 Resurvey after repair
 sure 11 months work
 3-4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 17.08.2018

MS First Capital Insurance Ltd

36 Robinson Road #16-01

City House

Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SGT5331Z TOYOTA VIOS (2006)

To Supply

1)	1pc	Left side mirror assy.	\$	234.00	<i>bro ✓</i>
2)	1pc	Left side mirror outer cover	\$	61.30	<i>mis ✓</i>
3)	1pc	Left front door	\$	1,053.34	<i>bf ✓</i>
4)	1pc	Left front door window glass	\$	431.50	<i>x</i>

Sub total parts	\$	1,780.14	<i>1348.64</i>
Less: 25% discount	\$	(445.03)	<i>- 337.16</i>
	\$	1,335.11	<i>1011.48</i>

L/charges

1)	To tuff kote.	\$	50.00	<i>30</i>
2)	To transfer left front door handle, trim board & mechanism parts.	\$	60.00	<i>40</i>
3)	To remove left front door. Repair left rear door. Replace the above parts. Align & adjust left front door & left rear door.	\$	500.00	<i>400</i>

- 4) To putty, respray painting left front door inlet & outer, left rear door and left side mirror outer cover. To polish.

\$ 600.00

450

Sub total L/charges	\$ 1,210.00	980.00
Estimated Grand Total	\$ 2,545.11	1931.48
		- 386.29
		1545.19

Tanpin 97495249
WP

20/8/18 E Spr

Resny after repair

sur e Mandan wu

3-4 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015144/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6716M	Veh. Inspected	SGT 5331Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006180MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	17/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053HY4204217263	Colour	BLACK	
Odometer	293046	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	GOODRIDE	6 mm	
L/H Front Tyre	185/65 R15	GOODRIDE	6 mm	
R/H Rear Tyre	185/65 R15	GOODRIDE	6 mm	
L/H Rear Tyre	185/65 R15	GOODRIDE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2018	Inspection Date	20/08/2018	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 5331Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LEFT SIDE MIRROR ASSY	BROKEN	234.00	234.00
1	LEFT SIDE MIRROR OUTER COVER	MISSING	61.30	61.30
1	LEFT FRONT DOOR	BENT	1,053.34	1,053.34
1	LEFT FRONT DOOR WINDOW GLASS	NOT NECESSARY	431.50	-
	LESS 25% DISCOUNT		-445.03	-337.16
			1,335.11	1,011.48
	LABOUR			
	TO TUFF KOTE.		50.00	30.00
	TO TRANSFER LEFT FRONT DOOR HANDLE,TRIM BOARD & MECHANISM PARTS.		60.00	40.00
	TO REMOVE LEFT FRONT DOOR,REPAIR LEFT REAR DOOR,REPLACE THE ABOVE PARTS,ALIGN & ADJUST LEFT FRONT DOOR & LEFT REAR DOOR.		500.00	400.00
	TO PUTTY,RESPRAY PAINTING LEFT FRONT DOOR INLET & OUTER,LEFT REAR DOOR AND LEFT SIDE MIRROR OUTER COVER.TO POLISH.		600.00	450.00
			1,210.00	920.00
	GRAND TOTAL		2,545.11	1,931.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00

Report Ref No. CS/FCI18015144/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.