

ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:			
Type of Claim :	TP	Vehicle No.	SLH1864H
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Make & Model	HONDA GRACE 1.5 DX HYBRID
		Year of Manufacture	2016
		Chassis No.	GM41104615
Ins Company :AIG	VS AXA	Engine No.	LEB5254629
Excess :		Policy No.	1 - 1
Date of Accident : 15.	.08.2018	Time of Accident	: 13:15
Suggested Days of Repair	11000	In-house Vehicle Asse	essor
Repair Estimate		Case Owner	
Parts (a) Cost / List Price Items	\$ 1,571.10	Signature	* <u>* * * * * * * * * * * * * * * * * * </u>
Parts (a) Cost / List Frice items	Ψ 1,071.10	Contact No	
Plus/Less20%	\$ 314.22	Frt Counter Operation 63837103 – Patrick Tia	on
Total of Cost / List	\$ 1,256.88	63837730 - Brenda Ng	
(b) Nett Price Items	\$ -	63837466 – Rohani braddell_cr@sparkcarca	are.com
Less	<u> </u>	Workshop Operation	
Total of Nett Item		63837656 - Ngo Toh W 63837362 -	ee
	_	63838115 - William Wa 63838115 - Andrew G	
(c) Special Nett Items	\$ -	braddell operation@spa	
Total Parts Cost (Appendix A)	\$ 1,256.88		
Labour (Appendix B)	\$ 1,140.00		
Total Repair Cost	\$ 2,396.88		
The above total will be subjected	to 7% G.S.T.		
		0.1	C- 88 0782

Name of Surveyor	640 Qip8	288 0282
Company	LES '	
Survey conducted on	:at	
Remarks By Surveyor		pas by put.
(a) The repair of this vehicle is	authorized / is not authorized until further notice.	betere paint photos
(b) Recommended Days of Re	pair :day(s)	la lace banslands
(c) Resurvey	: Required / Not Required	
(d) Excess	:\$	
(e) Signature of surveyor	: Date	

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	SLH1864H	Case Owner	: 0
Make & Model	:	HONDA GRACE 1.5 DX HY	Year Manufacture	2016
Chassis No	:	GM41104615	Engine No	LEB5254629
Sales Order	:		Supplier	
Order By	:	<u> </u>	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N	Disposition By Surveyor
1	Bonnet / hu	1		\$	920.80			
2	Bonnet insulator clips / 16C	5		\$	19.50			
3	Bonnet lock X	1		\$	86.90			
4	Front grille / L ·	1		\$	150.40			
	Front grille chrome garnish /	1		\$	180.90			
6	Front grille chrome moulding	1		\$	125.00			
7	Front grille badge / MC	1		\$	27.10			
8	Front grille top garnish ?	1		\$	29.30			
9	Front grille top garnish clips ?	8		\$	31.20			
10	0	1						
11	0	1						
12	0	1						
13	0	1						
14	0	1						
15	0	1						
16	0	1						
17	0	1						
18	0	1						
19	0	1						
20	0	1						
21	0	1						
22	0	1						
23	0	1						
24	0	1						
25	0	1						
26	0	1						
27	0	1						
28	0	1						
29	0	1						
30	0	1						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. : SLH1864H		SLH1864H	Case Owner	:	0	
Make & Model	:	NDA GRACE 1.5 DX HYBRID	Year of Manufacture	:	2016	

S/No	Labour Description	Esimated Price	Adjusted Price
1	Labour charges to repair and panel beat the frontt supp panel and replace damaged parts.	ort \$600.00	240
	parier and replace damaged parts.		
2	To check wiring functions.	\$40.00	1.
3	To putty, apply primer & spray-paint the bonnet, front supplied and affected areas.	upport \$500.00	250
	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting		
	To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis		
	No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
Ξ	Acknowledged by Repairer Signature:		
	Date:	25 636	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.