

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	reg. No. 13300713017 GOT reg. No. 13-3007130-17				
Affiliated to Federation Internationale Des Experts En Automobile					
AIG ASIA PACIFIC INSURANCE PTE LTD Ref : CS3/AIG18011087/Gtbs2-1					
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 ATTN: BENNIE TAN		Date: 04-09-2018 Code: AIG			
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SCK 66S	Veh. Inspected	SKS 8000S	
	Policy No.	2100501971	Coverage (\$)	0.00	
	Claim No.	0056791127SG	Excess (\$)	0.00	
	Assign From	BENNIE TAN	Assign Date	12/08/2018	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VELLFIRE	c.c	2362	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	ANH208329487	Colour	BLACK	
	Odometer	220716	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/50R18	YOKOHAMA	6 mm	
	L/H Front Tyre	235/50R18	YOKOHAMA	6 mm	
	R/H Rear Tyre	235/50R18	YOKOHAMA	6 mm	
	L/H Rear Tyre	235/50R18	YOKOHAMA	6 mm	
4.	I. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5. General Information					
	Accident Date	11/06/2018	Inspection Date	24/08/2018	
	Survey held at	YEOW KOON MOTOR SPRAY PAINTING			
		BLK 9002 TAMPINES STREET 93 #01-34 TAMPINES INDUSTRIAL PARK A . SINGAPORE 528836			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate Days of Repair

4 Working Days