



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6743 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the o/s front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 15 working days to complete.
5. Enclosed number of photograph : 146 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: WC 4413 C
Report No: TP/ 18014-05/MY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front windscreen glass	Damage	\$ 1286.00	\$ ✓ 1286.00 CR ✓
1	Front windscreen rubber	Necessary	\$ 282.00	\$ ✓ 282.00 NEC ✓
1	Wiper blade	Intact	\$ 28.00	\$
1	Wiper panel	Damage	\$ 565.00	\$ 565.00 SVCX
1	Wiper arm	Damage	\$ 185.00	\$ ✓ 185.00 BT ✓
1	Wiper linkage	Intact	\$ 485.00	\$
1	Front headlamp	Damage	\$ 540.00	\$ 384.10 540.00 BR ✓
1	Front signal lamp	Damage	\$ 185.00	\$ ✓ 185.00 BR ✓
1	Headlamp bracket	Necessary	\$ 168.00	\$ ✓ 168.00 NEC ✓ D
1	Front panel 'ISUZU' emblem	Necessary	\$ 68.00	\$ ✓ 68.00 NEC ✓
1	Front panel 'CHY' emblem	Not Necessary	\$ 45.00	\$ 45.00 NN X
1	Front panel damper	Intact	\$ 120.00	\$
1	Front corner panel	Damage	\$ 375.00	\$ ✓ 375.00 DVC ✓
1	Front hood panel centre grille	Intact	\$ 182.50	\$
1	Front hood panel side grille	Intact	\$ 78.50	\$
2	Front panel rubbers	Necessary	\$ 280.00	\$ ✓ 280.00 CuTV
1	Dashboard panel	Intact	\$ 625.00	\$
1	Dashboard instrument cluster	Intact	\$ 442.50	\$
1	Meter assy	Intact	\$ 1062.00	\$
1	Meter cover	Intact	\$ 269.00	\$
1	Front bumper	Damage	\$ 1060.00	\$ ✓ 1060.00 DIS ✓
1	Front bumper bracket	Necessary	\$ 260.00	\$ ✓ 260.00 NEC ✓ B
1	Front bumper centre pad	Damage	\$ 360.00	\$ 200.00 360.00 DIS ✓
2	Front bumper top side pads	Damage	\$ 250.00	\$ 250.00 CuT
1	Front fog lamp	Damage	\$ 218.00	\$ 218.00 CuTV ✓
1	Lamp panel	Damage	\$ 336.00	\$ 336.00 DD ✓
1	Radiator	Intact	\$ 3210.00	\$ 2500.00
1	Turbo oil cooler	Damage	\$ 2850.00	\$ 2850.00 DD ✓
1	Front door	Damage	\$ 1850.00	\$ 1850.00 RX
1	Front door glass	Intact	\$ 460.00	\$
1	Front door glass channel	Intact	\$ 211.50	\$
1	Front panel	Damage	\$ 1240.00	\$ 1240.00 DD ✓
1	Front panel rubber seal	Damage	\$ 102.00	\$ ✓ 102.00 CuT
1	Cabin o/s rear panel	Damage	\$ 1189.00	\$ 1189.00 DD ✓
1	Cabin rear panel lower garnish	Damage	\$ 278.00	\$ ✓ 278.00 CuTV
1	Cabin rear panel air-vent	Intact	\$ 331.00	\$
1	Cabin rear panel inner trim	Damage	\$ 293.00	\$ 293.00 SVCX

List Items Sub Total

\$ 21770.00

\$ 14265.00

10846.10

Vehicle No: WC 4413 C
Report No: TP/ 18014-05/MY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
List Items Total c/f			\$ 21770.00	\$ 14265.00 10846-10
<u>List Items</u>				
1	Washer tank	Damage	\$ 125.00	\$ 125.00 CUT ✓
1	Front door glass outer moulding	Damage	\$ 189.00	\$ 189.00 NN X
1	Front door lower hinge	Damage	\$ 195.00	\$ 195.00 BT ✓
1	Front door inner lock	Damage	\$ 325.00	\$ 325.00 SV ✓
1	Front door outer handle	Intact	\$ 297.00	\$
1	Front door rubber	Necessary	\$ 255.00	\$ 255.00 SV ✓
1	Front door window switch	Damage	\$ 178.00	\$ 178.00 BR ✓
1	Front door board	Intact	\$ 458.00	\$
1	Front door side mirror	Intact	\$ 280.00	\$
1	Front door side mirror stay	Intact	\$ 325.00	\$
1	Front door outer garnish	Damage	\$ 389.00	\$ 389.00 DD ✓
1	Front door signal lamp	Intact	\$ 180.00	\$
1	Front door pillar	Damage	\$ 896.00	\$ 896.00 XR
1	Wheel arch panel	Repair	\$ 655.00	\$
1	Front 1st step	Intact	\$ 187.00	\$
1	Step support garnish	Damage	\$ 455.00	\$ 380.00 455.00 BT ✓
1	Wheel arch muddyguard	Damage	\$ 168.00	\$ 168.00 CUT ✓
			\$ 27327.00	\$ 17440.00 12761.70
Discount 15.0%			\$ 4099.05	\$ 2616.00 1914.16
			\$ 23227.95	\$ 14824.00 10846.90
<u>Special Nett Items</u>				
1	ERP Bracket	Damage	\$ 30.00	\$ 30.00 20 NEC ✓
			\$ 30.00	\$ 30.00

Spare Parts Total \$ 23257.95 \$ 14854.00

Vehicle No: WC 4413 C
Report No: TP/ 18014-05/MY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 23257.95	\$ 14854.00
1	To provide towing service charge.	\$ 120.00	\$ 100.00
2	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 120.00	\$ 60.00 40
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 100.00 60
4	To remove and refit air-con system, refill gas and test for leakages.	\$ 180.00	\$ 120.00 NN X
5	To remove and refit dashboard, meters instrument, disconnect wirings, ductings, connectors to facilitate the repairs.	\$ 400.00	\$ 200.00 350.00
6	To remove and refit front windscreen glass.	\$ 180.00	\$ 120.00
7	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$ 100.00	\$ 60.00 X
8	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2800.00	\$ 1200.00 2200.00 900
9	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2500.00	\$ 1980.00
10	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 180.00	\$ 60.00 120.00
Total		\$ 29987.95	\$ 20064.00

Vehicle No: WC 4413 C
Report No: TP/ 18014-05/MY / 2018


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
Sub Total c/f		\$ 29987.95	\$ 20064.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 16100.00

SDLS: SIXTEEN THOUSAND ONE HUNDRED ONLY


Qualified Appraiser

L/S

Repair days 12

TG Lim



4/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2018		14 May 2018 10:14 Edit Adj Rpt	S\$10,500.00 Edit Estimates	S\$10,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD , Co. Reg. No.: 200302202M								
Main Claimant:	TAT HING TRANSPORT PTE LTD , Co. Reg. No.: 201414922Z								
Vehicle Reg. No.:	WC4413C	Date of Loss:	27/04/2018 14:00 - :59 [78 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557627	Policy/Cover Note No.:	A28729875MKC (Comprehensive) Coverage: 18/05/2017 - 17/05/2018						
Vehicle Reg. No. (Insured):	XD3656H	Policy No. (Claimant):							
		Excess:							
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 23/08/2018]								
Driver/Custodian (Insured):	YAP CHONG LIN (), NRIC: F7464425L, Tel: +6583011412								
Adj Asg. Remarks:	Liability 100% TP reject SJE - assign LKK Auto Consultants								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (20/08/2018): Report Send Back Alerts - WC4413C (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WC4413C (557627)

[XD3656H]

TP

TAT HING TRANSPORT PTE LTD

Apr 27 2018 2:00PM

[SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD]











Fook Heng Motor Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
MSIG Insurance (Singapore) Pte. Ltd. (HQ)					
Accident Statement					
1	09/05/18 15:11	From: SC - Reg. No: XD3656H, Claimant: SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)					
1	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
14	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
15	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
16	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
17	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
18	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
19	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
20	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
21	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
22	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
23	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
24	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
25	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
26	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
27	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
28	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
29	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
30	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
31	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
32	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	24/07/18 12:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	24/07/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	24/07/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	24/07/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	24/07/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	24/07/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	24/07/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
85	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
86	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
87	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
88	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
89	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
90	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
91	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
92	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
93	24/07/18 12:17	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/05/18 15:11	WC4413C e-file report From: SC - Reg. No: XD3656H, Claimant: SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD		Load PDF	
2	09/05/18 15:13	TP PRI Request		Load PDF	
3	20/08/18 14:31	LOD - GIA fees - LTA Search- Repair & survey bill		Load PDF	
4	20/08/18 14:31	Survey Report		Load PDF	
5	20/08/18 14:31	Survey Photo 1		Load PDF	
6	20/08/18 14:31	Survey Photo 2		Load PDF	
7	20/08/18 14:31	Survey Photo 3		Load PDF	
8	20/08/18 14:31	Survey Photo 4		Load PDF	
9	20/08/18 14:31	Survey Photo 5		Load PDF	
10	20/08/18 14:31	Survey Photo 6		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/09/18 10:16	COLOUR PHOTO		Load PDF	
2	05/09/18 10:16	PRS Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008715/BSBE2-1

Date: 05/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28729875MKC

Claimant Vehicle No: WC4413C

Insured Vehicle No: XD3656H

Date of Loss: 27/04/2018

Nature of Claim: TP

Claim No: 557627

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WC4413C

Make & Model: ISUZU CYH52S, 15.7 D (M)

Engine No: 6WG1415411

Reg. Date: 25/10/2011 (Man. Year: 2011)

Chassis No: JALCYH52SB7000172

Colour: White/Blue

Odometer: 188096 km

Engine Capacity: 15681 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5

Front Left Side: Windforce 6 mm

Rear Left Side: Windforce 6 mm

Front Right Side: Windforce 6 mm

Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	23,257.95	10,458.93	12,799.02	55.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,730.00	2,680.00	4,050.00	60.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,987.95	13,138.93	16,849.02	56.19
Approved Total (Overridden) (\$\$)		10,500.00		
Nett Amount (\$\$)	29,987.95	10,500.00	19,487.95	64.99

INSPECTION

Date of Assignment: 14/05/2018

Date Inspected: 14/05/2018 Inspected At:

Fook Heng Motor Service (HQ)
29 SUNGAI KADUT STREET 4
SINGAPORE 729054

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Sep 2018)	
Parts:	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WC4413C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,286.00 FL	*1,286.00 FL
2	1		*FRONT WINDSCREEN RUBBER	Necessary	282.00 FL	*282.00 FL
3	1		*WIPER BLADE	Intact	28.00 FL	*- FL
4	1		*WIPER PANEL	Serviceable	565.00 FL	*- FL
5	1		*WIPER ARM	Bent	185.00 FL	*185.00 FL
6	1		*WIPER LINKAGE	Intact	485.00 FL	*- FL
7	1		*FRONT HEADLAMP	Broken	540.00 FL	*384.10 FL
8	1		*FRONT SIGNAL LAMP	Broken	185.00 FL	*185.00 FL
9	1		*HEADLAMP BRACKET	Distorted	168.00 FL	*168.00 FL
10	1		*FRONT PANEL ISUZU EMBLEM	Necessary	68.00 FL	*68.00 FL
11	1		*FRONT PANEL CHY EMBLEM	Not Necessary	45.00 FL	*- FL
12	1		*FRONT PANEL DAMPER	Intact	120.00 FL	*- FL
13	1		*FRONT CORNER PANEL	Cracked	375.00 FL	*375.00 FL
14	1		*FRONT HOOD PANEL CENTRE GRILLE	Intact	182.50 FL	*- FL
15	1		*FRONT HOOD PANEL SIDE GRILLE	Intact	78.50 FL	*- FL
16	2		*FRONT PANEL RUBBERS	Cut	280.00 FL	*280.00 FL
17	1		*DASHBOARD PANEL	Intact	625.00 FL	*- FL
18	1		*DASHBOARD INSTRUMENT CLUSTER	Intact	442.50 FL	*- FL
19	1		*METER ASSY	Intact	1,062.00 FL	*- FL
20	1		*METER COVER	Intact	269.00 FL	*- FL
21	1		*FRONT BUMPER	Distorted	1,060.00 FL	*1,060.00 FL
22	1		*FRONT BUMPER BRACKET	Bent	260.00 FL	*260.00 FL
23	1		*FRONT BUMPER CENTRE PAD	Distorted	360.00 FL	*200.00 FL
24	2		*FRONT BUMPER TOP SIDE PADS	Cut	250.00 FL	*250.00 FL
25	1		*FRONT FOG LAMP	Cut	218.00 FL	*218.00 FL
26	1		*LAMP PANEL	Dented	336.00 FL	*336.00 FL
27	1		*RADIATOR	Intact	3,210.00 FL	*- FL
28	1		*TURBO OIL COOLER	Dented	2,850.00 FL	*2,500.00 FL
29	1		*FRONT DOOR	Repair	1,850.00 FL	*- FL
30	1		*FRONT DOOR GLASS	Intact	460.00 FL	*- FL
31	1		*FRONT DOOR GLASS CHANNEL	Intact	211.50 FL	*- FL
32	1		*FRONT PANEL	Dented	1,240.00 FL	*1,240.00 FL
33	1		*FRONT PANEL RUBBER SEAL	Cut	102.00 FL	*102.00 FL
34	1		*CABIN O/S REAR PANEL	Dented	1,189.00 FL	*1,189.00 FL
35	1		*CABIN REAR PANEL LOWER GARNISH	Cut	278.00 FL	*278.00 FL
36	1		*CABIN REAR PANEL AIR-VENT	Intact	331.00 FL	*- FL
37	1		*CABIN REAR PANEL INNER TRIM	Serviceable	293.00 FL	*- FL
38	1		*WASHER TANK	Cut	125.00 FL	*125.00 FL
39	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	189.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT DOOR LOWER HINGE	Bent	195.00 FL	*195.00 FL
41	1		*FRONT DOOR INNER LOCK	Serviceable	325.00 FL	*- FL
42	1		*FRONT DOOR OUTER HANDLE	Intact	297.00 FL	*- FL
43	1		*FRONT DOOR RUBBER	Serviceable	255.00 FL	*- FL
44	1		*FRONT DOOR WINDOW SWITCH	Broken	178.00 FL	*178.00 FL
45	1		*FRONT DOOR BOARD	Intact	458.00 FL	*- FL
46	1		*FRONT DOOR SIDE MIRROR	Intact	280.00 FL	*- FL
47	1		*FRONT DOOR SIDE MIRROR STAY	Intact	325.00 FL	*- FL
48	1		*FRONT DOOR OUTER GARNISH	Dented	389.00 FL	*389.00 FL
49	1		*FRONT DOOR SIGNAL LAMP	Intact	180.00 FL	*- FL
50	1		*FRONT DOOR PILLAR	Repair	896.00 FL	*- FL
51	1		*WHEEL ARCH PANEL	Repair	655.00 FL	*- FL
52	1		*FRONT 1ST STEP	Intact	187.00 FL	*- FL
53	1		*STEP SUPPORT GARNISH	Bent	455.00 FL	*380.00 FL
54	1		*WHEEL ARCH MUDDYGUARD	Cut	168.00 FL	*168.00 FL
55	1		*ERP BRACKET	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 27,357.00 12,301.10

- List Item Discount on L Items 15.00/15.00% (S\$) 4,099.05 1,842.17

Total Parts (S\$) 23,257.95 10,458.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE CHARGE	New	120.00	100.00
2	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS	New	120.00	40.00
3	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS	New	150.00	60.00
4	TO REMOVE AND REFIT AIR-CON SYSTEM, REFILL GAS AND TEST LEAKAGES	New	180.00	0.00
5	TO REMOVE AND REFIT DASHBOARD, METERS, INSTRUMENT, DISCONNECT WIRINGS, DUCTINGS, CONNECTORS TO FACILITATE THE REPAIRS	New	400.00	200.00
6	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE AND REFIT THE DOOR LOCK MECHANISM, REGULATOR GEAR, WINDOW GLASS, HANDLE, INNER BOARD, HINGES, CHANNEL TO FACILITATE THE REPAIRS	New	100.00	0.00
8	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	2,800.00	1,200.00
9	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	2,500.00	900.00
10	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	180.00	60.00
Gross Labour Cost (\$\$)			6,730.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >