

**PREMIER AUTOMOTIVE SERVICES PTE LTD**

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0030

Assessor Report

Version: PREMIERA/1

Printed: 21/08/2018

2642	1	R/R C-MEMBER BRACKET	866422T500	X see	0%	54.00*
3288	1	R/R OUTER LAMP	924122T510	/ see	0%	421.00*
3486	1	R/R OUTER SIDE PANEL	715042TC00	<del>see</del> see	0%	1,205.00*
3414	1	R/R REFLECTOR	924062T500	/ see	0%	46.00*
2652	1	R/R VENT GRILLE	975103V000	X see	0%	30.00*
4202	1	R/R WHEELHOUSE CVR	868222T500	X see	0%	120.00*
3015	1	REAR BADGE	863202T500	/ see	0%	29.00*
2583	1	REAR BUMPER	866112T500	/ returned	0%	696.00*
2644	1	REAR BUMPER DAMPER	866202T500	X see	0%	114.00*
2770	1	REAR BUMPER SPOILER	866122T500	/ returned	0%	206.00*
2640	1	REAR BUMPER SUPPORT	866312T500	X see	0%	607.00*
2711	1	REAR PANEL	691002T000	X see	0%	250.00*
3160	1	REAR SCREEN BOND KIT	ZK20063001A	X see	0%	80.81U
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS	X see	0%	0.00
3173	2	REAR SCREEN SPACER	871143K000	X see	0%	7.20U
3171	10	REAR SCREEN SUPPORTS	861143D000	X see	0%	15.30U
f: OEM Parts					Sub Total	<b>\$5,406.31</b>
g: Original					Deduction from RRP (35 %)	<b>-\$1,892.21</b>
h: Secondhand					<b>Total Parts</b>	<b>\$3,514.10</b>
p: Parallel						
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
REAR BUMPER CLIPS SPECIALIST	0% / see	\$48.00
REVERSE SENSOR SPECIALIST	/ see	<del>\$280.00</del> 200
SEALANT SPECIALIST	0% / see	\$50.00
FENDER SHIELD SPECIALIST	X see	\$28.00
CLIPS		
REAR FENDER SPECIALIST	0% / see	\$60.00
STICKER		
BOOTLID STICKER SPECIALIST	/ see	\$100.00
<b>Total Extras</b>		<b>\$566.00</b>

**Final Calculation**

<b>Total Parts</b>	<b>\$3,514.10</b>
<b>Labour</b>	
Total Panel/Mechanical	\$915.00 / 605
Total Paintwork	\$605.00 / 375
<b>Total Labour</b>	<b>\$1,520.00</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$566.00
<b>Total of Additional Costs</b>	<b>\$566.00</b>
<b>Total Paint/Material Costs</b>	<b>\$249.95</b> 152.51
<b>Grand Total Excludes GST</b>	<b>\$5,850.05</b>
GST @ 7 %	<b>\$409.50</b>
<b>Grand Total Includes GST</b>	<b>\$6,259.55</b>

Assessment Notes

Kelvin LIM  
21/8/18 1005h.  
5 Days.  
PP  
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before enter into painting
- To display damaged parts for resurvey
- Parts prices are displayed on board
- Third party survey on a "no prejudice" basis
- No illegal modifications allowed
- Supplemental work shall be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: SHB8083C  
Assessment Number: MSIG0030  
Version: LKKAUTO/12  
Date Calculated: 05/09/2018 09:27

Full Report - V1  
Registration: SHB8083C  
Printed: 05/09/2018 16:28

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	18/08/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	SHB8083C	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

Vehicle	Model Specs	
Manufacturer:	KIA	PREPARE OFF VEHICLE
Model:	Optima	
Sub Model:	BASE MODEL	
Model Sheet Number:	2836 01	
Registration:	SHB8083C	
Registration Month:	November	
Registration Year:	2015	
VIN Number:		
Odometer:	Not Known	
Colour:		
Engine Number:		
Fuel Level:	%	

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	21/08/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHB8083C

Full Report - V1



Assessment Number: MSIG0030

Registration: SHB8083C

Version: LKKAUTOC/12

Printed: 05/09/2018 16:28

Date Calculated: 05/09/2018 09:27



**Addresses**

**Cost Summary**

Total Labour	\$980.00
Total Paint/Material	\$152.51
Total Parts	\$1,748.50
Total of Additional Costs	\$458.00
Excess:	TBA
Grand Total Exc GST:	\$3,339.01
7 % GST:	\$233.73
Grand Total Inc GST:	\$3,572.74

**Repair Information**

**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR  
Price/Dent = \$50.00/HR

**Repair /**

Guide Number	Repair Details	WU	Cost Price (\$)
87755R00	R + R R/SILL TRIM	3.0	15.00
86520R00	RENEW REAR BUMPER (REMOVED)	11.0	55.00
87111R00	REAR SCREEN R + R	22.0	110.00
	INCLUDES: REAR SEAT BACKREST AND ALL REQUIRED TRIMS REMOVE AND REFIT		
69200R00)	R + R BOOTLID	5.0	25.00
NO NUMBER	R + R BOOT LID BADGE	2.0	10.00
NO NUMBER	RENEW R/R SIDE PANEL	72.0	360.00
85875R00)	R + R R/R SILL MOULDING	1.0	5.00
68869R00)	R + R R/LOAD COMPARTMENT TRIM	1.0	5.00
85710R00	R + R BOOT CARPET	2.0	10.00
68869R0B)	R + R L/- AND R/BOOT TRIM (ADD)	2.0	10.00

**LABOUR COST**

<b>Total Work Units</b>	<b>121.0</b>	
<b>Corrosion Protection External Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Corrosion Protection Internal Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Sub Total</b>	<b>12.1HRS</b>	<b>\$605.00</b>
<b>Paint Labour</b>	<b>7.5HRS</b>	<b>\$375.00</b>
<b>Total Labour</b>	<b>19.6HRS</b>	<b>\$980.00</b>

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- BASECOAT CLEAR		
3486	R/R OUTER SIDE PANEL NEW PART PAINTING	31.0	
2583	REAR BUMPER NEW PART PAINT K1R	14.0	

**LABOUR COST - PAINT**

Claim Reference: SHB8083C  
 Assessment Number: MSIG0030  
 Version: LKKAUTOC/12  
 Date Calculated: 05/09/2018 09:27

Full Report - V1  
 Registration: SHB8083C  
 Printed: 05/09/2018 16:28

TIME(PAINT)	45.0	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	75.0	
Total Paintwork Labour	7.5HRS	\$375.00
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting		\$44.55
New Part Painting - Plastic K1R		\$70.36
Material-Constant Main Work Metal		\$28.60
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$152.51
Pearlescent Uplift @ 0.0%		\$0.00
<b>Total Paint Material Cost</b>		<b>\$152.51</b>

**PARTS**

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3288	1	R/R OUTER LAMP	924122T510		0%	421.00*
3486	1	R/R OUTER SIDE PANEL	715042TC00		0%	1,205.00F
3414	1	R/R REFLECTOR	924062T500		0%	46.00*
3015	1	REAR BADGE	863202T500		0%	29.00*
2583	1	REAR BUMPER	866112T500		0%	696.00*
2770	1	REAR BUMPER SPOILER	866122T500		0%	206.00*
3160	1	REAR SCREEN BOND KIT	ZK20063001A		0%	0.00F
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS		0%	0.00
3173	2	REAR SCREEN SPACER	871143K000		0%	0.00F
3171	10	REAR SCREEN SUPPORTS	861143D000		0%	0.00F
3169	1	REAR WINDOW MLDG	Renew		0%	87.00F
f: OEM Parts			Saving			\$103.31
g: Original			Sub Total			\$2,690.00
h: Secondhand			Deduction from RRP (35 %)			-\$941.50
p: Parallel			<b>Total Parts</b>			<b>\$1,748.50</b> ✓
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
REAR BUMPER CLIPS SPECIALIST	0%	\$48.00
REVERSE SENSOR SPECIALIST		\$200.00
SEALANT SPECIALIST	0%	\$50.00
REAR FENDER SPECIALIST		\$60.00
STICKER		
BOOTLID STICKER SPECIALIST	0%	\$100.00
<b>Total Extras</b>		<b>\$458.00</b> ✓

**Final Calculation**

<b>Total Parts</b>		<b>\$1,748.50</b> ✓
<b>Labour</b>		
Total Panel/Mechanical	\$605.00 ✓	
Total Paintwork	\$375.00 ✓	
<b>Total Labour</b>		<b>\$980.00</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHB8083C

Full Report - V1

Assessment Number: MSIG0030

Registration: SHB8083C

Version: LKKAUTOC/12

Printed: 05/09/2018 16:28

Date Calculated: 05/09/2018 09:27

---

Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$458.00	
<b>Total of Additional Costs</b>		<b>\$458.00</b>
<b>Total Paint/Material Costs</b>		<b>\$152.51</b>
<b>Grand Total Excludes GST</b>		<b>\$3,339.01</b>
GST @ 7 %		\$233.73
<b>Grand Total Includes GST</b>		<b>\$3,572.74</b>

---

### Assessment Notes

---

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		21 Aug 2018 09:31 <a href="#">Edit Adj Rpt</a>	<b>S\$2,650.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SOVEREIGN SECURITY SERVICES PTE LTD, Co. Reg. No.: 199105539W								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: NA								
Vehicle Reg. No.:	SHB8083C	Date of Loss:	18/08/2018 13:00 - :59 [33 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567843	Policy/Cover Note No.:	27019209SMP (Comprehensive) Coverage: 02/12/2017 - 01/12/2018						
Vehicle Reg. No. (Insured):	SBF9168K	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN ] ... [Final Rpt due 20/09/2018]								
Driver/Custodian (Insured):	APPASAMY NAGENDERAN (61 / Male), NRIC: S1241472B								
Adj Asg. Remarks:	SJE AGREE LKK and contact 65446676 / 65446689. Liab-100%								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### Claim Documents

**\*SHB8083C (567843)**  
**[SBF9168K]**  
 TP  
**PREMIER TAXIS PTE LTD**  
**Aug 18 2018 1:00PM**  
**[SOVEREIGN SECURITY SERVICES PTE LTD]**  
**Premier Taxis Pte Ltd - Changi**

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	24/08/18 17:10	Adjuster Immediate Advice		Load HTM			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
2	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
3	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
4	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
5	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
6	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
7	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
8	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
9	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
10	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
11	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
12	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
13	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
14	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
15	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
16	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
17	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
18	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
19	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
20	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
21	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
22	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
23	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
24	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
25	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
26	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
27	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
28	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
29	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
30	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
31	21/08/18 19:10	General View		Load JPG	<input checked="" type="checkbox"/>		
32	05/09/18 17:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
33	05/09/18 17:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
34	05/09/18 17:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			<input checked="" type="checkbox"/>
35	05/09/18 17:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	20/08/18 16:29	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1	Load PDF	
2	20/08/18 16:29	PRI & THIRD PARTY REPORT	1	Load PDF	
3	20/08/18 17:04	SJE AGREE LKK	1	Load PDF	
		OI ACCIDENT REPORT	1	Load PDF	
No	Relabel/Reorder			Thumbnail	Print
1	06/09/18 09:54	LKK Auto Consultants Pte Ltd (HQ)	1	Load PDF	
		AUTODAX			

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/MSG18015189/K1SD3E2

**Date:** 10/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27019209SMP
<b>Claimant Vehicle No :</b> SHB8083C	<b>Insured Vehicle No :</b>	SBF9168K
Date of Loss: 18/08/2018	Nature of Claim: TP	Claim No: 567843

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB8083C</b>	Engine No:	D4FDFH314179
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5642417
Reg. Date:	06/11/2015 (Man. Year: 2015)	Odometer:	480458 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	4,080.10	2,206.50	1,873.60	45.92	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,769.95	1,132.51	637.44	36.01	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>5,850.05</b>	<b>3,339.01</b>	<b>2,511.04</b>	<b>42.92</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>2,650.00</b>			
	(S\$)	5,850.05	2,650.00	3,200.05	54.70
<b>+ GST 7.00/7.00% (S\$)</b>	409.50	185.50	224.00	54.70	
<b>Nett Amount (S\$)</b>	<b>6,259.55</b>	<b>2,835.50</b>	<b>3,424.05</b>	<b>54.70</b>	

INSPECTION

Date of Assignment:	21/08/2018		
Date Inspected:	21/08/2018	Inspected At:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02 Singapore 486443
Estimated Period of Repair:	5.0 days		

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
<b>Parts:</b> 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHB8083C)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,119.00 FL	*- FL
2	1		*BOOTLID OUT PANEL	Repair	290.00 FL	*- FL
3	1		*LWR REAR WINDOW MLDG	Necessary	87.00 FL	*87.00 FL
4	1		*R/R BUMPER BRACKET	Serviceable	29.00 FL	*- FL
5	1		*R/R C-MEMBER BRACKET	Serviceable	54.00 FL	*- FL
6	1		*R/R OUTER LAMP	Cracked	421.00 FL	*421.00 FL
7	1		*R/R OUTER SIDE PANEL	Dented	1,205.00 FL	*1,205.00 FL
8	1		*R/R REFLECTOR	Cracked	46.00 FL	*46.00 FL
9	1		*R/R VENT GRILLE	Serviceable	30.00 FL	*- FL
10	1		*R/R WHEELHOUSE CVR	Repair	120.00 FL	*- FL
11	1		*REAR BADGE	Necessary	29.00 FL	*29.00 FL
12	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
13	1		*REAR BUMPER DAMPER	Serviceable	114.00 FL	*- FL
14	1		*REAR BUMPER SPOILER	Deformed	206.00 FL	*206.00 FL
15	1		*REAR BUMPER SUPPORT	Serviceable	607.00 FL	*- FL
16	1		*REAR PANEL	Serviceable	250.00 FL	*- FL
17	1		*REAR SCREEN BOND KIT	Not Necessary	80.81 FL	*- FL
18	1		*SET REAR SCREEN FIX (NPA)	Not Necessary	0.00 FL	*- FL
19	2		*REAR SCREEN SPACER	Not Necessary	7.20 FL	*- FL
20	10		*REAR SCREEN SUPPORTS	Not Necessary	15.30 FL	*- FL
21	1		*REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
22	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*SEALANT	Necessary	50.00 FS	*50.00 FS
24	1		*FENDER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
25	1		*REAR FENDER STICKER	Necessary	60.00 FS	*60.00 FS
26	1		*BOOTLID STICKER	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,972.31</b>	<b>3,148.00</b>
- List Item Discount on L Items 35.00/35.00% (S\$)	1,892.21	941.50
<b>Total Parts (S\$)</b>	<b>4,080.10</b>	<b>2,206.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL PANEL / MECHANICAL	New	915.00	605.00
2	TOTAL PAINTWORK	New	605.00	375.00
3	TOTAL PAINT / MATERIAL COSTS	New	249.95	152.51
			<b>Gross Labour Cost (S\$)</b>	<b>1,769.95</b>
				<b>1,132.51</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >