

12/03/2003

ASS. REC. BY:

REF: CS/CTI18015191/Ktd3/n2

Special Instruction:

Survivor:
Munnen

Kenneth

ASSIGNMENT (Office)

From (Person): chong Baun Sen

of

CTI

Date/Time: 20/8/18 @ 5.06pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 8391T

Insured:

SLS 7844T

at Workshop m/s

Ah Lim Motor

Tel:

6483 1241

of

10 AMK Ind. Park 2A # 01-09

Policy No:

DMPCS N3081271700

Claim No:

8NM18D03983C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/08/2018

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

24/8/18 @ 1pm owner writing

Date/Time:

9.44am @ 21/8/18

Person Contacted:

Zila

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SKR 8391T - X
	SLS 7844T - X
	Part by Part \$3566.91 (Red: \$2578.56: 41%)

(08/11/12) wof
ASS. REC. BY:

REF: C11

ASSIGNMENT

From: Date: 24/8/18

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JKR 8391 T

at Workshop n/s Ah Lim Motor

of 10 AMK Ind. park 2A # 01-09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

1 pm @ owner waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3-5 days Res.: Yes or No

Lum Sum: 1.8.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKR 8391 T Yr Regn: 03, 15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Gashga c.c. 1197

Colour: n. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 48847 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: STNFEAT11 U 1284838

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 18/8/18

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 24/8/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
27/8 File pass to Catherine

RECEIVED 12 DEC 2018

Date/Time, File Pass to?

1) 12/12 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format : TP

Lump Sum / I.B.I. (\$) 3566, 91



LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

CHINA TAIPING INSURANCE (S) PTE LTD

Ref: CS/CTI18015191/Ktd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date: 21-08-2018



Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7844T	Veh. Inspected	SKR 8391T
Policy No.	DMPCSN3081271700	Coverage (\$)	0.00
Claim No.	SNM18D03983C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/08/2018	Inspect Date / Time	24/08/2018(-)
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Report Ref No. CS/CTI18015191/Ktd3

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		20 Aug 2018 17:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHEN TIEJUN, ID: S2678046B		
Main Claimant:	CHYE SOON HUAT, ID: S6946965E		
Vehicle Reg. No.:	SKR8391T	Date of Loss:	16/08/2018 08:00 - :59
Claim Type:	TP / SNM18D03983C02	Policy/Cover Note No.:	DMPCSN3081271700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLS7844T	Policy No. (Claimant):	MP307015
		Excess:	S\$0.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	HL Assurance Pte Ltd (HQ) - Tel: 69226030		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/08/2018]		
Driver/Custodian (Insured):	CHEN TIEJUN (54 / Male), NRIC: S2678046B		
Adj Asg. Remarks:	EST \$6499.58, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6965E

Vehicle Details

Vehicle No.:

SKR8391T

Vehicle to be Exported:

No

Intended De-registration Date:

16 Aug 2018

Vehicle Make:

NISSAN

Vehicle Model:

QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Primary Colour:

Grey

Manufacturing Year:

2014

Engine No.:

HRA2106321A

Chassis No.:

SJNFEAJ11U1284838

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$19,382.00

Original Registration Date:

12 Mar 2015

First Registration Date:

12 Mar 2015

Transfer Count:

0

Actual ARF Paid:

\$9,382.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Mar 2025

PARF Rebate Amount:

\$7,036.00

Intended COE Rebate Details

COE Expiry Date:

11 Mar 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$57,199.00

COE Rebate Amount:

\$37,552.00

Total Rebate Amount:

\$44,588.00

The information contained herein is correct as at 16 Aug 2018

OK



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimumo@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: CHYE SOON HUAT
495 YIO CHU KANG ROAD
#07-01
SINGAPORE 787080

Estimate No: MC0913364
Date: 20 Aug 2018
Policy No: MP307015
Veh Reg No: SKR8391T
Make/Model: NISSAN QASHQAI 1.2 DIG

ATTN:

Your Ref No: SKR8391T
Claim Type: Third Party - CHINA TAI-PING
Accident Date: 16/08/2018
TP Veh Reg No: SLS7844T

bumble like Not what we want
1.B.1
Return by 3-5 days
P/p 1.10pm

Estimate Repair Cost to Vehicle No :SKR8391T

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1- TAILGATE-LOGO-(QASHQAI)-LH	1-PC	nn 87.00	X
2 REAR BUMPER	1 PC	nn 717.00	—
3 REAR BUMPER SIDE RETAINERS	12PC	nn 21.80	4 + 35.90
4 REAR BUMPER CLIPS	12 PC	nn 52.80	—
5 REAR BUMPER REINFORCEMENT	1 PC	nn 619.20	7-Photo
6 REAR BUMPER REINFORCEMENT BRACKET	1 PC	nn 126.00	7 Photo
7- REAR-BUMPER-SPONGE	1-PC	nn 126.40	X
8- REAR-BUMPER-LOWER-SIDE-REFLECTOR	2-PC	nn 110.00	X
9- REAR-END PANEL	1-PC	nn 482.60	X
10- REAR-END PANEL-TOP GARNISH	1-PC	nn 73.50	X
11- REAR-FENDER-WHEEL-ARCH	1-PC	nn 483.00	X
		2,949.30	
	Less 10%	294.93	2,654.37
Special Nett			
12 REVERSE SENSOR SIDE	2 SET	Start 560.00	—
13 REVERSE SENSOR CTR	2 SET	Start 560.00	—
		1,120.00	1,120.00
LABOUR			
14 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20
15- TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1-PC	nn 280.00	X
16 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	160.00	60
17- TO SPRY-ANTI-RUST-COATING-ON-AFFECTED-AREAS.	1-PC	nn 120.00	X
18 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL, RR BUMPER REINFORCEMENT TO KNOCK & REPAIR TAILGAT, SPARE TYRE PANEL, REAR FENDER RH INNER PANELS & AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	400
19 TO SPRAY TAILGATE, REAR BUMPER, REAR BUMPER REINFORCEMENT, SPARE TYRE PANEL, END PANEL, REAR FENDER RH.	1 PC	900.00	500
		2,300.00	2,300.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHYE SOON HUAT
495 YIO CHU KANG ROAD
#07-01
SINGAPORE 787080

Estimate No: MC0913364
Date: 20 Aug 2018
Policy No: MP307015
Veh Reg No: SKR8391T
Make/Model: NISSAN QASHQAI 1.2
DIG

ATTN:

Your Ref No: SKR8391T
Claim Type: Third Party
Accident Date: 16/08/2018
TP Veh Reg No: SLS7844T

Estimate Repair Cost to Vehicle No :SKR8391T

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 6,074.37
		Add GST @ 7%	425.21
		Total Amount Payable	S\$ 6,499.58

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FOUR HUNDRED NINETY NINE AND CENTS FIFTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



6145.47



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHYE SOON HUAT
495 YIO CHU KANG ROAD
#07-01
SINGAPORE 787080

Estimate No: MC0913364
Date: 20 Aug 2018
Policy No: MP307015
Veh Reg No: SKR8391T
Make/Model: NISSAN QASHQAI 1.2 DIG

ATTN:

Your Ref No: SKR8391T
Claim Type: Third Party - CHINA TAI-PING
Accident Date: 16/08/2018
TP Veh Reg No: SLS7844T

*Not authorized
1.B.1
Recovery by painting
3-5 days*

Estimate Repair Cost to Vehicle No :SKR8391T

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 TAILGATE LOGO (QAHSQAI) LH	1 PC	an 87.00	X
2 REAR BUMPER	1 PC	Bu 717.00	—
3 REAR BUMPER SIDE RETAINERS	2 PC	also 71.80	LT
4 REAR BUMPER CLIPS	12 PC	me 52.80	—
5 REAR BUMPER REINFORCEMENT	1 PC	BT 619.20	✓
6 REAR BUMPER REINFORCEMENT BRACKET	1 PC	BT 126.00	✓
7 REAR BUMPER SPONGE	1 PC	SLC 126.40	X
8 REAR BUMPER LOWER SIDE REFLECTOR	2 PC	SL 110.00	X
9 REAR END PANEL	1 PC	R 482.60	X
10 REAR END PANEL TOP GARNISH	1 PC	SL 73.50	X
11 REAR FENDER WHEEL ARCH	1 PC	SLC 483.00	X
		2,949.30	
	Less 10%	294.93	2,654.37
Special Nett			
12 REVERSE SENSOR SIDE	2 SET	shot 560.00	—
13 REVERSE SENSOR CTR	2 SET	shot 560.00	—
		1,120.00	1,120.00
LABOUR			
14 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
15 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	an 280.00	X
16 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	160.00	601
17 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	an 120.00	X
18 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,RR BUMPER REINFORCEMENT.TO KNOCK & REPAIR TAILGAT,SPARE TYRE PANEL,REAR FENDER RH INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	4001
19 TO SPRAY TAILGATE,REAR BUMPER,REAR BUMPER REINFORCEMENT,SPARE TYRE PANEL,END PANEL, REAR FENDER RH.	1 PC	900.00	501
		2,300.00	2,300.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : CHYE SOON HUAT
495 YIO CHU KANG ROAD
#07-01
SINGAPORE 787080

Estimate No: MC0913364
Date: 07 Sep 2018
Policy No: MP307015
Veh Reg No: SKR8391T
Make/Model: NISSAN QASHQAI 1.2 DIG

ATTN:

Your Ref No: SNM18D03983
Claim Type: Third Party
Accident Date: 16/08/2018
TP Veh Reg No: SLS7844T

Estimate Repair Cost to Vehicle No :SKR8391T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR BUMPER CLIPS (WHITE)	3 PC	52.20	
2 REAR BUMPER LOW COVER	1 PC	26.80	
		79.00	
	Less 10%	7.90	71.10
	Total		S\$ 71.10
	GST Amount		S\$ 4.98
	Total Amount Payable		S\$ 76.08

The above vehicle was surveyed by KENNETH KONG -LKK on 24/08/2018

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : CHYE SOON HUAT
495 YIO CHU KANG ROAD
#07-01
SINGAPORE 787080

Claim No: MC0913364
No: MF0911468
Date: 09 Nov 2018
Policy No: MP307015
Veh Reg No: SKR8391T
Make/Model: NISSAN QASHQAI 1.2 DIG

ATTN:

Your Ref No: SNM18D03983
Claim Type: Third Party
Accident Date: 16/08/2018
TP Veh Reg No: SLS7844T

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKR8391T

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	717.00	
2 REAR BUMPER SIDE RETAINER RH	1 PC	35.90	
3 REAR BUMPER CLIPS	12 PC	52.80	
4 REAR BUMPER REINFORCEMENT	1 PC	619.20	
5 REAR BUMPER REINFORCEMENT BRACKET RH	1 PC	126.00	
6 REAR BUMPER CLIPS (WHITE)	3 PC	52.20	
7 REAR BUMPER LOW COVER	1 PC	26.80	
		1,629.90	
	Less 10%	162.99	1,466.91
Special Nett			
8 REVERSE SENSOR SIDE	2 SET	560.00	
9 REVERSE SENSOR CTR	2 SET	560.00	
		1,120.00	1,120.00
LABOUR			
10 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
11 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
12 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,RR BUMPER REINFORCEMENT.TO KNOCK & REPAIR TAILGAT,SPARE TYRE PANEL,REAR FENDER RH INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	
13 TO SPRAY TAILGATE,REAR BUMPER,REAR BUMPER REINFORCEMENT,SPARE TYRE PANEL,END PANEL, REAR FENDER RH.	1 PC	500.00	
		980.00	980.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore
Tel: 6483 1244



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047

TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg

GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : CHYE SOON HUAT
495 YIO CHU KANG ROAD
#07-01
SINGAPORE 787080

Claim No: MC0913364
No: MF0911468
Date: 09 Nov 2018
Policy No: MP307015
Veh Reg No: SKR8391T
Make/Model: NISSAN QASHQAI 1.2 DIG

ATTN:

Your Ref No: SNM18D03983
Claim Type: Third Party
Accident Date: 16/08/2018
TP Veh Reg No: SLS7844T

Repair Cost to Vehicle No (For Finalization):SKR8391T

Description	Quantity	List Price	Amount
		SS	SS
	Total		SS 3,566.91
	Less Excess		SS 0.00
	Amount Before GST		SS 3,566.91
	Add GST @ 7%		249.68
	Total Amount Payable		SS 3,816.59

TOTAL: SINGAPORE DOLLAR THREE THOUSAND EIGHT HUNDRED SIXTEEN AND CENTS FIFTY NINE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 24/08/2018

For AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORIZED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015191/KTD3N2

Date: 17/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3081271700
Claimant Vehicle No :	SKR8391T	Insured Vehicle No :	SLS7844T
Date of Loss:	16/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03983C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR8391T	Engine No:	HRA2106321A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Chassis No:	SJNFEAJ11U1284838
Reg. Date:	12/03/2015 (Man. Year: 2014)	Odometer:	46847 km
Colour:	Metallic Grey		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 3 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,845.47	2,586.91	1,258.56	32.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	980.00	1,320.00	57.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,145.47	3,566.91	2,578.56	41.96
+ GST 7.00/7.00% (\$\$)	430.18	249.68	180.50	41.96
Nett Amount (\$\$)	6,575.65	3,816.59	2,759.06	41.96

INSPECTION

Date of Assignment:	20/08/2018	
Date Inspected:	24/08/2018 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR8391T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOGO (QASHQAI) LH	Not Necessary	87.00 FL	*- FL
2	1		*REAR BUMPER	Buckled	717.00 FL	*717.00 FL
3	1		*REAR BUMPER SIDE RETAINERS	O/s Distorted	71.80 FL	*35.90 FL
4	12		*REAR BUMPER CLIPS	Necessary	52.80 FL	*52.80 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	619.20 FL	*619.20 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET	Bent	126.00 FL	*126.00 FL
7	1		*REAR BUMPER SPONGE	Serviceable	126.40 FL	*- FL
8	1		*REAR BUMPER LOWER SIDE REFLECTOR	Serviceable	110.00 FL	*- FL
9	1		*REAR END PANEL	Repair	482.60 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	73.50 FL	*- FL
11	1		*REAR FENDER WHEEL ARCH	Serviceable	483.00 FL	*- FL
12	2		*SET REVERSE SENSOR SIE	Shorted	560.00 FS	*560.00 FS
13	2		*SET REVERSE SENSOR CTR	Shorted	560.00 FS	*560.00 FS
14	3		*REAR BUMPER CLIPS (WHITE)	Cracked	52.20 FL	*52.20 FL
15	1		*REAR BUMPER LOW COVER	Dented	26.80 FL	*26.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,148.30	2,749.90
- List Item Discount on L Items 10.00/10.00% (S\$)	302.83	162.99
Total Parts (S\$)	3,845.47	2,586.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL CUSHION SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	280.00	-
3	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	160.00	60.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	120.00	-
5	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,RR BUMPER REINFORCEMENT.TO KNOCK & REPAIR TAILGATE,SPARE TYRE PANEL,REAR FENDER RH INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
6	TO SPRAY TAILGATE,REAR BUMPER,REAR BUMPER REINFORCEMENT,SPARE TYRE PANEL,END PANEL,REAR FENDER RH	New	900.00	500.00
Gross Labour Cost (S\$)			2,300.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >