

22/03/2002

A REC. BY:

REF:

CS / SPF 18015196 / T170627

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Lim Wei Yea

of

SPF

Date/Time: 20082018 338pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 704A

Insured:

at Workshop m/s

SMRT

Tel:

of

60 Woodlands Ind Park E4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

04.09.2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

QX 704A - X

7/9/18

Revert to Wei Yea thru email.

Tanpho

REF:

SPF

AD-01/01/01

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No. QX704A. Yr Regn: \_\_\_\_\_  
 Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Avante C.C. \_\_\_\_\_  
 Colour: white A/C Insured / Std / NI / NA  
 Sp. Reading: 209711 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: \_\_\_\_\_  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: 77  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Fallen  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 4/4/18  
 Survey held at 2B Sg Kalut Drive  
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Parts : \$2521.00 , Man Hour : 29 hours

RECEIVED 13 NOV 2018

Date/Time, File Pass to?

1) typ4

Date/Time, File Return to?

2)

Report Format :

Lump Sum / LB : \$

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp \$

☐

: Inter Insp \$

☐

: Tech Insp \$

☐

: Material \$

Survey Fee

Transportation

Sub Total

Grand Total

Net Total

1

TOTAL

200

200

## Catherine Chong (LKK Auto)

---

**From:** Wei Yea LIM (SPF) <LIM\_Wei\_Yea@spf.gov.sg>  
**Sent:** Monday, 20 August, 2018 3:38 PM  
**To:** assignments  
**Cc:** Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto)'  
**Subject:** Appraisal Services for SPF vehicles at SMRT Automotive Services (QX704A)  
**Attachments:** QX704A.XLSX

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 704A

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM  
Contract Management  
AEMD, Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4844



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18015196/T1rb		
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 21-08-2018		
		Code : SPF3		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.	Veh. Inspected		QX 704A	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	LIM WEI YEA	Assign Date	20/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	Inspection Date		04/09/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				



**Scope Of Work**  
**Home Team Agency**

**SCOPE OF WORK**

**1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:**

CONTRACTOR:	SMRT	VEH TYPE:	FRC	UNIT:	SENGKANG NPC
VEH NO:	QX704A	REPAIR TYPE:	ACCIDENT		
VEH MAKE/MODEL:	HYUNDAI AVANTE	ODOMETER:	209711		


**Reference No.** 0704/SPF/4W/18/08/13

**iLMS No.** 1100010327

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
<b>1</b>	<b>Scope Of Repairs</b>					
1.1	Front Bumper <i>de</i>	\$250.00	1		250.00	250.00
1.2	Front Bumper Retainers LH & RH <i>de</i>	\$45.00	2		45.00	90.00
1.3	Front Bumper Reinforcement <i>bt</i>	\$135.00	1		135.00	135.00
1.4	Front Bumper Sponge <i>and</i>	\$65.00	1		65.00	65.00
1.5	Front Bumper Lower Grill <i>de</i>	\$35.00	1		35.00	35.00
1.6	Front Support Panel <i>bt</i>	\$360.00	1		360.00	360.00
1.7	Centre Engine Lower Cover <i>de</i>	\$30.00	1		30.00	30.00
1.8	RHS Fog Lamp Cover <i>mis</i>	\$26.00	1		26.00	26.00
1.9	RHS Head Lamp <i>and</i>	\$235.00	1		235.00	235.00
1.10	RHS Head Lamp Bracket <i>de</i>	\$25.00	1		25.00	25.00
1.11	Wiper Tank <i>X</i>	\$50.00	1		50.00	50.00
1.13	Radiator <i>bt</i>	\$280.00	1		280.00	280.00
1.14	Radiator Upper Hose <i>twi</i>	\$35.00	1		35.00	35.00
1.15	Radiator Lower Hose <i>de</i>	\$35.00	1		35.00	35.00
1.16	Radiator Fan Motor Assy <i>bt</i>	\$220.00	1		220.00	220.00
1.17	Air-Con Condenser <i>bt</i>	\$230.00	1		230.00	230.00
1.18	Air-Con Condenser Piping <i>bt</i>	\$420.00	1		420.00	420.00
1.19	Front Number Plate with Casing <i>mis</i>	\$50.00	1		50.00	50.00
<b>2</b>	<b>Additional Services</b>					
2.1	Front RH Door Frame Rubber Seal <i>X</i>	\$150.00	1		150.00	150.00
2.2	Front LH Door Frame Rubber Seal <i>X</i>	\$150.00	1		150.00	150.00
2.3	Rear LH Door Frame Rubber Seal <i>X</i>	\$150.00	1		150.00	150.00
2.4	Front LH Door Scuff <i>X</i>	\$30.00	1		30.00	30.00
<b>Remarks:</b> Items 1.20-1.23 requires Overseas Indentment ETA:- 6 to 8 weeks					<b>Parts Total:</b>	<b>\$ 3,051.00</b>

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
<b>1</b>	<b>Scope Of Repairs</b>			
1.1	<b>Front Bumper &amp; Front Number Plate:</b>		5	0.00
	Remove & Replace Front Bumper			
	Remove & Replace Both Side Front Bumper Retainers			
	Remove & Replace Both Side Front Bumper Brackets			
	Replace Front Number Plate			
	Replace RHS Fog Lamp Cover			
	Remove & Re-Install back Emblem & Radiator Grill onto new Front Bumper			
	Putty & Spray Paint for Front Complete Bumper (2 colours)			
1.2	<b>Front Bumper Lower Grill &amp; Engine Under Cover</b>		1	0.00
	Remove & Replace Front Bumper Lower Grill			
	Replace Centre Engine Lower Cover			
1.3	<b>Front Support Panel:</b>		4	0.00
	Remove & Replace Front Support Panel			
1.4	<b>Front Bumper Reinforcement &amp; Sponge:</b>		4	0.00
	Remove & Replace Front Bumper Reinforcement			
	Remove & Replace Front Bumper Sponge			
1.5	<b>RHS Head Lamp:</b>		1	0.00
	Remove & Replace RHS Head Lamp			
	Remove & Replace RHS Head Lamp Bracket			
	Wiring for RHS Head Lamp			
1.6	<b>Wiper Tank:</b> <i>X</i>		1	0.00
	Remove & Replace Wiper Tank			
1.7	<b>Radiator:</b>	<i>6</i>	8	0.00
	Remove & Replace Raditor			
	Remove & Replace Raditor Upper Hose			
	Remove & Replace Radiator Lower Hose			
	Remove & Replace Radiator Fan Motor Assy			
	Top Up Coolant for Radiator			
1.8	<b>Air-Con Condenser:</b>	<i>8</i>	12	0.00
	Remove & Replace Air-Con Condenser			
	Remove & Replace Air-Con Condenser Piping			
	Top Up Air-Con Gas			
<b>2</b>	<b>Additional Services</b>			

2.1	<b>Rubber Seal &amp; Door Scuff:</b> ✕		2	0.00
	Remove & Replace front RH Door Frame Rubber Seal ✕			
	Replace Front LH Door Frame Rubber Seal ✕			
	Replace Rear LH Door Frame Rubber Seal ✕			
	Replace front LH Door Scuff ✕			
2.2	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80
2.3	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20
			<b>Labour Total:</b>	<b>\$ 238.00</b>
			<b>GRAND TOTAL :</b>	<b>\$ 3,289.00</b>
			<b>Total sum billed under SOR only :</b>	<b>\$ 238.00</b>
			<b>Total sum billed under CVR only :</b>	<b>\$ 3,051.00</b>
<b>Contractor shall complete the entire repair within <u>40</u> working days upon vehicle collection date . (Include parts awaiting time)</b>				

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:	*	Name:	
Date:	16.08.2018	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	FRONT BUMPER	1	DEFORMED	\$250.00	\$250.00	
1.2	FRONT BUMPER RETAINER LH & RH	2	NECESSARY	\$45.00	\$90.00	
1.3	FRONT BUMPER REINFORCEMENT	1	BENT	\$135.00	\$135.00	
1.4	FRONT BUMPER SPONGE	1	CRACKED	\$65.00	\$65.00	
1.5	FRONT BUMPER LOWER GRILLE	1	DENTED	\$35.00	\$35.00	
1.6	FRONT SUPPORT PANEL	1	BENT	\$360.00	\$360.00	
1.7	CENTRE ENGINE LOWER COVER	1	DENTED	\$30.00	\$30.00	
1.8	RHS FOG LAMP COVER	1	MISSING	\$26.00	\$26.00	
1.9	RHS HEAD LAMP	1	CRACKED	\$235.00	\$235.00	
1.10	RHS HEAD LAMP BRACKET	1	NECESSARY	\$25.00	\$25.00	
1.11	WIPER TANK	1	NOT NECESSARY	\$50.00	\$0.00	
1.12	RADIATOR	1	BENT	\$280.00	\$280.00	
1.13	RADIATOR UPPER HOSE	1	TWISTED	\$35.00	\$35.00	
1.14	RADIATOR LOWER HOSE	1	DENTED	\$35.00	\$35.00	
1.15	RADIATOR FAN MOTOR ASSY	1	JAM	\$220.00	\$220.00	
1.16	AIR-CON CONDENSER	1	BENT	\$230.00	\$230.00	
1.17	AIR-CON CONDENSER PIPING	1	BENT	\$420.00	\$420.00	
1.18	FRONT NUMBER PLATE WITH CASING	1	MISSING	\$50.00	\$50.00	
<b>2</b>	<b>SCOPE OF REPAIRS</b>					
1.1	Front Bumper & Front Number Plate:					5
	Remove & Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers					
	Remove & Replace Both Side Front Bumper Brackets					
	Replace Front Number Plate					
	Replace RHS Fog Lamp Cover					
	Remove & Re-install back Emblem & Radiator Grill onto new Front Bumper					
	Putty & Spray Paint for Front Complete Bumper (2 colours)					
1.2	Front Bumper Lower Grill & Engine Under Cover					1
	Remove & Replace Front Bumper Lower Grill					
	Replace Centre Engine Lower Cover					
1.3	Front Support Panel:					4
	Remove & Replace Front Support Panel					
1.4	Front Bumper Reinforcement & Sponge:					4
	Remove & Replace Front Bumper Reinforcement					
	Remove & Replace Front Bumper Sponge					
1.5	RHS Head Lamp:					1
	Remove & Replace RHS Head Lamp					
	Remove & Replace RHS Head Lamp Bracket					
	Wiring for RHS Head Lamp					
1.6	Wiper Tank:					
	Remove & Replace Wiper Tank					
1.7	Radiator:					6
	Remove & Replace Raditor					
	Remove & Replace Raditor Upper Hose					
	Remove & Replace Radiator Lower Hose					
	Remove & Replace Radiator Fan Motor Assy					
	Top Up Coolant for Radiator					
1.8	Air-Con Condenser:					8
	Remove & Replace Air-Con Condenser					
	Remove & Replace Air-Con Condenser Piping					
	Top Up Air-Con Gas					
2.1	Rubber Seal & Door Scuff:					0
	Remove & Replace front RH Door Frame Rubber Seal					
	Replace Front LH Door Frame Rubber Seal					
	Replace Rear LH Door Frame Rubber Seal					
	Replace front LH Door Scuff					
COSTING		TOTAL PARTS COST			\$2,521.00	
		TOTAL MAN-HOUR				29

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	FRONT BUMPER	1	DEFORMED	\$250.00	\$250.00	
1.2	FRONT BUMPER RETAINER LH & RH	2	NECESSARY	\$45.00	\$90.00	
1.3	FRONT BUMPER REINFORCEMENT	1	BENT	\$135.00	\$135.00	
1.4	FRONT BUMPER SPONGE	1	CRACKED	\$65.00	\$65.00	
1.5	FRONT BUMPER LOWER GRILLE	1	DENTED	\$35.00	\$35.00	
1.6	FRONT SUPPORT PANEL	1	BENT	\$360.00	\$360.00	
1.7	CENTRE ENGINE LOWER COVER	1	DENTED	\$30.00	\$30.00	
1.8	RHS FOG LAMP COVER	1	MISSING	\$26.00	\$26.00	
1.9	RHS HEAD LAMP	1	CRACKED	\$235.00	\$235.00	
1.10	RHS HEAD LAMP BRACKET	1	NECESSARY	\$25.00	\$25.00	
1.11	WIPER TANK	1	NOT NECESSARY	\$50.00	\$0.00	
1.12	RADIATOR	1	BENT	\$280.00	\$280.00	
1.13	RADIATOR UPPER HOSE	1	TWISTED	\$35.00	\$35.00	
1.14	RADIATOR LOWER HOSE	1	DENTED	\$35.00	\$35.00	
1.15	RADIATOR FAN MOTOR ASSY	1	JAM	\$220.00	\$220.00	
1.16	AIR-CON CONDENSER	1	BENT	\$230.00	\$230.00	
1.17	AIR-CON CONDENSER PIPING	1	BENT	\$420.00	\$420.00	
1.18	FRONT NUMBER PLATE WITH CASING	1	MISSING	\$50.00	\$50.00	
<b>2</b>	<b>SCOPE OF REPAIRS</b>					
1.1	Front Bumper & Front Number Plate:					5
	Remove & Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers					
	Remove & Replace Both Side Front Bumper Brackets					
	Replace Front Number Plate					
	Replace RHS Fog Lamp Cover					
	Remove & Re-Install back Emblem & Radiator Grill onto new Front Bumper					
	Putty & Spray Paint for Front Complete Bumper (2 colours)					
1.2	Front Bumper Lower Grill & Engine Under Cover					1
	Remove & Replace Front Bumper Lower Grill					
	Replace Centre Engine Lower Cover					
1.3	Front Support Panel:					4
	Remove & Replace Front Support Panel					
1.4	Front Bumper Reinforcement & Sponge:					4
	Remove & Replace Front Bumper Reinforcement					
	Remove & Replace Front Bumper Sponge					
1.5	RHS Head Lamp:					1
	Remove & Replace RHS Head Lamp					
	Remove & Replace RHS Head Lamp Bracket					
	Wiring for RHS Head Lamp					
1.6	Wiper Tank:					
	Remove & Replace Wiper Tank					
1.7	Radiator:					6
	Remove & Replace Raditor					
	Remove & Replace Raditor Upper Hose					
	Remove & Replace Radiator Lower Hose					
	Remove & Replace Radiator Fan Motor Assy					
	Top Up Coolant for Radiator					
1.8	Air-Con Condenser:					8
	Remove & Replace Air-Con Condenser					
	Remove & Replace Air-Con Condenser Piping					
	Top Up Air-Con Gas					
2.1	Rubber Seal & Door Scuff:					0
	Remove & Replace front RH Door Frame Rubber Seal					
	Replace Front LH Door Frame Rubber Seal					
	Replace Rear LH Door Frame Rubber Seal					
	Replace front LH Door Scuff					
<b>COSTING</b>		<b>TOTAL PARTS COST</b>			<b>\$2,521.00</b>	
		<b>TOTAL MAN-HOUR</b>				<b>29</b>





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18015196/T1rbe2

CONTRACT MANAGEMENT SECTION  
(SINGAPORE POLICE FORCE) 1 MOUNT  
PLEASANT ROAD BLK 8 OLD POLICE  
ACADEMY SINGAPORE 298333

Date : 03-12-2018



ATTN : LIM WEI YEA

Code : SPF3

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 704A
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From LIM WEI YEA	Assign Date	20/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KMH DU41BMAU019537	Colour	WHITE
Odometer	209711	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	Inspection Date	04/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	

## 5a. Remarks

--



Registration No. QX 704A

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT BUMPER	1	DEFORMED	\$250.00	\$250.00	
1.2	FRONT BUMPER RETAINER LH & RH	2	NECESSARY	\$45.00	\$90.00	
1.3	FRONT BUMPER REINFORCEMENT	1	BENT	\$135.00	\$135.00	
1.4	FRONT BUMPER SPONGE	1	CRACKED	\$65.00	\$65.00	
1.5	FRONT BUMPER LOWER GRILLE	1	DENTED	\$35.00	\$35.00	
1.6	FRONT SUPPORT PANEL	1	BENT	\$360.00	\$360.00	
1.7	CENTRE ENGINE LOWER COVER	1	DENTED	\$30.00	\$30.00	
1.8	RHS FOG LAMP COVER	1	MISSING	\$26.00	\$26.00	
1.9	RHS HEAD LAMP	1	CRACKED	\$235.00	\$235.00	
1.10	RHS HEAD LAMP BRACKET	1	NECESSARY	\$25.00	\$25.00	
1.11	WIPER TANK	1	NOT NECESSARY	\$50.00	\$0.00	
1.12	RADIATOR	1	BENT	\$280.00	\$280.00	
1.13	RADIATOR UPPER HOSE	1	TWISTED	\$35.00	\$35.00	
1.14	RADIATOR LOWER HOSE	1	DENTED	\$35.00	\$35.00	
1.15	RADIATOR FAN MOTOR ASSY	1	JAM	\$220.00	\$220.00	
1.16	AIR-CON CONDENSER	1	BENT	\$230.00	\$230.00	
1.17	AIR-CON CONDENSER PIPING	1	BENT	\$420.00	\$420.00	
1.18	FRONT NUMBER PLATE WITH CASING	1	MISSING	\$50.00	\$50.00	
2	SCOPE OF REPAIRS					
1.1	Front Bumper & Front Number Plate:					5
	Remove & Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers					
	Remove & Replace Both Side Front Bumper Brackets					
	Replace Front Number Plate					

	Replace RHS Fog Lamp Cover					
	Remove & Re-Install back Emblem & Radiator Grill onto new Front Bumper					
	Putty & Spray Paint for Front Complete Bumper (2 colours)					
1.2	<b>Front Bumper Lower Grill &amp; Engine Under Cover</b>					1
	Remove & Replace Front Bumper Lower Grill					
	Replace Centre Engine Lower Cover					
1.3	<b>Front Support Panel:</b>					4
	Remove & Replace Front Support Panel					
1.4	<b>Front Bumper Reinforcement &amp; Sponge:</b>					4
	Remove & Replace Front Bumper Reinforcement					
	Remove & Replace Front Bumper Sponge					
1.5	<b>RHS Head Lamp:</b>					1
	Remove & Replace RHS Head Lamp					
	Remove & Replace RHS Head Lamp Bracket					
	Wiring for RHS Head Lamp					
1.6	<b>Wiper Tank:</b>					
	Remove & Replace Wiper Tank					
1.7	<b>Radiator:</b>					6
	Remove & Replace Raditor					
	Remove & Replace Raditor Upper Hose					
	Remove & Replace Radiator Lower Hose					
	Remove & Replace Radiator Fan Motor Assy					
	Top Up Coolant for Radiator					
1.8	<b>Air-Con Condenser:</b>					8
	Remove & Replace Air-Con Condenser					
	Remove & Replace Air-Con Condenser Piping					
	Top Up Air-Con Gas					
2.1	<b>Rubber Seal &amp; Door Scuff:</b>					0
	Remove & Replace front RH Door Frame Rubber Seal					
	Replace Front LH Door Frame Rubber Seal					
	Replace Rear LH Door Frame Rubber Seal					
	Replace front LH Door Scuff					

COSTING	TOTAL PARTS COST	\$2,521.00	
	TOTAL MAN-HOUR		29

Registration No. QX 704A

Vehicle Inspected By

MOHAMAD TAUFIKH

*M.MATAI, AMSAE-A*

*Automotive Assessor*

ADRIAN LING WAI PING

*B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI*

*Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.