

ASS. REC. BY:

REF

es/fcc18015203/God3

n2

Special Instruction:

Surveyor

Guo Qiang

ASSIGNMENT (Office)

CWS

From (Person):

Lurene Juo

of

FCI

Date/Time:

2018/11/8 @ 6:51pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 5914C

Insured:

SHC 7929P

at Workshop m/s

N-SI Automotive

Tel:

68420051

of

2 kaki Bkt Ave 2 # 01-17/18

Policy No:

Claim No:

D18006211MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

8:34am @ 21/8/18

Person Contacted:

Melody

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 5914C - X

SHC 7929P - X

(08/11/13) wef

ASS: REC. BY:

REF: FCI

c72067

ASSIGNMENT

From:

Date: 21/08/2018

Estimated Cost:

OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLU 5914C

at Workshop m/s

N-51 Automotive

of

2 Kaki Bkt Ave 2 # 01-18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Gt Estimate.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 5914C

Yr Regn:

G7 Rec 2017

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

73929

T/Radio:

Insured / Std / NI / NA

Eng/No:

RU31266013

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In Order / Jammed / Leaked / Burnt orBrake: ☒ In Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60 R16

R:

N

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21-08-18

Survey held at

W/S

5:15 pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/12 Finalised \$4800 with kheng (Red 6295.36, 56%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

170+15

Transportation:

50

S + RS, SI

50+50

Photos

112

Others

TOTAL

447

Report Format: TP

Lump Sum / I.B.I: (\$4800)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015203/Grd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7929P	Veh. Inspected	SLU 5914C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006211MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/08/2018	Inspection Date	21/08/2018	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	20-08-2018	Our Ref No. D18006211MFSH
Accident Date	18-08-2018	Claim Type. Third Party
Insured Vehicle	SHC7929P	Third Party Vehicle. SLU5914C
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	MELODY CHIN	
Contact No.	68420051/ 81138483	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLU5914C
Vehicle to be Exported:	No
Intended De-registration Date:	23 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	LEB5966033
Chassis No.:	RU31266013
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,254.00
Original Registration Date:	07 Dec 2017
First Registration Date:	07 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$53,289.00
Total Rebate Amount:	\$57,039.00

The information contained herein is correct as at 23 Aug 2018

OK



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 98168908

ESTIMATE

Repair Code : CLM14719

Date in : 20/08/2018

Vehicle Num. : SLU5914C

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31266013/LEB5966033

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER ✓ <i>RE</i>	1	762.70	762.70 ✓
REAR BUMPER LOWER COVER <i>R</i> ✓ <i>RE</i>	1	250.00	250.00 ✓
REAR BUMPER REFLECTOR L/R <i>RH / CRA - LH X NN</i>	2	141.10 ✓	282.20
REAR BUMPER SIDE L/R <i>RH - LH</i>	2	195.00 ✓	390.00 ✓
REAR BUMPER SIDE RETAINER L/R <i>X NN</i>	2	23.00	46.00 X
REAR END PANEL <i>BT</i>	1	415.60	415.60 ✓
REAR END PANEL INNER TOP GARNISH <i>R</i> ✓ <i>RE</i>	1	98.00	98.00 ✓
REAR EXHAUST CHROME TAIL PIPE <i>R</i> ✓ <i>BT</i>	1	135.00	135.00 ✓
REAR EXHAUST RUBBER MOUNTING <i>R</i> ✓ <i>BT</i>	2	16.50	33.00 ✓
REAR EXHAUST SILENCER BOX <i>R</i> ✓ <i>BT</i>	1	517.70	517.70 ✓
REAR EXHAUST SILENCER BOX GASKET <i>X NN</i>	1	48.30	48.30 X
REAR FENDER ARCH GARNISH L/R <i>R</i> ✓ <i>BR</i>	2	195.00	390.00 ✓
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>X</i>	1	485.30	485.30 X
REAR FLOOR PANEL INNER TOP BOARD COVER <i>X</i>	1	430.30	430.30 X
Δ REAR RH FENDER INNER TRIM GARNISH <i>R</i> ✓ <i>RE</i>	1	295.00	295.00 ✓
REAR TAILGATE <i>huc</i>	1	953.30	953.30 ✓
REAR TAILGATE 'HYBRID' EMBLEM <i>huc</i>	1	75.80	75.80 ✓
REAR TAILGATE 'VEZEL' EMBLEM <i>huc</i>	1	56.20	56.20 ✓

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 98168908

ESTIMATE

Repair Code : CLM14719

Date in : 20/08/2018

Vehicle Num. : SLU5914C

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31266013/LEB5966033

REAR TAILGATE HINGES L/R	X NN	2	50.00	100.00	X
REAR TAILGATE INNER PULL GARNISH	/	1	27.50	27.50	/
REAR TAILGATE INNER TRIM GARNISH	X / See	1	153.40	153.40	/
REAR TAILGATE MECHANISM LOCK	X	1	180.00	180.00	X
△ REAR TAILGATE OUTER GARNISH	X	1	220.00	220.00	X
△ REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM	X NN	1	25.00	25.00	X
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	X	2	38.50	77.00	X
△ REAR TAILGATE REFLECTOR L/R	X	2	413.20	826.40	X
REAR TAILGATE RUBBER GUIDE STOPPER L/R	X	2	18.50	37.00	X
REAR TAILGATE WEATHER STRIP	X / Twl	1	96.80	96.80	/
REAR TAILGATE WINDSCREEN INNER SEAL	/ / MLC	2	50.00	100.00	/
REAR TAILGATE WINDSCREEN MOULDING	/	2	50.00	100.00	/
△ REAR TAILLAMP L/R	X NN	2	474.60	949.20	X
			Subtotal before discount	4407.1	8,556.70
Percentage discount 20%			20% : 1696.1	3756.88	711.34
			Sub-total 1	6,845.36	
REAR BUMPER CLIPS - SET	/ MLC	1	50.00	30	50.00 /
REAR BUMPER REVERSE SENSOR	/ DM	1	250.00	220	250.00 /

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98168908

ESTIMATE

Repair Code : CLM14719

Date in : 20/08/2018

Vehicle Num. : SLU5914C

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31266013/LEB5966033

REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	20	30.00	/
REAR FENDER ARCH GARNISH CLIPS L/R - SET	2	40.00	60	80.00	/
REAR FLOOR PANEL INSULATOR MAT	1	300.00	X	300.00	X
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	100.00	40	100.00	/
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	40.00	20	40.00	/
REAR TAILGATE REVERSE CAMERA	1	800.00	X	800.00	X
REAR TAILGATE SPOILER CLIPS - SET	1	50.00	X	50.00	X
REAR TAILGATE WINDSCREEN SEALANT	1	60.00	X	60.00	X
REAR TAILLAMP CLIPS L/R - SET	2	30.00	X	60.00	X
Subtotal before discount			CP1. 200	1,820.00	
Percentage discount 0%				0.00	
Sub-total 2				1,820.00	
Parts-total				8,665.36	

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	40	80.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	650	800.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	100 P	140.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 98168908

ESTIMATE

Repair Code : CLM14719

Date in : 20/08/2018

Vehicle Num. : SLU5914C

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31266013/LEB5966033

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.

Labour Total	750	900.00
Parts & Labour Total	1740	11,095.36

*** This is a computer-generated document which requires no signature.***

page 4

5 Days.

lumpsum repair.

After repair photos.

Gmo Qvg

21/8/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015203/Gcd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7929P	Veh. Inspected	SLU 5914C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006211MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31266013	Colour	SILVER	
Odometer	73929	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/08/2018	Inspection Date	21/08/2018	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5914C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	762.70	762.70
1	REAR BUMPER LOWER COVER	DEFORMED	250.00	250.00
2	REAR BUMPER REFLECTOR L/R @\$141.10	O/S CRACKED / N/S NOT NECESSARY	282.20	141.10
2	REAR BUMPER SIDE L/R @\$195.00	O/S CUT	390.00	195.00
2	REAR BUMPER SIDE RETAINER L/R @\$23.00	NOT NECESSARY	46.00	-
1	REAR END PANEL	BENT	415.60	415.60
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	98.00	98.00
1	REAR EXHAUST CHROME TAIL PIPE	BENT	135.00	135.00
2	REAR EXHAUST RUBBER MOUNTING @\$16.50	BENT	33.00	33.00
1	REAR EXHAUST SILENCER BOX	BENT	517.70	517.70
1	REAR EXHAUST SILENCER BOX GASKET	NOT NECESSARY	48.30	-
2	REAR FENDER ARCH GARNISH L/R @\$195.00	BROKEN	390.00	390.00
1	REAR FLOOR PANEL COMPARTMENT TRAY GARNISH	NOT NECESSARY	485.30	-
1	REAR FLOOR PANEL INNER TOP BOARD COVER	NOT NECESSARY	430.30	-
1	REAR RH FENDER INNER TRIM GARNISH	DEFORMED	295.00	295.00
1	REAR TAILGATE	BUCKLED	953.30	953.30
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	75.80	75.80
1	REAR TAILGATE "VEZEL" EMBLEM	NECESSARY	56.20	56.20
2	REAR TAILGATE HINGES L/R @\$50.00	NOT NECESSARY	100.00	-
1	REAR TAILGATE INNER PULL GARNISH	DEFORMED	27.50	27.50
1	REAR TAILGATE INNER TRIM GARNISH	DEFORMED	153.40	153.40
1	REAR TAILGATE MECHANISM LOCK	NOT NECESSARY	180.00	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	220.00	-
1	REAR TAILGATE OUTER GARNISH "H" LOGO EMBLEM	NOT NECESSARY	25.00	-
2	REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R @\$38.50	NOT NECESSARY	77.00	-
2	REAR TAILGATE REFLECTOR L/R @\$413.20	NOT NECESSARY	826.40	-
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R @\$18.50	NOT NECESSARY	37.00	-
1	REAR TAILGATE WEATHER STRIP	TWISTED	96.80	96.80
2	REAR TAILGATE WINDSCREEN MOULDING @\$50.00	NECESSARY	100.00	100.00

Report Ref No. CS/FCI18015203/Gcd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP L/R @\$474.60 LESS 20% DISCOUNT	NOT NECESSARY	949.20 -1,691.34 6,765.36	- -939.22 3,756.88
2	REAR TAILGATE WINDSCREEN INNER SEAL @\$50.00 (SN) LESS 20% DISCOUNT	NECESSARY	100.00 -20.00 80.00	20.00 - 20.00
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	220.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
2	SET REAR FENDER ARCH GARNISH CLIPS L/R @\$40.00 (SN)	NECESSARY	80.00	60.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-
1	SET REAR TAILGATE INNER TRIM GARNISH CLIPS (SN)	NECESSARY	100.00	40.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
1	REAR TAILGATE REVERSE CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR TAILGATE SPOILER CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
2	SET REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NOT NECESSARY	60.00	-
			1,820.00	390.00
LABOUR				
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		80.00	40.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		140.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		800.00	650.00

Report Ref No. CS/FCI18015203/Gcd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		140.00	100.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		900.00	750.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		140.00	60.00
	TO TRANSFER REAR TAILGATE INNER TRIM BOARD,WIPER MOTOR,MECHANISM LOCK OUTER HANDLE.		80.00	60.00
			2,430.00	1,840.00
GRAND TOTAL			11,095.36	6,006.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS/FCI18015203/Gcd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.