

ASS. REC. BY:

REF:

CS/FCI18015205/K/rd3

n2

Special Instruction:

Surveyor:

Kalin

ASSIGNMENT (Office)

From (Person):

CWS

May Chua

of

FCI

Date/Time:

21/8/18 12:59pm

Estimated Cost:

Bill to:

OD / ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8937P

Insured:

SHA 2390K

at Workshop n/s:

Premier Automotive

Tel:

65446689

of

23 chengji south Ave 2 #03-02

Policy No:

Claim No:

D18006249 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/08/2018

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time:

1:06pm @ 21/8/18

Person Contacted:

Vincent

Vehicle:

☒ IN

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHB 8397P-X

SHA 2390K-X

24/8/18

Revert thru email.

(08/11/13)

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHO 8937P Yr Regn: 21 Mar 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685Colour: Silver A/C: Ins / Std / NI / NASp. Reading: 43002 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KNAH M414 ME 54 6204Gen. Cond: Good / F / Poor / BurntSteering: Inorder / J / Jammed / Leaked / Burnt orBrake: Inorder / J / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD AJRim or

Tyre Size: F: 205/65R16R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ac Wil / es

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 17/8/10 D.O.I. 21/8/10

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front / Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/9/10	Checked 4/5 \$11100 / 9 Pp. Red: 9313.70, 46%

PCZ

41

RECEIVED 02 OCT 2010

Date/Time, File Pass to?

☐ : Prell. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 9Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$ _____

Photos

Others

TOTAL

10X15: 150

170 + 150

50

50

93

513

Report Format: TPLump Sum / t.B.I: (\$ 11100.00)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015205/K1rd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2390K	Veh. Inspected	SHB 8937P
Policy No.		Coverage (\$)	0.00
Claim No.	D18006249MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	21/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/08/2018	Inspection Date	21/08/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Your Ref: D18006249MFSH

Our Ref: CS/FCI18015205/K1rd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8937P .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.08.2018 at the premises of M/s PREMIER AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>19,877.30</u> .
Revised Estimate Amount	: S\$ <u>9,215.40</u> .
"Check" Items Amount	: S\$ <u>2,386.20</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:
The vehicle sustained damages
at front and rear portion.



Yours faithfully
MOHAMAD TAUFIKH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-08-2018	Our Ref No.	D18006249MFSH
Accident Date	17-08-2018	Claim Type.	Third Party
Insured Vehicle	SHA2390K	Third Party Vehicle.	SHB8397P SHB 89379
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02		
Contact Person.	VINCENT CHUA		
Contact No.	62148880/ 65446689	Fax No.	62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MAY CHUA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, August 24, 2018 12:31 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006249MFSH/1
Attachments: SHB 8937P.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SHB 8937P.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, August 21, 2018 1:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006249MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 21 August 2018 12:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006249MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	31 Mar 2014 / 10:08:53	Receipt No.:	AACCK001-AX239-140331-000015
Asset Type:	Vehicle	Transaction Amount:	\$71,161.00
Asset ID:	SHB8937P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140331100853119377		

Vehicle No.:	SHB8937P
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	31 Mar 2014
Original Registration Date:	31 Mar 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5462214
Engine No.:	D4FDDH308144
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,776.00
Minimum PARF Benefit:	\$7,365.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	31 Mar 2014 10:08:53
COE No.:	2014033101001241M
COE Expiry Date:	30 Mar 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$58,745.00
Lifespan Expiry Date:	30 Mar 2022
Owner ID Type:	Company

CASH SALE/WORK ORDER No:AD 8701



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL: 6743 1987 (3 LINES) FAX: 6743 0013

Reg No: 200415052W

Date, 17/8/18

賣號

Messrs:

車號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time:

15:48-16:10-16:47

AMOUNT:

\$

注意 本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed

經手人

Authorised by:

收貨人

Received by:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8937 P

1 pc	Bonnet <i>X again</i>	\$	979.00
1 pc	Bonnet insulator <i>X su</i>	\$	219.00
1 pc	Bonnet lock <i>X su</i>	\$	36.00
1 pc	Bonnet lifter <i>X su</i>	\$	70.00
1 pc	Bonnet lock base <i>X su</i>	\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 <i>X su</i>	\$	46.00
1 pc	Bonnet weatherstrip <i>X su</i>	\$	58.00
1 pc	Bonnet lock cover <i>X su</i>	\$	15.00
1 pc	Bonnet cable long <i>X su</i>	\$	25.00
1 pc	Bonnet cable short <i>X su</i>	\$	15.00
1 pc	Bonnet grille <i>X su</i>	\$	385.00
1 pc	Support panel <i>X su</i>	\$	645.00
1 pc	Front bumper <i>Replaced</i>	\$	531.00
1 pc	Front bumper emblem <i>re</i>	\$	44.00
1 pc	Front bumper centre grille <i>re</i>	\$	174.00
1 pc	Front bumper lower stiffer <i>X su</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>X su</i>	\$	14.00
1 pc	Front bumper lip <i>X su</i>	\$	52.00
1 pc	Front bumper inner sponge <i>re</i>	\$	110.00
1 pc	Front bumper upper reinforcement <i>re</i>	\$	40.00
1 pc	Front bumper reinforcement <i>re</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>re</i>	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 <i>X su</i>	\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 <i>X su</i>	\$	102.00
1 pc	Air con condenser <i>re</i>	\$	805.00
1 pc	Radiator <i>re</i>	\$	669.00
1 pc	Air duct <i>re</i>	\$	210.00
1 pc	Wiper top garnish <i>X su</i>	\$	368.00
2 pcs	Rear license plate lamp @ \$30.00 <i>X su</i>	\$	60.00
1 pc	Boot lid <i>re</i>	\$	1,119.00
1 pc	Boot lid lock <i>X su</i>	\$	99.00
1 pc	Bootlid lock cable <i>X su</i>	\$	35.00
1 pc	Bootlid striker <i>X su</i>	\$	21.00
1 pc	Bootlid emblem <i>re</i>	\$	27.00
1 pc	Bootlid CRDi <i>re</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X su</i>	\$	96.00
1 pc	Boot lid lower garnish <i>re</i>	\$	290.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8937 P

2 pcs	Bootlid hinges @ \$66.00	X repair	\$	132.00
2 pcs	Bootlid hinge torsion bar @ \$33.00	X 5"	\$	66.00
1 pc	Bootlid inner trim	X sec	\$	190.00
1 pc	End panel	—	\$	250.00
1 pc	End panel garnish	2/ cr	\$	74.00
1 pc	Towing hook bracket	X sec	\$	68.00
1 pc	Spare tyre clamp	2/ broken	\$	6.00
1 pc	Rear muffler assy	—	\$	1,009.00
1 pc	Rear exhaust pipe hanger	X repair	\$	49.00
1 pc	Exhaust pipe heat protector	X sec	\$	71.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00	as is ✓ cr	\$	842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00	X sec	\$	700.00
1 pc	Rear bumper	—	\$	696.00
1 pc	Rear bumper lower cover	—	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	—	\$	58.00
1 pc	Rear bumper inner sponge	—	\$	114.00
1 pc	Rear bumper reinforcement	—	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	2/ broken	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	2/ cr	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	2/ cr	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	—	\$	92.00
			\$	15,557.00
			Less 10%	\$ 1,555.70
			\$	14,001.30

S/NETT

1 set	Rear bumper clips	—	\$	48.00
1 set	End panel inner garnish clips	2/ sec	\$	30.00
1 set	Bootlid inner trim clips	X "	\$	52.00
1 set	Bootlid lower garnish clips	X "	\$	60.00
1 set	Bootlid stickers	—	\$	100.00
1 set	Reverse sensor	—	\$	280.00
2 pcs	Rear n/s & o/s fender stickers	n/s X o/s ✓	\$	120.00
1 set	Floorboard compartment insulating paddings	—	\$	120.00
1 set	Wiper garnish clips	X "	\$	48.00
1 pc	Front no. plate with casing	—	\$	50.00
1 pc	Front bumper clips	—	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	X "	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	X "	\$	6.00
1 set	Bonnet insulator clips	X "	\$	52.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8937 P

Sundry	\$ 50.00 20
Towing Fee	\$ 50.00 /
To check for wiring and to focus head lamps	\$ 80.00 X 44
To dismantle / refit rear exhaust pipe	\$ 120.00 50
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc.	\$ 2,200.00 1200
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s fender, rear o/s fender, front bumper, bonnet, X	\$ 1,800.00 1440
To apply rustproofing on the repaired and replaced panels.	\$ 250.00 50
	\$ 19,877.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

204137.0

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvi 10014
 21/8/18 1804
 9 Days
 4/5
 After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:


PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Aug-18

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8937 P

1 pc	Blower Assy		\$	596.00
			Less 10%	\$ 59.60
				<u>\$ 536.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

*THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.*





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015205/K1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2390K	Veh. Inspected	SHB 8937P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006249MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5462214	Colour	SILVER	
Odometer	430002	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2018	Inspection Date	21/08/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8937P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	979.00	-
1	BONNET INSULATOR	SERVICEABLE	219.00	-
1	BONNET LOCK	SERVICEABLE	36.00	-
1	BONNET LIFTER	SERVICEABLE	70.00	-
1	BONNET LOCK BASE	SERVICEABLE	13.00	-
2	BONNET HINGE O/S & N/S @\$23.00	SERVICEABLE	46.00	-
1	BONNET WEATHERSTRIP	SERVICEABLE	58.00	-
1	BONNET LOCK COVER	SERVICEABLE	15.00	-
1	BONNET CABLE LONG	SERVICEABLE	25.00	-
1	BONNET CABLE SHORT	SERVICEABLE	15.00	-
1	BONNET GRILLE	CRACKED	385.00	385.00
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	645.00	-
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER CENTRE GRILLE	CRACKED	174.00	174.00
1	FRONT BUMPER LOWER STIFFER	SERVICEABLE	134.00	-
1	FRONT BUMPER TOW HOOK COVER	SERVICEABLE	14.00	-
1	FRONT BUMPER LIP	SERVICEABLE	52.00	-
1	FRONT BUMPER INNER SPONGE	TORN	110.00	110.00
1	FRONT BUMPER UPPER REINFORCEMENT	BENT	40.00	40.00
1	FRONT BUMPER REINFORCEMENT	BENT	328.00	328.00
2	FRONT BUMPER O/S & N/S SIDE RETAINER @\$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S UPPER BRACKET @\$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @\$16.00	SERVICEABLE	32.00	-
2	N/S & O/S HEADLAMP @\$1028.00	CRACKED	2,056.00	2,056.00
2	FRONT BUMPER O/S & N/S FOG LAMP COVER @\$66.00	SERVICEABLE	132.00	-
2	FRONT BUMPER O/S & N/S PROTECTOR @\$51.00	SERVICEABLE	102.00	-
1	AIR CON CONDENSER	BENT	805.00	805.00
1	RADIATOR	BENT	669.00	669.00

Report Ref No. CS/FCI18015205/K1rd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR DUCT	CRACKED	210.00	210.00
1	WIPER TOP GARNISH	SERVICEABLE	368.00	-
2	REAR LICENSE PLATE LAMP @\$30.00	SERVICEABLE	60.00	-
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	SERVICEABLE	99.00	-
1	BOOTLID LOCK CABLE	SERVICEABLE	35.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	CRACKED	290.00	290.00
2	BOOTLID HINGES @\$66.00	TO REPAIR SEE LABOUR	132.00	-
2	BOOTLID HINGE TORSION BAR @\$33.00	SERVICEABLE	66.00	-
1	BOOTLID INNER TRIM	SERVICEABLE	190.00	-
1	END PANEL	DENTED	250.00	250.00
1	END PANEL GARNISH	CRACKED	74.00	74.00
1	TOWING HOOK BRACKET	SERVICEABLE	68.00	-
1	SPARE TYRE CLAMP	BROKEN	6.00	6.00
1	REAR MUFFLER ASSY	BENT	1,009.00	1,009.00
1	REAR EXHAUST PIPE HANGER	TO REPAIR SEE LABOUR	49.00	-
1	EXHAUST PIPE HEAT PROTECTOR	SERVICEABLE	71.00	-
2	REAR O/S & N/S TAIL LAMP @\$421.00	CRACKED	842.00	842.00
2	BOOTLID N/S & O/S REFLECTOR @\$350.00	SERVICEABLE	700.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	CRACKED	58.00	58.00
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	BENT	108.00	108.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00

Report Ref No. CS/FCI18015205/K1rd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	CRACKED	92.00	92.00
1	BLOWER ASSY (ADDITIONAL)	CRACKED	596.00	596.00
	LESS 10% DISCOUNT		-1,615.30	-1,154.70
			14,537.70	10,392.30
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
2	REAR N/S & O/S FENDER STICKERS (SN)	O/S NECESSARY / N/S NOT NECESSARY	120.00	60.00
1	SET FLOORBOARD COMPARTMENT INSULATING PADDINGS (SN)	NECESSARY	120.00	120.00
1	SET WIPER GARNISH CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT NO PLATE WITH CASING (SN)	CRACKED	50.00	35.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
2	FRONT N/S & O/S HEAD LAMP LOWER CLIP @\$6.00 (SN)	NOT NECESSARY	12.00	-
2	FRONT N/S & O/S HEAD LAMP SIDE CLIP @\$3.00 (SN)	NOT NECESSARY	6.00	-
1	SET BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	52.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			1,076.00	661.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT REAR EXHAUST PIPE.		120.00	50.00
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00

Report Ref No. CS/FCI18015205/K1rd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, TO HEAT/WELD, CUT-OFF THE THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FLOORBOARD COMPARTMENT, ETC. INCLUSIVE OF THE REPAIR OF BONNET, SUPPORT PANEL, BOOTLID HINGES AND REAR EXHAUST PIPE HANGER.		2,200.00	1,200.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, FLOORBOARD COMPARTMENT, END PANEL, REAR N/S FENDER, REAR O/S FENDER, FRONT BUMPER, BONNET.		1,800.00	1,440.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	50.00
			4,800.00	2,870.00
GRAND TOTAL			20,413.70	13,923.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,100.00

Report Ref No. CS/FCI18015205/K1rd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.