

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

8 Rays .

Unsym repair

After repair photo's .

Caro Rep - 82880282

21/8/18

(3rd party claim against EQ Insurance insured XDT240Y)

Estimate repair

Vehicle No. : SJX 3144D

Make & Model : Toyota Aulis

Chassis No. : _____

Date of survey : _____

Submitted by

COE expiry

Engine No.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01a	Front reinforcement bar BT / BT	01	\$410.00		
01	Rear boot / BT	01	\$920.00		
02	Rear bumper - re	01	\$715.00		
03	Tailgate (boot) LH/RH Lamps	01+01	\$524.00		
	@ \$262.6 each x 02 pcs / CR1				
04	Rear lamps LH/RH Lamps	01+01	\$498.80		
	@ \$249.4 each x 02 pcs / CR1				
05	Rear sensor x 02 @ \$140 each / PM 01+01		\$280.00		
06	LH fender (rear) X repair	01	\$515.00		* repair
07	RH fender (rear) X repair	01	\$515.00		* repair
08	Front bumper / CR1	01	\$695.6		
09	Front LH fender X	01	\$459.5		* repair
10	Support panel (front) X	01	\$495.1		* repair
11	Front license plate c/w casing / CR1	01	\$85.00		
12	LH rear door X	01	\$461.0		* repair
13	Rear end panel / CR1	01	\$475.6		
14	Lettering 1.6 wti & ATRIS (set) / CR1	01	\$195.0		
15	Bumper top chrome (front) / CR1	01	\$462.5		
	Special net				
01	Clips & retainer @ \$11.00 x 2 x 2 (ft/rea)	01	\$44.00		
	LABOUR Description				
01	Dismantle / Assembly of all affected parts.	01	\$460.0	200	
02	Panel knocking (fenders/dor/leud panel & etc) putty & grind	01	\$1,200.00	1000	
03	Sensor holes drilling x 2	01	\$120.0	40 33	
04	Spray painting including anti-rust, polish & wash	01	\$1,600.0	1480	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.