

ASS. REC. BY:

REF: CS/FCI/8015015/Dgd3ⁿ²
Special Instruction:

Surveyor:

CWS

Bryon

ASSIGNMENT (Office)

From (Person):

Jahne Yang

of

FCI

Date/Time: 21/8/18 @ 12:56pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 90424

Insured:

8HB 4327B

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

AMIC Autopoint #01-05/06

Policy No:

Claim No:

D180662S1MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/08/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

12:58pm @ 21/8/18

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHA 90424 - NA/AIG/8015053/21	DOA: 18/8/18
	8HB 4327B - CC3/KIT/8012194/Tlub3	DOA: 29/6/18
28/8-	Revert via email preli advice	


ASSIGNMENT

CVE July 2020

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No. SHA 9042U Yr Regn: 2012 / July
 Type: M. Car / M. Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Sonata c.c. 1991
 Colour: Yellow A/C: Insured / Std / NI / NA
 Sp. Reading: 269896 T/Radio: Insured / Std / NI / NA
 Eng No: D4EAC137920
 C/No: KMHE.T41VMCA827956
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 14 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Tyre Size: F: 215/60 R16
 R: — — —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 18/08/2018 D.O.I. 29/08/2018
 Survey held at Chunni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front y Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First Capital SHB 4327B Vehicle balance est 2 years at time of loss. 23 mths.
25/09/18	Insured 2/15 15000/- with 14 days of rev (Red 11786.94, 44%)

RECEIVED 27 SEP 2018

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 1) 24/9 15000/-
 Date/Time, File Return to?

Days Of Repair: 14
 Resurvey No. of Trip: 2

Report Format: 78
 Lump Sum / I.D.T. (\$) 15000

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee: 170+240
 Transportation: 50
50+50
144
704
 16x15=240
 170+240
 50
 50+50
 144
 704



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015215/Dqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4327B	Veh. Inspected	SHA 9042U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006251MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/08/2018	Inspection Date	21/08/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006251MFSH

Date: 28/8/2018

Our Ref: CS/FCI18015215/Dqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 9042U

Please be informed that we had conducted the inspection of the abovementioned vehicle 28/8/2018 at the premises of M/s Chun Ni Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>26,786.94</u>
Revised Estimate Amount	: S\$ <u>18,831.38</u>
"Check" Items Amount	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the Front and rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-08-2018	Our Ref No. D18006251MFSH
Accident Date	18-08-2018	Claim Type. Third Party
Insured Vehicle	SHB4327B	Third Party Vehicle. SHA9042U
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65425119/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 28 August 2018 4:59 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006257MFSH/1
Attachments: PRELI ADVISED SHA 9042U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHA 9042U**
Repair days: 12

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 21 August 2018 5:13 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006257MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 21 August 2018 4:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006257MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

CHUNNI MOTOR WORK PTE LTD
REPAIR ESTIMATE*

to Survey by LKK

VEHICLE NO : SHA 9042U

DATE : 20.08.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>Dented</i>			\$ 1,151.80 ✓
	Front Bumper Cover <i>Dented</i>			\$ 538.80 ✓
	Front Bumper Sponge <i>2 rim</i>			\$ 136.30 <i>2 X</i>
	Front Bumper Reinforcement <i>2 rim</i>			\$ 504.10 <i>2 X</i>
	Front Bumper Protector (LH) <i>broken</i>			\$ 29.20 ✓
	Front Bumper Bracket (LH) <i>NH</i>			\$ 20.10 X
	Headlamp Support Panel Assy <i>broken</i>			\$ 1,023.00 <i>2 X</i>
	Headlamp (LH/RH) <i>rhs broken also broken</i>	\$	797.90	\$ 1,595.80 <i>2 X</i>
	Front Fender (LH/RH) <i>Dented</i>	\$	593.00	\$ 1,186.00 ✓
	Front Wheel Rim (LH/RH) <i>NH</i>	\$	284.70	\$ 569.40 X
	Front Wheel Hub Cap (LH/RH) <i>CWT</i>	\$	145.00	\$ 290.00 ✓
	Inter Cooler <i>2 rim</i>			\$ 771.50 <i>2 X</i>
			5814.60	
	SUB TOTAL			\$ 7,816.00
	LESS 20%			\$ 1,563.20
	DISCOUNTED TOTAL			\$ 6,252.80
	Front Door Comfort Logo (LH/RH) <i>NH</i>	\$	75.00	\$ 150.00 Nett ✓
	Front Tyre (LH/RH) <i>NH</i>	\$	207.00	\$ 414.00 Nett X
			150/-	\$ 564.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 600/-
	Spray Painting Charge			\$ 800.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 NH
	FRT Wheel Alignment			\$ 120.00 60/-
			1330/-	
	TOTAL LABOUR			\$ 2,120.00

SHA 9042U

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Bnc</i>			\$ 1,349.50
	Boot Lid Rubber <i>deformed</i>			\$ 110.90
	Boot Lid Hinge (LH/RH) <i>sew</i>	S	170.60	\$ 341.20
	Boot Lid Lock Upper <i>wt</i>			\$ 132.10
	Boot Lid Lock Lower <i>wt</i>			\$ 30.30
	Boot Lid Key Lock <i>Dmc</i>			\$ 78.20
	Boot Lid Sonata Plate <i>hlc</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>hlc</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>hlc</i>			\$ 26.10
	Boot Lid CRDI Plate <i>hlc</i>			\$ 22.70
	Boot Lid Lamp (LH/RH) <i>broken/cracked</i>	S	230.20	\$ 460.40
	Licence Lamp (LH/RH) <i>svc</i>	S	32.50	\$ 65.00
	Boot Lid Absorber <i>hnl</i>			\$ 62.90
	Boot Lid Trimboard <i>deformed</i>			\$ 165.40
	Boot Lid Trimboard Clips (11pcs) <i>hlc</i>			\$ 11.00
	Rear Bumper <i>hnc</i>			\$ 578.40
	Rear Bumper Reinforcement <i>broken</i>			\$ 483.30
	Rear Bumper Clip <i>hlc</i>			\$ 22.00
	Rear Bumper Bracket <i>svc</i>	S	49.00	\$ 98.00
	Rear Bumper Sponge <i>form</i>			\$ 137.40
	Rear Bumper Under Cover <i>form</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>wt</i>	S	38.00	\$ 76.00
	Tail Lamp (LH/RH) <i>broken</i>	S	344.00	\$ 688.00
	Tail Lamp Quarter Panel (LH/RH) <i>Dental</i>	S	93.80	\$ 187.60
	Rear Panel <i>hnc</i>			\$ 391.80
	Rear Panel Garnish <i>broken mounting</i>			\$ 95.80
	Spare Tyre Holder <i>hnl</i>			\$ 27.60
	Tail Lamp Panel Top (LH/RH) <i>Dental</i>	S	217.40	\$ 434.80
	Spare Tyre Panel <i>hnc</i>			\$ 863.00
	Spare Tyre Panel Cushion <i>wt</i>			\$ 200.30
	Rear Towing Hook <i>hnl</i>			\$ 135.30
	Member Assy- Rear Floor Centre <i>hnl</i>			\$ 163.60
	Panel Assy-Rear Floor Side (LH/RH) <i>N/S Dental</i>	<i>o/s r/s</i>	88.55	\$ 177.10
	Rear Floor Chassis Member <i>N/S Bnc</i>			\$ 1,280.50
	Exhaust Pipe Insulator <i>hnl</i>			\$ 56.10
	Exhaust Silencer <i>hnl</i>			\$ 723.00
	Exhaust Pipe Hanger <i>hnl</i>			\$ 56.10
	Rear Fender (LH/RH) <i>Bnc</i>	S	1,935.90	\$ 3,871.80
	Rear Fender Inner Panel (LH/RH) <i>form</i>	S	1,255.00	\$ 2,510.00
	Rear Fender Inner Lining (LH/RH) <i>svc</i>	S	74.10	\$ 148.20
	Rear Fender Corner Hardboard Cover (LH) <i>wt</i>			\$ 204.30
	Rear Windscreen Moulding <i>hlc</i>		12303.75	\$ 60.00
	SUB TOTAL		9843.00	\$ 16,779.30
	LESS 20%			\$ 3,355.86
	DISCOUNTED TOTAL			\$ 13,423.44

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid City Cab Logo & Tel No Sticker <i>hlc</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>hlc</i>			\$ 100.00	Nett ✓
	Rear No.Plane <i>broken</i>			\$ 25.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Dem</i>			\$ 135.70	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>hlc</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Fender Comfort Sticker (LH/RH) <i>hlc</i>		\$ 30.00	\$ 60.00	Nett ✓
	Rear Windscreen Sealant <i>hlc</i>			\$ 46.00	Nett ✓
	Rear Door Tel No. Sticker (LH) <i>hlc</i>			\$ 10.00	Nett ✓
			<i>606.70</i>	\$ 606.70	
	Labour Charge				
	Panel Beating			\$ 2,000.00	1200/-
	Spray Painting Charge			\$ 1,350.00	800/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 80.00	40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 80.00	60/-
	Remove/Refix Rear Windscreen Glass			\$ 100.00	80/-
	Remove/Refix Reverse Sensor			\$ 80.00	40/-
	Remove/Refix Fuel Tank			\$ 80.00	NN
			<i>2250/-</i>		
	TOTAL LABOUR			\$ 3,820.00	
	ESTIMATE TOTAL			\$ 26,786.94	
	<i>23/08/2018 @ 1200h</i>			<i>18831.38</i>	
	<i>H/A Antimal</i>			<i>4/515000/-</i>	
	<i>2/5m to 10 days</i>				
	<i>14</i>				
	<i>Ryan</i>				
	<i>2KK Auto</i>				
	<i>8</i>				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015215/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 4327B	Veh. Inspected	SHA 9042U
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18006251MFSH	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	21/08/2018
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI SONATA	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	KMHET41VMCA827956	Colour	YELLOW
	Odometer	269896	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	18/08/2018	Inspection Date	23/08/2018
	Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9042U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	1,151.80	1,151.80
1	FRONT BUMPER COVER	DENTED	538.80	538.80
1	FRONT BUMPER SPONGE	NOT NECESSARY	136.30	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	504.10	-
1	FRONT BUMPER PROTECTOR (LH)	BROKEN	29.20	29.20
1	FRONT BUMPER BRACKET (LH)	NOT NECESSARY	20.10	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,023.00	1,023.00
2	HEADLAMP (LH/RH) @\$797.90	BROKEN	1,595.80	1,595.80
2	FRONT FENDER (LH/RH) @\$593.00	DENTED	1,186.00	1,186.00
2	FRONT WHEEL RIM (LH/RH) @\$284.70	NOT NECESSARY	569.40	-
2	FRONT WHEEL HUB CAP (LH/RH) @\$145.00	CUT	290.00	290.00
1	INTER COOLER	NOT NECESSARY	771.50	-
1	BOOT LID	BUCKLED	1,349.50	1,349.50
1	BOOT LID RUBBER	DEFORMED	110.90	110.90
2	BOOT LID HINGE (LH/RH) @\$170.60	TO REPAIR SEE LABOUR	341.20	-
1	BOOT LID LOCK UPPER	BENT	132.10	132.10
1	BOOT LID LOCK LOWER	BENT	30.30	30.30
1	BOOT LID KEY LOCK	DAMAGED	78.20	78.20
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID "H" EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
2	BOOT LID LAMP (LH/RH) @\$230.20	BROKEN / CRACKED	460.40	460.40
2	LICENCE LAMP (LH/RH) @\$32.50	SERVICEABLE	65.00	-
1	BOOT LID ABSORBER	NOT NECESSARY	62.90	-
1	BOOT LID TRIMBOARD	DEFORMED	165.40	165.40
11	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	REAR BUMPER	BUCKLED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	BROKEN	483.30	483.30

Report Ref No. CS/FCI18015215/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$49.00	SERVICEABLE	98.00	-
1	REAR BUMPER SPONGE	TORN	137.40	137.40
1	REAR BUMPER UNDER COVER	TORN	185.80	185.80
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	BENT	76.00	76.00
2	TAIL LAMP (LH/RH) @\$344.00	BROKEN	688.00	688.00
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$93.80	DENTED	187.60	187.60
1	REAR PANEL	BUCKLED	391.80	391.80
1	REAR PANEL GARNISH	MOUNTING BROKEN	95.80	95.80
1	SPARE TYRE HOLDER	NOT NECESSARY	27.60	-
2	TAIL LAMP PANEL TOP (LH/RH) @\$217.40	DENTED	434.80	434.80
1	SPARE TYRE PANEL	BUCKLED	863.00	863.00
1	SPARE TYRE PANEL CUSHION	BENT	200.30	200.30
1	REAR TOWING HOOK	NOT NECESSARY	135.30	-
1	MEMBER ASSY-REAR FLOOR CENTRE	NOT NECESSARY	163.60	-
2	PANEL ASSY-REAR FLOOR SIDE (LH/RH) @\$88.55	N/S DENTED / O/S TO REPAIR SEE LABOUR	177.10	88.55
1	REAR FLOOR CHASSIS MEMBER N/S	BUCKLED	1,280.50	1,280.50
1	EXHAUST PIPE INSULATOR	NOT NECESSARY	56.10	-
1	EXHAUST SILENCER	NOT NECESSARY	723.00	-
1	EXHAUST PIPE HANGER	NOT NECESSARY	56.10	-
2	REAR FENDER (LH/RH) @\$1935.90	BUCKLED	3,871.80	3,871.80
2	REAR FENDER INNER PANEL (LH/RH) @\$1255.00	TO REPAIR SEE LABOUR	2,510.00	-
2	REAR FENDER INNER LINING (LH/RH) @\$74.10	SERVICEABLE	148.20	-
1	REAR FENDER CORNER HARDBOARD COVER (LH)	BENT	204.30	204.30
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
	LESS 20% DISCOUNT		-4,919.06	-3,623.67
			19,676.24	14,494.68
	SPECIAL NETT ITEMS			
2	FRONT DOOR COMFORT LOGO (LH/RH) @\$75.00 (SN)	NECESSARY	150.00	150.00
2	FRONT TYRE (LH/RH) @\$207.00 (SN)	NOT NECESSARY	414.00	-

Report Ref No. CS/FCI18015215/Dqd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID CITY CAB LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR NO PLATE (SN)	BROKEN	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
2	REAR FENDER COMFORT STICKER (LH/RH) @\$30.00 (SN)	NECESSARY	60.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR TEL NO STICKER (LH)(SN)	NECESSARY	10.00	10.00
			1,170.70	756.70
	LABOUR			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF BOOT LID HINGE (LH/RH), PANEL ASSY-REAR FLOOR SIDE O/S AND REAR FENDER INNER PANEL (LH/RH) .		3,000.00	1,800.00
	SPRAY PAINTING CHARGE.		2,150.00	1,400.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		180.00	80.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		80.00	60.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		100.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
			5,940.00	3,580.00
GRAND TOTAL			26,786.94	18,831.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/FCI18015215/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.