

A.S. REC. BY:

REF:

CS/CTI18015243/KS13

n2

Special Instruction:

Survivor:
Makman

From (Person):

Kenneth
Youny Tay

of

CTI

Date/Time:

21/8/18 @ 3:40pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIM10032

Insured:

SKG 6693T

at Workshop m/s

3 1/2 # Motor

Tel:

6453 4730

of

160 Sin Ming Drive # 07-02

Policy No:

DMPCSN3077051700

Claim No:

SNM18D0402502

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/08/2018

CA / REV / REP. / REV 24 HRS

lup)

23/8/18 @

H.O.D. Endorsement:

Date/Time:

4:17pm @ 21/8/18

Person Contacted:

Ms. Wong

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SIM10032-X
	SKG 6693T - CS/CTI18008346/T1q.b DOA: 5/1/2018
7/4/12	\$4174.00 email & call memo
17/12/12	Confirmed P/P \$4,174.00 @ 6 days with Kenneth (\$1,285.00 Red - 24%)

(08/11/13) wef

REF: C11

ASS. REC. BY:

ASSIGNMENT

From: Date: 23/8/18

Estimated Cost:

ON (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SIM 10032

at Workshop m/s

S & H Motor

of 160 Sin Ming Drive # 07-02

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS cup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SIM 10032 Yr Regn: 06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A) MPV

Make:

Toy wish

c.c

1798

Colour:

M. Orange

A/C: Insured / Std / NI / NA

Sp. Reading

19493

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDGG 20W 20 J00 8872

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / BY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

17/8/18

D.O.I.

23/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rec N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/8 File pass to Catherine

RECEIVED 17 DEC 2018

17/12/2018

Date/Time, File Pass to?

17/12/18



: Preli. Report



: Final Report

1) Typst

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$) 4,174.00 p/p



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015243/Ksd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 6693T	Veh. Inspected	SJM 1003Z
Policy No.	DMPCSN3077051700	Coverage (\$)	0.00
Claim No.	SNM18D04025C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/08/2018	Inspection Date	23/08/2018
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018 Sendback Est	20 Aug 2018 18:22 \$5,329.00	21 Aug 2018 15:40 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	POH ENG CHIEW, ID: S7728459A		
Main Claimant:	CHAY WENG YEE, ID: S1481838C		
Vehicle Reg. No.:	SJM1003Z	Date of Loss:	17/08/2018 09:00 - :59 [13 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04025C02	Policy/Cover Note No.:	DMPCSN3077051700
Vehicle Reg. No. (Insured):	SKG6693T	Policy No. (Claimant):	VPA/P1946911
		Excess:	\$0.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/08/2018]		
Adj Asg. Remarks:	EST \$5702.03, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1838C
Vehicle Details	
Vehicle No.:	SJM1003Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Orange
Manufacturing Year:	2017
Engine No.:	2ZR1950188
Chassis No.:	JTDGG20W20J006872
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	29 Jun 2017
First Registration Date:	29 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2027
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$40,088.00
Total Rebate Amount:	\$55,054.00

The information contained herein is correct as at 20 Aug 2018

OK



TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	17/08/2018
Vehicle Reg. No.:	SJM1003Z	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHAY WENG YEE		
<hr/>			
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	29/06/2017
Vehicle Colour:	Metallic Orange		
Engine No:	2ZR1950188	Chassis No:	JTDGG20W20J006872
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6 days		
<hr/>			
Description of Accident/Loss	REFER ATTACHED REPORT.		
Present Location:	S & AMP; H MOTOR PTE LTD (SIN MING)		
<hr/>			

*Not withain
1.3.1
Penny B&Pain*

COST OF CLAIMS	Amount
Parts	2,111.00
Miscellaneous Items	628.00
Labour	2,590.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,329.00
+ GST 7.00% (S\$)	373.03
Nett Amount (S\$)	5,702.03

This claim is handled by: LUM WEE KEAT

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Aug 2018)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SJM1003Z/20/08/2018 18:22

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Tail door	0.00	0.00	Bt *550.00 F ✓
2	1		*Tail door weather strip	0.00	0.00	nd 1011 *120.00 F ✓
3	1		*Tail door lock	0.00	0.00	nd *140.00 F ✓
4	1		*Tail door "Wish" chrome moulding"	0.00	0.00	Wap *110.00 F ✓
5	1		*Tail door 'Valve' Plate	0.00	0.00	nd *45.00 F ✓
6	1		*Tail door 'Elegance' Plate	0.00	0.00	nd *55.00 F ✓
7	1		*Tail door emblem	0.00	0.00	nd *38.00 F ✓
8	1		*LH reverse lamp	0.00	0.00	CM *135.00 F ✓
9	1		*LH tail lamp	0.00	0.00	CM *140.00 F ✓
10	1		*Rear bumper	0.00	0.00	Bt *250.00 F ✓
11	1		*Rear bumper clips (1 set)	0.00	0.00	nd *28.00 F ✓
12	1		*Rear body end panel	0.00	0.00	Bt *195.00 F ✓
13	1		*Rear body end panel trim cover	0.00	0.00	Bu *130.00 F ✓
14	1		*LH rear bumper bracket	0.00	0.00	R *35.00 F X
15	1		*LH rear bumper retainer	0.00	0.00	nd *45.00 F ✓
16	1		*Rear windscreen outer moulding	0.00	0.00	nd *95.00 F ✓

F=Franchise part

Total Parts (\$\$)

2,111.00

S & H Motor Pte Ltd/SJM1003Z/20/08/2018 18:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Rear parking sensors (1 set)	360.00 <i>2000</i>
2	1	Rear windscreen inner rubber seal	28.00 <i>200</i>
3	1	Rear windscreen sealant	60.00 <i>400</i>
4	1	Reverse Camera	180.00 <i>X</i>
Sub Total (S\$)			628.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove and reinstall rear windscreen and conduct water leak test	New	120.00 <i>✓</i>
2	To spray paint affected rear and inner damaged portion inclusive of preparatory works and material	New	1,100.00 <i>800</i>
3	To remove and reinstall rear compartment garnish, rear seats to facilitate repairs	New	120.00 <i>600</i>
4	To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and tailgate alignment	New	1,050.00 <i>700</i>
5	To disconnect wire harness to facilitate repairs and check for damage and reconnect rear camera, rear locking, rear parking wiring system and check for full functionality	New	80.00 <i>200</i>
6	To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes	New	120.00 <i>X</i>
Gross Labour Cost (S\$)			2,590.00

S & H Motor Pte Ltd/SJM1003Z/20/08/2018 18:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Aug 2018)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SJM1003Z/31/08/2018 16:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear end panel antenna	0.00	0.00	CNA *90.00 F
2	1		*LH rear bumper reflector	0.00	0.00	CNA *40.00 F
Total Parts (S\$)						130.00

F=Franchise part

S & H Motor Pte Ltd/SJM1003Z/31/08/2018 16:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015243/KSD3N2

Date: 21/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3077051700
Claimant Vehicle No :	SJM1003Z	Insured Vehicle No :	SKG6693T
Date of Loss:	17/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04025C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM1003Z	Engine No:	2ZR1950188
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W20J006872
Reg. Date:	29/06/2017 (Man. Year: 2017)	Odometer:	19493 km
Colour:	Metallic Orange		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,241.00	2,206.00	35.00	1.56
Miscellaneous Items	628.00	268.00	360.00	57.32
Labour	2,590.00	1,700.00	890.00	34.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,459.00	4,174.00	1,285.00	23.54
+ GST 7.00/7.00% (\$\$)	382.13	292.18	89.95	23.54
Nett Amount (\$\$)	5,841.13	4,466.18	1,374.95	23.54

INSPECTION

Date of Assignment:	21/08/2018	Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	23/08/2018	Inspected At:	S & H Motor Pte Ltd (Sin Ming)
			160 Sin Ming Drive #07-02, Sin Ming
			AutoCity
			Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2018)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJM1003Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Tail door	Bent	550.00 F	*550.00 F
2	1		*Tail door weather strip	Dented/Distorted	120.00 F	*120.00 F
3	1		*Tail door lock	Dented	140.00 F	*140.00 F
4	1		*Tail door "Wish"" chrome moulding"	Warped	110.00 F	*110.00 F
5	1		*Tail door 'Valve' Plate	Necessary	45.00 F	*45.00 F
6	1		*Tail door 'Elegance' Plate	Necessary	55.00 F	*55.00 F
7	1		*Tail door emblem	Necessary	38.00 F	*38.00 F
8	1		*LH reverse lamp	Cracked	135.00 F	*135.00 F
9	1		*LH tail lamp	Cracked	140.00 F	*140.00 F
10	1		*Rear bumper	Bent	250.00 F	*250.00 F
11	1		*Rear bumper clips (1 set)	Necessary	28.00 F	*28.00 F
12	1		*Rear body end panel	Bent	195.00 F	*195.00 F
13	1		*Rear body end panel trim cover	Buckled	130.00 F	*130.00 F
14	1		*LH rear bumper bracket	Repair	35.00 F	*- F
15	1		*LH rear bumper retainer	Distorted	45.00 F	*45.00 F
16	1		*Rear windscreen outer moulding	Necessary	95.00 F	*95.00 F
Supplementary #1						
17	1		*Rear end panel antenna	Cracked	90.00 F	*90.00 F
18	1		*RH rear bumper reflector	Cracked	40.00 F	*40.00 F

F=Franchise part.

Total Parts (S\$) 2,241.00 2,206.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Rear parking sensors (1 set) (DENTED)	360.00	200.00
2	1	Rear windscreen inner rubber seal (NECESSARY)	28.00	28.00
3	1	Rear windscreen sealant (NECESSARY)	60.00	40.00
4	1	Reverse Camera (SERVICEABLE)	180.00	0.00
Sub Total (S\$)			628.00	268.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove and reinstall rear windscreen and conduct water leak test	New	120.00	120.00
2	To spray paint affected rear and inner damaged portion inclusive of preparatory works and material	New	1,100.00	800.00
3	To remove and reinstall rear compartment garnish, rear seats to facilitate repairs	New	120.00	60.00
4	To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and tailgate alignment	New	1,050.00	700.00
5	To disconnect wire harness to facilitate repairs and check for damage and reconnect rear camera, rear locking, rear parking wiring system and check for full functionality	New	80.00	20.00
6	To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes	New	120.00	-
Gross Labour Cost (S\$)			2,590.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >