

ASS. REC. BY:

REF: CS/CT118015250/R11d3⁰² Special Instruction:

Surveyor

Denise

ASSIGNMENT (Office)

From (Person):

Jumyn ty

of

CTI

Date/Time: 21/8/18 ② 4:04pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX1790L

Insured:

SLG 2933R

at Workshop m/s

Sin Sheng Engineering

Tel:

G8639595

of

3-teeh park Crescent

Policy No:

DMPCSN 3107 341801

Claim No:

8NM18D 04055C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20/08/2018

(Client's Record)

23/8/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

5pm ② 21/8/18

Person Contacted:

susan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GX1790L - NJA / INCO8014607/y1

D.O.A. 10/5/2008

SLG 2933R -

lump sum \$4500, 6 days (Red: 2839, 38%)

Surveyor: PASUL

REF:

11924

106 XPMY. 2017/P6B

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: Q 6x 1790L
 at Workshop m/s: SIN SHAW
 of: 316th PK cels com
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8K
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 6x 1790L Yr Regn: 2004 / P6B
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA HIACE DIESEL C.C. 2986
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 31071 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: LH1621016464
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nir / S/Rim / STD A/Rim or
 Tyre Size: F: 185R14C
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or ANSTONE

Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 20/08/18 D.O.I. 23/08/18
 Survey held at SIN SHAW

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

RECEIVED 14 SEP 2018

Date/Time, File Pass to?

1) 14/9 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 4500/-)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	21 Aug 2018		21 Aug 2018 16:04 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEE HENG SHOON, ID: S1657413I		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GX1790L	Date of Loss:	20/08/2018 10:00 - :59
Claim Type:	TP / SNM18D04055C02	Policy/Cover Note No.:	DMPCSN3107341801 (Comprehensive)
Vehicle Reg. No. (Insured):	SLG2933R	Policy No. (Claimant):	29004183
		Excess:	S\$0.00
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/08/2018]		
Driver/Custodian (Insured):	CHEE HENG SHOON (54 / Male), NRIC: S1657413I		
Adj. Asg. Remarks:	NO EST, ASSIGN XING QUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015250/R1td3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 2933R	Veh. Inspected	GX 1790L
Policy No.	DMPCSN3107341801	Coverage (\$)	0.00
Claim No.	SNM18D04055C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/08/2018	Inspection Date	23/08/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Denise Tay (LKKAUTO)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Thursday, 13 September 2018 10:07 AM
To: Denise Tay (LKKAUTO)
Cc: Rasul (LKKAUTO); SUR; CS A Team
Subject: Re: PRI of GX1790L (CTI REF: SNM18D04055C02)

Hi Ms Denise,

We are agreed.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On 12 September 2018 at 16:21, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear Susan,

Offer at lump sum \$4500/-, 6 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1196N

Vehicle Details

Vehicle No.:

GX1790L

Vehicle to be Exported:

No

Intended De-registration Date:

31 Dec 2018

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE DIESEL

Primary Colour:

Green

Manufacturing Year:

2003

Engine No.:

5L5400297

Chassis No.:

LH1621010404

Maximum Power Output:

-

Open Market Value:

\$21,926.00

Original Registration Date:

25 Feb 2004

First Registration Date:

25 Feb 2004

Transfer Count:

2

Actual ARF Paid:

\$1,097.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

24 Feb 2019

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$25,709.00

COE Rebate Amount:

\$795.00

Total Rebate Amount:

\$795.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 21 Aug 2018

OK

8,000
795

7205

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

Estimate : ES002577

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Date : 21/08/2018

Vehicle Num. : GX1790L

Make/Model : TOYOTA LH 162-2003

Chassis/Eng# : LH1621010404/5L5400297

Accident Date : 20/08/2018

Claim No. :

Reference : SLG2933R

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BUMPER		377.40 <i>Top</i>
2.	2	BUMPER SIDE BRACKET	78.20	156.40 <i>PA</i>
3.	1	BUMPER REINFORCEMENT		285.20 <i>BT</i>
4.	2	REAR LAMP	332.60	665.20 <i>SCA</i>
5.	1	REAR DOOR ASSY		1,950.30 <i>BU</i>
6.	1	REAR DOOR WEATHERSTRIP		295.40 <i>HA</i>
7.	1	REAR DOOR GARNISH		195.20 <i>X nn</i>
8.	1	DOOR HANDLE		125.80 <i>X nn</i>
9.	1	DOOR LOCK		245.10 <i>BT</i>
10.	1	REAR END PANEL		695.20 <i>BT</i>
11.	1	REAR GLASS WEATHERSTRIP		225.60 <i>HA</i>
12.	1	REAR END PANEL INNER		635.10 <i>PA</i>
13.	1	SPARE TYRE BRACKET		295.20 <i>repair</i>
14.	1	SPARE TYRE HOOK		65.80 <i>X nn</i>
15.	1	SPARE TYRE BOLT		15.80 <i>X nn</i>
16.	1	'TOYOTA' EMBLEM		55.80 <i>HA</i>
17.	1	EXHAUST REAR PIPE		695.50 <i>X nn</i>

List Total S\$:

6,980.00

25.00% Discount S\$:

1,745.00

5,235.00

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS :		
		70km/h Sticker		20.00 <i>HA</i>

15

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

Estimate : ES002577

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Date : 21/08/2018
Vehicle Num. : GX1790L
Make/Model : TOYOTA LH 162-2003
Chassis/Eng# : LH1621010404/5L5400297
Accident Date : 20/08/2018
Claim No. :
Reference : SLC2933R
Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1	8 PAX STICKER		15 20.00 20.00
3.	1	NUMBER PLATE		20.00 Xnn

Nett Total S\$: 60.00
10.00% Discount S\$: 6.00

54.00

LABOUR :
TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS

100.00

TO PANEL BEAT/REPAIR REAR BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

1,150.00 ~~1,150.00~~ 700

SPRAY PAINTING

600.00 ~~600.00~~ 500

TO APPLY TUFF KOTE

120.00 ~~120.00~~ 80

TOWING CHARGES

80.00

LOSS OF USE : 8 DAYS @ \$ 120/DAY

Labour Total S\$:

2,050.00

RASUL
Hp 90010068
6 days
4s
23/08/18 @ 1700
28/8/18

Total S\$: 7,339.00

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey after paint



YISHUN TOWING PTE LTD

Blk 4015 Ang Mo Kio Industrial Park 1, #01-502, Singapore 569631

Tel: 6458 8480 HP: 9628 8480 Fax: 6288 8480

Website: www.yishuntowing.com

Reg. No. 200106908W GST No. 200106908W

M/s SIN SHENH

WORK ORDER

No. 251288

Order By:

AT 1345 DT 1437

Date: 20/08/18

車牌
Vehicle No. GX1790L

車型
Model T-Miteo

From: FORD RD HUCE

To: TECH PC CREG

Remarks:

Day/Night

Customer Signature & Company Stamp

Authorised Signature

Tow Truck No.: XE8480P

All business transactions with Yishun Towing Pte Ltd are subject to its Standard Conditions in so far as these Conditions are applicable. Copies of these conditions may be obtained upon request. Note: Please see terms & conditions on the reverse side.



LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015250/R1TD3N2

Date: 17/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3107341801
Claimant Vehicle No :	GX1790L	Insured Vehicle No :	SLG2933R
Date of Loss:	20/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04055C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX1790L	Engine No:	5L5400297
Make & Model:	TOYOTA HIACE, 2.5 (M)	Chassis No:	LH1621010404
Reg. Date:	25/02/2004 (Man. Year: 2003)	Odometer:	310771 km
Colour:	White		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185R14C	Rear Tyre Size:	185R14C
Front Left Side:	Austone 7 mm	Rear Left Side:	Austone 7 mm
Front Right Side:	Austone 7 mm	Rear Right Side:	Austone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,289.00	4,217.02	1,071.98	20.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,460.00	590.00	28.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,339.00	5,677.02	1,661.98	22.65
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	7,339.00	4,500.00	2,839.00	38.68
+ GST 7.00/7.00% (S\$)	513.73	315.00	198.73	38.68
Nett Amount (S\$)	7,852.73	4,815.00	3,037.73	38.68

INSPECTION

Date of Assignment:	21/08/2018	
Date Inspected:	23/08/2018 Inspected At:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park Singapore 638129
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Sep 2018)	
Parts:	N/A	TOYOTA HIACE 2.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX1790L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	377.40 FL	*377.40 FL
2	2		*BUMPER SIDE BRACKET	Bent	156.40 FL	*156.40 FL
3	1		*BUMPER REINFORCEMENT	Bent	285.20 FL	*285.20 FL
4	2		*REAR LAMP	Scratched	665.20 FL	*665.20 FL
5	1		*REAR DOOR ASSY	Buckled	1,950.30 FL	*1,950.30 FL
6	1		*REAR DOOR WEATHERSTRIP	Necessary	295.40 FL	*295.40 FL
7	1		*REAR DOOR GARNISH	Not Necessary	195.20 FL	*- FL
8	1		*DOOR HANDLE	Not Necessary	125.80 FL	*- FL
9	1		*DOOR LOCK	Bent	245.10 FL	*245.10 FL
10	1		*REAR END PANEL	Bent	695.20 FL	*695.20 FL
11	1		*REAR GLASS WEATHERSTRIP	Necessary	225.60 FL	*225.60 FL
12	1		*REAR END PANEL INNER	Bent	635.10 FL	*635.10 FL
13	1		*SPARE TYRE BRACKET	Repair	295.20 FL	*- FL
14	1		*SPARE TYRE HOOK	Not Necessary	65.80 FL	*- FL
15	1		*SPARE TYRE BOLT	Not Necessary	15.80 FL	*- FL
16	1		*TOYOTA EMBLEM	Necessary	55.80 FL	*55.80 FL
17	1		*EXHAUST REAR PIPE	Not Necessary	695.50 FL	*- FL
18	1		*70KM/H STICKER	Necessary	20.00 FN	*15.00 FN
19	1		*8PAX STICKER	Necessary	20.00 FN	*15.00 FN
20	1		*NUMBER PLATE	Not Necessary	20.00 FN	*- FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	7,040.00	5,616.70
- List Item Discount on L Items 25.00/25.00% (S\$)	1,745.00	1,396.68
- Nett Item Discount on N Items 10.00/10.00% (S\$)	6.00	3.00
Total Parts (S\$)	5,289.00	4,217.02

Report was unsubmitted during this print-out.