

REF: III 15257/Nea3 - ②

Surveyor: N/A

REF: III 15257/Nea3 - ②

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YN 2468 B Yr Regn: 10 Aug 201

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU NPR75HSA C.C. 5,193

Colour: GREEN A/C: Insured / Std / Nil /

Sp. Reading: 196, 057 T/Radio: Insured / Std / Nil /

Eng/No: _____

C/No: JAA NPR754B7101619

Gen. Cond: Good Fair / Poor / Burnt

Steering: In Use / Jammed / Leaked / Burnt or

Brake: In Use / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: 215/75 R17.5

R: 215/75 R17.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MLC (R)

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 5 mm

L/Bal. 6 mm L/Bal. 5 mm

D.O.A. 3/8/18 D.O.I. 5/9/18

Survey held at HUA HONG

Des. of Damages: Frt Rev / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$ _____

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL