

ComfortDelGro Engineering

205 Braddell Road S(579701) ACCIDENT REPAIR ESTIMATE

	ACCIDENT N	EFAIR ESTIMATE	
Our Ref:			
Type of Claim :	TP	Vehicle No. :	SLK6917R
Type of Claim .		Make & Model :	HONDA GRACE HYB 1.5DX A
		Year of Manufacture :	2016
		Chassis No. :	GM41105440
Ins Company :	AIG / III	Engine No. :	
Excess :		Policy No. :	
Date of Accident :	21/08/2018	Time of Accident :	
Suggested Days of Repair :		In-house Vehicle Assessor	
Repair Estimate		Case Owner :	Andrew
		Signature :	
Parts (a) Cost / List Price Items	S -	Contact No	
Plus/Less 20%	s -	Frt Counter Operation	
Total of Cost / List	s -	6383 7466 – Patrick Tia 6383 7730 - Brenda Ng	
Total of Cost / List	3	6383 7890 – Rohani	
(b) Nett Price Items	s -	braddell cr@sparkcarcare.com	
Less	<u> </u>	Workshop Operation	
Total of Nett Item		63837656 - Ngo Toh Wee 63837362 - Andrew Goh	
		63838115 - William Wang	
(c) Special Nett Items	<u>s</u> -	braddell operation@sparkcarca	are.com
Total Parts Cost (Appendix A)	<u> </u>		Not 1.76
Labour (Appendix B)	\$ 2,730.00		Not betharter Rehmay 86 pai
Total Repair Cost	\$ 2,730.00		Mehmay 86
The above total will be subjected to	7% G.S.T.		pai
	Thursday.	Kenness	
Name of Surveyor			
Company		23/8/18 at	
Survey conducted on	:	at	
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized / is not authorized	red until further notice.	
(b) Recommended Days of Rep	air :	75 day(s)	
(c) Resurvey	: Required / No	Required	
(d) Excess	:\$		
(e) Signature of surveyor		Le Date:	23/8/18

(e) Signature of surveyor

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	SLK6917R	Case Owner	:	Andrew
Make & Model	:	HONDA GRACE HYB 1.5D	Year Manufacture	:	2016
Chassis No	:	GM41105440	Engine No	:	0
Sales Order	:		Supplier	:	
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper Bn	1					
2	Front bumper side retainer LH	1					_
3	Front bumper side retainer RH	1					X
4	Front bumper clips	10					_
5	LH front fender	1		·			X
6	LH front fender inner shield	1					×
7	LH front fender inner shield clips	10					X
8	LH front fender emblem HYRBID Na	1					_
9	Headlamp LH mg cm	1					_
10	Headlamp lower bracket LH	1					1
11	Radiator grille CM	1					2
12	Radiator grille outer chrome moulding	1					.7
13	Radiator grille emblem logo	1					7
14	Radiator grille lower chrome moulding	1					7
15	Radiator grille base bracket	1					7
16	Radiator grille top bracket LH	1					×
17	Radiator grille top bracket RH //	1					X
18	LH front wheel cap	1					X
19	LH front tyre (ROADSTONE Npriz AH 5)	. 1					×
20	LH front rim	1					×
21	LH shock absorber	1					X
22	LH wheel hub	1					*
23	LH wheel hub bearing	1					X
24	LH knuckle arm	1					×
25	LH front tie rod	1					X
26	LH front tie rod end	1					×
27	LH front lower arm	1					X
	LH front lower arm ball joint	1					×
29	0	0					X
	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No.	:	SLK6917R	Case Owner	: :	Andrew	
Make & Model	:	ONDA GRACE HYB 1.5DX A	Year of Manufacture	: :	2016	

S/No	Labour Description	Esimated Price	Adjusted Price
1	To dismantle abd replace LH front suspension and undercarriage to	\$280.00	X
	facilitate repairs and bleed brakes system.		
2	To panel beat, repair front support panel, bonnet and to replace	\$960.00	4801
	LH front damaged parts		
3	To check wiring functions	\$120.00	201
4	To putty and spray paint front bumper, LH front fender, bonnet,	\$1,250.00	7501
	front support panel and all affected areas		
5	To check and re-set steering geometry and wheel alignment	\$120.00	X
	LKK Auto Consultants hence notify		
	* To resurvey before/after soray painting:		
	Parts prices are subject to confirmation		
	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to finel on.		
	and approval from Insurance Company		
	Acknowledged by Repairer Signature:		
	Date:		
	9 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.