21/08/2018 1st



205 Braddell Road S(579701)

Type of Claim : TP

ACCIDENT REPAIR ESTIMATE

Vehicle No. : SLK6917R

U	ur	K	e	:

		Make & Model :	HONDA GRACE HYB 1.5DX
		Year of Manufacture :	2016
		Chassis No. :	GM41105440
Ins Company : A	AIG / III	Engine No. :	
Excess :		Policy No. :	
Date of Accident : 21	1/08/2018	Time of Accident :	
Suggested Days of Repair :		In-house Vehicle Assessor	
Repair Estimate		Case Owner :	Andrew
Parts (a) Cost / List Price Items	e.	Signature :	
rarts (a) Cost/List Frice items	\$ -	Contact No	
Plus/Less 20%	\$ -	Frt Counter Operation	
Total of Cost / List	s -	6383 7466 – Patrick Tia 6383 7730 - Brenda Ng	
Total of Cost / List		6383 7890 - Rohani	
(b) Nett Price Items	<u> </u>	braddell_cr@sparkcarcare.com	<u>n</u>
Less		Workshop Operation	
Total of Nett Item		63837656 - Ngo Toh Wee 63837362 - Andrew Goh	
rotal of Nett Item		63838115 - William Wang	
(c) Special Nett Items			
Total Parts Cost (Appendix A)	<u>s - </u>	braddell operation@sparkeard	care.com
Labour (Appendix B)	\$ 2,730.00		
Total Repair Cost	\$ 2,730.00		
The above total will be subjected to 7	% G.S.T.		

Name of Surveyor	•		
Company			
Survey conducted on	:	at	
Remarks By Surveyor			
(a) The repair of this vehicle is au	thorized / is not authorize	ed until further notice.	
(b) Recommended Days of Repair			
(c) Resurvey	: Required / Not		
(d) Excess	:\$		
(e) Signature of surveyor			
ACCIDENT REPAIR ESTIMATES F3			

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	: SLK6917R	Case Owner	: Andrew
Make & Model	: HONDA GRACE HYB 1.5D	Year Manufacture	: <u>2016</u>
Chassis No	: GM41105440	Engine No	: <u>0</u>
Sales Order	:	Supplier	:
Order By	:	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper	1		******		3/11	Surveyor
2	Front bumper side retainer LH	1					
3	Front bumper side retainer RH	1					
4	Front bumper clips	10					
5	LH front fender	1					
6	LH front fender inner shield	1					
7_	LH front fender inner shield clips	10					
8	LH front fender emblem HYRBID	1					
9	Headlamp LH	1					
10	Headlamp lower bracket LH	1					
11	Radiator grille	1					
12	Radiator grille outer chrome moulding	1					
13	Radiator grille emblem logo	1					
14	Radiator grille lower chrome moulding	1					
15	Radiator grille base bracket	1					
16	Radiator grille top bracket LH	1					
17	Radiator grille top bracket RH	1					
18	LH front wheel cap	1					
19	LH front tyre (ROADSTONE Npriz AH 5)	1					
20	LH front rim	1					
21	LH shock absorber	1					
22	LH wheel hub	1					
23	LH wheel hub bearing	1					
24	LH knuckle arm	I					
25	LH front tie rod	1					
26	LH front tie rod end	1					
27	LH front lower arm	1					
28	LH front lower arm ball joint	1					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

21/08/2018 4:06 PM

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

_		•			
1	n	ь	^	31	144
ı.	a	IJ	u	u	

Vehicle No.	:	SLK6917R	Case Owner	:	Andrew
Make & Model	:	ONDA GRACE HYB 1.5DX A	Year of Manufacture	:	2016

	& Model: JNDA GRACE HYB 1.5DX A Year of Manufacture		: 2016			
/No	Labour Description	Esimated Price	Adjusted Price			
1	To dismantle abd replace LH front suspension and undercarriage to	\$280.00				
·········	facilitate repairs and bleed brakes system.					
2	To panel beat, repair front support panel, bonnet and to replace	\$960.00				
	LH front damaged parts					
3	To check wiring functions	\$120.00	****			
4	To putty and spray paint front bumper, LH front fender, bonnet,	\$1,250.00				
	front support panel and all affected areas					
5	To check and re-set steering geometry and wheel alignment	\$120.00				

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.