



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

EA 9817 L

*Not Authorized
Resurvey Beyond*

Parts	(a) Cost / List Price Items	\$	5,765.97
	Plus/Less 25%	\$	1,441.49
	Total of Cost / List	\$	4,324.48
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	1,145.00
Total Parts Cost		\$	5,469.48
Labour		\$	3,340.00
Total		\$	8,809.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 23/8/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 23/8/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **EA 9817 L**
Make & Model : **TOYOTA SIENTA**
Chassis No. : **NHP1707121803**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$70.22		✓
2	Rear windscreen sealant	1	\$50.00	S.N	✗
3	Reverse sensor	2	\$400.00	S.N	2000
4	Rear number plate	1	\$45.00	S.N	X
5	Rear bumper	1	\$377.80		✓
6	Rear bumper lower centre	1	\$242.40		✓
7	Rear bumper lower garnish LH	1	\$172.40		✓
8	Rear bumper lower garnish RH	1	\$172.40		X
9	Rear bumper reflector LH	1	\$68.20		?
10	Rear bumper reflector RH	1	\$68.20		X
11	Rear bumper clip	10	\$40.00		4
12	Rear bumper side retainer LH	1	\$78.02		X
13	Rear bumper side retainer RH	1	\$78.02		X
14	Tail door	1	\$1,276.30		✓
15	Tail door lock	1	\$478.30		✓
16	Tail door emblem	1	\$69.74		✓
17	Wording "hybrid synergy drive"	1	\$48.37		✓
18	Tail door reflector LH	1	\$195.60		X
19	Tail door reflector RH	1	\$195.60		X
20	Tail door trim	1	\$167.80		?
21	Tail door trim clip	10	\$40.00		?
22	Tail end panel	1	\$678.40		?
23	Tail end panel garnish	1	183.41		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **EA 9817 L**
Make & Model : **TOYOTA SIENTA**
Chassis No : **NHP1707121803**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip	10	\$40.00		✓
25	Boot weatherstrip	1	\$397.60		✓
26	Tail lamp LH	1	\$387.60		X
27	Tail lamp RH	1	\$387.60		X
28	Reverse sensor cover LH	1	\$35.40		✓
29	Reverse camera	1	\$650.00	S.N	X
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **EA 9817 L** Submit By : **Carmen Lim**
Make & Model : **TOYOTA SIENTA** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	600
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$180.00	60
7	To transfer boot mechanism to new boot	\$120.00	60
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.