

ASS. REC. BY:

REF:

CS/FCI18015324/K19d3

n2

Special Instruction:

Surveyor:

CWS

Kalin

ASSIGNMENT (Office)

From (Person):

Gileen Lee

of

FCI

Date/Time:

23/8/18 @ 2:31pm

Estimated Cost:

Bill to:

OD ☒ TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HB 8772Y

Insured:

8HC 2198P

at Workshop m/s:

Premier Automotive

Tel:

6544 6689

of

23 Chongji South Ave 2 #03-02

Policy No:

Claim No:

D18006 288MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/08/2018

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

3:34pm @ 23/8/18

Person Contacted:

Vincent

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

8HB8772Y - X

8HC2198P - X

24/8/18 @

4:51p revised to Gileen Lee by email.

(08/11/13)

Surveyor: Kalvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB 8772Y Yr Regn: 17 Feb, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685Colour: Silver A/C: Ins / Std / Nil / NASp. Reading: 489028 T/Radio: Ins / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: KNAHMY14AE545X276Gen. Cond: Good / 6 / Poor / BurntSteering: Inorder / 6 / Jammed / Leaked / Burnt orBrake: Inorder / 6 / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or AchillesFront 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 21/8/10 D.O.I. 23/8/10Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/9/8	Insured C/S \$2400/ 30%. (Red to 1966.70, 45%) FCZ 4s.

RECEIVED 13 SEP 2010

Date/Time, File Pass to? ☐ : Prel. Report1) 12/9 tykin ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: 7pLump Sum / I.B.I. (\$) 2400Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

135
50
50
34
269




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015324/K1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-08-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 2198P	Veh. Inspected	SHB 8772Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18006288MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	23/08/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	21/08/2018	Inspection Date	23/08/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006288MFSH

Date: 24 August 2018

Our Ref: CS/FCI18015324/K1qd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8772Y .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/08/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 4,366.10 .
Revised Estimate Amount	: S\$ 1,995.90 .
"Check" Items Amount	: S\$ 861.30 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Yours faithfully

Kalvin Ang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

Date	22-08-2018	Our Ref No.	D18006288MFSH
Accident Date	21-08-2018	Claim Type.	Third Party
Insured Vehicle	SHC2198P	Third Party Vehicle.	SHB8772Y
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02		
Contact Person.	VINCENT CHUA		
Contact No.	62148880/ 65446689	Fax No.	62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 24 August 2018 4:51 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18006288MFSH/1  
**Attachments:** CSFCI18015324K1qd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHB 8772Y.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 24 August 2018 4:08 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18006288MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 23 August 2018 2:31 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [EILEENLEE@MSFIRSTCAPITAL.COM.SG](mailto:EILEENLEE@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18006288MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	17 Feb 2014 / 11:02:28	Receipt No.:	AACCK001-AX239-140217-000022
Asset Type:	Vehicle	Transaction Amount:	\$70,862.00
Asset ID:	SHB8772Y	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140217110228802119		

Vehicle No.:	SHB8772Y
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)

First Registration Date: 17 Feb 2014

---

Original Registration Date:	17 Feb 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5454276
Engine No.:	D4FDDH308843
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,632.00
Minimum PARF Benefit:	\$7,279.00
PARF Eligibility:	Y

---

No. of Transfer:	0
Effective Ownership Date/Time:	17 Feb 2014 11:02:28
COE No.:	2014021701000847C
COE Expiry Date:	16 Feb 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$58,590.00
Lifespan Expiry Date:	16 Feb 2022
Owner ID Type:	Company

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG: 200707743D GST REG: 200707743D

23-Aug-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8772 Y

1 pc	Bootlid emblem	X 44	\$	27.00
1 pc	Bootlid CRDi	— ne	\$	29.00
1 pc	End panel garnish	X su	\$	74.00
1 pc	Rear bumper	— Behind	\$	696.00
1 pc	Rear bumper lower cover	— cl	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	✓ on	\$	58.00
1 pc	Rear bumper inner sponge	✓ on	\$	114.00
1 pc	Rear bumper reinforcement	✓ on	\$	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00	✓ on	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	✓ on	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	✓ on	\$	36.00
				<hr/>
				\$ 1,989.00
				Less 10%
				\$ 198.90
				<hr/>
				\$ 1,790.10

### S/NETT

1 set	Rear bumper clips	— ne	\$	48.00
1 set	Bootlid stickers	— ne	\$	100.00
1 set	Reverse sensor	— slater	\$	<del>280.00</del> 200
1 set	End panel inner garnish clips	— X	\$	28.00
Sundry ne				\$ <del>50.00</del> 20
To dismantle / replace reverse sensor to new bumper and reset to the same				\$ <del>120.00</del> 50
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.				\$ <del>180.00</del> X 11
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, bootlid, etc				\$ <del>850.00</del> 400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel,				\$ <del>800.00</del> 540
To apply rustproofing on the repaired and replaced panels.				\$ <del>120.00</del> X 11
				<hr/>
				\$ 4,366.10

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalua (CKK)  
23/8/18 1630 hrs  
3 Days  
45  
After Repair photo





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015324/K1qd3n2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-09-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2198P	Veh. Inspected	SHB 8772Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18006288MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	23/08/2018

### 2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5454276	Colour	SILVER
Odometer	489028	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	ACHILLES	7 mm
L/H Front Tyre	205/65 R16	ACHILLES	7 mm
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	21/08/2018	Inspection Date	23/08/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8772Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOTLID EMBLEM	NOT NECESSARY	27.00	-
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	END PANEL GARNISH	SERVICEABLE	74.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	CRACKED	58.00	58.00
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER N/S & O/S STAY @\$53.00	BENT	106.00	106.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
	LESS 10% DISCOUNT		-198.90	-188.80
			1,790.10	1,699.20
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			506.00	368.00
<b>LABOUR</b>				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, BOOTLID, ETC.		850.00	400.00

Report Ref No. CS/FCI18015324/K1qd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON BOOTLID,BOOTLID LOWER GARNISH,REAR BUMPER,END PANEL.	NOT NECESSARY	800.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	-
			2,070.00	970.00
GRAND TOTAL			4,366.10	3,037.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/FCI18015324/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.