

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2888H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GLASS ROOF (SN)	SMASHED	14,168.00	8,500.00
1	ROOF LINER ASSEMBLY (SN)	DEFORMED	2,600.00	1,800.00
1	ROOF LINER CLIPS/FASTENERS (SN)	NECESSARY	120.00	50.00
			16,888.00	10,350.00
	<u>LABOUR</u>			
	RETROFIT PANAROMIC ROOF ASSY.		1,200.00	600.00
	WATER PROOFING TEST.	NOT NECESSARY	180.00	-
	RESPRAY ROOF & AFFECTED AREAS.		1,200.00	500.00
	PAINT PROTECTION ON AFFECTED AREAS.	NOT NECESSARY	800.00	-
	WINDSCREEN & WINDOWS POLISHING & DEBRIS REMOVAL.		650.00	200.00
	DIAGNOSTICS & RESET FAULT CODES.		250.00	150.00
	CODING OF CONTROL UNIT (ROOF MOTOR).	NOT NECESSARY	550.00	-
	REMOVAL & REPLACEMENT ROOF LINER.		450.00	200.00
			5,280.00	1,650.00
	GRAND TOTAL		22,168.00	12,000.00

RECOMMENDED COST OF REPAIRS	12,000.00

Report Ref No. CS/IAS18015339/Gvd3s2

8

XING GUO QIANG

M.MATAI, AMSAE-A
Automotive Assessor

X:2.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.