

REC. BY:

REF: CS/FCI18015349/Kad3ep

Special Instruction:

Viewed

WWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

23/8/18 @ 224pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD9262k

Insured:

SHD 4968R

at Workshop m/s

Tins Carb

Tel:

6287 6666

of

No 2 AMLC87-63

Policy No:

Claim No:

D18006284MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/8/18

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

2:49pm @ 23/8/18

Person Contacted:

Candy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SHD 9262k - CC3/FCI13010010/Ky/n

DOA: 13/3/13

SHD 4968R - CC3/FCI15009387/Ky 3/c3

DOA: 12/3/15

24/8/18 @ 4.35pm revised to Eileen Lee by email.

61h @ 400d (Red 11600249, 97%)

ASS. REC. BY:

REF: 1702/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14D 9262K Yr Regn: 11 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Chevrolet Enrce c.c. 1.9 P1

Colour: White (R) A/C: Insured / Std / NI / NA

Sp. Reading: 861968 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL11A69RTBB 05 8852

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 2 mm


L/Bal. 2 mm

D.O.A. 20/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

29/8 File pass to Catherine

RECEIVED 09 OCT 2017

Date/Time, File Pass to?

1) 09/10 Trans: ☐ : Prell. Report

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / I.B.I. (\$) TP 4000

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - P.S. SI

Fixtures

Others

TOTAL

110x15=1650

170+1650

50

32

1902

MOTOR SURVEY ASSIGNMENT

Date	21-08-2018	Our Ref No. D18006284MFSH
Accident Date	20-08-2018	Claim Type. Third Party
Insured Vehicle	SHD4968R	Third Party Vehicle. SHD9262K
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015349/Kqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4968R	Veh. Inspected	SHD 9262K
Policy No.		Coverage (\$)	0.00
Claim No.	D18006284MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	23/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/08/2018	Inspection Date	23/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 24 August 2018 4:35 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006284MFSH/1
Attachments: CSFCI18015349Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHD 9262K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 23 August 2018 2:50 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006284MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 23 August 2018 2:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006284MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006284MFSH

Date: 24 August 2018

Our Ref: CS/FCI18015349/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 9262K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/08/2018 at the premises of M/s TRANS CAB. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>120,002.49</u> .
Revised Estimate Amount	: S\$ <u>15,836.85</u> .
"Check" Items Amount	: S\$ <u>6,095.93</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9262K
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Aug 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1443561K
Chassis No.:	KL1LA69RJB058852
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,811.00
Original Registration Date:	11 Nov 2011
First Registration Date:	11 Nov 2011
Transfer Count:	0
Actual ARF Paid:	\$13,811.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2019
PARF Rebate Amount:	\$8,977.00

Intended COE Rebate Details

COE Expiry Date:	10 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$39,041.00
COE Rebate Amount:	\$5,973.00
Total Rebate Amount:	\$14,950.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 17:10
Date Of Accident	20/08/2018 13:30
Exact Location Of Accident	PUNGGOL CENTRAL X PUNGGOL WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9262K
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	FUN TOW KENG
NRIC No	S6808531D
Date Of Birth	03/03/1968
Occupation	OUTDOOR
Date Of Driving Pass	28/02/1990
Driving Experience	28 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96740128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 233 BAIN STREET #18-07
Postcode	180233
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 20.08.2018 at about 1330hours, I was travelling straight on the fourth lane along Punggol Central with green lights on my favour. While crossing the junction, suddenly I felt an impact. Vehicle B (SHD4968R) which came from opposite lane without observing for traffic lights and oncoming vehicle. Hence, Vehicle B's front portion had collided onto my taxi's right side front portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4968R
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SEAH CHIEW SWEE
NRIC/Passport Number	S1319573J
Contact Number	96937027
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow Insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GVA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9262K**AAD1808-170**

Not Authored
Proposed 11 Lys @ 400d
Book Value ?

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9262K

KL1LA69RJB058852

CHEVROLET

EPICA 2.0

20.8.2018

FCIL**PART****LIST**

1	1	Front Fender RH	\$	<i>Bu</i>	837.60	✓
2	1	Front Fender Liner RH	\$	<i>CM</i>	47.00	—
3	1	Front Fender Inner Wheel House Panel RH	\$	<i>R</i>	1,437.00	X
4	1	Front Fender LH	\$	<i>Bu</i>	837.60	—
5	1	Front Fender Liner LH	\$	<i>CM</i>	47.00	✓
6	1	Front Fender Inner Wheel House Panel LH	\$	<i>R</i>	1,437.00	X
7	1	Front Bumper	\$	<i>CM</i>	1,202.00	✓
8	1	Front Bumper Lower Absorber	\$	<i>Z</i>	180.00	✓
9	1	Front Bumper Reinforcement	\$	<i>R</i>	356.00	✓
10	1	Front Bumper Retainer RH	\$	<i>CM</i>	102.00	✓
11	1	Front Bumper Retainer LH	\$	<i>CM</i>	102.00	✓
12	1	Front Bumper Lower Grille	\$	<i>D11 / D12</i>	78.00	✓
13	1	Front Bumper Lower Stiffener	\$	<i>R</i>	134.37	✓
14	1	Front Bumper Bracket LH	\$	<i>D11</i>	10.00	✓
15	1	Front Bumper Bracket RH	\$	<i>D11</i>	10.00	✓
16	1	Bumper Fog Lamp Cover RH	\$	<i>M11</i>	32.40	✓
17	1	Bumper Fog Lamp Cover LH	\$	<i>Su</i>	32.40	X
18	1	Bonnet	\$	<i>Bu</i>	1,250.00	✓
19	1	Bonnet hinge RH	\$	<i>R</i>	36.00	✓
20	1	Bonnet hinge LH	\$	<i>R</i>	36.00	✓
21	1	Bonnet Moulding	\$	<i>D11</i>	161.97	✓
22	1	Bonnet Lock	\$	<i>D11</i>	60.00	✓
23	1	Bonnet cable	\$	<i>Su</i>	125.00	X
24	1	Front Support Panel Assy	\$	<i>R</i>	1,222.32	✓
25	1	Headlamp RH	\$	<i>CM</i>	816.00	✓
26	1	Headlamp LH	\$	<i>M11</i>	816.00	✓
27	1	Windscreen Washer Tank - Filler Neck	\$	<i>D11</i>	4.80	✓
28	1	Windscreen Washer Tank	\$	<i>Su</i>	62.00	X
29	1	Windscreen Washer Tank Motor	\$	<i>Su</i>	51.00	X

Trans-cab Auto Services Pte Ltd**AAD1808-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9262K

30	1	Washer Tank Hose	\$	21.00	X
31	1	Radiator Assembly	\$	618.00	X
32	1	Radiator upper hose	\$	30.00	✓
33	1	Radiator lower hose	\$	120.00	X
34	1	Radiator Grille (Grille A-Rad)	\$	367.00	✓
35	1	Radiator Grille Top Cover	\$	45.02	✓
36	1	Fan Blade(A/C)	\$	536.00	✓
37	1	Fan Blade(Radiator)	\$	634.00	X
38	1	Aircon Condenser	\$	600.00	✓
39	1	Aircon hose - condenser to compressor	\$	450.00	} Re.
40	1	Aircon hose - compressor to evaporator	\$	624.00	
41	1	Aircon hose - condenser to evaporator	\$	580.00	
42	1	Aircon hose - condenser to compressor	\$	450.00	
43	1	Aircon hose - compressor to evaporator	\$	624.00	
44	1	Aircon hose - condenser to evaporator	\$	580.00	}
45	1	Aircon compressor - pump	\$	1,847.95	
46	1	Aircon compressor bracket	\$	245.30	} X
47	1	Aircon condensor bottom bushing	\$	119.00	
48	1	Air Cleaner Assembly (Cleaner A-Air)	\$	112.00	
49	1	Air Filter (element A-Air Cleaner)	\$	39.00	
50	1	Air-cleaner intake duct	\$	89.25	
51	1	Air-cleaner intake duct hose (top)	\$	75.85	
52	1	Air intake resonator top (square)	\$	14.52	
53	1	Air intake resonator (beside fender)	\$	20.01	
54	1	Air intake resonator hose (bottom)	\$	60.90	
55	1	Air intake resonator tank top bracket	\$	45.00	
56	1	Resonator A-A/CL	\$	137.00	
57	1	Alternator assembly	\$	1,040.00	
58	1	Battery (Battery A)	\$	405.00	
59	1	Battery tray	\$	65.00	
60	1	Battery fastener bracket	\$	23.50	
61	1	Battery fastener bolt	\$	46.00	
62	1	Front Fuse Box (support panel top)	\$	215.00	
63	1	Front Fuse Top Cover	\$	25.00	
64	1	Fuse Box	\$	716.00	
65	1	Fuse box top (cover)	\$	250.00	
66	1	Fuse Box Lower	\$	60.00	
67	1	Fuse box centre cover	\$	380.00	

Trans-cab Auto Services Pte Ltd**AAD1808-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9262K

68	1	Engine main harness wire	\$	Sn	1,500.00	
69	1	Gear box assy	\$	M	20,800.00	
70	1	Cross member	\$	Sn	1,030.71	
71	1	Gear box cross member bracket	\$	M	450.00	
72	1	Gear Box Mounting RH	\$	Sn	142.50	
73	1	Engine block	\$	Sn	28,895.40	
74	1	Engine mounting side	\$	Sn	175.00	
75	1	Engine lower splashield cover	\$	Sn	240.00	
76	1	Front Centre Cross Member	\$	Sn	763.50	
77	1	Front Centre Member (Member A-Frt Susp, Ctr)	\$	M	265.63	
78	1	Engine suspension cross member	\$	Sn	344.07	
79	1	Engine oil sump	\$	Sn	500.00	
80	1	Engine oil sump strainer	\$	Sn	125.60	
81	1	Engine overhaul gasket	\$	Sn	98.70	
82	1	Engine oil sump sealant	\$	Sn	45.00	
83	1	Engine Splash Cover RH (Cover A-Engine)	\$	Sn	168.00	
84	1	Engine Splash Cover LH (Cover A-Engine)	\$	Sn	168.00	
85	1	ECU assy	\$	Sn	4,575.65	
86	1	ABS pump	\$	Sn	5,547.45	
87	1	ABS pump pipe	\$	Sn	325.33	
88	1	Steering Rack & Pinion Assy (Gear A-Strg)	\$	M	905.51	
89	1	Steering Rack End (Spring A-Clock)	\$	M	88.56	
90	1	Steering Tie-Rod End (End -Tie Rod)	\$	M	67.00	
91	1	Steering wheel Assy (Wheel A-Strg)	\$	Sn	258.41	
92	1	Steering Wheel Air Bag (Module A-Air Bag,Driver)	\$	Burn	1,681.48	✓
93	1	Steering Wheel Air Bag Sensor(Sensor Air Bag)	\$	new	680.00	✓
94	1	Steering Wheel air bag control unit	\$	new	1,543.22	✓
95	1	Power steering pump	\$	Sn	1,755.31	
96	1	Power steering reservoir tank	\$	Sn	120.00	
97	1	Power steering inlet / outlet pipe	\$	Sn	65.00	
98	1	Power steering pump pulley	\$	Sn	66.00	
99	1	Power steering hose - pressure	\$	Sn	256.00	
100	1	Power steering hose - non pressure	\$	Sn	312.11	
101	1	Dash Board (Panel A-Inst)	\$	Sn	1,420.63	
102	1	Dash Board Air Bag (Module A-Air Bag , Pass)	\$	Sn	1,792.96	
103	1	Dash Board Air Bag Sensor (Sensor-Air Bag)	\$	Sn	965.33	
104	1	Dash Board air bag control unit	\$	Sn	1,543.22	
105	1	Dash Board lower fuse box assy	\$	Sn	545.60	

Trans-cab Auto Services Pte Ltd**AAD1808-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9262K

106	1	Wiper/Signal switch	\$	S ₂	108.20	}
107	1	Glove box	\$	S ₂	61.00	
108	1	Console Box top cover	\$	S ₂	250.00	
109	1	Console Box front	\$	S ₂	213.00	
110	1	Front Shock Absorber Assy RH	\$	S ₂	216.17	
111	1	Front Shock Absorber Top Mounting RH	\$	S ₂	48.32	
112	1	Front Shock Absorber Assy LH	\$	S ₂	216.17	
113	1	Front Shock Absorber Top Mounting LH	\$	S ₂	48.32	
114	1	Front Lower Arm RH	\$	S ₂	283.00	
115	1	Front Lower Arm LH	\$	S ₂	283.00	
116	1	Front Knuckle Arm RH	\$	S ₂	230.00	
117	1	Front Knuckle Arm LH	\$	S ₂	230.00	
118	1	Front Hub Unit	\$	S ₂	376.00	
119	1	Front Disc Brake RH	\$	S ₂	157.55	
120	1	Front Disc Brake LH	\$	S ₂	157.55	
121	1	Front Strut Bar Bracket LH	\$	S ₂	235.01	
122	1	Front Stabilizer Bar	\$	S ₂	234.00	
123	1	Front Stabilizer Bar Link RH	\$	S ₂	51.79	
124	1	Front Stabilizer Bar Link LH	\$	S ₂	51.79	
125	1	Front Stabilizer Bar Bracket RH	\$	N	105.75	
126	1	Front Stabilizer Bar Bracket LH	\$	N	105.75	
127	1	Front Stabilizer Bar Bush RH	\$	S ₂	66.00	}
128	1	Front Stabilizer Bar Bush LH	\$	S ₂	66.00	
129	1	Front Beam A - Impact RH	\$	N	214.00	}
130	1	Front Beam A - Impact LH	\$	N	214.00	
131	1	Drive Shaft RH	\$	N	900.00	}
132	1	Drive Shaft LH	\$	N	900.00	
133	1	Interm Axle Shaft (Centre)	\$	S ₂	241.14	}
134	1	Front Seat Belt RH	\$	T ₂	402.50	
135	1	Front safety belt cover garnish	\$	S ₂	125.00	

TOTAL	\$	110,851.65
10%	\$	11,085.17
	\$	99,766.49

Specical Nett

1	1 Set	Front Bumper Fastener Clip	\$	N ₂	24.00	✓
2	2	Front Windscreen Sealant	\$	N ₂	100.00	✓

Trans-cab Auto Services Pte Ltd**AAD1808-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9262K

3	1	Front Windscreen Inner Sponge Seal	\$	na	100.00	30sn
4	1 Set	Radiator Grille Top Cover Clip	\$	na	10.00	✓
5	1 Set	Front licence plate with holder	\$.B	192.00	20sn
6	1 Set	Radiator Grille clip	\$	na	35.00	✓
7	1 Set	Front Fender Liner clip RH	\$	na	30.00	✓
8	1 Set	Louver Cowl Top clip	\$	na	30.00	X
9	2	Bonnet stopper	\$	na	15.00	X

TOTAL	\$	536.00
--------------	-----------	---------------

TOTAL PARTS	\$	100,302.49
--------------------	-----------	-------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	9001
Towing Fees.	\$	120.00	501
Putty and spray painting of the affected portion.	\$	6,000.00	10001
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	440.00	1201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2501
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X

Trans-cab Auto Services Pte Ltd**AAD1808-170**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9262K

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To replace, refix and top up coolant for radiator	\$	170.00	501
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	1001
To rust-proofing of the affected areas.	\$	170.00	1201
To transfer of end panel fittings and conduct water seepage test.	\$	nn 170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To remove and renew engine and gear box mounting.	\$	nn 380.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	nn 380.00	X
To lift-up engine with gear box and refit.	\$	nn 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00	X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00	X
To remove and refit ABS pump relay to enable repair.	\$	nn 380.00	X
To remove and refit air bag system and reset.	\$	480.00	2001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL	\$	19,700.00
Over All Total	\$	120,002.49
Repair Days		25 DAYS

8 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015349/Kqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4968R	Veh. Inspected	SHD 9262K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006284MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	23/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KL1LA69RJBB058852	Colour	WHITE / RED	
Odometer	861968	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	8 mm	
L/H Front Tyre	195/65 R15	GITI	8 mm	
R/H Rear Tyre	195/65 R15	GITI	8 mm	
L/H Rear Tyre	195/65 R15	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2018	Inspection Date	23/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9262K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RH	BENT	837.60	837.60
1	FRONT FENDER LINER RH	CRACKED	47.00	47.00
1	FRONT FENDER INNER WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT FENDER LH	BUCKLED	837.60	837.60
1	FRONT FENDER LINER LH	CRACKED	47.00	47.00
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT BUMPER	CRACKED	1,202.00	1,202.00
1	FRONT BUMPER LOWER ABSORBER	TORN	180.00	180.00
1	FRONT BUMPER REINFORCEMENT	BENT	356.00	356.00
1	FRONT BUMPER RETAINER RH	CRACKED	102.00	102.00
1	FRONT BUMPER RETAINER LH	CRACKED	102.00	102.00
1	FRONT BUMPER LOWER GRILLE	DISTORTED / DENTED	78.00	78.00
1	FRONT BUMPER LOWER STIFFENER	BENT	134.37	134.37
1	FRONT BUMPER BRACKET LH	DISTORTED	10.00	10.00
1	FRONT BUMPER BRACKET RH	DISTORTED	10.00	10.00
1	BUMPER FOG LAMP COVER RH	MISSING	32.40	32.40
1	BUMPER FOG LAMP COVER LH	SERVICEABLE	32.40	-
1	BONNET	BENT	1,250.00	1,250.00
1	BONNET HINGE RH	BENT	36.00	36.00
1	BONNET HINGE LH	BENT	36.00	36.00
1	BONNET MOULDING	DENTED	161.97	161.97
1	BONNET LOCK	DISTORTED	60.00	60.00
1	BONNET CABLE	SERVICEABLE	125.00	-
1	FRONT SUPPORT PANEL ASSY	BENT	1,222.32	1,222.32
1	HEADLAMP RH	CRACKED	816.00	816.00
1	HEADLAMP LH	MTG BROKEN	816.00	816.00
1	WINDSCREEN WASHER TANK - FILLER NECK	DENTED	4.80	4.80
1	WINDSCREEN WASHER TANK	SERVICEABLE	62.00	-
1	WINDSCREEN WASHER TANK MOTOR	SERVICEABLE	51.00	-

Report Ref No. CS/FCI18015349/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WASHER TANK HOSE	SERVICEABLE	21.00	-
1	RADIATOR ASSEMBLY	SERVICEABLE	618.00	-
1	RADIATOR UPPER HOSE	PUNCTURE	30.00	30.00
1	RADIATOR LOWER HOSE	SERVICEABLE	120.00	-
1	RADIATOR GRILLE (GRILLE A-RAD)	MISSING	367.00	367.00
1	RADIATOR GRILLE TOP COVER	CRACKED	45.02	45.02
1	FAN BLADE (A/C)	CRACKED	536.00	536.00
1	FAN BLADE (RADIATOR)	SERVICEABLE	634.00	-
1	AIRCON CONDENSER	BENT	600.00	600.00
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	SERVICEABLE	450.00	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	SERVICEABLE	624.00	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	580.00	-
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	SERVICEABLE	450.00	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	SERVICEABLE	624.00	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	580.00	-
1	AIRCON COMPRESSOR - PUMP	SERVICEABLE	1,847.95	-
1	AIRCON COMPRESSOR BRACKET	SERVICEABLE	245.30	-
1	AIRCON CONDENSOR BOTTOM BUSHING	SERVICEABLE	119.00	-
1	AIR CLEANER ASSEMBLY (CLEAR A-AIR)	SERVICEABLE	112.00	-
1	AIR FILTER (ELEMENT A-AIR CLEANER)	SERVICEABLE	39.00	-
1	AIR-CLEANER INTAKE DUCT	SERVICEABLE	89.25	-
1	AIR-CLEANER INTAKE DUCT HOSE (TOP)	SERVICEABLE	75.85	-
1	AIR INTAKE RESONATOR TOP (SQUARE)	SERVICEABLE	14.52	-
1	AIR INTAKE RESONATOR (BESIDE FENDER)	SERVICEABLE	20.01	-
1	AIR INTAKE RESONATOR HOSE (BOTTOM)	SERVICEABLE	60.90	-
1	AIR INTAKE RESONATOR TANK TOP BRACKET	TO REPAIR SEE LABOUR	45.00	-
1	RESONATOR A-A/CL	SERVICEABLE	137.00	-
1	ALTERNATOR ASSEMBLY	SERVICEABLE	1,040.00	-
1	BATTERY (BATTERY A)	SERVICEABLE	405.00	-
1	BATTERY TRAY	SERVICEABLE	65.00	-
1	BATTERY FASTENER BRACKET	TO REPAIR SEE LABOUR	23.50	-

Report Ref No. CS/FCI18015349/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BATTERY FASTENER BOLT	TO REPAIR SEE LABOUR	46.00	-
1	FRONT FUSE BOX (SUPPORT PANEL TOP)	SERVICEABLE	215.00	-
1	FRONT FUSE TOP COVER	SERVICEABLE	25.00	-
1	FUSE BOX	SERVICEABLE	716.00	-
1	FUSE BOX TOP (COVER)	SERVICEABLE	250.00	-
1	FUSE BOX LOWER	SERVICEABLE	60.00	-
1	FUSE BOX CENTRE COVER	SERVICEABLE	380.00	-
1	ENGINE MAIN HARNESS WIRE	SERVICEABLE	1,500.00	-
1	GEAR BOX ASSY	TO REPAIR SEE LABOUR	20,800.00	-
1	CROSS MEMBER	SERVICEABLE	1,030.71	-
1	GEAR BOX CROSS MEMBER BRACKET	TO REPAIR SEE LABOUR	450.00	-
1	GEAR BOX MOUNTING RH	SERVICEABLE	142.50	-
1	ENGINE BLOCK	SERVICEABLE	28,895.40	-
1	ENGINE MOUNTING SIDE	SERVICEABLE	175.00	-
1	ENGINE LOWER SPLASHIELD COVER	SERVICEABLE	240.00	-
1	FRONT CENTRE CROSS MEMBER	SERVICEABLE	763.50	-
1	FRONT CENTRE MEMBER (MEMBER A-FRT SUSP, CTR)	TO REPAIR SEE LABOUR	265.63	-
1	ENGINE SUSPENSION CROSS MEMBER	SERVICEABLE	344.07	-
1	ENGINE OIL SUMP	SERVICEABLE	500.00	-
1	ENGINE OIL SUMP STRAINER	SERVICEABLE	125.60	-
1	ENGINE OVERHAUL GASKET	SERVICEABLE	98.70	-
1	ENGINE OIL SUMP SEALANT	SERVICEABLE	45.00	-
1	ENGINE SPLASH COVER RH (COVER A-ENGINE)	SERVICEABLE	168.00	-
1	ENGINE SPLASH COVER LH (COVER A-ENGINE)	SERVICEABLE	168.00	-
1	ECU ASSY	SERVICEABLE	4,575.65	-
1	ABS PUMP	SERVICEABLE	5,547.45	-
1	ABS PUMP PIPE	SERVICEABLE	325.33	-
1	STEERING RACK & PINION ASSY (GEAR A-STRG)	TO REPAIR SEE LABOUR	905.51	-
1	STEERING RACK END (SPRING A-CLOCK)	TO REPAIR SEE LABOUR	88.56	-

Report Ref No. CS/FCI18015349/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING TIE-ROD END (END-TIE ROD)	TO REPAIR SEE LABOUR	67.00	-
1	STEERING WHEEL ASSY (WHEEL A-STRG)	SERVICEABLE	258.41	-
1	STEERING WHEEL AIR BAG (MODULE A-AIR BAG, DRIVER)	BURST	1,681.48	1,681.48
1	STEERING WHEEL AIR BAG SENSOR (SENSOR AIR BAG)	NECESSARY	680.00	680.00
1	STEERING WHEEL AIR BAG CONTROL UNIT	NECESSARY	1,543.22	1,543.22
1	POWER STEERING PUMP	SERVICEABLE	1,755.31	-
1	POWER STEERING RESERVOIR TANK	SERVICEABLE	120.00	-
1	POWER STEERING INLET / OUTLET PIPE	SERVICEABLE	65.00	-
1	POWER STEERING PUMP PULLEY	SERVICEABLE	66.00	-
1	POWER STEERING HOSE - PRESSURE	SERVICEABLE	256.00	-
1	POWER STEERING HOSE - NON PRESSURE	SERVICEABLE	312.11	-
1	DASH BOARD (PANEL A-INST)	SERVICEABLE	1,420.63	-
1	DASH BOARD AIR BAG (MODULE A-AIR BAG, PASS)	SERVICEABLE	1,792.96	-
1	DASH BOARD AIR BAG SENSOR (SENSOR-AIR BAG)	SERVICEABLE	965.33	-
1	DASH BOARD AIR BAG CONTROL UNIT	SERVICEABLE	1,543.22	-
1	DASH BOARD LOWER FUSE BOX ASSY	SERVICEABLE	545.60	-
1	WIPER / SIGNAL SWITCH	SERVICEABLE	108.20	-
1	GLOVE BOX	SERVICEABLE	61.00	-
1	CONSOLE BOX TOP COVER	SERVICEABLE	250.00	-
1	CONSOLE BOX FRONT	SERVICEABLE	213.00	-
1	FRONT SHOCK ABSORBER ASSY RH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	SERVICEABLE	48.32	-
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	SERVICEABLE	48.32	-
1	FRONT LOWER ARM RH	SERVICEABLE	283.00	-
1	FRONT LOWER ARM LH	SERVICEABLE	283.00	-
1	FRONT KNUCKLE ARM RH	SERVICEABLE	230.00	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	230.00	-
1	FRONT HUB UNIT	SERVICEABLE	376.00	-
1	FRONT DISC BRAKE RH	SERVICEABLE	157.55	-
1	FRONT DISC BRAKE LH	SERVICEABLE	157.55	-
1	FRONT STRUT BAR BRACKET LH	SERVICEABLE	235.01	-

Report Ref No. CS/FCI18015349/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT STABILIZER BAR	SERVICEABLE	234.00	-
1	FRONT STABILIZER BAR LINK RH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR LINK LH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR BRACKET RH	TO REPAIR SEE LABOUR	105.75	-
1	FRONT STABILIZER BAR BRACKET LH	TO REPAIR SEE LABOUR	105.75	-
1	FRONT STABILIZER BAR BUSH RH	SERVICEABLE	66.00	-
1	FRONT STABILIZER BAR BUSH LH	SERVICEABLE	66.00	-
1	FRONT BEAM A - IMPACT RH	TO REPAIR SEE LABOUR	214.00	-
1	FRONT BEAM A - IMPACT LH	TO REPAIR SEE LABOUR	214.00	-
1	DRIVE SHAFT RH	TO REPAIR SEE LABOUR	900.00	-
1	DRIVE SHAFT LH	TO REPAIR SEE LABOUR	900.00	-
1	INTERM AXLE SHAFT (CENTRE)	SERVICEABLE	241.14	-
1	FRONT SEAT BELT RH	JAMMED	402.50	402.50
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
	LESS 10% DISCOUNT		-11,085.17	-1,426.43
			99,766.48	12,837.85
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	24.00	24.00
2	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SET RADIATOR GRILLE TOP COVER CLIP (SN)	NECESSARY	10.00	10.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	192.00	20.00
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	35.00	35.00
1	SET FRONT FENDER LINER CLIP RH (SN)	NECESSARY	30.00	30.00
1	SET LOUVER COWL TOP CLIP (SN)	NOT NECESSARY	30.00	-
2	BONNET STOPPER (SN)	NOT NECESSARY	15.00	-
			536.00	189.00

Report Ref No. CS/FCI18015349/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.		480.00	200.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT FENDER INNER WHEEL HOUSE PANEL RH, FRONT FENDER INNER WHEEL HOUSE PANEL LH, AIR INTAKE RESONATOR TANK TOP BRACKET, BATTERY FASTENER BRACKET, BATTERY FASTENER BOLT, GEAR BOX ASSY, GEAR BOX CROSS MEMBER BRACKET, }		7,500.00	900.00
	FRONT CENTRE MEMBER (MEMBER A-FRT SUSP. CTR), STEERING RACK & PINION ASSY (GEAR A-STRG), STEERING RACK END (SPRING A-CLOCK), STEERING TIE-ROD END (END-TIE ROD), FRONT STABILIZER BAR BRACKET RH, FRONT STABILIZER BAR BRACKET LH, FRONT BEAM A - IMPACT RH, FRONT BEAM A - IMPACT LH, DRIVE SHAFT RH AND DRIVE SHAFT LH. }		-	-
	TOWING FEES.		120.00	50.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,000.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		440.00	120.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		380.00	250.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS.		380.00	100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00

Report Ref No. CS/FCI18015349/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
			19,700.00	2,810.00
GRAND TOTAL			120,002.48	15,836.85

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00
---	--	--	--	-----------------

Report Ref No. CS/FCI18015349/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.