

22/03/2002

ASS. REC. BY:

REF: CS/FCI18015354/Uqd3/n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Laurene jaw

of

FCI

Date/Time:

21/8/18 @ 6:04pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 2116U

Insured:

SHC 0478U

at Workshop m/s

Specialist Motor

Tel:

67472112

of

81k 3018A, ubi Rd 1 #01-24/26

Policy No:

Claim No:

D18006223MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/8/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

10:14am @ 23/8/18

Person Contacted:

Hui Lin

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SIN 2116U - CC4 / AIG 17021283 / K2b3q2 DOA: 5/11/17
	SHC 478U - CS / FCI 15021109 / Rgbd1 DOA: 30/11/15
	Revert via email preli advise

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

F01/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SYN 2116Uat Workshop m/s: Specialists

of _____

Insured: SAC 478U

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 17500?

IDAC Accident Rpt: _____ Consistent? : Yes or No

GLA / PR Seen: ✓ Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L1A 12763

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SYN 2116U Yr Regn: 2109Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Honda civic c.c. 1595Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 114631 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF D 46209 S 200 455Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45 ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 19/8/18D.O.I. 24/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orRear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5 mls plus note 4737

30/8/18 confirmed L/S @ 4100 with h.u. in (Red @ 5487.50, 57%)
MV: @ 17.5K (27); GLA: @ 12763; NV: @ 4737.

RECEIVED 07 SEP 2010

Date/Time, File Pass to?

☐

: Preli. Report

10/9/18 typist☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 4100

170
50
50
67
337



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015354/Uqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 478U	Veh. Inspected	SJN 2116U
Policy No.		Coverage (\$)	0.00
Claim No.	D18006223MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	23/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/08/2018	Inspection Date	24/08/2018
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006223MFSH

Date: 28/8/2018

Our Ref: CS/FCI18015354/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJN 2116U

Please be informed that we had conducted the inspection of the abovementioned vehicle
28/8/2018 at the premises of M/s Specialist Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>9,587.50</u>
Revised Estimate Amount	: S\$ <u>5,049.60</u>
"Check" Items Amount	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
Rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

MARCUS

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-08-2018	Our Ref No. D18006223MFSH
Accident Date	19-08-2018	Claim Type. Third Party
Insured Vehicle	SHC0478U	Third Party Vehicle. SJN2116U
Survey Location	BLK 3018A UBI ROAD 1 #01-24-26	
Contact Person.	HUI LIN	
Contact No.	67472112/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SPECIALISTS MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 28 August 2018 5:32 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006223MFSH/1
Attachments: PRELI ADVISED SJN 2116U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJN 2116U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 23 August 2018 10:16 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006223MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 21 August 2018 6:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006223MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Honda Civic

Price Range ▼

Depreciation ▼

2009 ▼

Vehicle Type ▼

Home » Used Cars » Dickson Automobile » Honda Civic 1.8A VTi-S

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Honda Civic 1.8A VTi-S

Overview

Financial

Accessories

Similar

Research

Photos

Map



Listen | Advise | Serve

DICKSON AUTOMOBILE PTE LTD

A member of DICKSON AUTO GROUP

Established since 1988

FB 515133
ISO 9001:2008

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price \$18,800**Depreciation** -**Reg Date** 04-Feb-2009
(5mths 10days COE left)**Manufactured** 2008**Mileage** 164,094 km (17.2k /yr)**Transmission** Auto**Engine Cap** 1,799 cc**Road Tax** \$978 /yr**Power** 103.0 kW (138 bhp)
View specs of the Honda Civic (2006-2012)**Curb Weight** 1,219 kg**Features** 1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Paddle Shifter, Multi Function Steering Control, Cruise Control, ABS, 4 x Disc Brakes.**Accessories** Sports Rims, Factory Fitted Audio System, Electrical Retractable Side Mirrors With Indicators, Upholstery Leather Seats, Reverse Sensors.**Description** Affordable Down Payment At \$5K Plus Only! Well Kept In Tip Top Condition By Single Owner! Professional Evaluation And Grooming Package Available! A Stylish Sedan That You Must Not Miss! Buy It From Us With ASeller Infor
Company

Car Tyres



Compare



Honda Civic

Price Range ▼

Depreciation ▼

2009 ▼

Vehicle Type ▼

Home » Used Cars » Dickson Automobile » Honda Civic 1.8A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Honda Civic 1.8A

Overview

Financial

Accessories

Similar

Research

Photos

Map



Listen | Advise | Serve

DICKSON AUTOMOBILE PTE LTD

A member of DICKSON AUTO GROUP

Established since 1988

PS 516133
ISO 9001:2008

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price **\$18,800****Depreciation** \$8,680 /yr

View models with similar depreciation

Reg Date 27-Mar-2009
(7mths 2days COE left)**Manufactured** 2009**Mileage** 99,000 km (10.5k /yr)**Transmission** Auto**Engine Cap** 1,799 cc**Road Tax** \$978 /yr**Power** 103.0 kW (138 bhp)
View specs of the Honda Civic (2006-2012)**Curb Weight** 1,219 kg**Features** Powerful And Responsive 1.8L I-Vtec Engine, 5 Speed Auto Transmission, Dual Airbag, ABS, 4 x Disc Brakes, Electrical Retractable Side Mirrors.**Accessories** Original CD Audio System, Solar Film, Fog Lamp, Sport Rims, Leather Seats, Reverse Sensors.**Description** Extremely Low Mileage! Very Good Condition! Extended Warranty Available! A Sporty And Powerful Sedan Designed To Give You Superb Handling Enhancing Your Driving Experience. Buy It From Us With A Peace Of

Location Ma

Seller Infor

Company

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7082E
Vehicle Details	
Vehicle No.:	SJN2116U
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L 5AT
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R16A14001504
Chassis No.:	JHMF46209S200455
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,281.00
Original Registration Date:	09 Feb 2009
First Registration Date:	09 Feb 2009
Transfer Count:	1
Actual ARF Paid:	\$25,281.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2019
PARF Rebate Amount:	\$12,640.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$2,693.00
COE Rebate Amount:	\$123.00
Total Rebate Amount:	\$12,763.00

The information contained herein is correct as at 24 Aug 2018

OK

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJN2116U/1808123

20th August 2018

The Manager
Motor Claim Dept.
MS First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
Singapore 068877

not Admit
2/3 \$400/2
24/8/18
Cheng Hengye
Sly.

Date of Accident : 19th August 2018
Location : Jalan Eunos
Third Party Vehicle No : SHC 478 U (Your insured)
Repair Cost For Vehicle No : SJN 2116 U Honda Civic

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover 300500	1	610.70	\$ 610.70 —
2	Rear boot cover emblem (H) 22	1	25.70	\$ 25.70 ✓
3	Rear boot cover hinge L&R 2	2	23.10	\$ 46.20 X
4	Rear boot cover reflector L&R MS CR	2	202.40	\$ 404.80 120
5	Rear boot cover lock 22	1	194.40	\$ 194.40 ✓
6	Rear boot cover weather strip 22	1	97.60	\$ 97.60 ✓
7	Rear lamp assy L&R CR	2	308.70	\$ 617.40 ✓
8	Rear end panel 300500	1	300.50	\$ 300.50 ✓
9	Rear end panel garnish 22	1	56.10	\$ 56.10 ✓
10	Rear end panel garnish clips 11	1set	35.00	\$ 35.00 X
11	Rear bumper fascia 22 638	1	730.50	\$ 730.50 —
12	Rear bumper clips 22	1set	35.00	\$ 35.00 —
13	Rear bumper side retainer L&R 300	2	14.60	\$ 29.20 —
14	Rear bumper bracket L&R 11	2	13.90	\$ 27.80 X
15	Rear exhaust silencer assy 11	1	535.20	\$ 535.20 X
16	Rear exhaust silencer chrome 11	1	196.40	\$ 196.40 X
17	Rear bumper sensor (s/nett) shield	1	380.00	\$ 380.00 2005. ✓
18	Reverse camera (s/nett) 2005	1	880.00	\$ 880.00 3005. ✓
19	Rear bumper lower lip (s/nett) CR	1	380.00	\$ 380.00 — S.N
20	Rear boot spoiler (s/nett) 22	1	380.00	\$ 380.00 X
21	Rear end panel sealer (s/nett) 22	1	80.00	\$ 80.00 505. ✓
				\$ 6,042.50

207

P-2807

207
2245.6

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJN2116U/1808123

20th August 2018

Balance b/f	\$ 6,042.50
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding rear boot cover, rear bumper, rear end panel, remove & install all damage parts, straighten & re-align body	\$ 1,800.00 800
Tuff-kote on damage parts	\$ 120.00 80
Spray painting on damage parts	\$ 1,400.00 1000
Remove & refix rear bumper sensor	\$ 80.00 50
Check all lighting after repairs	\$ 45.00 20
Remove & refix rear exhaust silencer	11 \$ 100.00 2
Labour Charge	\$ 3,545.00
Total Amount	\$ 9,587.50

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015354/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 478U	Veh. Inspected	SJN 2116U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006223MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMFD46209S200455	Colour	SILVER	
Odometer	114631	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	FALKEN	5 mm	
L/H Front Tyre	215/45 ZR17	FALKEN	5 mm	
R/H Rear Tyre	215/45 ZR17	FALKEN	5 mm	
L/H Rear Tyre	215/45 ZR17	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/08/2018	Inspection Date	24/08/2018	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 2116U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT COVER	BADLY DENTED	610.70	610.70
1	REAR BOOT COVER EMBLEM (H)	NECESSARY	25.70	25.70
2	REAR BOOT COVER HINGE L&R @\$23.10	TO REPAIR SEE LABOUR	46.20	-
2	REAR BOOT COVER REFLECTOR L&R @\$202.40	N/S CRACKED	404.80	202.40
1	REAR BOOT COVER LOCK	TWISTED	194.40	194.40
1	REAR BOOT COVER WEATHER STRIP	TWISTED	97.60	97.60
2	REAR LAMP ASSY L&R @\$308.70	CRACKED	617.40	617.40
1	REAR END PANEL	BADLY DENTED	300.50	300.50
1	REAR END PANEL GARNISH	TWISTED	56.10	56.10
1	SET REAR END PANEL GARNISH CLIPS	NOT NECESSARY	35.00	-
1	REAR BUMPER FASCIA	DENTED	730.50	638.00
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
2	REAR BUMPER SIDE RETAINER L&R @\$14.60	BENT	29.20	29.20
2	REAR BUMPER BRACKET L&R @\$13.90	NOT NECESSARY	27.80	-
1	REAR EXHAUST SILENCER ASSY	NOT NECESSARY	535.20	-
1	REAR EXHAUST SILENCER CHROME	NOT NECESSARY	196.40	-
	LESS 20% DISCOUNT		-	-561.40
			3,942.50	2,245.60
SPECIAL NETT ITEMS				
1	REAR BUMPER SENSOR (SN)	SHORTED	380.00	200.00
1	REVERSE CAMERA (SN)	DAMAGED	880.00	300.00
1	REAR BUMPER LOWER LIP (SN)	CRACKED	380.00	380.00
1	REAR BOOT SPOILER (SN)	NOT FITTED	380.00	-
1	REAR END PANEL SEALER (SN)	NECESSARY	80.00	50.00
			2,100.00	930.00
LABOUR				
	CUT OUT,RENEW,KNOCKING & WELDING REAR BOOT COVER,REAR BUMPER,REAR END PANEL,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY.INCLUSIVE OF THE REPAIR OF REAR BOOT COVER HINGE L&R .		1,800.00	800.00

Report Ref No. CS/FCI18015354/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF-KOTE ON DAMAGE PARTS.		120.00	80.00
	SPRAY PAINTING ON DAMAGE PARTS.		1,400.00	1,000.00
	REMOVE & REFIX REAR BUMPER SENSOR.		80.00	50.00
	CHECK ALL LIGHTING AFTER REPAIRS.		45.00	20.00
	REMOVE & REFIX REAR EXHAUST SILENCER.	NOT NECESSARY	100.00	-
			3,545.00	1,950.00
	GRAND TOTAL		9,587.50	5,125.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/FCI18015354/Uqd3n2

MARKET VALUE: \$17,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,763.00=NETT VALUE: \$4,737.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.