

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG16009066/KEA3Q2-1
Date: 14/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100310310
Claimant Vehicle No : SKB4061G **Insured Vehicle No :** SKG1799E
 Date of Loss: 13/05/2016 Nature of Claim: TP Claim No: 2046201587SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB4061G**
 Make & Model: SUBARU LEGACY, 2.5 GT WAGON TURBO (A) Engine No: EJ25E033429
 Reg. Date: 01/11/2005 (Man. Year: 2005) Chassis No: JF1BR9KV3AG008350
 Colour: Metallic Grey Odometer: 51923 km
 Engine Capacity: 2457 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18 Rear Tyre Size: 225/45Z R18
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,073.20	5,035.90	1,037.30	17.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,612.00	6,081.00	2,531.00	29.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,685.20	11,116.90	3,568.30	24.30
+ GST 7.00/7.00% (S\$)	1,027.96	778.18	249.78	24.30
Nett Amount (S\$)	15,713.16	11,895.08	3,818.08	24.30
+ Loss of Use (17.0 x S\$100.00/day) (S\$)		1,700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,597.08		

INSPECTION

Date of Assignment: 18/05/2016
 Date Inspected: 18/05/2016 Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh)
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PIPE CUTTER AY	Serviceable	51.00 FL	*- FL
2	1		*EXH PIPE AY R BST	Bent	1,080.00 FL	*1,080.00 FL
3	1		*MUFFLER ASSY LH 6WL	Bent	738.00 FL	*738.00 FL
4	1		*MUFFLER ASSY R 6W	Repair	738.00 FL	*- FL
5	1		*FLOOR PANEL RR	Bent	414.00 FL	*414.00 FL
6	1		*SKIRT COMPL R WGN	Bent	288.00 FL	*288.00 FL
7	1		*BMPR PUNCHING 2.5GTS FRT BUMPER	Buckled	594.00 FL	*594.00 FL
8	1		*BUMPER FACE R W	Torn	594.00 FL	*594.00 FL
9	1		*FRT BUMPER FOAM	Cracked	180.00 FL	*180.00 FL
10	1		*BRKT SD UP R W	Repair	18.00 FL	*- FL
11	1		*BRKT SD UPR R W LH	Repair	18.00 FL	*- FL
12	0		*FRT RH SIDE BRACKET		-	-
13	0		*FRT LH SIDE BRACKET		-	-
14	1		*FRT BUMPER BEAM	Repair	421.20 FL	*- FL
15	1		*BEAM CPL R	Bent	208.80 FL	*208.80 FL
16	1		*COVER INTAKE F	Necessary	92.00 FL	*82.80 FL
17	1		*PANEL COML R GAT TAILGATE	Bent	1,072.80 FL	*1,072.80 FL
18	1		*GLASS AY R/G	Necessary	1,350.00 FL	*1,350.00 FL
19	1		*STRIKER R/G	Bent	21.60 FL	*21.60 FL
20	1		*REEFLEX AY RH	Cracked	21.60 FL	*21.60 FL
21	1		*RELFLX ASSY LH	Serviceable	21.60 FL	*- FL
22	1		*FRT GRILLE ASSY	Serviceable	576.00 FL	*- FL
23	1		*FRT GRILLE EMBLEM	Serviceable	81.60 FL	*- FL
24	1		*LETTER MK R LEG	Necessary	64.80 FL	*64.80 FL
25	1		*LETTER MK R AWD	Necessary	108.00 FL	*108.00 FL
26	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
27	1		*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
28	2		*EYES REVERSE SENSOR	Dented	300.00 FS	*300.00 FS
29	1		*SUNDRIES	Necessary	120.00 FS	*50.00 FS
30	1		*REAR RH SIDE BRACKET	Distorted	18.00 FL	*18.00 FL
31	1		*REAR LH SIDE BRACKET	Distorted	18.00 FL	*18.00 FL
32	1		*FLOOR SD R CP RH	Bent	82.80 FL	*82.80 FL
33	1		*BRKY CORNER W RRH	Necessary	28.80 FL	*28.80 FL
34	1		*BRKT CORNER W RLH	Necessary	28.80 FL	*28.80 FL
35	1		*FRT RH CORNER BRACKET	Distorted	43.20 FL	*43.20 FL
36	1		*COVER HOOK R WG	Missing	14.40 FL	*14.40 FL
37	1		*COVER EXH R RH	Dented	88.00 FL	*88.00 FL
38	1		*MUD GUARD RRH	Cracked	72.00 FL	*72.00 FL
39	1		*LATCH & ACT AY RG	Bent	176.40 FL	*176.40 FL
40	1		*WSTR DR R G	Distorted / Dented	144.00 FL	*144.00 FL
41	1		*GRILLE AIR VENT	Cracked	57.60 FL	*57.60 FL
42	1		*LAMP ASSY -H/MOUNT	Cracked	251.60 FL	*251.60 FL
43	1		*LENS & BODY CPL	Cracked	289.00 FL	*289.00 FL
44	1		*RH TAILLAMP	Cracked	289.00 FL	*289.00 FL
45	1		*LENS & BODY CPL	Cracked	289.00 FL	*289.00 FL
46	1		*BRKT RH	Distorted	23.80 FL	*23.80 FL
47	1		*TRIM PNL AY R/G	Dented	399.60 FL	*399.60 FL
48	1		*EDGE FLR R AY	Necessary	43.20 FL	*43.20 FL
49	1		*SUPPORTER HOLDER	Necessary	5.40 FL	*5.40 FL
50	1		*HLDR ASSY SP WHL	Necessary	10.80 FL	*10.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,636.40	9,631.80
- List Item Discount on L Items 50.00/50.00% (\$\$)	5,563.20	4,595.90
Total Parts (\$\$)	6,073.20	5,035.90

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY FRT BUMPER ,FRT BUMPER BRAM ,FRT PANEL ,REAR BUMPER ,REAR BUMPER BEA, REAR END PANEL ,TAILGATE ,SPARE WHEEL PANEL	New	2,400.00	1,440.00
2	REPLACE & REPAIR FRT BUMPER ,FRT BUMPER BEAM ,FRT PANEL ,REAR BUMPER ,REAR BUMPER BEAM REAR END PANEL SPARE WHEEL PANEL ,TAILGATE	New	2,000.00	1,600.00
3	REMOVE & REFIX REAR UNDERCARRIAGE (*CHECK)	New	456.00	456.00
4	TO CONDUCT WATER SEEPAGE TEST	New	85.00	85.00
5	REMOVE & REPLACE EXHAUST	New	114.00	114.00
6	COOLING SYSTEM PRESSURE TEST	New	85.00	85.00
7	TRANSFER TAILGATE MECHANISM	New	95.00	95.00
8	WHEEL ALIGNMENT (*CHECK)	New	171.00	171.00
9	REMOE & REFIX REAR SEAT & CARPET (*CHECK)	New	342.00	342.00
10	REMOVE & REFIX REAR BOOT GARNISH & TRIMS	New	114.00	114.00
11	REMOVE & REFIX A/C CONDENSER & RADIATOR (*CHECK)	New	171.00	171.00
12	REMOVE & REPLACE REAR WINDSCREEN	New	342.00	342.00
13	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	New	120.00	120.00
14	TO CONDUCT CAR O TRONIC CHASSIS ALIGNMENT & MEASUREMENT(*CHECK)	New	1,000.00	0.00
15	REMOVE & REFIX FUEL TANK (*CHECK)	New	171.00	0.00
16	CONDUCT FRONT & REAR LIGHTING TEST	New	56.00	56.00
17	TO CONDUCT FRT & REAR PORTION ANTI-RUST COATING	New	290.00	290.00
18	TO CONDUCT FRT & REAR PORTION PROTECTOR COATING	New	250.00	250.00
19	TO SUPPLY & INSTALL SPARE TYRE SEALANT MAT	New	150.00	150.00
20	VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT	New	200.00	200.00
Gross Labour Cost (\$\$)			8,612.00	6,081.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >