

ASS. REC. BY:

REF:

CS/CTE18015386/Ksd3

n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

monica chung

of

MSG

Date/Time: 23/8/18 @ 4.09pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 6365G

Insured:

SJX72284

at Workshop m/s

Wei Lee Motor

Tel:

6456 9830

of

Blk 9 Sin Ming Ind. Est #01-32

Policy No:

A29057765AVW

Claim No:

567743

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/08/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:06am @ 24/8/18

Person Contacted:

Karen

Vehicle IN/OUT

Date/Time	Action/Instruction (→) Estimate
	SJK 6365G - CC1/ASM18062592/R1mb3s2 DOA: 1/2/18
	SJX72284 - es/MSG18010176/R1hbs2 DOA: 24/8/18
18/8	L1 Sp @ 1800 Cu sum by email
20/09/18	Confirmed HS \$1,800.00 @ 8 days with Kenneth (\$4,252.48 Red - 70%)

ASS. REC. BY:

REF: MSG-1

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Wei Lu

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 813,800

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SYK 63656 Yr Regn: 10, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda Civic c.c. 1799

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 147907 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF016309S200736

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 17/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18 File pass to Catherine

RECEIVED 21 SEP 2018

Date/Time, File Pass to?

20/09/18

1) Typist

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Fixtures

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I: (\$ 1,300/- 4/5)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015386/Ksd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 7228U	Veh. Inspected	SJK 6365G
Policy No.	A29057765AVW	Coverage (\$)	0.00
Claim No.	567743	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	24/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/08/2018	Inspection Date	23/08/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		23 Aug 2018 16:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN CHEE KIANG (CHEN ZHIJIAN), ID: S7232273H, Tel: +6596988594			
Main Claimant:	KH LEASING PTE. LTD., Co. Reg. No.: 201611813C			
Vehicle Reg. No.:	SJK6365G	Date of Loss:	17/08/2018 20:00 - :59 [117 Months and 19 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 567743	Policy/Cover Note No.:	A29057765AVW (Comprehensive) Coverage: 15/11/2017 - 14/11/2018	
Vehicle Reg. No. (Insured):	SJX7228U	Policy No. (Claimant):		
		Excess:	S\$1,500.00	
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/08/2018]			
Driver/Custodian (Insured):	TAN CHEE KIANG (CHEN ZHIJIAN) (45 / Male), NRIC: S7232273H, Tel: +6596988594			
Adj Asg. Remarks:	on WP. LIABILITY : 100% Please appoint LKK AUTO CONSULTANTS PTE LTD to conduct the survey . Kindly contact MS KAREN SEAH @ 6456 9830			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

ALL ASSOCIATED TASKS [Filter]

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

1813C

Vehicle Details

Vehicle No.:

SJK6365G

Vehicle to be Exported:

Yes

Intended De-registration Date:

30 Aug 2018

Vehicle Make:

HONDA

Vehicle Model:

HONDA CIVIC 1.8L 5AT

Primary Colour:

Brown

Manufacturing Year:

2008

Engine No.:

R18A14004561

Chassis No.:

JHMF16309S200736

Maximum Power Output:

103.0 kW (138 bhp)

Open Market Value:

\$23,035.00

Original Registration Date:

29 Oct 2008

First Registration Date:

29 Oct 2008

Transfer Count:

1

Actual ARF Paid:

\$23,035.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

28 Oct 2018

PARF Rebate Amount:

\$11,517.00

Intended COE Rebate Details

COE Expiry Date:

28 Oct 2018

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$14,400.00

COE Rebate Amount:

\$228.00

Total Rebate Amount:**\$11,745.00**

The information contained herein is correct as at 21 Aug 2018

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*Not Authorized
L1 by 8?
Resurvey After Paint
8 days*

21, August 2018

MSIG Insurance (S) PL
4 Shenton Way
#21-01 SGX Centre 2
S 068807

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SJX7228U
Accident involving vehicle no: SJK6365G/SJX7228U
DOA: 17/08/2018 AT Penang Rd & Somerset Rd

Dear officer incharge
To supply—

Description	Qty	Amount
Lid	1 <i>B₁</i>	610.00 ✓
Lid reflector @202.30	2 <i>n/s car</i>	404.60 ✓
Lid-1.8 emblem	1 <i>n</i>	24.50 ✓
Lid-H logo	1 <i>n</i>	24.70 ✓
Lid-i-tec emblem	1 <i>n</i>	33.50 ✓
End panel	1 <i>B₁</i>	300.80 ✓
End panel top garnish	1 <i>n/s D₁</i>	66.00 ✓
Boot weather strip	1 <i>D₁ D₁</i>	107.00 <i>50% n</i>
Taillamp @ 308	2 <i>n/s car</i>	616.00 ✓
Spare tyre panel	1 <i>B₁</i>	536.50 ✓
Rear bumper	1 <i>B₁</i>	635.00 ✓
Rear bumper retainer @28	2 <i>D₁</i>	56.00 ✓
Lid lock	1 <i>n</i>	194.00 ✓
Rear fender,Lh	1 <i>n</i>	741.50 X
Civic emblem	1 <i>n</i>	27.00 ✓
Rear tool compartment	1 <i>n</i>	276.00 X
Parts		4,653.10
Parts less		930.62
		3,722.48

Tow fee
 Reverse sensor
 To remove/replace rear windscreen glass
 To remove damaged parts and attachments.
 Cut n weld damaged fender, panel.
 Repair/reshape all damaged/dented areas.
 Replace/align all parts into position
 To spray paint.

50.00 ✓
DL 220.00 *2005a*
na 160.00 X

1,000.00 *Pool*
 900.00 *Pool*

6,052.48

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118015386/KSD3N2

Date: 24/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29057765AVW
Claimant Vehicle No :	SJK6365G	Insured Vehicle No :	SJX7228U
Date of Loss:	17/08/2018	Nature of Claim:	TP
		Claim No:	567743

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK6365G	Engine No:	R18A14004561
Make & Model:	HONDA CIVIC, 1.8 L 5AT (A)	Chassis No:	JHMF16309S200736
Reg. Date:	29/10/2008 (Man. Year: 2008)	Odometer:	147907 km
Colour:	Metallic Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 2 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,942.48	2,668.14	1,274.34	32.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,750.00	360.00	17.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,052.48	4,418.14	1,634.34	27.00
Approved Total (Overridden) (\$\$)		1,800.00		
Nett Amount (\$\$)	6,052.48	1,800.00	4,252.48	70.26

INSPECTION

Date of Assignment:	23/08/2018	
Date Inspected:	23/08/2018 Inspected At:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Singapore 575644
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2018)
Parts: 143	HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK6365G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LID	Bent	610.00 FL	*610.00 FL
2	1		*LID REFLECTOR	N/s Cracked	404.60 FL	*202.30 FL
3	1		*LID-1.8 EMBLEM	Necessary	24.50 FL	*24.50 FL
4	1		*LID-H LOGO	Necessary	24.70 FL	*24.70 FL
5	1		*LID-I-TEC EMBLEM	Necessary	33.50 FL	*33.50 FL
6	1		*END PANEL	Bent	300.80 FL	*300.80 FL
7	1		*END PANEL TOP GARNISH	Mtg Distorted	66.00 FL	*66.00 FL
8	1		*TAILLAMP	N/s Cracked	616.00 FL	*308.00 FL
9	1		*SPARE TYRE PANEL	Bent	536.50 FL	*536.50 FL
10	1		*REAR BUMPER	Bent	635.00 FL	*635.00 FL
11	2		*REAR BUMPER RETAINER	Distorted	56.00 FL	*56.00 FL
12	1		*LID LOCK	Dented	194.00 FL	*194.00 FL
13	1		*REAR FENDER,RH	Repair	741.50 FL	*- FL
14	1		*CIVIC EMBLEM	Necessary	27.00 FL	*27.00 FL
15	1		*REAR TOOL COMPARTMENT	Serviceable	276.00 FL	*- FL
16	1		*REVERSE SENSOR	Dented	220.00 FS	*200.00 FS
17	1		*BOOT WEATHER STRIP (50%)	Distorted	85.60 FS	*53.50 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,851.70	3,271.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	909.22	603.66
Total Parts (\$\$)	3,942.48	2,668.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOW FEE	New	50.00	50.00
2	TO REMOVE/REPLACE REAR WINDSCREEN GLASS	New	160.00	-
3	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED FENDER,PANEL,REPAIR/RESHAPE ALL DAMAGED/DENTED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION	New	1,000.00	900.00
4	TO SPRAY PAINT	New	900.00	800.00
Gross Labour Cost (\$\$)			2,110.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >