

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III18015398/UPS3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SLC8427S	<b>Insured Vehicle No :</b>	SHC8931A
Date of Loss: 23/08/2018	Nature of Claim: TP	Claim No: MCT18080651

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8427S	Engine No:	G4FGGH612930
Make & Model:	KIA FORTE K3, 1.6 SX (A)	Chassis No:	KNAFZ411MG5600916
Reg. Date:	27/05/2016 (Man. Year: 2016)	Odometer:	33774 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,893.61	4,967.41	926.20	15.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	2,480.00	540.00	17.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,913.61</b>	<b>7,447.41</b>	<b>1,466.20</b>	<b>16.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,850.00</b>		
<b>(S\$)</b>	8,913.61	5,850.00	3,063.61	34.37
<b>+ GST 7.00/7.00% (S\$)</b>	623.95	409.50	214.45	34.37
<b>Nett Amount (S\$)</b>	<b>9,537.56</b>	<b>6,259.50</b>	<b>3,278.06</b>	<b>34.37</b>
<b>+ Loss of Use (9.0 x S\$60.00/day) (S\$)</b>		540.00		
<b>Nett Liability (S\$)</b>		<b>6,799.50</b>		

### INSPECTION

Date of Assignment:	23/08/2018	
Date Inspected:	24/08/2018 Inspected At:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	7.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2019)
<b>Parts:</b>	143	KIA FORTE K3 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC8427S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE W/HOLDER	Bent	45.00 FS	*40.00 FS
2	1		*FRONT NUMBER PLATE BASE GARNISH	Cut	78.50 FL	*78.50 FL
3	1		*REAR NUMBER PLATE	Bent	45.00 FS	*40.00 FS
4	1		*REAR BOOT	Badly Dented	695.50 FL	*695.50 FL
5	2		*REAR BOOT HINGES	Repair	191.20 FL	*- FL
6	1		*REAR BOOT LOCK	Twisted	85.20 FL	*85.20 FL
7	1		*REAR BOOT CYCLE AND CARRIAGE BADGE	Necessary	45.00 FL	*45.00 FL
8	1		*REAR BOOT LOGO	Necessary	98.10 FL	*98.10 FL
9	1		*REAR BOOT K3 EMBLEM	Necessary	48.10 FL	*48.10 FL
10	1		*REAR BOOT FORTE EMBLEM	Necessary	92.10 FL	*92.10 FL
11	1		*REAR BOOT LAMP RH	Cracked	405.90 FL	*405.90 FL
12	1		*RH TAILLAMP	Cracked	595.90 FL	*595.90 FL
13	12		*REAR BOOT TRIM CLIPS	Not Necessary	36.00 FL	*- FL
14	1		*REAR BOOT RUBBER BEADING	Twisted	368.20 FL	*368.20 FL
15	1		*REAR BUMPER	Distorted	685.20 FL	*685.20 FL
16	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
17	2		*REAR BUMPER RETAINER	Bent	158.40 FL	*158.40 FL
18	1		*REAR BUMPER LOWER GARNISH	Distorted	480.20 FL	*210.00 FL
19	1		*REAR BUMPER REFLECTOR RH	Cracked	110.50 FL	*110.50 FL
20	1		*REAR BUMPER REINFORCEMENT	Distorted	350.50 FL	*350.50 FL
21	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	224.40 FL	*224.40 FL
22	1		*REAR BUMPER PARKING SENSOR	Shorted	250.00 FL	*250.00 FL
23	4		*REAR BUMPER LOWER BRACKET	Bent	152.80 FL	*152.80 FL
24	1		*REAR END PANEL	Badly Dented	580.10 FL	*580.10 FL
25	1		*REAR END PANEL GARNISH	Twisted	110.50 FL	*110.50 FL
26	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	310.10 FL	*- FL
27	1		*FRONT BUMPER SPONGE	Not Necessary	210.50 FL	*- FL
28	2		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,532.90</b>	<b>5,504.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	639.29	537.49
<b>Total Parts (\$\$)</b>	<b>5,893.61</b>	<b>4,967.41</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO KNOCK AND STRAIGHTEN SPARE TYRE COMPARTMENT .CUT & WELD DAMAGED PANEL .ADJUST & REALIGN THE SAME	New	1,300.00	1,180.00
2	TO PUTTY AND SPRAY RH FRONT FENDER ,LH FRONT FENDER ,REAR BOOT (INNER & OUTER),REAR END PANEL,SPARE TYRE COMPARTMENT AND REAR BUMPER	New	1,200.00	1,100.00
3	TO JACK AND STRAIGHTEN RH REAR CHASSIS	New	250.00	0.00
4	TO JACK AND STRAIGHTEN REAR EXHAUST PIPE	New	50.00	50.00
5	TO REMOVE BOOT COMPARTMENT BOTH SIDE TRIM GARNISH TO ASSIST WORKLOAD	New	80.00	60.00
6	TO RUST PROOF THE AFFECTED AREAS	New	80.00	60.00
7	TO CHECK WIRING AND ALL LIGHTING	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,020.00</b>	<b>2,480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >