



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 619P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT (CONSISTENT)	BUCKLED / CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT (CONSISTENT)	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT (CONSISTENT)	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH (CONSISTENT)	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH (CONSISTENT)	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT (CONSISTENT)	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT (CONSISTENT)	SERVICEABLE	28.61	-
1	RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT' (CONSISTENT)	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME (CONSISTENT)	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	177.22	-
1	HORN (CONSISTENT)	SERVICEABLE	314.17	-
1	HORN BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH (CONSISTENT)	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,941.63	-

Report Ref No. CC3/ASM18015414/Kfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	405.73	-
1	BONNET STRUT LH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET STRUT RH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE (CONSISTENT)	SERVICEABLE	119.19	-
1	BONNET CABLE COVER (CONSISTENT)	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER (CONSISTENT)	SERVICEABLE	92.36	-
1	BONNET SEAL INNER (CONSISTENT)	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH (CONSISTENT)	BENT	783.83	783.83
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH (CONSISTENT)	SERVICEABLE	130.84	-
1	WIPER RESERVOIR (CONSISTENT)	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK (CONSISTENT)	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR (CONSISTENT)	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER (CONSISTENT)	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE (CONSISTENT)	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY (CONSISTENT)	SERVICEABLE	363.40	-
1	AIR CLEANER BOX (CONSISTENT)	SERVICEABLE	464.20	-
1	TURBO DUCT (CONSISTENT)	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE (CONSISTENT)	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT (CONSISTENT)	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH (CONSISTENT)	SERVICEABLE	92.36	-
1	ENGINE UNDERTRAY (CONSISTENT)	SERVICEABLE	564.98	-
1	A/C CONDENSER (CONSISTENT)	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER (CONSISTENT)	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER (CONSISTENT)	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH (CONSISTENT)	SERVICEABLE	58.81	-

Report Ref No. CC3/ASM18015414/Kfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C CONDENSER GARNISH RH (CONSISTENT)	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR (CONSISTENT)	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VAVLE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR (CONSISTENT)	SERVICEABLE	334.29	-
1	A/C PIPE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C COMPRESSOR (CONSISTENT)	SERVICEABLE	2,684.61	-
1	AIR COOLER (CONSISTENT)	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG) (CONSISTENT)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT) (CONSISTENT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER (CONSISTENT)	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD (CONSISTENT)	SERVICEABLE	17.96	-
1	RADIATOR (CONSISTENT)	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER (CONSISTENT)	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER (CONSISTENT)	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER (CONSISTENT)	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING (CONSISTENT)	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH (CONSISTENT)	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH (CONSISTENT)	SERVICEABLE	1,479.46	-
1	RADIATOR TANK (CONSISTENT)	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER (CONSISTENT)	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER (CONSISTENT)	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE (CONSISTENT)	SERVICEABLE	61.18	-
1	AUTO COMPUTER (CONSISTENT)	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER (CONSISTENT)	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (ROCK & PINION) (CONSISTENT)	SERVICEABLE	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y (CONSISTENT)	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y (CONSISTENT)	SERVICEABLE	4,413.11	-
1	DOOR PANEL FRT LH (CONSISTENT)	BENT	2,844.66	2,844.66
1	LOWER ARM LH L70Y (CONSISTENT)	SERVICEABLE	685.76	-
1	KNUCKLE ARM LH L70Y (CONSISTENT)	SERVICEABLE	846.98	-
1	ABSORBER FRT LH L70Y (CONSISTENT)	SERVICEABLE	360.54	-
1	AIR CLEANER BOX (CONSISTENT)	SERVICEABLE	464.20	-

Report Ref No. CC3/ASM18015414/Kfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CLEANER HOSE (CONSISTENT)	SERVICEABLE	175.85	-
1	DOOR HARNESS WIRE LH (CONSISTENT)	SERVICEABLE	2,670.00	-
1	DOOR MIRROR ASSY LH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	DOOR PANEL FRT LH (CONSISTENT)	REPEATED	2,844.66	-
	LESS 10% DISCOUNT		-7,370.68	-622.37
			66,336.13	5,601.38
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN) (CONSISTENT)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN) (CONSISTENT)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN) (CONSISTENT)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN) (CONSISTENT)	SERVICEABLE	80.00	-
1	FRONT LEFT TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	FRONT LEFT TYRE RIM (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CLASSIS' (SN) (CONSISTENT)	NECESSARY	50.00	15.00
			1,402.50	141.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, HEADLAMP PANEL FRT LH, HEADLAMP PANEL FRT RH, BONNET, BONNET HINGE LH, BONNET HINGE RH AND BONNET LOCK.		5,400.00	500.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP OIL, COOLER PIPE AND FINALE CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-

Report Ref No. CC3/ASM18015414/Kfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			16,400.00	1,300.00
GRAND TOTAL			84,138.63	7,042.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,650.00

Report Ref No. CC3/ASM18015414/Kfb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.