

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Togs to the state of the state				
Affiliated to Federation Internationale Des Experts En Automobile					
COMLAW LLC*			Ref: CS/LAW18015499/Avd3e2		
64 CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Date: 28-05-2019  Code: L050			
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SGQ 5239Z	Veh. Inspected	GBB 3818D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CLS.2017.215855	Excess (\$)	0.00	
	Assign From	CHUA LI SUAN	Assign Date	21/07/2018	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	JTFAT35Y20K200319	Colour	WHITE	
	Odometer	493283	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15	OHTSU	6 mm	
	L/H Front Tyre	195 R15	OHTSU	6 mm	
	R/H Rear Tyre	155 R12C	HANKOOK	6 mm	
	L/H Rear Tyre	155 R12C	HANKOOK	6 mm	
4.	4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5. General Information					
	Accident Date	20/04/2017	Inspection Date	01/04/2019	
	Survey held at	BLK 2 KAKI BUKIT AVE 2 #02-25			
	Repairer	r H S AUTOMOTIVE SERVICES			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate Days of Repair

5 Working Days