

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III18015506/KPA3Q2

**Date:** 11/11/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> PA9465M	<b>Insured Vehicle No :</b>	SHA7665K
Date of Loss: 15/08/2018	Nature of Claim: TP	Claim No: MCT18080421

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA9465M		
Make & Model:	SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A)	Engine No:	6621594
Reg. Date:	02/08/2010 (Man. Year: 2010)	Chassis No:	YS2K4X20001869858
Colour:	Blue/Silver	Odometer:	0 km
Engine Capacity:	9290 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 9/9 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 9/9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,614.74	26,418.83	1,195.91	4.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,930.00	8,560.00	3,370.00	28.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>39,544.74</b>	<b>34,978.83</b>	<b>4,565.91</b>	<b>11.55</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>33,000.00</b>		
<b>(\$\$)</b>	39,544.74	33,000.00	6,544.74	16.55
<b>+ GST 7.00/7.00% (\$\$)</b>	2,768.13	2,310.00	458.13	16.55
<b>Nett Amount (\$\$)</b>	<b>42,312.87</b>	<b>35,310.00</b>	<b>7,002.87</b>	<b>16.55</b>
<b>+ Loss of Use (14.0 x S\$200.00/day) (\$\$)</b>		2,800.00		
<b>Nett Liability (\$\$)</b>		<b>38,110.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>38,000.00</b>		

### INSPECTION

Date of Assignment:	24/08/2018	
Date Inspected:	27/08/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	12.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 Jun 2019)	
<b>Parts:</b>	N/A	SCANIA KUB4X2 9.3L A/T ABS TURBO 9.3 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PA9465M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT WINDSCREEN GLASS	Cracked	5,095.11 FL	*5,095.11 FL
2	1		*FRT WINDSCREEN GLASS MOULDING	Necessary	314.76 FL	*314.76 FL
3	1		*FRT PANEL	Cracked	1,440.00 FL	*1,440.00 FL
4	1		*FRT PANEL STRUCTURE	Bent	3,850.00 FL	*3,850.00 FL
5	1		*WIPER ARM LH	Not Necessary	498.79 FL	*- FL
6	1		*WIPER BLADE LH	Not Necessary	230.00 FL	*- FL
7	1		*HEADLAMP LH	Cracked	1,390.81 FL	*1,390.81 FL
8	1		*HEADLAMP RH	Cracked	1,390.81 FL	*1,390.81 FL
9	1		*FRT BUMPER	Broken	2,688.00 FL	*2,688.00 FL
10	1		*FRT BUMPER STRUCTURE	Bent	2,304.00 FL	*2,304.00 FL
11	1		*FRT BUMPER FOG LAMP LH	Cracked	358.30 FL	*358.30 FL
12	1		*FRT BODY PANEL LOWER	Bent	5,288.00 FL	*5,288.00 FL
13	1		*SEALANT	Necessary	320.00 FS	*320.00 FS
14	1		*INNER SEAL	Necessary	160.00 FS	*160.00 FS
15	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
16	1		*FRT PANEL STICKER COMFORTBUS	Necessary	300.00 FS	*300.00 FS
17	1		*FRT NUMBER PLATE	Missing	45.00 FS	*45.00 FS
18	1		*STICKER	Necessary	1,000.00 FS	*460.00 FS
19	1		*FRT PANEL HINGE SYSTEM	Bent	1,480.00 FL	*1,480.00 FL
20	1		*FRT PANEL LOCK	Bent	123.80 FL	*123.80 FL
21	1		*FRT PANEL FRAME	Bent	1,788.00 FL	*1,788.00 FL
22	1		*AIR REGULATOR	Distorted	386.00 FL	*386.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>30,477.38</b>	<b>29,208.59</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	2,862.64	2,789.76
<b>Total Parts (\$\$)</b>	<b>27,614.74</b>	<b>26,418.83</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND RENEW FRT WINDSCREEN GLASS	New	800.00	680.00
2	TO KNOCK ,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS FRT PANEL ,FRT PANEL STRUCTURE ,FRT BODY PANEL ,FRT BUMPER ,FRT BUMPER STRUCTURE ,BOTH HEADLAMP AND ETC	New	4,000.00	3,200.00
3	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS FRT PANEL,FRT PANEL STRUCTURE ,FRT BODY PANEL ,FRT BUMPER ,FRT BUMPER STRUCTURE AND ETC	New	2,000.00	1,500.00
4	TO CHECK WIRING AND LIGHTING	New	50.00	20.00
5	TO REMOVE AND INSTALL DASHBOARD TO FACILITATE REPAIR	New	280.00	280.00
6	TO KNOCK ,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS FRT FIRE WALL ,FRT BODY PANEL FRAME ,FRT PANEL FRAME,FRT PANEL HINGE SYSTEM AND ETC	New	4,800.00	2,880.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,930.00</b>	<b>8,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >