

ComfortDelGro Engineering

205 Braddell Road S(579701) ACCIDENT REPAIR ES

ur Ref:			
ype of Claim :	TP	Vehicle No.	PA9465M
		Make & Model	SCANIA KUB4X2 9.3L
		Year of Manufacture	2010
		Chassis No.	YS2K4X20001869858
s Company :	III VS III	Engine No.	:
xcess :		Policy No.	1
ate of Accident :	8/11/2018	Time of Accident	0825
uggested Days of Repair :		In-house Vehicle Asses	SSOC
Repair Estimates		Case Owner	:
		Signature	
arts (a) Cost / List Price Iter	ns \$ 24,848.58	Contact No	
Plus/Less 10%	\$ 2,484.86	Frt Counter Operation	n
Total of Cost / List	\$ 22,363.72	63837466 – Patrick 63837730 - Brenda	
(b) Nett Price Items	\$ -	63837890 – Rohani braddell_cr@sparkcareca	ar.com
Less		Back-end Operation	
Total of Nett Item		63837656 - Ngo 63837362 - Andrew	
(c) Special Nett Items	\$ 1,851.00	63838115 - William braddell_operation@spar	kcarcar.com
otal Parts Cost (Appendix	A) \$ 24,214.72		Nor Norther 11 Ly 8?
abour (Appendix B)	\$ 7,130.00		11 km 82
otal Repair Cost	\$ 31,344.72	/	Record in
he above total will be subjec	ted to 7% G.S.T.		why Ath
Name of Surveyor		Kenner	
Company		LICIE	
Survey conducted on		27/8/18 at	
,		- V U	
Remarks By Surveyor			
(a) The repair of this vehicle			
(b) Recommended Days o	f Repair :	/ 2day(s)	
(c) Resurvey	: Required / N	Required	
(d) Excess	:\$		
(e) Signature of surveyor		Le Date:	27/8/18

Spark Car Care ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	:	PA9465M	Case Owner	:	0
Make & Model	1	SCANIA KUB4X2 9.3L	Year Manufacture	:	2010
Chassis No	:	YS2K4X20001869858	Engine No	:	0
Sales Order	***		Supplier	:	
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description		QTY	Cost Price		List Price	Nett Price		S/N	Disposition By Surveyor
1	FRT WINDSCREEN GLASS		1	CRI	\$	5,095.11				
2	FRT WINDSCREEN GLASS MOULDING		1	an	\$	314.76				
3	SEALANT		1				Ma	\$	320.00	-
4	INNER SEAL		1				ny	\$	160.00	_
5	ERP BRACKET		1				ne	\$	26.00	
6	FRT PANEL		1	cht	\$	1,440.00				
7	FRT PANEL STICKER "COMFORTBUS"		1				mi	\$	300.00	
8	FRT PANEL STRUCTURE		1	R	\$	3,850.00				
9	WIPER ARM LH		1		\$	498.79				7
10	WIPER BLADE LH		1		\$	230.00				1
11	HEADLAMP LH		1	cns	\$	1,390.81				_
12	HEADLAMP RH		1	cm	\$	1,390.81				
13	FRT BUMPER		1	Bn	\$	2,688.00				_
14	FRT BUMPER STRUCTURE		0	By	\$	2,304.00				
15	FRT BUMPER FOG LAMP LH		0	cm	\$	358.30				
16	FRT NUMBER PLATE		0				wil	\$	45.00	
17	STICKER		0				(Bill)	\$	1,000.00	7
18	FRT BODY PANEL LOWER		0	Ry	\$	5,288.00				
19	0		0				10	7		
20	0		0				100			
21	0		0							
22	0	LKK AL	to Co	nsultants hence	not	fv	1			
23	0	me Ke	paigeri	of the following:		,				
24	0	To disp	av Ban	fore/after spray pail aged part(s) during	nting					
25	0	- Faits p	ices an	subject to confirm	ation					
26	0	 I hird pa 	rty sur	ev is on a "Without	Drois	idice" basis				
27	0	Suppler	nerfary	item(s) must be						
28	0	is subje	et to fin	al approval from Ins	urvey	e Company				
29		Acknowle				- Ampany				
30		Signature	0	repairer						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

L	2	n	~		
_	а	u	v	u	

Vehicle No. :	PA9465M	Case Owner	:	0	
Make & Model:	SCANIA KUB4X2 9.3L	UB4X2 9.3L Year of Manufacture		2010	

S/No	Labour Description	Esimated Price	Adjusted Price
	TO REMOVE AND RENEW FRT WINDSCREEN GLASS	\$800.00	5001
	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS		
	FRT PANEL, FRT PANEL STRUCTURE, FRT BODY PANEL, FRT		
	BUMPER, FRT BUMPER STRUCTURE, BOTH HEADLAMP AND ETC	\$4,000.00	32001
	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS FRT PANEL,		
	FRT PANEL STRUCTURE, FRT BODY PANEL, FRT BUMPER, FRT		
	BUMPER STRUCTURE AND ETC	\$2,000.00	1500
	TO CHECK WIRING AND LIGHTING	\$50.00	201
	TO REMOVE AND INSTALL DASHBOARD TO FACILITATE REPAIR	\$280.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.