:direc	A dia 18 CS3 MSG 18007989 AH67
Surveyor 1	vene tan or MSIG Descrition 27082018
OD TE WS/T To Impect Vehicl at Workshop ra/s	TRESTOD RESTEVATINUTINUTICS SKA 92004 Insured: GR 6392 B C.H. Motor Vehicle Tel 6841 8841 6748 8888 Blk 3010 A Ubi Road 1# 01-30
Policy No. A	BIK 3019 A Ubi Road 1# 01-30 289 107 53 MKC Claim No. 557012/IT Brown 12/06/2018 @ Morning
Make of Ven (Client's Reserd) CA / REV / I	REP. / REV 24 TIRE 1WP) 02pm@ 11 6 18 Person Contacted Mrs. QULK Vehicle IN OUT
	Action/Instruction (X) Estimate
13 4 18	Dismontial
15 618	After Reprise -
	To submit 9.8K 07 Days 01/10/18 188. (Red: 200 :18%)
	Menmen Surveyor put Marcus, New remains as Adrian

7. 1

ASSIGNMENT

From Date:	Veh No. SKA 9200	U. Yr Regn: 7-9	4 Jan 2
Estimated Cost:	Type M.C. M.Cycle / Bus / Van		
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	Mono Andi Q5	60	3197
at Workshop mis	Colour Beaun.	A/C Insured /	Std / NI / NA
ul	Golour Beswar. Sp. Reading 100615.	T/Radio: Insured /	Std / NI / NA
Insured	Eng/No		
Policy No.	C/No:		
Claims No.	Gen, Cont Goody Fair / Poor / B	urnt	
Sum Insured: Excest:	Steering: Inother / Jammed / Leal	ked / Burnt or	
(Client's Record)	Brake: learder / Jammed / Leal	ked / Burnt or	
Make of Veh:	Modi: Nil / 8/Rim / STD A/Rim		
	Tyre Size: F: 233	45220	
(Policy Condition)	Tyre Size: F: 235	145RZO.	
Remark. The veh had commenced its N/S	OIS BS DUN / EXNOVA / GY / FS / L		SUMI /
repair at the time of inspection.	тоуотуоко ст		
Bal. or Market Value:	Eront	Bear	4
IDAC Accident Rport: Consistent? Yes or No	R/Bal. 06 mm	R/Bal.	06, mm
GIA / PR Seen: Consistent? Yes or No	L/Bal. 06 mm	LIBal	96 mm
Est. Repoirs: G days Res.: Yes or No	D.O.A.	001 12/06/	18
Lum Sum: % 3 Val. Yes or No	Survey held at C-H	molos 1	
GA / REV / REP. / 24 HRS Vehicle: IN	Des. of Damages Frt / Rear / C		op or
Ditte: Person Contacted:	The U/C / Chassis frame / E		lue to collision
TP MS/6 TRS. Estimated repair ra	4- coo, 27 squ	1.600 Am	3)2018
Code/Texe, File Page 207 : Preli, Report	Days Of Repair:		
: Final Report	Resurvey No. of Trip:	Survey Fee:	120
Down File Return 3/37	т П	Example below	50
Add	1 Fee: Site Insp (\$) 2:82 3	
*	Inferview (\$	3 Hotel	
Report Format	Tech Ings (5	Others	10
Lump Sum / LB I: (%	Windshiel 15		
		year	180

Catherine Chong (LKK Auto)

From:

Irene Tan <irene_tan@sg.msig-asia.com>

Sent:

Monday, 27 August, 2018 3:44 PM

To:

Veron Chen (LKKAuto); 'Olivia Lau (LKKAuto)'; 'Shiau Chan (LKKAuto)'; 'Admin-D

(LKKAuto)'

Cc:

'assignments'

Subject:

Please prepare paper survey report on SKA9200U; Our claim no.: 557012/IT

Importance:

High

Good afternoon Veron.

We refer to your PRI report dated 11.7.18.

Please prepare and upload your paper survey report asap.

Best Regards

Irene Tan

Senior Executive, Claims Services (Motor)

Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msig-asia.com





Insurer Claims Team of the Year 2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg







A Member of MS&AD INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rp	it	Adj Submitted	Ins Auth'ed	Status		
Main	30 Apr 2018		11 Jun 2018 16:10 Edit Adj Rpt	S\$0.00 Edit Estima		S\$0.00 View Rpt	0.00 Pending f		for Survey Repo	
	Main		Reference		Claim C	etails	Docum	ents	Show All	
CLAIM S	UBFOLDER DET	TAIL5					[Cre	ated by insu	rer]	
nsured:		cool	AIR SERVICE,	Co. Reg. No.:	530858	21E, Tel: +6598	750032			
tain Clair	mant:	HES	HIMIN, ID: 5832	1090G						
/ehicle Re	eg. No.:	SKA	9200U		Date of Loss:			4/2018 11:00 · Months and 3 (Date (Man Yr))		
Claim Typ	pet	TP/	557012		Policy/0	Cover Note No.:	Cove	A28910753MKC (Comprehensive) Coverage: 23/03/2018 - 22/03/2019		
Vehicle Reg. No. (Insured):		GR63	6392B		Policy No. (Claimant):					
					Excess:			5\$600.00		
lepairer:			C.h.motor Vehicle Repair Training (HQ) BLK 3019A UBI ROAD 1 #01-30, 408713 Ubi - Tei:							
fandling	Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Irene Tan Gek Ing - 6594 2541]							
Adjuster:			Auto Consultants 8/2018]	Pte Ltd (HQ) - Tel:	6256-3561 [Har	ndled by ADRIAN	LING] [Fi	nai Rpt due	
Driver/Cu	stodian (Insured)	: HO G	JAN HUAT (), NR	IC: 5180611	BZ, Te	1: +6598750032				
Adj Asg. I	Remarks:		. liability against of EYOR ASSIGNMENT			E SJE APPOINT LK	C AUTO CONSULT	ANTS AS SJE(ACCORDING TO	
ASSOCIA	ATED MAIL REC	EIVED					View /	MI Comp	ose Case Mail	
			ack Alerts - SKA9 f Assignment: SK							
a		1000					Hero u v	Monarca		
ALL ASS	OCIATED TASE	cs				View All Searc	h Tasks O	reate New Task	Complete	
Due Da		Type Task	Group Subje	ct Handi	er	Assigned By	Completed On	Created	On Done?	

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths Agents for Trade Marks (Incorporated with fimited liability) 2 0 AUG 2018 (T

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
ALDREY WONG SUHSIEN
PAUL YAP TAI SAN
ANALLI DIO MUNIAMDY
SEGA PARAM
TIMARY ANURACHA
ONG BOCK KEE
DIAME ANG KIM NOI
RAVENDRA KRISHNASAWY
TAY HAG RAN
JANGE HAN JIA LIN

Unique Entity Number: 200721148H

HEAD OFFICE

133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Branch: 490 Toa Payoh Lorong 6 #03-11 HDB Hub Singapore 310490 HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
•: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawlic.com

BRANCH

TEL: (65) 63580703

FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

557012

Our Ref

: JH1-ylv-Ins-C115-107015-18-er

Your Ref

: GR 6392 B

16 August 2018

SELWYN TAN YINGXIAN

URGENT

MSIG INSURANCE (SINGAPORE) PTE. LTD.

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attention: Motor Claims Department

BY HAND

COOL AIR SERVICES

Blk 451B Sengkang West Way

#14-383

Singapore 792451

(For your information Only)

Dear Sirs.

CLAIMANT : HE SHIMIN

ACCIDENT INVOLVING SKA 9200 U & GR 6392 B ON 28-APR-2018 OUTSIDE TERENE AT BUKIT TIMAH AT ABOUT 2345 HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 28-Apr-2018 OUTSIDE TERENE AT BUKIT TIMAH AT ABOUT 2345 HOURS involving our client's vehicle registration number SKA 9200 U and vehicle registration number GR 6392 B driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

Costs of Repair	\$12,000.00
Loss of Use (10 days x \$280.00 per day)	\$ 2,800.00
Pre-repair Loss of Use (3 days)	\$ 840.00
LTA/GIA/TP report/search fees	\$ 39.00
Survey report fees	\$ 678.00
Costs (with GST)	\$ 1,284.00
Incidentals (with GST)	\$ 128.40
TOTAL:-	\$17,769.40
	Loss of Use (10 days x \$280.00 per day) Pre-repair Loss of Use (3 days) LTA/GIA/TP report/search fees Survey report fees Costs (with GST) Incidentals (with GST)

Your). Uplood a) WLI A 2 Here a4/8/18

.../2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Continuation Sheet Page 2.

Our Ref

: JH1-ylv-Ins-C115-107015-18-er

Your Ref

: GR 6392 B

16 August 2018

MSIG INSURANCE (SINGAPORE) PTE. LTD.

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attention: Motor Claims Department

COOL AIR SERVICES

Blk 451B Sengkang West Way

#14-383

Singapore 792451

We enclose a copy of each of the following documents for your consideration:-

- (a) Police/GIA report lodged by driver of SKA 9200 U & GR 6392 B:
- (b) LTANet Search;
- (c) Certificate of Insurance;
- (d) Final Repair Bill;
- (e) Surveyor's report & invoice; and
- (f) 88 original photographs depicting the damages to motor vehicle SKA 9200 U.

(P.S:- Original photographs will be sent to insurance co. only)

- (P.S:- Kindly return us all original photographs within 7 days hereof)

We have notified your insurers of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurers.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

JANICE HAN (HEAD OFFICE)

Encl

c: SKA 9200 U- By fax: 6743 6878 only

(As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.)

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



進發汽車冷氣電系修理 ((IS/107015

C. H. MOTOR VEHICLE REPAIR TRAINING

(CAR AIRCON & SERVICE) Blk 3019A #01-30 Ubi Road 1, Singapore 408713 Tel: 6841 8841 Fax: 6743 6878 Reg. No. 29274500A

			CE / CASH	SALE
M/S_He	Shimi n	Nº	20059	
SWARDAY		Date:	8-8-201	ક
Vehicle No: SEA	19200 U Time in:			
Quantily	Particulars		\$	cts
	lost of agenirs		12000	00
				_
				_
		共計 Total \$	13000	00

C. H. MOTOR VEHICLE REPAIR TRAINING

Business Reg 201404434D

INVOICE

Ms He Shimin Blk 66 Lorong 4 Toa Payoh #11-307 Singapore 310066

Invoice No.

: HA/1807-77


Date

: 31/07/2018

	Descriptions		Amount (SGD)
Services rendere	ed for appraiser / inspection report :-		
Survey Fee			
Photographs			
Transport Fees			
Re-inspection Fee	25		
		Total:	SGD: \$ 678.00
SGD Dollar:	Six Hundred Seventy Eight Dollars Only.		
Our Reference	: PAS/TP/0250618		
Vehicle No.	: SKA9200U		
Make & Model	: Audi Q5 (A)		
Your Claim No.	: Third Party Claim		

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD". Please indicate our "INVOICE NO." on the reverse side of the cheque. Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD

Correspondence Address: 1 Simei St 3 #02-24 S(529890) Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0250618

Date of Report

: 31/07/2018

To: Ms He Shimin

Date of Assignment : 12/06/2018

Blk 66 Lorong 4 Toa Payoh

Report requested by : Ms He Shimin

#11-307

Date of Accident

: 28/04/2018

Singapore 310066

Date of Inspection

: 12/06/2018

Claim No.

: Third Party Claim

Policy No.

: -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SKA9200U

Engine Capacity (cc) : 3197cc

Make & Model

: Audi Q5 (A)

Milcage (km)

. 100615km

Date of Registration

: 25/01/2011

Chassis / Frame No. : WAUZZZ8R4BA062497

Colour

: Met. Brown

Engine No.

: CAL080058

TYRE CONDITION

Front LH

: 5 mm

Front RH

: 5 mm

: Pirelli Make

Make

: Pirelli

Rear LH

: 5 mm

Rear RH

: 5 mm

Mnke

: Bridgestone

Make

: Bridgestone

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre trends)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location :

M/s. C. H. Motor Vehicle Repair Training

Blk 3019A, Ubi Road 1, #01-30, Singapore 408713

ASSESSMENT

Repairer's Estimate

Revised Amount

: \$ 17,105.95

Less Excess

: \$

Recommended Reserve

: \$ 14,990.70

: \$ 12,000.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 Working Days

Dischiluter: This report is intended for the exclusive was of the addresses solely in relation to the loss accurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any relinace an this report by any third party.

PAS

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 8722 8508 Email pasvos@hotmail.com

Business Reg 201404434D

Vehicle No: SKA9200U

Report No. : PAS/TP/0250618

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. C. H. Motor Vehicle Repair Training, Blk 3019A, Ubi Road 1, #01-30, Singapore 408713.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The bonnet, front support panel, front chassis members, front bumper, front fenders, headlamps, front grille, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$14,990.70.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$12,000.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers
Correspondence Address: 1 Simel St.3 #02-24 S(529890)
Mobile 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Business Reg 201404434D

Vehicle No.: SKA9200U

Report No.: PAS/TP/0250618

APPRAISEMENT SCHEDULE

8	No.	Qty	Parts Descriptions	Condition				epairer's timate (S\$)	Ass		Our ment (SS)
	1	1 pc	Frt grille assy	Dented/Cracked			3	1,505.00		\$	1,505.00
	2	2 pcs	Headlamp assy R/L	Cracked/Loop Broken	S	2,858.00	S	5,716.00		S	5,716.00
	3	2 pcs	Headlamp bracket R/L	LH Cracked	S	136.00	s	272.00		5	136.00
	4	I pc	Frt bumper assy	Dented		12-5-22-7-10	5	2,325.00		5	2,325.00
	5	2 pcs	Frt bumper foglamp grille R/L	LH Cracked	\$	118.00	5	236.00		S	118.00
	6	2 pcs	Frt bumper foglamp R/L	Refit	S	227.00	\$	454.00		S	. ×
	7	1 pc	Frt bumper lower spoiler	Refit			5	540.00		\$. 7 /
	8	1 pc	Frt bumper lower end plate	Dented/Cracked			\$	167.00		S	167.00
	9	2 pcs	Frt bumper guide R/L	Broken/Cracked	\$	64.00	\$	128.00		S	128.00
	10	I pc	Frt bumper absorber	Dented/Cracked			\$	97.00		S	97.00
	11	1 pc	Frt bumper reinforcement	Dented			\$	571.00		5	571.00
8	12	2 pcs	Frt bumper reinforc. bracket R/L	LH Bent	5	207.00	\$	414.00		\$	207.00
	13	1 pc	Frt radiator support top cover	Refit			\$	109.00		S	
	14	1 pc	Frt radiator support	Dented/Distorted			S	970.00		\$	970.00
	15	1 pc	Frt radiator support stay	Dented/Cracked			S	72.00		\$	72.00
	16	2 pcs	Frt radiator sight shield R/L	LH Cracked	5	53.00	\$	106.00		\$	53.00
	17	1 pc	Horn	Refit			S	178.00		5	· X
	18	1 pc	Frt fender LH Pepu	Dented/Distorted	X	100	\$	841.00		\$	841.00
	19	1 pc	Bonnet	Dented/Repair	1	1095		(Ref	er labo	our	no. 6 & 8)
	20	1 pc	Frt apron panel LH	Dented/Repair	10	0540-25					no. 6 & 8)
	21	2 pcs	Frt chassis member R/L	Dented/Repair		W. 125-7 (S.)					6,7 & 8)
							\$	14,701.00	-	\$	12,906.00
				1	.ess	Discount: 5%	\$	735.05	5%	\$	645.30
				List Pa	rts S	ub-Total:	S	13,965.95	-	5	12,260.70
	1	l bot	Radiator coolant	Necessary		S/N	S	80.00		\$	60.00
(Special N	ett S	ub-Total :	S	80.00	-	s	60.00
					Day	rts Total :	-	14,045.95	9	*	12,320.70

60



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(528890) Mobile 9295 2204 Fax: 6722 8508 Email. pasvcs@hotmail.com

Business Reg 201404434D

	Report No	: PAS/TP/02506	18
200 200 100	pairer's	Our	
s	60.00	s 50.0	6
2	120.00	\$ 120.0	0-
s	100.00	\$ 80:00	66
\$	80.00	\$ 60.00	0
\$	60.00	\$ 40.00	0
\$	1,200.00	\$ 1,100.00	8
S	320.00	\$ 300.00	X
\$	1,000.00	\$ 800.00	500
			10
S	120.00	\$ 120.00	1
S	3,060.00	\$ 2,670.00	
\$	17 105 95	\$ 14 000 70	-
	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	Repairer's Estimate (SS) \$ 60.00 \$ 120.00 \$ 100.00 \$ 80.00 \$ 60.00 \$ 1,200.00 \$ 320.00 \$ 1,000.00	Estimate (S\$) Assessment (S\$) \$ 60.00 \$ 50.00 \$ 120.00 \$ 120.00 \$ 100.00 \$ 80.00 \$ 80.00 \$ 60.00 \$ 60.00 \$ 40.00 \$ 1,200.00 \$ 1,100.00 \$ 320.00 \$ 300.00 \$ 1,000.00 \$ 120.00 \$ 3,060.00 \$ 2,670.00

ir Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 12,000.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 10 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

88 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

tolal 1227025 HS 9.8K



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-098235

Date of Request:

28/06/2018

Your Ref No:

INS-C115-107015-18-ER

VISION LAW LLC

133 New Bridge Road #18-01/02

Chinatown Point Singapore 059413

Dear Sir/Madam.

Date of Accident:

28/04/2018

Vehicle No:

SKA9200U

Place of Accident:

OUTSIDE TERENE AT BT TIMAH

Involving Vehicle No: GR6392B

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)		AMOUNT (S\$)
GR6392B	OUTSIDE TERENE AT BT TIMAH	14.00	1	13.08
GST Amount				0.92
Total Amount Due	(GST Inclusive)			14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

SEARCH RESULTS

Our Ref No:

GR-18-098122

Date of Request:

27/06/2018

Your Ref No:

INS-C115-107015-18-ER

VISION LAW LLC

133 New Bridge Road #18-01/02

Chinatown Point Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident:

28/04/2018

Place of Accident:

OUTSIDE TERRENE AT BUKIT TIMAH

Client Vehicle No:

SKA9200U

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENTE
GR6392B		ACCIDENT DATE
0,100320	JALAN JURONG KECHIL	28/04/2018 11:50

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-098122

Date of Request:

27/06/2018

Your Ref No:

INS-C115-107015-18-ER

VISION LAW LLC

133 New Bridge Road #18-01/02

Chinatown Point Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident:

28/04/2018

Place of Accident:

OUTSIDE TERRENE AT BUKIT TIMAH

Client Vehicle No: SKA9200U

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

Enquire Vehicle & Owner Information (Vehicle No. GR6392B As At 28 Apr 2018 / 12:00:00)

Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

C115

Current Owner Details

Owner ID Type:

Business

Owner ID:

53085821E

Owner Name:

COOL AIR SERVICES

Registered Address Type: HD8/HUDC

Registered Block/House No.:451B

Registered Street Name: SENGKANG WEST WAY

Registered Unit No.:

#14-383

Registered Building Name: -

Registered Postal Code:

792451 Current Vehicle Details

GR6392B

Vehicle No.:

Make Description/Model: TOYOTA/TOYOTA HIACE VAN TURBO 5 DR MANUAL

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case N	otified	Est Submitted	Adj Assigned	Adi Rot		Adj Submitted	Ins Auth'er	d To		
	0 Apr 2018	11 Jun 2018 S\$9,		1018 11 Jun 2018 \$\$9,800.00 \$\$9,800.00 16:10 \$\$9,800.00		Ins Author	P	Pending for Surve Report Cancel Case		
м	ain	R	eference	Cla	im Detai	ils	Docum	ents	\Box	Show All
CLAIM SUB	FOLDER DE	TAILS				[Create	d by insurer]			
Insured:	COOL AIR	SERVICE. Co.	Reg. No.: 53085821	E. Tel: +65	9875003	2	***************************************			
Main Claimant:	HE SHIMI	N, ID: S83210	90G							
Vehicle Reg. No.:	SKA920	ou		0	ate of Lo		018 11:00 - :59 ths and 3 Days		Reg Date (Man Yr)]
Claim Type:	TP / 557	012		0.00	olicy/Cov		53MKC (Compre e: 23/03/2018 -		19	
Vehicle Reg. No. (Insured):	GR63928				olicy No. Claimant	8				
					xcess	5\$600.0				
Repairer:	C.h.motor	Vehicle Repair	Training (HQ) BLK	3019A UBI R	OAD 1 #	01-30, 40871	3 Ubi - Tel:			
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65 68	27 7888	[Handled I	by Irene Tan G	iek Ing - 6	5594 2541]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [tandled t	y MARCUS C	HUA] [Fina	I Rpt du	e 29/08/	2018]
Driver/Custo dian (Insured):	HO GUAN	HUAT (), NRIC:	S1806118Z, Tel:	+6598750032	В					
Adj Asg. Remarks:		oility against oi -1 NT LISTING CHA	00% TP DISAGREE S RT)	SJE APPOINT	KK AUT	O CONSULTAN	ITS AS SJE(ACC	ORDING T	O SURVEYO)R
ASSOCIATE	D MAIL RE	CEIVED						View All	Compos	e Case Ma
			Back Alerts - SKA9 of Assignment: SK							
	TATED TAS	KS⊟				View All	Search Tasks	Create	New Task	Complet
ALL ASSOC			Group Subjec	t Handler	1	signed By	Completed	On I	Created Or	Dane

Merimen e-Claims Page 1 of 3

Claim Documents

*SKA9200U (557012)

[GR6392B]

TP

HE SHIMIN

Apr 28 2018 11:00AM

[COOL AIR SERVICE]

C.h.motor Vehicle Repair Training

Ass	essment Reports		1 per p	age V	4
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/05/18 09:57	Accident Statement From:OD - Reg. No: GRSJ928, Claimant: COOL ATR SERVICE	0	Load HTM	
Pho	otos/Images		3 per p	age 🔻	V
Nα	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	13/06/18 13:44	General View	0	Load JPG	7
2	13/06/18 13:44	General View	0	Load JPG	×.
3	13/06/18 13:44	General View	0	Load JPG	~
4	13/06/18 13:44	General View	0	Load JPG	Z
5	13/06/18 13:44	General View	0	Load JPG	3
6	13/06/18 13:44	General View	0	Load JPG	4
7	13/06/18 13:44	General View	0	Load JPG	2
8	13/06/18 13:44	General View	0	Load JPG	~
9	13/06/18 13:44	General View	0	Load JPG	3
10	13/06/18 13:44	General View	0	Load JPG	4
11	13/06/18 13:44	General View	0	Load JPG	Z)
12	13/06/18 13:44	General View	0	Load JPG	Z)
13	13/06/18 13:44	General View	0	Load JPG	4
14	13/06/18 13:44	General View	0	Load JPG	V
15	13/06/18 13:44	General View	0	Load JPG	~
16	13/06/18 13:44	General View	0	Load JPG	3
17	13/06/18 13:44	General View	0	Load JPG	V
18	13/06/18 13:44	General View	0	Load JPG	V
19	13/06/18 13:44	General View	0	Load JPG	N
20	13/06/18 13:44	General View	0	Load JPG	V
21	13/06/18 13:44	General View	0	Load JPG	V
22	13/06/18 13:44	General View	0	Load JPG	~
23	13/06/18 13:44	General View	0	Load JPG	V
24	13/06/18 13:44	General View	0	Load JPG	V
25	13/06/18 13:44	General View	0	Load JPG	~
26	13/06/18 13:44	General View	0	Load JPG	V
27	13/06/18 13:44	General View	0	Load JPG	V
28	19/06/18 20:25	Dismantled Parts	0	Load JPG	V
29	19/06/18 20:25	Dismantled Parts	0	Load JPG	N.
30	19/06/18 20:25	Dismantled Parts	0	Load JPG	W
31	19/06/18 20:25	Dismantled Parts	0	Load JPG	1
32	19/06/18 20:25	Dismantled Parts	0	Load JPG	V
33	19/06/18 20:25	Dismantled Parts	0	Load 3PG	(2)

Merimen e-Claims Page 2 of 3

Ass	Assessment Reports		1 per pag	1 per page 🔍	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		humbnail	*
34	19/06/18 20:25	Dismantled Parts	0	Load JPG	2
15	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
16	19/06/18 20:25	Dismantled Parts	0	Load JPG	1
37	19/06/18 20:25	Dismantled Parts	0	Load JPG	
18	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
39	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
10	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
11	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
12	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
13	19/06/18 20:25	Dismantied Parts	0	Load JPG	5
14	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
15	19/06/18 20:25	Dismantled Parts		Load JPG	6
16	19/06/18 20:25	Dismantled Parts		Load JPG	5
17	19/06/18 20:25	Dismantled Parts		Load JPG	6
18	19/06/18 20:25	Dismantled Parts		Load JPG	5
9	19/06/18 20:25	Dismantled Parts		Load JPG	5
50	19/06/18 20:25	Dismantled Parts		Load JPG	5
51		Dismantled Parts	121	Load JPG	5
100	19/06/18 20:25			DATE OF STREET	5
25	19/06/18 20:25	Dismantled Parts		Load JPG	_
53	19/06/18 20:25	Dismantled Parts		Load JPG	5
4	19/06/18 20:25	Dismantled Parts		Load JPG	5
55	19/06/18 20:25	Dismantled Parts		Load JPG	5
56	19/06/18 20:25	Dismantled Parts	1.7	Load JPG	6
57	19/06/18 20:25	Dismantled Parts		Load JPG	5
58	19/06/18 20:25	Dismantled Parts		Load JPG	5
59	19/06/18 20:25	Dismantled Parts	1.5	Load JPG	6
50	19/06/18 20:25	Dismantled Parts		Load JPG	6
51	19/06/18 20:25	Dismantled Parts		Load JPG	6
52	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
53	19/06/18 20:25	Dismantled Parts	0	Load JPG	6
54	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
55	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
56	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
57	19/06/18 20:25	Dismantied Parts	0	Load JPG	5
8	19/06/18 20:25	Dismantled Parts	0	Load JPG	6
9	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
70	19/06/18 20:25	Dismantled Parts	0	Load JPG	6
1	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
72	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
73	19/06/18 20:25	Dismantled Parts	0	Load JPG	5
74	19/06/18 20:25	Dismantled Parts		Load JPG	6
75	19/06/18 20:25	Dismantled Parts		Load JPG	6
76	19/06/18 20:25	Dismantled Parts		Load JPG	5
77	19/06/18 20:25	Dismantled Parts		Load JPG	5
78	19/06/18 20:25	Dismantled Parts	-	Load JPG	5
79	19/06/18 20:25	Dismantled Parts		Load JPG	5
	District Color Color Color	Dismantled Parts		Load JPG	6
30	19/06/18 20:25	Lie Aprilla and Aprilla (Add)		Load JPG	5
81	19/06/18 20:25	Dismantled Parts		Load JPG	5
82	19/06/18 20:25	Dismantled Parts Dismantled Parts		Load JPG	5

Page 3 of 3

Ass	Assessment Reports		1 per	1 per page 🔍	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	19/06/18 20:25	Dismantled Parts	0	Load JPG	V
85	26/06/18 09:47	Photo After Spray	0	Load JPG	W
86	26/06/18 09:47	Photo After Spray	0	Load JPG	V
67	26/06/18 09:47	Photo After Spray	0	Load JPG	V
88	26/06/18 09:47	Photo After Spray	0	Load 3PG	Z
89	26/06/18 09:47	Photo After Spray	0	Load JPG	V
90	26/06/18 09:47	Photo After Spray	0	Load JPG	∀
91	26/06/18 09:47	Photo After Spray	0	Load JPG	V
92	26/06/18 09:47	Photo After Spray	0	Load JPG	W
93	26/06/18 09:47	Photo After Spray	0	Load JPG	V
04	26/06/18 09:47	Photo After Spray	0	Load JPG	V
95	26/06/18 09:47	Photo After Spray	0	Load 3PG	V
96	26/06/18 09:47	Photo After Spray	0	Load JPG	V
97	26/06/18 09:47	Photo After Spray	0	Load JPG	∀
96	26/06/18 09:47	Photo After Spray	0	Load JPG	Z
99	26/06/18 09:47	Photo After Spray	0	Load 3PG	V
e	26/06/18 09:47	5.50 m m m m m m m m m m m m m m m m m m m	0	Load JPG	∀
100		Photo After Spray		-	_
101	26/06/18 09:47	Photo After Spray	0	Load JPG	₹
102	26/06/18 09:47	Photo After Spray	0	Load JPG	V
103	26/06/18 09:47	Photo After Spray	0	Load JPG	V
104	26/06/18 09:47	Photo After Spray	0	Load JPG	V
Doc	umentation		1 per	page V	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	_
1	02/05/18 09:57	TPD SKA9200U GIA REPORT.PDF	0	Load PDF	
2	11/06/18 15:32	BH Auto's confirmation that carowner withdraw car	Ö	Load PDF	
3	11/06/18 16:02	our instruction to LKK to followup with new repairer	0	Load PDF	
4	27/08/18 13:49	LOD with supporting documents	0	Load PDF	
5	27/08/18 13:54	TPD SKA9200E - COLOUR PHOTO	0	Load PDF	
6	27/08/18 13:54	TPD SKA9200E - COLOUR PHOTO	ō	Load PDF	
7	27/08/18 15:53	our instruction to LKK to prepare paper survey report	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/10/18 12:11	COLOUR PHOTO	0	Load PDF	
2	02/10/18 12:12	PRS Invoice	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18007989/ATBE2-1

Date:

02/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A28910753MKC

Claimant Vehicle SKA9200U

Insured Vehicle No:

GR6392B

No: Date of Loss:

28/04/2018

Nature of Claim:

TP

Claim No: 557012

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKA9200U

Make & Model:

AUDI Q5, 3.2 FSI S-LINE QUATTRO D/AB HID (A) Engine No:

CAL080058

Reg. Date: Colour:

25/01/2011 (Man. Year: 2010) Brown

Chassis No: Odometer:

WAUZZZ8R4BA062497 100615 km

Engine Capacity:

3197 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Rear Tyre Size:

255/45 R20

Front Tyre Size: Front Left Side:

Bridgestone 6 mm

255/45 R20

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,045.95	10,600.25	3,445.70	24.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,670.00	1,390.00	45.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,105.95	12,270.25	4,835.70	28.27
Approved Total (Overridden) (S\$)		9,800.00		
Nett Amount (S\$)	17,105.95	9,800.00	7,305.95	42.71

INSPECTION

Date of Assignment

11/06/2018

Date Inspected:

12/06/2018 Inspected At:

C.h.motor Vehicle Repair Training (HQ)

BLK 3019A UBI ROAD 1 #01-30

Singapore 408713

Estimated Period of Repair:

7.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded. https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 2/10/2018 Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Oct 2018)

Parts: M1-SUV AUDI Q5 3.2 FSI S-LINE QUATTRO D/AB HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA9200U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

C 1141

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT GRILLE ASSY	Dented / Cracked	1,505.00 FL	*1,505.00 FL
2	2		*HEADLAMP ASSY R/L	Cracked / Loop Broken	5,716.00 FL	*5,716.00 FL
3	1		*HEADLAMP BRACKET R/L	N/S Cracked	272.00 FL	*136.00 FL
4	1		*FRT BUMPER ASSY	Dented	2,325.00 FL	*2,325.00 FL
5	1		*FRT BUMPER FOGLAMP GRILLE R/L	N/S Cracked	236.00 FL	*118.00 FL
6	2		*FRT BUMPER FOGLAMP R/L	Refit	454.00 FL	*-FL
7	1		*FRT BUMPER LOWER SPOILER	Refit	540.00 FL	*-FL
8	1		*FRT BUMPER LOWER END PLATE	Dented / Cracked	167.00 FL	*167.00 FL
9	2		*FRT BUMPER GUIDE R/L	Broken / Cracked	128.00 FL	*128.00 FL
10	1		*FRT BUMPER ABSORBER	Dented / Cracked	97.00 FL	*97.00 FL
11	1		*FRT BUMPER REINFORCEMENT	Dented	571.00 FL	*571.00 FL
12	1		*FRT BUMPER REINFORCE. BRACKET R/L	N/S Bent	414.00 FL	*207.00 FL
13	1		*FRT RADIATOR SUPPORT TOP COVER	Refit	109.00 FL	*-FL
14	1		*FRT RADIATOR SUPPORT	Not Necessary	970.00 FL	*-FL
15	1		*FRT RADIATOR SUPPORT STAY	Dented / Cracked	72.00 FL	*72.00 FL
16	1		*FRT RADIATOR SIGHT SHIELD R/L	N/S Cracked	106.00 FL	*53.00 FL
17	1		*HORN	Refit	178.00 FL	*-FL
18	1		*FRT FENDER LH	Repair	841.00 FL	*-FL
19	1		*BONNET (NPA)	Repair	0.00 FL	*-FL
20	1		*FRT APRON PANEL LH (NPA)	Repair	0.00 FL	*-FL
21	2		*FRT CHASSIS MEMBER R/L (NPA)	Repair	0.00 FL	*-FL
22	1		*BOT RADIATOR COOLANT	Necessary	80.00 FS	*60.00 FS
F≍Fn	anchise	part S=Spc	Nett. L=ListitemDisc.	Sub Total (S\$)	14,781.00	11,155.00

Sub Total (S\$) 14,781.00 11,155.00 - List Item Discount on L Items 5.00/5.00% (S\$) 735.05 554.75

Total Parts (S\$) 14,045.95 10,600.25

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO CHECK FRONT ELECTRICAL SYSTEM AND REPAIR WIRE HARNESS	New	60.00	30.00
TO REMOVE AND REINSTALL A/C CONDENSER, A/C PIPINGS FOR NECESSARY REPAIRS (INCLUDE VACUUM & RECHARGE A/C GAS)	New	120.00	60.00
TO REMOVE AND REINSTALL RADIATOR & COOLING SYSTEM FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM)	New	100.00	60.00
TO REMOVE AND REINSTALL INTERCOOLER ASSY & PIPINGS (INCLUDE PRESSURE TEST AIR INTAKE SYSTEM)	New	80.00	60.00
TO REMOVE AND TRANSFER FRONT BUMPER SENSORS TO NEW BUMPER	New	60.00	40.00
TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,200.00	800.00
TO CONDUCT CHASSIS ALIGNMENTS	New	320.00	0.00
TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,000.00	500.00
TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING PROGRAMMING ON: - 9.1) FRONT BUMPER SENSOR CONTROL MODULE 9.2) CALIBRATE / FOCUS HEADLAMP	New	120.00	120.00
Gross Labour	Cost (S\$)	3,060.00	1,670.00
	TO CHECK FRONT ELECTRICAL SYSTEM AND REPAIR WIRE HARNESS TO REMOVE AND REINSTALL A/C CONDENSER, A/C PIPINGS FOR NECESSARY REPAIRS (INCLUDE VACUUM & RECHARGE A/C GAS) TO REMOVE AND REINSTALL RADIATOR & COOLING SYSTEM FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM) TO REMOVE AND REINSTALL INTERCOOLER ASSY & PIPINGS (INCLUDE PRESSURE TEST AIR INTAKE SYSTEM) TO REMOVE AND TRANSFER FRONT BUMPER SENSORS TO NEW BUMPER TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS TO CONDUCT CHASSIS ALIGNMENTS TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING PROGRAMMING ON: -9.1) FRONT BUMPER SENSOR CONTROL MODULE 9.2) CALIBRATE / FOCUS HEADLAMP	TO CHECK FRONT ELECTRICAL SYSTEM AND REPAIR WIRE NEW HARNESS TO REMOVE AND REINSTALL A/C CONDENSER, A/C PIPINGS NEW FOR NECESSARY REPAIRS (INCLUDE VACUUM & RECHARGE A/C GAS) TO REMOVE AND REINSTALL RADIATOR & COOLING NEW SYSTEM FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM) TO REMOVE AND REINSTALL INTERCOOLER ASSY & NEW PIPINGS (INCLUDE PRESSURE TEST AIR INTAKE SYSTEM) TO REMOVE AND TRANSFER FRONT BUMPER SENSORS TO NEW NEW BUMPER TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA NEW AND REPLACE DAMAGED PARTS TO CONDUCT CHASSIS ALIGNMENTS NEW ADJACENT AREA TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING NEW PROGRAMMING ON: - 9.1) FRONT BUMPER SENSOR	TO CHECK FRONT ELECTRICAL SYSTEM AND REPAIR WIRE New 60.00 HARNESS TO REMOVE AND REINSTALL A/C CONDENSER, A/C PIPINGS New 120.00 FOR NECESSARY REPAIRS (INCLUDE VACUUM & RECHARGE A/C GAS) TO REMOVE AND REINSTALL RADIATOR & COOLING New 100.00 SYSTEM FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM) TO REMOVE AND REINSTALL INTERCOOLER ASSY & New 80.00 PIPINGS (INCLUDE PRESSURE TEST AIR INTAKE SYSTEM) TO REMOVE AND TRANSFER FRONT BUMPER SENSORS TO New 60.00 NEW BUMPER TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA New 1,200.00 AND REPLACE DAMAGED PARTS TO CONDUCT CHASSIS ALIGNMENTS New 320.00 TO SPRAY PAINTING, BLENDING ON AFFECTED AND New 1,000.00 ADJACENT AREA TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING New 120.00 PROGRAMMING ON: -9.1) FRONT BUMPER SENSOR CONTROL MODULE 9.2) CALIBRATE / FOCUS HEADLAMP

< END OF ESTIMATES >