

AKK - LKK
(phone)



ESTEEM PERFORMANCE PTE LTD


Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMC 955 A

Not Authorized
1. B.1
Resurvey B6 paint

Parts	(a) Cost / List Price Items	\$	3,584.90
	Plus/Less 20%	\$	716.98
	Total of Cost / List	\$	2,867.92
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	295.00
Total Parts Cost		\$	3,162.92
Labour		\$	2,230.00
Total		\$	5,392.92



The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 3/8/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 3/8/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMC 955 A**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71211355**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>Mu</i>	1	\$120.00		✓
2	Rear windscreen sealant <i>Mu</i>	1	\$50.00	S.N	<i>Pass</i>
3	Reverse sensor	2	\$200.00	S.N	✓
4	Rear number plate <i>Sm</i>	1	\$45.00	S.N	X
5	Tail door <i>By</i>	1	\$1,193.00		✓
6	Tail door lock <i>R</i>	1	\$157.10		X
7	Tail door emblem <i>Mu</i>	1	\$38.00		✓
8	Wording "SHUTTLE" <i>Mu</i>	1	\$55.00		✓
9	Wording "HYBRID" <i>Mu</i>	1	\$80.10		✓
10	Tail door chrome <i>Sm</i>	1	\$383.10		X
11	Tail door trim <i>Sm</i>	1	\$320.00		X
12	Tail door trim clip <i>Mu</i>	10	N/A		X
13	Rear bumper <i>Bu/Ad</i>	1	\$1,150.60		✓
14	Rear bumper clip <i>Mu</i>	10	\$35.00		✓
15	Rear bumper side retainer LH <i>Sm</i>	1	\$26.50		X
16	Rear bumper side retainer RH <i>Sm</i>	1	\$26.50		X
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SMC 955 A** Submit By : **Carmen Lim**
Make & Model : **HONDA SHUTTLE** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$800.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$800.00	4001
3	To check wiring	\$50.00	151
4	To remove & refit reverse sensor	\$120.00	501
5	To tuff coat	\$100.00	301
6	To remove & refit rear windscreen.	\$120.00	✓
7	To transfer boot mechanism to new boot	\$120.00	601
8	To conduct water leakage tests to ensure proper air and sealing	120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.