

ASS. REC. BY:

REF: CS/CT18015571/Dsd3ⁿ²

Special Instruction:

Survivor
menmen

ASSIGNMENT (Office)

From (Person):

Judy Ty

of

CTI

Date/Time:

27/8/18 @ 1:21pm

Estimated Cost:

Bill to:

OD: TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHC 2683E

Insured:

SLJ 5869H

at Workshop m/s

Chunni Motor

Tel:

65425119

of

Bik 10 Amk Ind. Park 2A #01-05/06

Policy No:

DMHCSN1744271700

Claim No:

SNM18D04081C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/08/2018

28/08/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

cup

Date/Time:

4:02pm @ 27/8/18

Person Contacted:

Lynn

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 2683E - C3 / III / 6013518 / M / ver 3q2 DOA: 19/7/16

SLJ 5869H - x

25/09/18

Continued L/S \$16,950 @ 14 days with Bryan.

(\$10,535.10 Red - 38%)

REF:

ASSIGNMENT

COE Dec 2024

2016 Dec

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / IRV / MV

To be post Vehicle No: _____

at Workshop no: _____

of _____

Insured: _____


Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs: 14 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: **SHC 2683E** Yr Began: **2016**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai I40** CC: **1685**

Color: **Blue** A/C: Insured / Std / Nil / NA

Sp. Branding: **249143** IRadio: Insured / Std / Nil / NA

Eng/Mtr: **D4FDG691723**

CR No: **KMHLB41UMHU096724**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insider / Jammed / Leaked / Burnt or

Brake: Insider / Jammed / Leaked / Burnt or

Modi: **10** S/Rim / STD A/Rim orTyre Size: F: **205/60 R16**R: **— — —**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Henkoak**

Front

Rear

R/Bal: **S** mmR/Bal: **S** mmL/Bal: **S** mmL/Bal: **S** mmD.O.A: **22/08/2018**D.O.I: **28/08/2018**Survey held at **Chunni AMK**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front y Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/09/18 China Taping 8L5 5869H
O/S GIA seen. TP vehicle number reported in O/S GIA is
SHC 3683E. checked all other vehicle number correct.
so most likely its a typo error.

25/09/18 Jumper 2/5 169501- with 14 days & ✓

RECEIVED 27 SEP 2018

Date/Time, I do Pass to?

27/09/18

1) Typist

Editor/Amr, (No Return to)

2)



Preli. Report



Final Report

Days Of Repair: **14**Resurvey No. of Trip: **2**Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. 54

) Photos

) Others

220

Report Format :

Lump Sum / LB.L: (\$ **16,950/- HS**)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018		27 Aug 2018 13:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	OW CHIH WEI, Co. Reg. No.: 53364724W		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD		
Vehicle Reg. No.:	SHC2683E	Date of Loss:	22/08/2018 19:00 - :59
Claim Type:	TP / SNM18D04081C02	Policy/Cover Note No.:	DMHCSN1744271700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLJ5869H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2018]		
Adj Asg. Remarks:	EST \$27,485.10, ASSIGN HENRY NG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18015571/Dsd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 5869H	Veh. Inspected	SHC 2683E	
Policy No.	DMHCSN1744271700	Coverage (\$)	0.00	
Claim No.	SNM18D04081C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/08/2018	Inspection Date	28/08/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MCD818109061 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 23/08/2018 14:10
 SUBMITTED BY: Janet Lim Siang Gok

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/08/2018 14:10
 Date Of Accident 22/08/2018 19:05
 Exact Location Of Accident PIE TWDS CHANGI AIRPORT B/4 EUNOS EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC2683E
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0016
 Cover Note Number
Driver
 Name of Driver PEH YAP CHENG
 NRIC No S0098373Z
 Date Of Birth 28/03/1954
 Occupation OUTDOOR
 Date Of Driving Pass 15/04/1987
 Driving Experience 31 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-84321628
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address BLK 450 TAMPINES STREET 42
#08-100
Postcode 520450
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 5
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TAMPINES NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-5871999 - FAX NO: 65871699
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/201808123/2029

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLJ5869H
Vehicle Make/Model/Colour HONDA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGL8899A
Vehicle Make/Model/Colour TOYOTA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number 91246711
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT AND REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SGG7790L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT AND REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLE5595Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage REAR
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PEH YAP CHENG
Approximate Age
Injuries Sustain NECK AND BACK
Injured person in which vehicle? SHC2683E
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CHUNNI MOTOR WORKS PTE LTD
CO. REG. NO. 19930321R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 23.08.2018 @ 13:20 Hrs


Reporting Centre Personnel's Signature
Name: *Rubini*
NRIC/FIN No.:

SKETCH PLAN



Refer to the attachment.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to Police Report : T/20180823/2028.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

PORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303824RPolicyholder's Signature
Date & Time:
Driver's Signature
(If driver is not the policyholder)
Date & Time: 23.08.2018 @ 13:20 Hrs
Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

P.IE TOWARD AIRPORT.




S'0098373Z
Teh Yap Cheng



**SINGAPORE
POLICE FORCE**



T/20180823/2028

1 of 3

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

Report No. T/20180823/2028

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/08/2018 11:40		Vide Report No.:		Station Diary No.: 47	
Informant's Particulars					
Name of Informant: PEH YAP CHENG			Address: APT BLK 450 TAMPINES STREET 42 #08-100 SINGAPORE 520450		
ID Type / ID No.: NRIC NO / S0098373Z			Contact No.: Home/Office: Mobile: 84321628		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 28/03/1954	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/08/2018 19:05	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
PIE toward Changi before Eunos Exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGG7790L						0
SGL8899A						0
SHC2683E	Car				Slightly Damaged	0
SLE5595Z						0
SLJ5869H						0



**SINGAPORE
POLICE FORCE**



T/20180823/2028

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

2 of 3

Report No. T/20180823/2028

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	PEH YAP CHENG	ID No.	S0098373Z
Related Vehicle	SHC2683E (Car)	Contact No.	84321628
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	23/08/2018	Date Discharge	23/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 22nd August 2018 at about 1905hrs, I was travelling on the extreme right lane with my vehicle bearing registration plate SHC2683E along PIE toward Airport before Eunos Exit. When I was travelling on the extreme right lane the vehicle ahead of me slow down as such I followed. When my vehicle was stationary waiting for the vehicle in front to move, suddenly I felt an impact from the rear. Due to the impact my vehicle moved forward and collided onto the front vehicle. I alighted front my vehicle to discovered it was a chain collision involving 5 vehicles. The first vehicle is (SLE5595Z), followed by (SGG7790L), (SGL8899A), (SHC2683E) and the last vehicle is (SLJ5869H).

There is no passenger on board my vehicle. My vehicle has damages on the front and rear. I sustained on my neck and back as such I went to Sunshine Clinic Family Practice & Surgery located at Blk 445 Tampines St 42 #01-02 Singapore and was given 5 days medical leave from 23rd August 2018 - 27th August 2018.

**SINGAPORE
POLICE FORCE**

T/20180823/2028

3 of 3

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

Report No. T/20180823/2028

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 NURHIDAYAH BINTE TADIL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

23/08/2018 11:40

Officer In Charge Of Case:

TP / AEIT /

SSI 2 YEO GEAK ENG CE

Contact No.: 65476404

Classification Of Case:

Authentication Stamp

NP168



CHUNNI MOTOR WORK PTE LTD

10 Sunway Hwy 11kk

China Taipei

REPAIR ESTIMATE*

VEHICLE NO : SHC 2683E

DATE : 23.08.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>crack</i>			\$ 1,480.00	✓
	Radiator Grille H Emblem <i>cut</i>			\$ 290.80	✓
	Radiator Grille Chrome Moulding <i>crack</i>			\$ 395.50	✓
	Front Bumper Cover <i>distorted</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>torn</i>			\$ 142.20	✓
	Front Bumper Reinforcement <i>BT</i>			\$ 526.10	✓
	Front Bumper Grille (LH/RH) <i>HN</i>	\$	285.50	\$ 571.00	X
	Front Bumper Grille Airduct (LH/RH) <i>HN</i>	\$	155.00	\$ 310.00	X
	Front Bumper Bracket Top (LH/RH) <i>HN</i>	\$	22.40	\$ 44.80	X
	Front Bumper Retainer Mounting <i>HN</i>	\$	9.20	\$ 18.40	X
	Headlamp Support Top Cover <i>broken</i>			\$ 398.00	✓
	Headlamp Support Panel Assy <i>crack</i>			\$ 1,067.50	✓
	Headlamp (LH/RH) <i>mounting crack</i>	\$	1,388.00	\$ 2,776.00	✓ <i>photo</i>
	Radiator <i>BT</i>			\$ 850.20	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	X ✓
	Radiator Bracket (RH/LH) <i>SVC</i>	\$	6.50	\$ 13.00	X
	Radiator Hose Upper <i>HN</i>			\$ 47.40	X
	Radiator Hose Lower <i>HN</i>			\$ 47.40	X
	Radiator Expansion Tank <i>HN</i>			\$ 48.00	X
	Radiator Guard <i>broken</i>	\$	35.00	\$ 70.00	✓
	Horn Unit (LH/RH) <i>broken</i>	\$	86.75	\$ 173.50	✓
	Horn Wire <i>SVC</i>			\$ 156.50	X
	Aircon Condenser <i>BT</i>			\$ 1,137.35	✓
	Inter Cooler <i>BT</i>			\$ 921.90	✓
	Inter Cooler Mounting (2 PCS) <i>SVC</i>			\$ 25.90	X
			12074.20		
			9659.36		
	SUB TOTAL			\$ 13,356.60	
	LESS 20%			\$ 2,671.32	
	DISCOUNTED TOTAL			\$ 10,685.28	
	Front Number Plate <i>crack</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>SVC</i>			\$ 30.00	Nett X
			25.00		
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	50/-
	Tuff Kote			\$ 50.00	20/-
	Towing Charge			\$ 50.00	HN
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	TOTAL LABOUR			\$ 1,550.00	

830/-

SHC 2683E

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>Dented</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>deformed</i>			\$ 115.80	✓
	Boot Lid Lock Upper <i>DT</i>			\$ 137.90	✓
	Boot Lid Lock Lower <i>ray</i>			\$ 31.70	mx
	Boot Lid Key Lock <i>NH</i>			\$ 81.60	X
	BootLid Hyundai Plate <i>NH</i>			\$ 27.50	✓
	Boot Lid 'H' Emblem <i>NH</i>			\$ 27.20	✓
	Boot Lid CRDI Plate <i>NH</i>			\$ 41.00	✓
	Boot Lid Lamp (LH/RH) <i>Crack</i>		\$ 556.80	\$ 1,113.60	✓
	Boot Lid Trimboard <i>toyn</i>			\$ 172.70	✓
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00	✓
	Bootlid Moulding <i>SVC</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>NH</i>			\$ 41.00	✓
	Bootlid Lower Garnish <i>ray</i>			\$ 398.00	X
	Rear Bumper <i>Dented</i>			\$ 603.60	✓
	Rear Bumper Reinforcement <i>broken</i>			\$ 504.35	photo
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Dented</i>		\$ 180.00	\$ 360.00	✓
	Rear Bumper Clip 10 pcs <i>NH</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>NH</i>		\$ 49.00	\$ 98.00	X
	Rear Bumper Sponge <i>toyn</i>			\$ 143.40	photo
	Rear Bumper Under Cover <i>deformed</i>			\$ 225.00	✓
	Rear Bumper Reflector Lamp (LH/RH) <i>NH</i>		\$ 32.00	\$ 64.00	X
	Tail Lamp (LH/RH) <i>Crack</i>		\$ 565.60	\$ 1,131.20	✓
	Tail Lamp Quarter Panel (LH/RH) <i>NH</i>		\$ 226.50	\$ 453.00	X
	Rear Panel <i>Dented</i>			\$ 592.30	✓
	Rear Panel Garnish <i>monthly crack</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>Dented</i>			\$ 495.50	✓
	Spare Tyre Holder <i>NH</i>			\$ 28.80	X
	Spare Tyre Panel <i>Dented</i>			\$ 900.50	✓
	Spare Tyre Panel Cushion <i>SVC</i>			\$ 209.05	X
	Rear Towing Hook <i>NH</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>NH</i>			\$ 170.75	X
	Exhaust Pipe Insulator <i>NH</i>		\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>NH</i>		\$ 954.00	\$ 1,908.00	✓
	Exhaust Pipe Hanger <i>NH</i>		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>NH</i> <i>photo taken</i>			\$ 1,150.30	X
			10806.15		
			8644.92		
	SUB TOTAL			\$ 13,905.15	
	LESS 20%			\$ 2,781.03	
	DISCOUNTED TOTAL			\$ 11,124.12	
	Boot Lid Comfort Logo & Tel No. Sticker <i>NH</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>NH</i>			\$ 100.00	Nett ✓
	Rear No.Plake <i>Crack</i>			\$ 25.00	Nett ✓
	Rear Bumper Reverse Sensor <i>short</i>		540.70	\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>NH</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>NH</i>		\$ 100.00	\$ 200.00	Nett ✓
				\$ 540.70	

SHC 2683E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00 700/-
	Spray Painting Charge			\$ 1,250.00 600/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe		1490/-	\$ 360.00 80/-
	TOTAL LABOUR			\$ 3,530.00
	ESTIMATE TOTAL			\$ 27,485.10
	28/08/2018 @ 1130hrs			21189.98
	Not Author			1516950/-
	2/Sept 14			
	14 days.			
	14 days			
	LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damage 1 part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18015571/DSD3N2

Date: 04/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1744271700
Claimant Vehicle No :	SHC2683E	Insured Vehicle No :	SLJ5869H
Date of Loss:	22/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04081C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2683E	Engine No:	D4FDGU691723
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMHU096724
Reg. Date:	08/12/2016 (Man. Year: 2016)	Odometer:	249143 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,405.10	18,869.98	3,535.12	15.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	2,320.00	2,760.00	54.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,485.10	21,189.98	6,295.12	22.90
Approved Total (Overridden) (\$\$)		16,950.00		
(\$\$)	27,485.10	16,950.00	10,535.10	38.33
+ GST 7.00/7.00% (\$\$)	1,923.96	1,186.50	737.46	38.33
Nett Amount (\$\$)	29,409.06	18,136.50	11,272.56	38.33

INSPECTION

Date of Assignment: 27/08/2018

Date Inspected: 28/08/2018 Inspected At:

CHUNNI MOTOR REPAIRS PTE LTD
BLK 10 ANG MO KIO INDUSTRIAL
PARK 2A
AMK AUTOPOINT #03-19
SINGAPORE 568047

Estimated Period of Repair: 14.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2683E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
2	1		*RADIATOR GRILLE H EMBLEM	Cut	290.80 FL	*290.80 FL
3	1		*RADIATOR GRILLE CHROME MOULDING	Cracked	395.50 FL	*395.50 FL
4	1		*FRONT BUMPER COVER	Distorted	1,052.20 FL	*1,052.20 FL
5	1		*FRONT BUMPER SPONGE	Torn	142.20 FL	*142.20 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	526.10 FL	*526.10 FL
7	2		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	571.00 FL	*- FL
8	2		*FRONT BUMPER GRILLE AIRDUCT (LH/RH)	Not Necessary	310.00 FL	*- FL
9	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
10	2		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	18.40 FL	*- FL
11	1		*HEADLAMP SUPPORT TOP COVER	Broken	398.00 FL	*398.00 FL
12	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	1,067.50 FL	*1,067.50 FL
13	2		*HEADLAMP (LH/RH)	Mounting Cracked	2,776.00 FL	*2,776.00 FL
14	1		*RADIATOR	Bent	850.20 FL	*850.20 FL
15	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Broken	792.95 FL	*792.95 FL
16	2		*RADIATOR BRACKET (RH/LH)	Serviceable	13.00 FL	*- FL
17	1		*RADIATOR HOSE UPPER	Not Necessary	47.40 FL	*- FL
18	1		*RADIATOR HOSE LOWER	Not Necessary	47.40 FL	*- FL
19	1		*RADIATOR EXPANSION TANK	Not Necessary	48.00 FL	*- FL
20	2		*RADIATOR GUARD	Broken	70.00 FL	*70.00 FL
21	2		*HORN UNIT (LH/RH)	Broken	173.50 FL	*173.50 FL
22	1		*HORN WIRE	Serviceable	156.50 FL	*- FL
23	1		*AIRCON CONDENSER	Bent	1,137.35 FL	*1,137.35 FL
24	1		*INTER COOLER	Bent	921.90 FL	*921.90 FL
25	1		*INTER COOLER MOUNTING (2 PCS)	Serviceable	25.90 FL	*- FL
26	1		*BOOT LID	Dented	2,174.90 FL	*2,174.90 FL
27	1		*BOOT LID RUBBER	Deformed	115.80 FL	*115.80 FL
28	1		*BOOT LID LOCK UPPER	Bent	137.90 FL	*137.90 FL
29	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
30	1		*BOOT LID KEY LOCK	Not Necessary	81.60 FL	*- FL
31	1		*BOOTLID HYUNDAI PLATE	Necessary	27.50 FL	*27.50 FL
32	1		*BOOT LID H EMBLEM	Necessary	27.20 FL	*27.20 FL
33	1		*BOOT LID CRDI PLATE	Necessary	41.00 FL	*41.00 FL
34	2		*BOOT LID LAMP (LH/RH)	Cracked	1,113.60 FL	*1,113.60 FL
35	1		*BOOT LID TRIMBOARD	Torn	172.70 FL	*172.70 FL
36	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
37	1		*BOOTLID MOULDING	Serviceable	85.00 FL	*- FL
38	1		*BOOTLID I40 EMBLEM	Necessary	41.00 FL	*41.00 FL
39	1		*BOOTLID LOWER GARNISH	Repair	398.00 FL	*- FL
40	1		*REAR BUMPER	Dented	603.60 FL	*603.60 FL
41	1		*REAR BUMPER REINFORCEMENT	Broken	504.35 FL	*504.35 FL
42	2		*REAR BUMPER REINFORCEMENT BRACKET	Dented	360.00 FL	*360.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			(LH/RH)			
43	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
44	2		*REAR BUMPER BRACKET	Not Necessary	98.00 FL	*- FL
45	1		*REAR BUMPER SPONGE	Torn	143.40 FL	*143.40 FL
46	1		*REAR BUMPER UNDER COVER	Deformed	225.00 FL	*225.00 FL
47	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	64.00 FL	*- FL
48	2		*TAIL LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
49	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	453.00 FL	*- FL
50	1		*REAR PANEL	Dented	592.30 FL	*592.30 FL
51	1		*REAR PANEL GARNISH	Mounting Cracked	57.70 FL	*57.70 FL
52	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
53	1		*SPARE TYRE HOLDER	Not Necessary	28.80 FL	*- FL
54	1		*SPARE TYRE PANEL	Dented	900.50 FL	*900.50 FL
55	1		*SPARE TYRE PANEL CUSHION	Serviceable	209.05 FL	*- FL
56	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
57	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	170.75 FL	*- FL
58	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
59	2		*EXHAUST SILENCER	Bent	1,908.00 FL	*1,908.00 FL
60	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
61	1		*EXHAUST PIPE CENTRE	Not Necessary	1,150.30 FL	*- FL
62	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
63	1		*FRONT NO PLATE TRIM COVER	Serviceable	30.00 FS	*- FS
64	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
65	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
66	1		*REAR NO PLATE	Cracked	25.00 FS	*25.00 FS
67	1		*REAR BUMPER REVERSES ENSOR	Shorted	135.70 FS	*135.70 FS
68	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
69	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 27,857.45 23,446.05
 - List Item Discount on L Items 20.00/20.00% (S\$) 5,452.35 4,576.07

Total Parts (S\$) 22,405.10 18,869.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,500.00	800.00
3	WIRING CHARGE	New	150.00	60.00
4	TUFF KOTE	New	150.00	60.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	360.00	80.00
Gross Labour Cost (S\$)			5,080.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >