

2/10/2018

ASS. REC. BY:

REP: CS/FCI/18015543/1/1d3/n2

Special Instructions

Surveyor

ASSIGNMENT (Office)

From Person:

Jurere juw

of

FCI

Date/Time:

27/8/18 @ 11:44am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 3851 E

Insured:

SHB 4799Y

at Workshop n/s:

Progressive

Tel:

6844 4620

of

No. 1 Kaki Bkt Ave 6 #02-48/50

Policy No:

Claim No:

D18006376MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/8/2018

28/08/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

12:18pm @ 27/8/18

Person Contacted:

Mandy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKT 3851 E-X

SHB 4799Y - CS/FCI/17064769/Sqh3m2 DOA: 17/5/17

REF: FCL

ASSIGNMENT

From

Date: 28/08/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKT 3851E

at Workshop m/s

Progression

of

Bk 1 Kaki Bukit Ave 6 #02-48

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

40

IDAC Accident Report:

Consistent?: Yes or No

G/A PR Seen:

2

Consistent?: Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

L7A 30686

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKT 3851E

Yr Regn:

212

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

Honda civic

cc

1598

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp Reading:

120452

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMFB1630CS200197

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/8/18

D.O.I.

10/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rat.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/9/18 confirmed L/S \$1200 with air wing (Red: 136/1 53%)

Date/Time, File Pass to?

1) 5/10 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

TP

1200+

Days Of Repair:

2

Resurvey No. of Trip:

-

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Week-end (\$)

Survey Fee:

Transportation:

) \$ + PS \$

) Photos:

) Other:

TOTAL

110

50

40

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015593/Utd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4799Y	Veh. Inspected	SKT 3851E
Policy No.		Coverage (\$)	0.00
Claim No.	D18006376MFSH	Excess (\$)	0.00
Assign From	CWS (LUREN JAW)	Assign Date	27/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/08/2018	Inspection Date	10/09/2018
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	24-08-2018	Our Ref No. D18006376MFSH
Accident Date	23-08-2018	Claim Type. Third Party
Insured Vehicle	SHB4799Y	Third Party Vehicle. SKT3851E
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48/50	
Contact Person.	MANDY SIN	
Contact No.	68444620/ 0	Fax No. 68444625
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4876D

Vehicle Details

Vehicle No.: SKT3851E
Vehicle to be Exported: No
Intended De-registration Date: 24 Aug 2018
Vehicle Make: HONDA
Vehicle Model: CIVIC 1.6 VTiS AT
Primary Colour: Black
Manufacturing Year: 2011
Engine No.: R16B11000350
Chassis No.: JHMFB1630CS200197
Maximum Power Output: 92.0 kW (123 bhp)
Open Market Value: \$21,606.00
Original Registration Date: 09 Feb 2012
First Registration Date: 09 Feb 2012
Transfer Count: 3
Actual ARF Paid: \$21,606.00 10803

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Feb 2022
PARF Rebate Amount: \$14,043.00

Intended COE Rebate Details

COE Expiry Date: 08 Feb 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$48,112.00
COE Rebate Amount: \$16,643.00
Total Rebate Amount: \$30,686.00

The information contained herein is correct as at 24 Aug 2018

OK

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: SKT3851E

Claim Type: Third Party

Accident Date: 23-08-2018

TP Veh Reg No: SHB4799Y

Estimate No: EST0000697

Date: 05 Sep 2018

Policy No: GA380156/1

Veh Reg No: SKT3851E

Make/Model: HONDA CIVIC 1.6 VTIS AT

Chassis No: JHMFB1630CS200197

Engine No: R16B11000350

Reg. Date: 09-02-2012

Estimate Repair Cost to Vehicle No :SKT3851E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
HONDA CIVIC 1.6 VTIS AT				
List Price				
1 Front Grille	385.2000	1 PC	385.20	✓
2 Front Grille Clipse	5.5000	3 PC	16.50	✓
3 Front Bumper	785.4000	1 PC	785.40	✓
4 Front Bumper Reinforcement	357.2000	1 PC	357.20	✓
5 Front Bumper Side Retainer	32.2000	1 PC	32.20	✓
			1,576.50	
	Less 20%		315.30	1,261.20
Special Net				
6 Front Number Plate	50.0000	1 PC	50.00	50.00
Labour				
7 Panel Beating	650.0000	1 PC	650.00	250
8 Check Wiring	60.0000	1 PC	60.00	20
9 Rust Proofing	60.0000	1 PC	60.00	✓
10 Spray Painting	480.0000	1 PC	480.00	300
			1,250.00	1,250.00
Total			S\$ 2,561.20	

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FIVE HUNDRED SIXTY ONE AND CENTS TWENTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For PROGRESSIVE AUTO PTE LTD

AUTHORISED SIGNATURE

P-1138-52
202
910.81
1520.81



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015593/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4799Y	Veh. Inspected	SKT 3851E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006376MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JHMFB1630CS200197	Colour	BLACK	
Odometer	120452	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	6 mm	
L/H Front Tyre	205/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/08/2018	Inspection Date	10/09/2018	
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 3851E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT GRILLE	CRACKED	385.20	365.20
3	FRONT GRILLE CLIPSE @\$5.50	NOT NECESSARY	16.50	-
1	FRONT BUMPER	DENTED / DEFORMED	785.40	741.12
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	357.20	-
1	FRONT BUMPER SIDE RETAINER	NECESSARY	32.20	32.20
	LESS 20% DISCOUNT		-315.30	-227.70
			1,261.20	910.82
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	40.00
			50.00	40.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		650.00	250.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.	NOT NECESSARY	60.00	-
	SPRAY PAINTING.		480.00	300.00
			1,250.00	570.00
GRAND TOTAL			2,561.20	1,520.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FCI18015593/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.