

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

Not Authorized
LHL
2/5/18
LHL
6/9/18
Gdy.

ABWIN 諭輝

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 05/09/2018
TP Vehicle No. : GBG-1493-T
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

Owner : SENTOSA DEVELOPMENT CORPORATION
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5083736033-01
Vehicle No. : RU -3720-L
Make & Model : VOLVO B7RLE

Accident Date: 21/08/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAIL GATE LID WITH FORM <i>Dis</i>	\$3,949.24	✓
2	TAIL GATE LID ABSORBER STAY <i>Scrap/turn</i>	\$498.58	✓
2	TAILGATE LID HINGE <i>11</i>	\$442.30	X
1	TAILGATE LID LOCK ASSY <i>JM</i>	\$399.15	✓
1	TAILGATE LID LOCK OUTER OPENING <i>11</i>	\$292.12	X
1	TAIL GATE LID EMBLEM "VOLVO" <i>me</i>	\$185.90	✓
1	TAIL GATE LID OUTER PULL HANDLE <i>11</i>	\$129.33	X
1	RH CORNER PANEL GARNISH <i>11</i>	\$285.60	X
1	LH CORNER PANEL GARNISH <i>11</i>	\$285.60	X
1	REAR LICENCE PLATE LAMP <i>me</i>	\$92.29	✓
1	TAILLAMP RH <i>11</i>	\$680.90	X
1	TAILLAMP LH <i>11</i>	\$680.90	X
1	REAR BUMPER <i>Dis</i>	\$2,149.29	✓
1	REAR BUMPER REFLECTOR RH <i>11</i>	\$285.90	X
1	REAR BUMPER REFLECTOR LH <i>11</i>	\$285.90	X
1	REAR END PANEL <i>MS</i>	\$980.60	X
1	REAR END PANEL TOP GARNISH <i>MS</i>	\$398.60	X
1	REAR BUMPER REINFORCEMENT WITH STAY <i>BY</i>	\$1,419.49	✓
1	CRANKSHAFT PULLEY ASSY <i>R</i>	\$1,012.24	X
1	TURBO INTER COOLER HOSE NO.1 <i>11</i>	\$349.12	X
1	AIR CON CONDENSER <i>11</i>	\$4,500.00	X
1	RADIATOR <i>11</i>	\$6,500.00	X
1	TURBO INTER COOLER HOSE NO.2 <i>11</i>	\$299.13	X
1	REAR FLOOR PANEL <i>R</i>	\$3,850.60	X
Sub Total		\$29,952.78	
Discount 10% on Parts		(\$2,995.28)	
		\$26,957.50	

Special Nett

1	TAILGATE LID FRAME, ROD & LEVER <i>BY</i>	\$1,200.00	✓
---	---	------------	---

Date : 05/09/2018
 TP Vehicle No. : GBG-1493-T
 To : AIG ASIA PACIFIC INSURANCE PTE LTD
 Attn : Motor Claim Department

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : SENTOSA DEVELOPMENT CORPORATION
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5083736033-01
 Vehicle No. : RU -3720-L
 Make & Model : VOLVO B7RLE

Accident Date: 21/08/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	REAR LICENCE PLATE	SM \$60.00	✓
1	REAR CHASSIS CROSS-MEMBER	1 \$1,250.00	✓
1	REAR ENGINE COMPARTMENT STRUCTION AND FOAM MATERIAL	NS \$1,800.00	✓
1	REAR STICKER "50KM/H"	\$45.00	
1	DRIVE BELT ASSY	\$450.00	
	Sub Total	\$4,805.00	

Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$3,800.00	1500
TO SPRAY PAINT ON AFFECTED AREAS	\$3,500.00	1200
TO CHECK ALL NECESSARY WIRINGS	\$150.00	50
TO APPLY TUFF KOTE	\$150.00	X
TO CHECK LIGHTING AND FOCUS TAILAMP	\$150.00	X
TO TRANSFER REAR WINDSCREEN FITTING	\$380.00	X
TO TRANSFER REAR TAILGATE FITTING	\$380.00	100
TO DETACH & RENEW REVERSE SENSOR	\$150.00	X
Sub Total	\$8,660.00	

Sub Total \$40,422.50

GST 7% \$2,829.58

Total \$43,252.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: