

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHC2611M

DATE: 27. Aug. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 26. Aug. 2018

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover ✓			\$1,052.20
1	Front Bumper Sponge ?			\$142.20
1	Front Bumper Reinforcement ?			\$526.10
10	Front Bumper Clips ✓		\$2.20	\$22.00
1	Front Bumper Grille (LH) ✕			\$285.50
1	Front Bumper Bracket Top (LH) ?			\$22.40
1	Front Bumper Side Bracket (LH) ?			\$14.30
1	Headlamp Support Panel?			\$1,067.50
1	Headlamp (LH) ✓			\$1,388.00
1	Front Fender (LH) ✓			\$619.00
1	Front Fender Shield (LH) ✕			\$169.80
1	Front Wheel Cover (LH) ✕			\$150.70
	<b>SUB TOTAL</b>			<b>\$5,459.70</b>
	<b>LESS 20%</b>			<b>\$1,091.94</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$4,367.76</b>
				\$-
	<b>Labour Charge</b>			
1	Panel Beating			<del>400</del> \$500.00
1	Spray Painting Charge			<del>400</del> \$500.00
1	Tuff Kote			20 \$50.00
1	Wiring Charge			20 \$50.00
	<b>TOTAL LABOUR</b>			<b>\$1,100.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$5,467.76</b>
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

**TOTAL LABOUR**

**ESTIMATE TOTAL**

Ka hui LKK

28/8/18 10/10/18

3 Days

P14

Before Paint photo

Larry Ng