

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 8039S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER (CONSISTENT)	BENT	1,108.60	1,108.60
1	FRONT FENDER DUST COVER (CONSISTENT)	SERVICEABLE	316.00	-
1	FRONT BUMPER (CONSISTENT)	SERVICEABLE	1,613.70	-
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	DISTORTED	69.00	69.00
1	FRONT BUMPER FOG LAMP (CONSISTENT)	CUT	578.00	578.00
1	FRONT BUMPER FOG LAMP GARNISH (CONSISTENT)	SERVICEABLE	262.00	-
1	FRONT HEAD LAMP (CONSISTENT)	CUT	1,654.00	919.20
1	FRONT KNUCKLE ARM (CONSISTENT)	SERVICEABLE	897.20	-
1	FRONT WHEEL BEARING (CONSISTENT)	NOT NECESSARY	467.90	-
1	FRONT SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	965.70	-
1	FRONT LOWER ARM (CONSISTENT)	SERVICEABLE	857.80	-
1	ALLOY RIM (CONSISTENT)	TO REPAIR SEE LABOUR	1,260.00	-
	LESS 5% DISCOUNT		-502.50	-133.74
			9,547.40	2,541.06
	LABOUR			
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,PANEL BEAT AND ALIGN THE NECESSARY AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF ALLOY RIM.		700.00	400.00
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		600.00	450.00
	TO REPLACE AND INSTAL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR.	NOT NECESSARY	200.00	-
	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT.		80.00	60.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		180.00	30.00
	TO REPLACE ALLOY RIM & PERFORM WHEEL ALIGNMENT.		40.00	20.00
			1,850.00	980.00
	GRAND TOTAL		11,397.40	3,521.06

RECOMMENDED COST OF LUMP SUM REPAIRS	2,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM18015636/Kga3q2





Report Ref No. CC4/ASM18015636/Kga3q2

KONG SENG CHEONG

Licensed Appraiser