



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18015636/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CYNTHIA LOH

Date : 29-07-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 3423L	Veh. Inspected	SKQ 8039S
Policy No.	GA082628/1	Coverage (\$)	0.00
Claim No.	S8M00TGE	Excess (\$)	0.00
Assign From		Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model	VOLVO S60 D2 (A)	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	YV1FS84ABF2350416	Colour	METALLIC DARK GREY
Odometer	92848	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R17	MICHELIN	8 mm
L/H Front Tyre	235/45 R17	MICHELIN	8 mm
R/H Rear Tyre	235/45 R17	MICHELIN	8 mm
L/H Rear Tyre	235/45 R17	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/08/2018	Inspection Date	28/08/2018
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------