

SINCE

REF:

AXA

U

B3731M

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ4433B

Yr Regn:

11 Jul 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C.

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

038402

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

6K81005938

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

30-08-18

Survey held at

w/s

10AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

04/9 Coating separate from repair bill

L/S - \$2350+ (Red: \$2063.60/47.1%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10

Sin Ming AutoCare Singapore 575721

Tel No. : 6452 6657 Fax No. : 6451 4618

E-Mail : autosoon1@gmail.com

Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

SUNRANK

BLK 612B, PUNGGOL DRIVE #12-885

SINGAPORE 822612

Contact : 9821 7529

Estimate : ES000285

Date : 25/08/2018

Vehicle Num. : SLQ 4433 B

Make/Model : HONDA SHUTTLE 1.5G CVT-11.07.2017

Chassis/Eng# : GK81005938/L15B3536978

Accident Date : 25/08/2018

Claim No. :

Reference : TP/06/08/18

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	Rear tail gate assy		1,190.00
2.	1	Rear tail gate emblem		68.00
3.	1	Rear tail gate name badge		38.00
4.	1	Rear bumper facial assy		1,150.00
5.	8	Rear bumper facial clip	4.00	32.00
6.	1	Rear end panel		489.00

List Total S\$:

20.00% Discount S\$:

2,967.00
593.40
2,373.60

LABOUR :

1	To supply windshield sealant and dam rubber in repair	100	150.00	150.00
1	To remove windshield to facilitate tail gate replacment	100	150.00	150.00
1	To rewire damaged section and transfer wire harness	30	80.00	80.00
1	To supply reverse sensor	1	250.00	250.00
1	To remove tail gate spoiler, wiper and lock attachment trims, boards and transfer to new tail gate in repair	60	150.00	150.00
1	To putty and respray above mentioned panels and bumper	400	680.00	680.00
1	To remove/replace tail gate, panel beat damaged section and refix/realign tail gate and bumper in repair	300	580.00	580.00
1	To reseal new paint with ceramic coating by specialist	?	580.00	580.00

Labour Total S\$:

2,040.00

AutoSoon Pte Ltd

3 Days.
Lumpsum repair.
After repair photos.
Gino Qiang
82860282
30/8/18

Total S\$: 4413.60
GST @ 7% S\$: 308.95
Amount Due S\$: 4722.55

Link Auto Consultants hence notify the Repairer of the following:
• Resurvey before/after spray painting
• 2nd survey on damaged part(s) during resurvey
• Parts are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

INVOICE

BILL TO :

Name : Soon
Contact Number : 9635 1683
Company : Auto Soon Pte Ltd
Address : Blk 176 Sin Ming Drive
 #01-10/19, Sin Ming Autocare
 Singapore 575721

DATE : 31/8/2018
INVOICE : M1808065

Payment Mode : Cash

DESCRIPTION	UNIT	QTY	AMOUNT (\$)
Recoat Rear Bumber for SLQ 4433 B	500.00	1.00	500.00

Total :	\$	500.00
Paid :	\$	500.00

* Please register your warranty online to be effective within 14 days @ <http://www.ceramicpro.com.sg/warranty-register/> Ceramic PRO
Prestige card will be mailed to the address provided on warranty registration

Notes for new application / Re-application / Rejuvenate

Keep the surface dry. Dab the surface dry with a lightly damp Microfiber towel. Wash with quality shampoo and dry with clean chamois/Microfiber towel. Remove any contaminants promptly with proper method. Maintain the Nano-Hairs by applying Ceramic Pro SPORT once every 3 month or surface is losing its hydrophobic. Contact us immediately to avoid unnecessary cost for re-application if there are contaminants that cannot be cleaned off with shampoo. Do not use Shampoo for the Next 3 days. Apply a Layer of Ceramic PRO SPORT after the 3rd day of treatment.

9 Yishun Industrial Street 1 #01-69/70 North Spring Bizhub Singapore 768163



QUOTATION

BILL TO :

Name : TAY HOCK KEAT
Contact Number :
Vehicle Make/Model/Colour : HONDA SHUTTLE GREY
Vehicle Registration Number : SLQ 4433 B

DATE : 27/8/2018
QUOTATION : Q 1808061
VALID : 30 DAYS

DESCRIPTION	AMOUNT (SGD)
Recoat Rear Bumper	478.80
Invoice paid for initial application - Date : 20-7-17 Invoice : 175861 Warranty - 20174178 Package - Advance Comprehensive	

ESTIMATE : \$ 478.80

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18015639/Gub3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: XINYOU

Date : 31-10-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7392E	Veh. Inspected	SLQ 4433B
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00TEW	Excess (\$)	0.00
Assign From	XINYOU	Assign Date	30/08/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81005938	Colour	SILVER
Odometer	038402	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/08/2018	Inspection Date	30/08/2018
Survey held at	AUTOSOON PTE LTD BLK 176 SIN MING DRIVE #01-10 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4433B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAIL GATE ASSY (CONSISTENT)	BUCKLED	1,190.00	1,190.00
1	REAR TAIL GATE EMBLEM (CONSISTENT)	NECESSARY	68.00	68.00
1	REAR TAIL GATE NAME BADGE (CONSISTENT)	NECESSARY	38.00	38.00
1	REAR BUMPER FACIAL ASSY (CONSISTENT)	CUT	1,150.00	1,150.00
8	REAR BUMPER FACIAL CLIP @ \$4.00 (CONSISTENT)	NECESSARY	32.00	32.00
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	489.00	-
	LESS 20% DISCOUNT		-593.40	-495.60
			2,373.60	1,982.40
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
			250.00	-
	<u>LABOUR</u>			
	TO SUPPLY WINDSHIELD SEALANT AND DAM RUBBER IN REPAIR.		150.00	100.00
	TO REMOVE WINDSHIELD TO FACILITATE TAIL GATE REPLACEMENT.		150.00	100.00
	TO REWIRE DAMAGED SECTION AND TRANSFER WIRE HARNESS.		80.00	30.00
	TO REMOVE TAIL GATE SPOILER, WIPER AND LOCK ATTACHMENT TRIMS, BOARDS AND TRANSFER TO NEW TAIL GATE IN REPAIR.		150.00	60.00
	TO PUTTY AND RESPRAY ABOVE MENTIONED PANELS AND BUMPER.		680.00	400.00
	TO REMOVE / REPLACE TAIL GATE, PANEL BEAT DAMAGED SECTION AND REFIX / REALIGN TAIL GATE AND BUMPER IN REPAIR.		580.00	300.00
			-	-
			-	-
			-	-
			1,790.00	990.00
	GRAND TOTAL		4,413.60	2,972.40

Report Ref No. CC4/ASM18015639/Gub3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,350.00
---	--	--	----------

Report Ref No. CC4/ASM18015639/Gub3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.