

Torque 5 Pte Ltd (Co.Reg.No:201313221G)

No. 8 Kaki Bukit Ave 4,, #01-50

Singapore 415875

Tel: 64524457 Fax: 64524584 Email: sam.chang@torque5.com

INSURER: **FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00005147-01	Date of Loss:	25/08/2018
Vehicle Reg. No.:	SDQ8898L	Driveable?	
Driver Age/Info:	26 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LUI YUE CHOON		
Driver:	LUI YAN XUN SEAN		
Make/Model:	MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)	Vehicle Reg. Date:	22/01/2015
Vehicle Colour:	BLACK		
Engine No:	PY20463034	Chassis No:	JM6GJ1031F0146782
Odometer:	57007 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO ATTACHED		
Remarks:	VEHICLE CURRENTLY IN OUR WORKSHOP. KINDLY MAKE NECESSARY ARRANGEMENT. THANK YOU.		
Present Location:	TORQUE 5 PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	1,141.70
Miscellaneous Items	90.00
Labour	1,120.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,351.70
+ GST 7.00% (S\$)	164.62
Nett Amount (S\$)	2,516.32

This claim is handled by: STEPHANIE TEO WAN TINGGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2018)
Parts: 143 MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDQ8898L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper / <i>QC</i>	0.00	0.00	*420.00 F
2	1		*Front bumper retainer (LH) / <i>ABC</i>	0.00	0.00	*11.50 F
3	1		*Front bumper retainer (RH) / <i>?</i>	0.00	0.00	*11.50 F
4	1		*Front bumper reinforcement / <i>?</i>	0.00	0.00	*189.00 F
5	1		*Front bumper sponge / <i>?</i>	0.00	0.00	*57.50 F
6	2		*Front bumper parking sensor / <i>DAM</i>	0.00	0.00	*172.00 F
7	1		*Front bumper towing cap / <i>cut</i>	0.00	0.00	*13.80 F
8	1		*Front bumper lower grille / <i>?</i>	0.00	0.00	*40.00 F
9	1		*Radiator grille / <i>UPA</i>	0.00	0.00	*57.00 F
10	2		*Radiator chrome / <i>UPA</i>	0.00	0.00	*149.40 F
11	1		*Radiator grille emblem - logo / <i>ABC</i>	0.00	0.00	*20.00 F
Total Parts (S\$)						1,141.70

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Front bumper clip set	45.00
2	1	Front number plate casing	45.00
Sub Total (S\$)			90.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove and refit front bumper sensor	New	40.00
2	To apply undercoating on affected area	New	40.00
3	To check wiring and lighting system	New	40.00
4	To repair, replace and realign damage areas	New	500.00
5	To spray painting on affected areas	New	500.00
Gross Labour Cost (S\$)			1,120.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

3 Days.
part by part.
before paint photos.

Excess \$600

Not Authorized.

Gene Corp. 82880282

28/8/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: