

Surveyor
Merimen

From (Person):

Guo Qiong
Josey Koh

ASSIGNMENT (Office)

of FWD

Date/Time: 27/8/18 @ 4:01pm

Estimated Cost:

Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDQ 8898 L

Insured:

at Workshop m/s

Torque 5

Tel:

6452 4157

of

No. 8 Kaki Bkt Ave 4 # 01-50

Policy No:

PNPV2017-00005147-01

Claim No:

1201800010737

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A.

25/8/18

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:02am 28/8/18

Person Contacted:

Stephanie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SDQ 8898 L-X

29/8/18

Revert via merimen

29/8/18

Rece approved \$1711.70 from Josey via merimen

29/8/18

Informed Stephanie c/A ex \$600 by email

31/8/18

Final fig \$ 2184.35 confirmed (Recd 530, 20/9)

(08/11/13) wof

ASS. REC. BY:

REF: FWD

2417D

ASSIGNMENT

From:

Date:

28/08/2018

Veh No:

SDQ 8898 L Regn: 22 Jan 2015

Estimated Cost:

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Make:

Mazda 6 2.5 c.c. 2488

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

57007

T/Radio: Insured / Std / NI / NA

Eng/No:

JM6GJ1031 F0146782

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

28-08-18

Survey held at

w/s

2:40pm

Des. of Damages: ☒ Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$82K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

11/9/18

Re-confirmed \$1948.95 confirmed by email (Reel 616, 2417D)

RECEIVED 04 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

3/9 - typist

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

200

Transportation:

50

S + RS, \$

50

Photos

10

Others

TOTAL

310

Report Format :

merimen

Lump Sum / I.B.I. (\$

1948.95)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS/FWD18015648/Gvd3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 28-08-2018	
		Code : FWD	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SDQ 8898L
Policy No.	PNPV2017-00005147-01	Coverage (\$)	0.00
Claim No.	1201800010737	Excess (\$)	600.00
Assign From	MERIMEN (JOSEY LOH)	Assign Date	28/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/08/2018	Inspection Date	28/08/2018
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2018 Sendback Est	27 Aug 2018 15:28 S\$2,351.70	27 Aug 2018 16:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: LUI YUE CHOON , ID: S0052417D	
Vehicle Reg. No.: SDQ8898L	Date of Loss: 25/08/2018 15:00 - :59 [43 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 1201800010737	Policy/Cover Note No.: PNPV2017-00005147-01 (Comprehensive)
	Excess: S\$600.00
Repairer: Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457	
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2018]	
Driver/Custodian: LUI YAN XUN SEAN (26 / Male), NRIC: S9136060H, Tel: +6598362992	

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SDQ8898L (1201800010737)

OD

Aug 25 2018 3:00PM

[LUI YUE CHOON]

Torque 5 Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 03/09/2018 15:53 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2184.35) - SDQ8898L - Claim Handler: Josey Loh

Approved:2184.35.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Josey Loh	Date: 03 Sep 2018
<u>Preliminary Advice</u>	

Vehicle No	: SDQ8898L	Accident Date	: 25/08/2018
Make	: MAZDA 6	Policy No.	: PNPV2017-00005147-01
Assignment Date	: 27/08/2018	Excess	: S\$600.00
Date of Inspection	: 28/08/2018	Est. Duration of Repair	: 3.00
Inspection At	: TORQUE 5 PTE LTD (KAKI BUKIT) NO. 8 KAKI BUKIT AVE 4,, #01-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,714.35
Revised Amount	:S\$	2,184.35
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,184.35
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	60,800.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,200.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 29 August 2018 5:15 PM
To: assessment@torque5.com
Cc: SUR
Subject: SDQ 8898L-DOA: 25/8/2018 (FWD OD)

Dear Stephine,

As instructed by our client , please proceed to repair the insured vehicle **SDQ 8898L (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SDQ8898L (1201800010737)

OD

Aug 25 2018 3:00PM

[LUI YUE CHOON]

Torque 5 Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 29/08/2018 16:54 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1711.70) - SDQ8898L - Claim Handler: Josey Loh

Approved:1711.70.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Josey Loh	Date: 29 Aug 2018
<u>Preliminary Advice</u>	

Vehicle No	: SDQ8898L	Accident Date	: 25/08/2018
Make	: MAZDA 6	Policy No.	: PNPV2017-00005147-01
Assignment Date	: 27/08/2018	Excess	: S\$600.00
Date of Inspection	: 28/08/2018	Est. Duration of Repair	: 3.00
Inspection At	: TORQUE 5 PTE LTD (KAKI BUKIT) NO. 8 KAKI BUKIT AVE 4,, #01-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,351.70
Revised Amount	:S\$	1,385.20
Check Items (Estimated)	:S\$	326.50
Total	:S\$	1,711.70
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	60,800.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,200.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2417D
Vehicle Details	
Vehicle No.:	SDQ8898L
Vehicle to be Exported:	No
Intended De-registration Date:	28 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR HID
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	PY20463034
Chassis No.:	JM6GJ1031F0146782
Maximum Power Output:	138.0 kW (185 bhp)
Open Market Value:	\$21,316.00
Original Registration Date:	22 Jan 2015
First Registration Date:	22 Jan 2015
Transfer Count:	1
Actual ARF Paid:	\$16,843.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2025
PARF Rebate Amount:	\$12,632.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,289.00
COE Rebate Amount:	\$48,168.00
Total Rebate Amount:	\$60,800.00

The information contained herein is correct as at 28 Aug 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2417D

Vehicle Details

Vehicle No.:	SDQ8898L
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.5L SP6EAT SR HID
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	PY20463034
Chassis No.:	JM6GJ1031F0146782
Maximum Power Output:	138.0 kW (185 bhp)
Open Market Value:	\$21,316.00
Original Registration Date:	22 Jan 2015
First Registration Date:	22 Jan 2015
Transfer Count:	1
Actual ARF Paid:	\$16,843.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2025
PARF Rebate Amount:	\$12,632.00

Intended COE Rebate Details

COE Expiry Date:	21 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,289.00
COE Rebate Amount:	\$48,189.00
Total Rebate Amount:	\$60,821.00

The information contained herein is correct as at 27 Aug 2018

OK

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 25 / 8 / 2018 (dd/mm/yy) Time of Accident: 15 : 30 (24-HR-FORMAT)

Vehicle No.: SDA8898L Vehicle Make & Model: Mazda 6 2.5

Exact location of Accident: Slip road towards PIE (Lorong 6 Tanjong) and CTE

Policyholder's Name / IC No.: Lui Yue Choon 500524170

Driver's Name / IC No.: Lui Yan Xun Sean 59136060H (As Above) ☐

Driver's Contact No.: 98362992 Company Contact No.: _____

Driver's Address: BK 412 Serangoon Central #11-341 5550412

Insurance Company: FWD Email address (if any): seanlyx91@gmail.com

Relationship between Owner & Driver: (Please CIRCLE one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please TICK one only)

☒ Own Insurance / ☐ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

☒ Private use / ☐ Work purpose

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

No. of Passengers (Including Driver): 1

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☐ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: Poh Yong Wei Bernard 588123324 Vehicle No.: SL25222P

Driver's Contact No.: 90176051 Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No.: _____

Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No.: _____

Preferred Workshop Name: _____ Contact No.: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

vehicle A

On the stated date and venue, I was travelling straight along the slip road towards CTE / PIE (Lorong 6 Tan Payoh) on the right lane. Suddenly, vehicle B jammed break and I hit onto the rear of vehicle B. The reason for Vehicle B to jam break is because vehicle C suddenly cut into our lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Torque 5 Pte Ltd (Co.Reg.No:201313221G)

No. 8 Kaki Bukit Ave 4, #01-50

Singapore 415875

Tel: 64524457 Fax: 64524584 Email: sam.chang@torque5.com

INSURER:

FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00005147-01	Date of Loss:	25/08/2018
Vehicle Reg. No.:	SDQ8898L	Driveable?	
Driver Age/Info:	26 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LUI YUE CHOON		
Driver:	LUI YAN XUN SEAN		
Make/Model:	MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)	Vehicle Reg. Date:	22/01/2015
Vehicle Colour:	BLACK	Chassis No:	JM6GJ1031F0146782
Engine No:	PY20463034		
Odometer:	57007 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO ATTACHED		
Remarks:	VEHICLE CURRENTLY IN OUR WORKSHOP. KINDLY MAKE NECESSARY ARRANGEMENT. THANK YOU.		
Present Location:	TORQUE 5 PTE LTD (KAKI BUKIT)		

COST OF CLAIMS	Amount
Parts	1,141.70
Miscellaneous Items	90.00
Labour	1,120.00
Paintwork Labour	0.00
Towing	0.00
	2564.95
Gross Total (S\$)	2,351.70
+ GST 7.00% (S\$)	164.62
Nett Amount (S\$)	2,516.32

This claim is handled by: STEPHANIE TEO WAN TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2018)
Parts: 143 MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDQ8898L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper / <i>2C</i>	0.00	0.00	*420.00 F
2	1		*Front bumper retainer (LH) / <i>MBL</i>	0.00	0.00	*11.50 F
3	1		*Front bumper retainer (RH) / <i>MBL</i>	0.00	0.00	*11.50 F
4	1		*Front bumper reinforcement / <i>BT</i>	0.00	0.00	*189.00 F
5	1		*Front bumper sponge / <i>CRA</i>	0.00	0.00	*57.50 F
6	2		*Front bumper parking sensor / <i>DM (1pc)</i>	0.00	0.00	*172.00 F
7	1		*Front bumper towing cap / <i>MBL</i>	0.00	0.00	*13.80 F
8	1		*Front bumper lower grille / <i>CRA</i>	0.00	0.00	*40.00 F
9	1		*Radiator grille / <i>CRA</i>	0.00	0.00	*57.00 F
10	2		*Radiator chrome / <i>CRA</i>	0.00	0.00	*149.40 F
11	1		*Radiator grille emblem - logo / <i>MBL</i>	0.00	0.00	*20.00 F
Total Parts (\$\$)						1,141.70

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Front bumper clip set	45.00
2	1	Front number plate casing	45.00
Sub Total (S\$)			90.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove and refit front bumper sensor	New	40.00
2	To apply undercoating on affected area	New	40.00
3	To check wiring and lighting system	New	40.00
4	To repair, replace and realign damage areas	New	500.00
5	To spray painting on affected areas	New	500.00
Gross Labour Cost (S\$)			1,120.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 Days.
part by part.
before paint photos.
Excess \$600
Not Authorized.
One copy. 82880282
28/8/18.

[Signature]
28/8/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2018)
 Parts: 143 MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SDQ8898L)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper / <i>de</i>	0.00	0.00	*420.00 F
2	1		*Front bumper retainer (LH) / <i>Yabc</i>	0.00	0.00	*11.50 F
3	1		*Front bumper retainer (RH) / <i>RT</i>	0.00	0.00	*11.50 F
4	1		*Front bumper reinforcement / <i>R-RT</i>	0.00	0.00	*189.00 F
5	1		*Front bumper sponge / <i>R-RT</i>	0.00	0.00	*57.50 F
6	2		*Front bumper parking sensor / <i>DM</i>	0.00	0.00	*172.00 F
7	1		*Front bumper towing cap / <i>W</i>	0.00	0.00	*13.80 F
8	1		*Front bumper lower grille / <i>CA</i>	0.00	0.00	*40.00 F
9	1		*Radiator grille	0.00	0.00	*57.00 F
10	2		*Radiator chrome / <i>CA</i>	0.00	0.00	*149.40 F
11	1		*Radiator grille emblem - logo / <i>WBC</i>	0.00	0.00	*20.00 F
Total Parts (S\$)						1,141.70

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Supplementary Item

Radiator Grille Top Garnish

1 pc \$138.00 / CA

Front Reinforcement Garnish

1 pc \$40.25 / CA

Logo Garnish

1 pc \$35 / WBC.

Gmo Aul.

30/8/18

parts = 1504.35

S/N = 90

Labour = 590

P+S+L = 2184.35

confirmed \$2184.35 COR.

Gmo Aul.

21/8/18.

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Front bumper clip set	45.00
2	1	Front number plate casing	45.00
Sub Total (S\$)			90.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove and refit front bumper sensor	New	40.00
2	To apply undercoating on affected area	New	40.00
3	To check wiring and lighting system	New	40.00
4	To repair, replace and realign damage areas	New	500.00
5	To spray painting on affected areas	New	500.00
Gross Labour Cost (S\$)			1,120.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 Days.

part by part.

before paint photos.

Excess \$600

Not Authorized.

Gene Corp. 82880282

28/8/18.

Torque 5 Pte Ltd (Co.Reg.No:201313221G)

No. 8 Kaki Bukit Ave 4,, #01-50

Singapore 415875

Tel: 64524457 Fax: 64524584 Email: sam.chang@torque5.com

(SUPPLEMENTARY)**INSURER: FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00005147-01	Date of Loss:	25/08/2018
Vehicle Reg. No.:	SDQ8898L	Driveable?	
Driver Age/Info:	26 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LUI YUE CHOON		
Driver:	LUI YAN XUN SEAN		

Make/Model:	MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)	Vehicle Reg. Date:	22/01/2015
Vehicle Colour:	BLACK	Chassis No:	JM6GJ1031F0146782
Engine No:	PY20463034		
Odometer:	57007 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	4

Description of Accident/Loss	REFER TO ATTACHED
Present Location:	TORQUE 5 PTE LTD (KAKI BUKIT)

COST OF CLAIMS	Amount
Parts	213.25
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	213.25
+ GST 7.00% (S\$)	14.93
Nett Amount (S\$)	228.18
+ Previous Estimates (S\$)	2,516.32
Claim Total (S\$)	2,744.50

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2018)**Parts:** 143 MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Torque 5 Pte Ltd/SDQ8898L/30/08/2018 16:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Radiator grille top garnish (4t	0.00	0.00	*138.00 F
2	1		*Front reinforcement garnish (2A	0.00	0.00	*40.25 F
3	1		*Logo garnish WEC	0.00	0.00	*35.00 F
Total Parts (S\$)						213.25

F=Franchise part.

Torque 5 Pte Ltd/SDQ8898L/30/08/2018 16:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Torque 5 Pte Ltd/SDQ8898L/30/08/2018 16:43. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 11 September 2018 8:27 AM
To: assessment (assessment@torque5.com)
Cc: SUR; sam.chang (sam.chang@torque5.com); claims (claims@torque5.com)
Subject: RE: SDQ 8898 L - Finalisation And After Repair Photo.

Dear Lucas,

Re-confirmed \$1948.95 before excess \$600

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 10 September, 2018 3:55 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: FW: SDQ 8898 L - Finalisation And After Repair Photo.

CS/FWD18015648/Gvd3

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Monday, 10 September, 2018 2:30 PM
To: Admin A <admin-a@lkkauto.com>
Cc: 'sam.chang' <sam.chang@torque5.com>; 'claims' <claims@torque5.com>; 'assessment' <assessment@torque5.com>
Subject: SDQ 8898 L - Finalisation And After Repair Photo.

Dear All,

Please kindly check the attach and conform finalise amount ASAP.

Thanks.

Warmest Regards,

Lucas Chow

Assessor | Motor Claims Department



TORQUE 5
GROUP

Hotline (65) 6452 4457 | Fax (65) 6452 4584
Mobile (65) 8131 6518
Email lucas.chow@torque5.com
Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875
www.torque5.com



REVIVE YOUR DRIVE

SERVICING AND MAINTENANCE	AIR-CON AND ELECTRICAL REPAIRS	ENGINE OVERHAULS	TOWING SERVICES	ACCIDENT REPAIRS



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2018 Sendback Est	27 Aug 2018 15:28 S\$2,351.70	27 Aug 2018 16:01 Edit Adj Rpt	S\$1,948.95 Edit Estimates	S\$1,948.95 View Rpt		Pending for Survey Report Cancel Case
Supp #1	30 Aug 2018 16:42	30 Aug 2018 16:43 S\$213.25	30 Aug 2018 16:43			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	LUI YUE CHOON, ID: S0052417D		
Vehicle Reg. No.:	SDQ8898L	Date of Loss:	25/08/2018 15:00 - :59 [43 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800010737	Policy/Cover Note No.:	PNPV2017-00005147-01 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/09/2018]		
Driver/Custodian:	LUI YAN XUN SEAN (26 / Male), NRIC: S9136060H, Tel: +6598362992		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- FWD_SG (03/09/2018): Alert - Adj Mandate Approved (S\$2184.35) - SDQ8898L - Claim Handler: Josey Loh
- FWD_SG (29/08/2018): Alert - Adj Mandate Approved (S\$1711.70) - SDQ8898L - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SDQ8898L (1201800010737)

OD

Aug 25 2018 3:00PM

[LUI YUE CHOON]

Torque 5 Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	27/08/18 15:28	Torque 5 Pte Ltd (Kaki Bukit) Repairer Estimates	Load HTM	
2	30/08/18 16:43	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/18 15:09	Adjuster Immediate Advice	Load HTM	
2	03/09/18 11:52	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder		Thumbnail	Print
1	29/08/18 15:01	LKK Auto Consultants Pte Ltd (HQ) General View	Load JPG	☒
2	29/08/18 15:01	General View	Load JPG	☒
3	29/08/18 15:01	General View	Load JPG	☒
4	29/08/18 15:01	General View	Load JPG	☒
5	29/08/18 15:01	General View	Load JPG	☒
6	29/08/18 15:01	General View	Load JPG	☒
7	29/08/18 15:01	General View	Load JPG	☒
8	29/08/18 15:01	General View	Load JPG	☒
9	29/08/18 15:01	General View	Load JPG	☒
10	29/08/18 15:01	General View	Load JPG	☒
11	29/08/18 15:01	General View	Load JPG	☒
12	29/08/18 15:01	General View	Load JPG	☒
13	29/08/18 15:01	General View	Load JPG	☒
14	29/08/18 15:01	General View	Load JPG	☒
15	29/08/18 15:01	General View	Load JPG	☒
16	29/08/18 15:01	General View	Load JPG	☒
17	29/08/18 15:01	General View	Load JPG	☒
18	29/08/18 15:01	General View	Load JPG	☒
19	29/08/18 15:01	General View	Load JPG	☒
20	29/08/18 15:01	General View	Load JPG	☒
21	29/08/18 15:01	General View	Load JPG	☒
22	29/08/18 15:01	General View	Load JPG	☒
23	29/08/18 15:01	General View	Load JPG	☒
24	03/09/18 09:48	Dismantled Parts	Load JPG	☒
25	03/09/18 09:48	Dismantled Parts	Load JPG	☒
26	03/09/18 09:48	Dismantled Parts	Load JPG	☒
27	03/09/18 09:48	Dismantled Parts	Load JPG	☒
28	03/09/18 09:48	Dismantled Parts	Load JPG	☒
29	03/09/18 09:48	Dismantled Parts	Load JPG	☒
30	03/09/18 09:48	Dismantled Parts	Load JPG	☒
31	03/09/18 09:48	Dismantled Parts	Load JPG	☒
32	03/09/18 09:48	Dismantled Parts	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
33	03/09/18 09:48	Dismantled Parts	Load JPG	☒
34	03/09/18 09:48	Dismantled Parts	Load JPG	☒
35	03/09/18 09:48	Dismantled Parts	Load JPG	☒
36	03/09/18 09:48	Dismantled Parts	Load JPG	☒
37	03/09/18 09:48	Dismantled Parts	Load JPG	☒
38	03/09/18 09:48	Dismantled Parts	Load JPG	☒
39	03/09/18 09:48	Dismantled Parts	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/18 15:00	MARK ESTIMATE	Load PDF	
2	03/09/18 11:37	SUPPLEMENTARY	Load PDF	
3	03/09/18 11:47	1ST MARK ESTIMATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	27/08/18 09:26	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	27/08/18 09:26	Accident Photo	Load JPG	☒
2	27/08/18 09:26	Accident Photo	Load JPG	☒
3	27/08/18 09:26	Accident Photo	Load JPG	☒
4	27/08/18 09:26	Accident Photo	Load JPG	☒
5	27/08/18 09:26	Accident Photo	Load JPG	☒
6	27/08/18 09:26	Accident Photo	Load JPG	☒
7	27/08/18 09:26	Accident Photo	Load JPG	☒
8	27/08/18 09:26	Accident Photo	Load JPG	☒
9	27/08/18 09:26	Accident Photo	Load JPG	☒
10	27/08/18 09:26	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	27/08/18 09:26	Sketch Plan	Load JPG	☒
2	27/08/18 09:26	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18015648/GVD3E2

Date: 14/09/2018

REFERENCE

Insured/Claimant: LUI YUE CHOON Policy No: PNPV2017-00005147-01
Date of Loss: 25/08/2018 Nature of Claim: OD Claim No: 1201800010737

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDQ8898L
Make & Model: MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A) Engine No: PY20463034
Reg. Date: 22/01/2015 (Man. Year: 2014) Chassis No: JM6GJ1031F0146782
Colour: Black Odometer: 57007 km
Engine Capacity: 2488 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,354.95	1,268.95	86.00	6.35
Miscellaneous Items	90.00	90.00	0.00	0.00
Labour	1,120.00	590.00	530.00	47.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,564.95	1,948.95	616.00	24.02
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	2,564.95	1,348.95	1,216.00	47.41
+ GST 7.00/7.00% (S\$)	179.55	94.43	85.12	47.41
Nett Amount (S\$)	2,744.50	1,443.38	1,301.12	47.41

INSPECTION

Date of Assignment: 27/08/2018 Present Location: Torque 5 Pte Ltd (Kaki Bukit)
Date Inspected: 28/08/2018 Inspected At: Torque 5 Pte Ltd (Kaki Bukit)
No. 8 Kaki Bukit Ave 4., #01-50
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2018)
Parts:	143	MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDQ8898L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Deformed	420.00 F	*420.00 F
2	1		*Front bumper retainer (LH)	Necessary	11.50 F	*11.50 F
3	1		*Front bumper retainer (RH)	Necessary	11.50 F	*11.50 F
4	1		*Front bumper reinforcement	Bent	189.00 F	*189.00 F
5	1		*Front bumper sponge	Cracked	57.50 F	*57.50 F
6	1		*Front bumper parking sensor (2PCS)	Damaged - 1 pc only	172.00 F	*86.00 F
7	1		*Front bumper towing cap	Cut	13.80 F	*13.80 F
8	1		*Front bumper lower grille	Cracked	40.00 F	*40.00 F
9	1		*Radiator grille	Cracked	57.00 F	*57.00 F
10	2		*Radiator chrome	Cracked	149.40 F	*149.40 F
11	1		*Radiator grille emblem - logo	Necessary	20.00 F	*20.00 F
Supplementary #1						
12	1		*Radiator grille top garnish	Cut	138.00 F	*138.00 F
13	1		*Front reinforcement garnish	Cracked	40.25 F	*40.25 F
14	1		*Logo garnish	Necessary	35.00 F	*35.00 F
F=Franchise part.					Total Parts (S\$)	1,354.95 1,268.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front bumper clip set (NECESSARY)	45.00	45.00
2	1	Front number plate casing (BENT)	45.00	45.00
Sub Total (S\$)			90.00	90.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove and refit front bumper sensor	New	40.00	40.00
2	To apply undercoating on affected area	New	40.00	0.00
3	To check wiring and lighting system	New	40.00	0.00
4	To repair, replace and realign damage areas	New	500.00	300.00
5	To spray painting on affected areas	New	500.00	250.00
Gross Labour Cost (S\$)			1,120.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >