

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR IN	NSPECTION REPORT	
FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS3/FCI18015668	3/Gz4d3s2
			Date: 30-08-2018	
THE SE			Code: FCI2	
1.			ars :- (THIRD PARTY CLAIN	
	Insured Veh.	SHC 8767H	Veh. Inspected	FBJ 8484H
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18006067MFSH	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	28/08/2018
2.		Vehicle P	articulars & Condition	
	Make & Model	YAMAHA JUPITER MX	c.c	134
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	MH350C002CK482961	Colour	BLUE
	Odometer	82282 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	70/90R17	MAXXIS	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90-17	MAXXIS	4 mm
	L/H Rear Tyre			mm
4.		Desci	ription of Damages	
	THE VEHICLE SUBODY.	STAINED DAMAGES AT THE	FRONT PORTION AND N/S	
5.		Ger	neral Information	
	Accident Date	09/08/2018	Inspect Date / Time	28/08/2018 (04:20 PM)
	Survey held at	TRIKRISTAL AEROSPACE-	1 KAKI BUKIT AVE 6# 02-35	
	Repairer	-		
			Remarks	

Report Ref No. CS3/FCI18015668/Gz4d3s2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.