

ASS. REC. BY:

REF: CS/FCI18015694/D9d3n2

Special Instruction:

Surveyor

CWS

ASSIGNMENT (Office)

From (Person):

Lurene juw

of

PCI

Date/Time:

28/8/18 @ 4:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 3486B

Insured:

SHA 9218E

at Workshop m/s

Chunni Motor

Tel:

GS425119

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

D18006397 MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/08/2018

CA / REV / REP. / REV 24 HRS

(DS)

29/8/2018

H.O.D. Endorsement:

Date/Time

5:45pm @ 28/8/18

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 3486B - X
	SHA 9218E - X
27/9/18 @ 5:24pm	revised to Lurene by email.


ASSIGNMENT

COE March 2022

Name: _____ Date: _____
 Estimated Cost: _____
 ODI / TP / WS / TP RES / ODI RES / EVA / RV / MV
 Insured Vehicle No: _____
 Insured Vehicle No: _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Est. of Market Value

IDAC Accident Report Consistent? : Yes or No

GIA / PR / SCOR Consistent? : Yes or No

Est. Repairs: 108 days Res: Yes or No

Lump Sum: 20% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8HC 3486B Date: 2014 March
 Type: M/Gar / M/Car / Bus / Van / Lorry / Auto Prime Mover
 Truck / Trailer or

Make: Hyundai I40 CC: 1685
 Color: Blue AC: Insured / F/S / H / H / A
 Cap (Res/Ins): 755652 (Radio: Insured / F/S / H / H / A)
 Eng No: D4FDDU361917
 Chassis: KMHLB41UMBU052624
 Gen. Cond: 6 / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Modi: 8 / SRim / STD A/Rim or

Type Size: F: 205/60 R16
 R: - 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook

Front: R/Bal. 5' min L/Bal. 5' min
 Rear: R/Bal. 5' min L/Bal. 5' min
 D.O.A. 27/08/2018 D.O.I. 29/08/2018
 Survey held at Enunni AMK

Des. of Damages: F/R / Rear / O/S / N/S / U/C / Rooftop or
 O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction:
 First Capital SHH 9218E

25/09/18 Jnanu L/S 10500/- with 10 dgs 8%
 (Red \$ 5754.84, 35%)

RECEIVED 27 SEP 2018

Date/Time, L/S Page 107
 27/9/18 ☐ : Prel. Report
☐ : Final Report
 Date/Time, L/S Page 107

Days Of Repair: 10
 Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Workshop (\$)

Report Format: 74
 Lump Sum / L/S: 10500

Survey Fee: 615.90
 Transportation: 170.90
 50
 50+50
 134
 544



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006397MFSH
Our Ref: CS/FCI18015694/Dqd3

Date: 03 September 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 3486B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/08/2018 at the premises of M/s CHUNNI MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ 16,254.84 .
Revised Estimate Amount	: S\$ 13,134.64 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	27-08-2018	Our Ref No.	D18006397MFSH/)
Accident Date	27-08-2018	Claim Type.	Third Party
Insured Vehicle	SHA9218E	Third Party Vehicle.	SHC3486B
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06,		
Contact Person.	LYNN OR IRENE - 65421726		
Contact No.	64836016/ 0	Fax No.	65426039
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 3 September 2018 5:24 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006397MFSH/1
Attachments: CSFCI18015694Dqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHC 3486B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 28 August 2018 5:46 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006397MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 28 August 2018 4:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006397MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 3486B

MAKE :

MODEL : HYUNDAI i40

DATE : 27.08.2018

TEL : 6542 5119

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>broken</i>		\$	562.30 ✓
	Front Bumper Grille (RH) <i>SLC</i>		\$	40.30 X
	Front Bumper Bracket Top (RH) <i>HN</i>		\$	22.40 X
	Front Bumper Bracket (RH) <i>HN</i>		\$	24.60 X
	Headlamp Support Panel Assy <i>2 broken</i>		\$	1,067.50 2 ✓
	Headlamp (RH) <i>broken</i>		\$	1,388.00 ✓
	Radiator Bracket (RH) <i>HN</i>		\$	6.50 X
	Front Fender (RH) <i>Dented</i>		\$	619.00 ✓
	Front Fender Apron Panel (RH) <i>Dented</i>		\$	1,575.50 ✓ photo
	Front Fender Shield (RH) <i>deformed</i>		\$	169.80 ✓
	Aircon Condenser <i>HN</i>		\$	1,137.35 X
	Front Wheel Rim (RH) <i>2 set</i>		\$	351.90 2 ✓
	Front Wheel Hub Cap (RH) <i>int</i>		\$	150.70 ✓
	Front Wheel Bearing <i>2 Down</i>		\$	258.50 2 ✓
	Front Shock Absorber (Assy) (RH) <i>2 distribute</i>		\$	342.20 2 ✓
	Front Shock Absorber Mounting (RH) <i>HN</i>		\$	75.10 X
	Front Drive Shaft (RH) <i>the distribute</i>		\$	1,069.55 ✓
	Rack & Pinion Assy <i>the distribute</i>		\$	2,184.00 X ✓
	STG Tie End <i>2 distribute</i>		\$	69.50 2 ✓
	Front Suspension Lower Arm (RH) <i>the distribute</i>		\$	715.10 X ✓
	Knuckle Arm (RH) <i>2 distribute</i>		\$	582.95 2 ✓
	Engine Crossmember <i>the distribute</i>		\$	2,236.90 X ✓
	ABS Sensor <i>HN</i>		\$	261.50 X
				13343.40
				10674.72
	SUB TOTAL		\$	14,911.15
	LESS 20%		\$	2,982.23
	DISCOUNTED TOTAL		\$	11,928.92
	Front Tyre (RH) <i>SLC</i>		\$	216.00 Nett X
			\$	216.00
	Labour Charge		\$	1,100.00 500/-
	Panel Beating		\$	900.00 500/-
	Spray Painting Charge		\$	50.00 30/-
	Wiring Charge		\$	50.00 30/-
	Tuff Kote		\$	50.00 HN
	Towing Charge		\$	200.00 180/-
	Remove/Refix Undercarriage (FRT)		\$	120.00 60/-
	FRT Wheel Alignment		\$	480.00 HN
	Diagnostic & Resetting To Erase Fault Code		\$	
	TOTAL LABOUR		\$	2,950.00
	ESTIMATE TOTAL		\$	15,094.92

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

L/S 10500/-

1159.92

13134.64

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 3486 B

Technician:

Mileage: 755652

Time Printed 29.8.18 4:30 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°41'		-3°00' 3°00'
3°55'		-0°19' 5°41'
0°06'		-1°30' 1°30'
19°13'		
18°31'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
3°48'		-3°00' 3°00'
3°58'		-0°19' 5°41'
35°53'		-1°30' 1°30'
8°35'		
12°23'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-4°29'		-3°00' 3°00'
-0°03'		-3°00' 3°00'
10°38'		-3°00' 3°00'
35°59'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°50'		-3°30' 2°30'
-0°03'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-2°13'		-3°30' 2°30'
0°05'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°24'		-3°00' 3°00'
0°02'		-3°00' 3°00'
-0°04'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015694/Dqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9218E	Veh. Inspected	SHC 3486B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006397MFSH/1	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	28/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU052624	Colour	BLUE	
Odometer	755652	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/08/2018	Inspection Date	29/08/2018	
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3486B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	BROKEN	562.30	562.30
1	FRONT BUMPER GRILLE (RH)	SERVICEABLE	40.30	-
1	FRONT BUMPER BRACKET TOP (RH)	NOT NECESSARY	22.40	-
1	FRONT BUMPER BRACKET (RH)	NOT NECESSARY	24.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,067.50	1,067.50
1	HEADLAMP (RH)	BROKEN	1,388.00	1,388.00
1	RADIATOR BRACKET (RH)	NOT NECESSARY	6.50	-
1	FRONT FENDER (RH)	DENTED	619.00	619.00
1	FRONT FENDER APRON PANEL (RH)	DENTED	1,575.50	1,575.50
1	FRONT FENDER SHIELD (RH)	DEFORMED	169.80	169.80
1	AIRCON CONDENSER	NOT NECESSARY	1,137.35	-
1	FRONT WHEEL RIM (RH)	BENT	351.90	351.90
1	FRONT WHEEL HUB CAP (RH)	CUT	150.70	150.70
1	FRONT WHEEL BEARING	DAMAGED	258.50	258.50
1	FRONT SHOCK ABSORBER (ASSY)(RH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	75.10	-
1	FRONT DRIVE SHAFT (RH)	DISTORTED	1,069.55	1,069.55
1	RACK & PINION ASSY	DISTORTED	2,184.00	2,184.00
1	STG TIE END	DISTORTED	69.50	69.50
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	715.10	715.10
1	KNUCKLE AEM (RH)	DISTORTED	582.95	582.95
1	ENGINE CROSSMEMBER	DISTORTED	2,236.90	2,236.90
1	ABS SENSOR	NOT NECESSARY	261.50	-
1	HEADLAMP (LH)(ADDITIONAL)	MOUNTING BROKEN	1,388.00	1,388.00
1	WIPER CONTAINER (ADDITIONAL)	DEFORMED	61.90	61.90
	LESS 20% DISCOUNT		-3,272.21	-2,958.66
			13,088.84	11,834.64
SPECIAL NETT ITEMS				
1	FRONT TYRE (RH)(SN)	SERVICEABLE	216.00	-

Report Ref No. CS/FCI18015694/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			216.00	-
	LABOUR			
	PANEL BEATING.		1,100.00	500.00
	SPRAY PAINTING CHARGE.		900.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	180.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			2,950.00	1,300.00
	GRAND TOTAL		16,254.84	13,134.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,500.00

Report Ref No. CS/FCI18015694/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.