

REF:

Surveyor: NAZ

REF:

MSIG

CC3/MSH18015721/Ndb22

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBC 5076J

Policy No. 28620340MKC

Claims No. 569715

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMB 304J Yr Regn: 13 JUL 201

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN C.C. 10 518

Colour: WHITE A/C: Insured / Std / NI /

Sp. Reading: 469, 644 T/Radio: Insured / Std / NI /

Eng/No: _____

C/No: WMAA22270C7001398

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In O/S / Jammed / Leaked / Burnt or

Brake: In O/S / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 270/70 R 22-5

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 6/6 mm

L/Bal. 5 mm L/Bal. 6/6 mm

D.O.A. 4/8/18 D.O.I. 28/8/18

Survey held at SMART WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

DR REAR, REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>SMB 304J - X</u>
	<u>GBC 5076J - CC3 / MSH16015379 / migh3m2</u>
<u>10/9/18</u>	<u>Sent EST & GIA to Mr Chhin & Librel to create Meriten. claim</u>
<u>19/12/18</u>	<u>FINALIZED LUMP SUM REPAIR \$1750.00 / 1 DAY</u>
	<u>RECEIVED 24 DEC 2018</u>

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS. SI

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others 10

☐ : Weekend (\$ _____)

Report Format: TP

Lump Sum / I.B.I: (\$ 1750)

TOTAL

160

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, September 10, 2018 12:29 PM
To: 'Chhia Nyuk Pui'
Cc: Lionel Tan
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD, DOA: 04/08/2018, SMB 304J (TP VEHICLE), GBC 5076J (OI VEHICLE)
Attachments: SMB 304J EST.pdf; SMB 304J GIA.pdf

Dear Miss Chhia,

Please be informed that we had inspected the vehicle **SMB 304J** at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/08/2018 17:21
Date Of Accident	04/08/2018 00:25
Exact Location Of Accident	MANDAI AVENUE - BS:48141- OPP MANDAI CREMATORIUM &
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMB304J
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MAN
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	DII027592MFBP
Cover Note Number	
Driver	
Name of Driver	CHE MAZLAN BIN HASSAN
Passport No/FIN	G2067254X
Date Of Birth	10/01/1990
Occupation	OUTDOOR
Date Of Driving Pass	27/02/2014
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 6 ANG MO KIO ST 62

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 10

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

MY BUS WAS STATIONARY AT BUS STOP 48141 (OPP MANDAI CREMATORIUM & COLOMBARIUM), CONDUCTING PAX ACTIVITY WHEN A PTE VAN (GBC5076J) GRAZED THE REAR RIGHT PORTION OF MY BUS WHILE THE PTE VAN WAS OVERTAKING MY BUS. NO INJURY REPORTED. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC5076J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FN No.: S83403252

SKETCH PLAN

BNS STOP 48141



① 5MB 304J
② 68C 5076J

MANDAL AVENUE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)

100

Reporting Centre Personnel's Signature
Name: BALQISH

Name: **BALQISH**

0000000000

SMRT Accident Vehicle Repair Estimates


Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB304J
 Ref. No : BUS/08/18/1011
 Reg. Date : 15/08/2018
 Vehicle Type : BUS -12M
 Make : A22MAN
 Model : MAN
 Name of Driver : Che Mazlan Bin Hassan
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 04/08/2018 12:23:00 PM
 Accident Reported Date / Time : 13/08/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : MSIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :

Special Instruction to ARC, if any :

SMB304J - REAR RIGHT PORTION
 GBC5076J (TP) - INSURED WITH MSIG

Prepared Date : 15/08/2018 08:52:14 AM



Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 795.00	0.00
Total Spray Painting Charges	: 524.00	0.00
Total Material Charges	: 1,160.83	1,160.83
Other Charges	: 0.00	0.00
TOTAL	: 2,479.83	0.00
Lum Sum Total	: 2,500.00	0.00
No. of Repair Days	: 2.00	0.00
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	: 28/08/2018 08:52:25 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :
Remarks :

Prepared Date : 28/08/2018 08:52:25 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	0.00
Total Labour	795.00 530	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	524.00	0.00
Total Spray Painting & Panel Beating	524.00 400	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

NAZ LKK
28/8/18 1400
LIS
1 DAY
AFTER REPAIR PHOTO

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
88-25225-6039		6010298	STOP LAMP LED	1	1,141.70	10.00	1,027.53	Replace	Replace	No
4001F09-ACCE5020		6010373	REAR REFLECTOR PANEL RH	1	107.00	10.00	96.30	Replace	Replace	No
	COMMO	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
TOTAL MATERIALS								1,160.83	1,160.83	
TOTAL MATERIALS(Discounted)								1,160.83	1,160.83	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Part 4 - Spare Parts / Material Usage

1. The purpose of this form is to provide a record of the materials used in the repair of the vehicle.

2. The form should be filled out by the person responsible for the repair.

3. The form should be signed by the Surveyor after the repair is completed.

4. The form should be submitted to the appropriate authority for review.

5. The form should be kept on file for future reference.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 22/11/2018

User ID : CatherineLee

Section A - Accident Details


Registration Number	SMB304J
Case Reference Number	BUS/08/18/1011
Registration Date	13/07/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Che Mazlan Bin Hassan
Type of Accident	HEAD TO REAR
Accident Date and Time	04/08/2018 12:23 PM
Accident Reported Date and Time	13/08/2018 4:36 PM
Is Surveyor Required?	Yes
Survey by	MSIG
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	000024097728
Special Instruction to ARC, if any	SMB304J - REAR RIGHT PORTION GBC5076J (TP) - INSURED WITH MSIG
Prepared Date and Time	15/08/2018 8:52 AM
Chassis Number	WMAA22Z0C7001398
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$524.00	\$400.00
Total Spare Part Cost	\$815.78	\$815.78
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,134.78	\$1,745.78
Lump Sum Total	\$2,150.00	\$1,750.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Bus Estimator Team	NAZ -LKK 98804220
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/11/2018

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$524.00	\$400.00
Total Spray Painting & Panel Beating	\$524.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298		88-25225-6039	STOP LAMP LED	1.00	\$1,141.70	30.00	\$799.19	Replace	Replace
6010373		4001F09-ACCE5020	REAR REFLECTOR PANEL RH	1.00	\$107.00	30.00	\$74.90	Replace	Replace
4006314	COMMON		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace
6010300	VE	36-25103-6000	LAMP, REVERSE (MAN BUS)	1.00	\$77.60	30.00	\$54.32	Replace	Replace
6010371	Body	88-25215-0001	REFLECTOR, TRIM FOR MAN BUS	1.00	\$77.60	30.00	\$54.32	Replace	Replace
Total					\$1,440.90		\$1,019.73		

CRK
CRK
NEC
CRK
NEC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

PARTS \$1,019.73

2759.90

LESS L/S 20% \$ 815.78

LABOUR \$ 530

SPRAY \$ 400

TOTAL \$1,745.78

L/S TOTAL \$1,750

CONFIRMED LUMP SUM REPAIR \$1,750.00 / 1 DAY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018		10 Sep 2018 13:47 Edit Adj Rpt	S\$1,750.00 Edit Estimates	S\$1,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ORCHID LAUNDRY , Co. Reg. No.: 09852400C								
Main Claimant:	SMRT BUSES LTD , Co. Reg. No.: 198202292D								
Vehicle Reg. No.:	SMB304J	Date of Loss:	04/08/2018 00:00 - :59 [72 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569715	Policy/Cover Note No.:	28620340MKC (Comprehensive) Coverage: 30/10/2017 - 29/10/2018						
Vehicle Reg. No. (Insured):	GBC5076J	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 10/10/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB304J (569715)**
[GBC5076J]
TP
SMRT BUSES LTD
Aug 4 2018 12:00AM
[ORCHID LAUNDRY]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	24/12/18 15:56	Adjuster Immediate Advice							Load HTM		
Photos/Images								3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
2	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
3	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
4	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
5	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
6	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
7	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
8	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
9	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
10	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
11	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
12	22/11/18 11:26	General View							Load JPG	<input checked="" type="checkbox"/>	
13	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
14	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
15	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
16	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
17	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
18	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
19	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
20	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
21	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
22	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
23	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	
24	19/12/18 11:02	Photographs of Damaged Items							Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18015721/NCBE2

Date: 26/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28620340MKC

Claimant Vehicle No : SMB304J

Insured Vehicle No : GBC5076J

Date of Loss: 04/08/2018

Nature of Claim: TP

Claim No: 569715

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB304J**

Make & Model: MAN NL320F (A22), 10.5 D (M)

Engine No: 50330490113042

Reg. Date: 13/07/2012 (Man. Year: 2011)

Chassis No: WMAA22ZZ0C7001398

Colour: White

Odometer: 469644 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 270/70 R22.5

Rear Tyre Size: 270/70 R22.5 (D)

Front Left Side: Continental 5 mm

Rear Left Side: Continental 6/6 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,440.90	1,019.73	421.17	29.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,319.00	930.00	389.00	29.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,759.90	1,949.73	810.17	29.36
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	2,759.90	1,750.00	1,009.90	36.59

INSPECTION

Date of Assignment: 10/09/2018

Date Inspected: 28/08/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 26 Dec 2018)
Parts:	N/A	MAN NL320F (A22) 10.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB304J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STOP LAMP LED	Cracked	1,141.70 F	*1,141.70 FL
2	1		*REAR REFLECTOR PANEL RH	Cracked	107.00 F	*107.00 FL
3	1		*LAMP, REVERSE (MAN BUS)	Cracked	77.60 F	*77.60 FL
4	1		*REFLECTOR, TRIM:FOR MAN BUS	Necessary	77.60 F	*77.60 FL
5	1		*SEALANT SIKAFLEX	Necessary	37.00 FS	*37.00 FS
					Sub Total (\$\$)	1,440.90
					- List Item Discount on L Items 0.00/30.00% (\$\$)	0.00
					Total Parts (\$\$)	1,440.90
						1,019.73

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	524.00	400.00
Gross Labour Cost (\$\$)			1,319.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >