

ASS. REC. 158 REF CS3/MSG18005724/B9611 *Ring*

Surveyor: **Menimen** ASSIGNMENT (Office)

From (Person): **Elaine Ngu** of **MSIG** Date/Time: **29/08/2018**

Estimated Cost: Bill to:

OD: ☒ TD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: **C1BF 5432Z** Insured: **SF2 880T**

at Workshop no: **V-Tech Auto Service** Tel: **6264 6222**

of **No. 1 Soon Lee Street #06-04**

Policy No: **28849438 QMX** Claim No: **553636**

Sum Insured: Excess:

Make of Veh: D.O.A. **24/03/2018**
(Client's Record)

CA / REV / REP. / REV 24 HRS *1wp* H.O.D. Endorsement:

Date/Time: **9:26am @ 28/3/18** Person Contacted: **Ms. Chong** Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	DO NOT Finalize
	C1BF 5432Z - X	
	SF2 880T - CB/AIG09016152/W21	D.O.A. 1/3/2006
	Dismantle: 5/4/2018	
	After repair: 6/4/2018	
03/9/18	Submit US \$ 1500, 4 days (led to 29/08, 66%)	

3/9/2018

RECEIVED 05 SEP 2018

URGENT

PRS


REF: MSLH

ASSIGNMENT

From: _____ Date: 03/04/2016
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBF 54322
 at Workshop m/s: V-Tech
 of No. 1 Soon Lee St # 06-04
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBF 54322 Regn: DEC, 2016
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA Dyna C.C. 2982
 Colour: Silver AC: Insured / Std / NI / NA
 Sp. Reading: 4665 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFAT35490K267008
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: All / S/Rim / STD A/Rim or
 Tyre Size F: 195/75R15 BS
 R: 155R12 FS
 BS / DUN / EXNOVA / GY / LIZA / MIC / OHTSU / PIR / SUMIT
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 7 mm R/Bal: 8 mm
 L/Bal: 7 mm L/Bal: 8 mm
 D.O.A. 24/03/2018 D.O.I. 31/4/2018
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 No EST upon Survey

2500 1/2 - 3000 1/2

RECEIVED 26 APR 2016

Date/Time: File Pass to? ☐ : Preli. Report
 05/19/2016 ☐ : Final Report
 Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip: 2/4

Survey Fee:
 Transportation

Report Format: PRS TP
 Lump Sum / I.B.I. (\$) 1500

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

\$ + PE 10

1 Photo

1 Film

TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Mar 2018		27 Mar 2018 17:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHEUK YAN KIN BENJAMIN, ID: S7574815I								
Main Claimant:	EVERGRO TRADING, Co. Reg. No.: 53143264E								
Vehicle Reg. No.:	GBF5432Z	Date of Loss:	24/03/2018 15:00 - :59 [15 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 553636	Policy/Cover Note No.:	28849438QMX (Comprehensive) Coverage: 05/10/2017 - 04/10/2018						
Vehicle Reg. No. (Insured):	SFZ880T	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	V Tech Auto Service (soon Lee) (HQ) NO.1 SOON LEE STREET, #06-04, PIONEER CENTRE, SINGAPORE 627605, 627605 Pioneer - Tel: 62646222								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 31/08/2018]								
Adj Asg. Remarks:	Workshop : V-Tech Auto Service Address : No. 1 Soon Lee Street, #06-04/05/06/07 Pioneer Centre, Singapore 627605 Contact : Ms. Chong (tel: 6264 6211 / 6264 6233)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (29/08/2018): Report Send Back Alerts - GBF5432Z (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 04-18001/AY / 2018
Date of Report : 17 Apr 2018

Evergro Trading
c/o No.1 Soon Lee Street
#06-04/05/06/07 Pioneer Centre,
Singapore 627605

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 24 Mar 2018

As per your instruction dated 2 Apr 2018 with regard to the above matter. We have
carried out a physical inspection on the said vehicle GBF 5432 Z . We enclosed herewith
our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : GBF 5432 Z
Model : Toyota Dyna
Year / Capacity : 2016/2982
Chassis No : JTFAT35Y90K207008
Engine No : 1KD2655484
Mileage : 46615
Colour : Silver

2. TYRES CONDITION

		Size	Made	Balance		Rim
FRONT	O/S	195/75 R15	Bridgestone	7.00	mm	Normal
REAR	O/S	155 R12	Firestone	6.00/6.00	mm	Normal
FRONT	N/S	195/75 R15	Bridgestone	7.00	mm	Normal
REAR	N/S	155 R12	Firestone	6.00/6.00	mm	Normal

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : V-Tech Auto Service
No.1 Soon Lee Street
#06-04/05/06/07 Pioneer Centre
Singapore 627605

5. Estimated normal period of repair : 7 working days to complete.
6. Enclosed number of photograph : 101 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: GBF 5432 Z
Report No: TP/ 04-18001/AY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear tailgate	Damage	\$ 1137.70	\$ 1137.70 RX
1	Rear tailgate lock hinge	Damage	\$ 136.50	\$ 136.50 BTV
1	Rear tailgate stopper bracket	Damage	\$ 110.50	\$ 110.50 BTV
1	Rear tailgate 'DYNA' sticker	Necessary	\$ 34.10	\$ 34.10 NECV
1	Rear tailgate 'TOYOTA' sticker	Necessary	\$ 118.55	\$ 118.55 NECV
1	Rear tailgate lower member	Damage	\$ 485.90	\$ 485.90 BTV X
1	Rear o/s taillamp	Damage	\$ 293.10	\$ 293.10 CRV
1	Rear o/s side gate lower member	Damage	\$ 625.00	\$ 625.00 RX
1	Rear number plate panel	Damage	\$ 65.50	\$ 65.50 DDV
1	Rear spare tyre carriage	Damage	\$ 385.22	\$ 385.20 SVCX
1	Rear exhaust silencer pipe	Damage	\$ 850.60	\$ 850.60 SVCX X
1	Rear exhaust silencer mounting	Necessary	\$ 48.50	\$ 48.50 NN X
			\$ 4291.17	\$ 4291.15 758.25
	Discount	25.0%	\$ 1072.79	\$ 1072.79 189.56
			\$ 3218.38	\$ 3218.36 568.69
<u>Special Nett Items</u>				
1	Rear tailgate '70 km/h' sticker	Necessary	\$ 25.00	\$ 15.00 NECV
1	Rear number plate	Damage	\$ 40.00	\$ 35.00 SVCX
1	Rear reverse sensor (1 set)	Damage	\$ 300.00	\$ 200.00 280.00
			\$ 365.00	\$ 330.00 215.00

Spare Parts Total \$ 3583.38 \$ 3548.36 783.69

Vehicle No: GBF 5432 Z
Report No: TP/ 04-18001/AY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 3583.38	\$ ^{783.69} 3548.36
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00
2	To remove and refit rear bumper sensor.	\$ 100.00	\$ ^{60.00} 80.00
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1000.00	\$ ^{600.00} 880.00
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ ^{400.00} 880.00
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ ^{60.00} 90.00
Total		\$ 5883.38	\$ ^{1943.69} 5518.36

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ ~~4400.00~~ ^{4/3 1500/2}

SDLS: FOUR THOUSAND FOUR HUNDRED ONLY

Repair days 4


Qualified Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Mar 2018		27 Mar 2018 17:24 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEUK YAN KIN BENJAMIN, ID: S7574815I		
Main Claimant:	EVERGRO TRADING, Co. Reg. No.: 53143264E		
Vehicle Reg. No.:	GBF5432Z	Date of Loss:	24/03/2018 15:00 - :59 [15 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 553636	Policy/Cover Note No.:	28849438QMX (Comprehensive) Coverage: 05/10/2017 - 04/10/2018
Vehicle Reg. No. (Insured):	SFZ880T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	V Tech Auto Service (soon Lee) (HQ) NO.1 SOON LEE STREET, #06-04, PIONEER CENTRE, SINGAPORE 627605, 627605 Pioneer - Tel: 62646222		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 31/08/2018]		
Adj Asg. Remarks:	Workshop : V-Tech Auto Service Address : No. 1 Soon Lee Street, #06-04/05/06/07 Pioneer Centre, Singapore 627605 Contact : Ms. Chong (tel: 6264 6211 / 6264 6233)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (29/08/2018): Report Send Back Alerts - GBF5432Z (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF5432Z (553636)**
[SFZ880T]
TP
EVERGRO TRADING
Mar 24 2018 3:00PM
[CHEUK YAN KIN BENJAMIN]
V Tech Auto Service (soon Lee)

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/09/18 16:09	Accident Statement From: SC - Reg. No: SFZ880T, Claimant: BENJAMIN CHEUK YAN KIN	Load HTM	

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/04/18 10:24	General View	Load JPG	
2	26/04/18 10:24	General View	Load JPG	
3	26/04/18 10:24	General View	Load JPG	
4	26/04/18 10:24	General View	Load JPG	
5	26/04/18 10:24	General View	Load JPG	
6	26/04/18 10:24	General View	Load JPG	
7	26/04/18 10:24	General View	Load JPG	
8	26/04/18 10:24	General View	Load JPG	
9	26/04/18 10:24	General View	Load JPG	
10	26/04/18 10:24	General View	Load JPG	
11	26/04/18 10:24	General View	Load JPG	
12	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
13	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
14	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
15	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
16	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
17	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
18	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
19	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
20	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
21	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
22	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
23	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
24	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
25	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
26	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
27	26/04/18 10:24	Photographs of Damaged Parts	Load JPG	
28	26/04/18 10:25	Photo After Spray	Load JPG	
29	26/04/18 10:25	Photo After Spray	Load JPG	
30	26/04/18 10:25	Photo After Spray	Load JPG	
31	26/04/18 10:25	Photo After Spray	Load JPG	

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=695439&extid=268200&... 2/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005724/BQBS2-1

Date: 05/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28849438QMX

Claimant Vehicle No: GBF5432Z

Insured Vehicle No: SFZ880T

Date of Loss: 24/03/2018

Nature of Claim: TP

Claim No: 553636

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF5432Z

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2655484

Reg. Date: 01/12/2016 (Man. Year: 2016)

Chassis No: JTFAT35Y90K207008

Colour: Silver

Odometer: 46615 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15

Rear Tyre Size:

155 R12

Front Left Side: Bridgestone 7 mm

Rear Left Side:

Firestone 8 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side:

Firestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,583.38	783.69	2,799.69	78.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,160.00	1,140.00	49.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,883.38	1,943.69	3,939.69	66.96
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	5,883.38	1,500.00	4,383.38	74.50
+ GST 7.00/7.00% (S\$)	411.84	105.00	306.84	74.50
Nett Amount (S\$)	6,295.22	1,605.00	4,690.22	74.50

INSPECTION

Date of Assignment: 27/03/2018

Date Inspected: 03/04/2018 Inspected At:

V Tech Auto Service (soon Lee) (HQ)
NO.1 SOON LEE STREET, #06-04, PIONEER
CENTRE, SINGAPORE 627605
Singapore 627605

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Sep 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF5432Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,137.70 FL	*- FL
2	1		*REAR TAILGATE LOCK HINGE	Bent	136.50 FL	*136.50 FL
3	1		*REAR TAILGATE STOPPER BRACKET	Bent	110.50 FL	*110.50 FL
4	1		*REAR TAILGATE DYNA STICKER	Necessary	34.10 FL	*34.10 FL
5	1		*REAR TAILGATE TOYOTA STICKER	Necessary	118.55 FL	*118.55 FL
6	1		*REAR TAILGATE LOWER MEMBER	Repair	485.90 FL	*- FL
7	1		*REAR O/S TAILLAMP	Cracked	293.10 FL	*293.10 FL
8	1		*REAR O/S SIDE GATE LOWER MEMBER	Repair	625.00 FL	*- FL
9	1		*REAR NUMBER PLATE PANEL	Dented	65.50 FL	*65.50 FL
10	1		*REAR SPARE TYRE CARRIAGE	Serviceable	385.22 FL	*- FL
11	1		*REAR EXHAUST SILENCER PIPE	Repair	850.60 FL	*- FL
12	1		*REAR EXHAUST SILENCER MOUNTING	Not Necessary	48.50 FL	*- FL
13	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
14	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
15	1		*SET REAR REVERSE SENSOR	Cut	300.00 FS	*200.00 FS
					Sub Total (S\$)	4,656.17
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,072.79
					Total Parts (S\$)	3,583.38
						783.69

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.	New	50.00	40.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR.	New	100.00	60.00
3	TO REMOVE AND REPLACE THE ABOVE MENTIONED DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,000.00	600.00
4	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	1,000.00	400.00
5	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	150.00	60.00
Gross Labour Cost (\$\$)			2,300.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >