

Surveyor

XPR.

REF: ASM(AXA)

e

F22407

ASSIGNMENT

(-2021)

From: Date: 30082018

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 566 7949Y

at Workshop m/s: Torque 5

of Blk 8 Kaki Bukit Ave 4 #01-49

Insured:

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh:

Afternoon.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$17K + 17.5

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 30 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 566 7949Y

Yr Regn: 24 May 2006

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Verna C.C. 1399

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 138083 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHC M41A R BU 956 87

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Brim / STD A/Rim or

Tyre Size: F: 175 / 55 R15 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 30-08-18

Survey held at w/s 3:30pm

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

repair limit ~~\$4000~~ - \$5000.

4/5: +5,000 (RED +8,474.16 63%)

M.V: +17500

LTA: +10461

NBN: +5039

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

Report Format:

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015749/eb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 29-08-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 7756Z	Veh. Inspected	SGG 7949Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/08/2018	Inspection Date		
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Torque 5 Pte Ltd
 No 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGG7949Y
 Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187
 Year of Manufacture : 2006

Estimation No. : E18080017
 DOA : 07/08/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Rear bumper / Re	1.00	0.00	0.00 676.00
2	Rear bumper retainer (LH) X } NN	1.00	0.00	0.00 53.00
3	Rear bumper retainer (RH) X } NN	1.00	0.00	0.00 53.00
4	Rear bumper reinforcement X / BT	1.00	0.00	0.00 230.00
5	Rear bumper sponge R / CRA	1.00	0.00	0.00 160.00
6	Rear bumper bracket (LH) X } NN	1.00	0.00	0.00 60.00
7	Rear bumper bracket (RH) X } NN	1.00	0.00	0.00 60.00
8	Bootlid / BT	1.00	0.00	0.00 1035.60
9	Bootlid emblem - logo X / NN	1.00	0.00	0.00 58.00
10	Bootlid emblem - Verna X / Re	1.00	0.00	0.00 58.00
11	Bootlid emblem - M1.4	1.00	0.00	0.00 58.00
12	Bootlid lock / BT	1.00	0.00	0.00 53.00
13	Bootlid lock catch X	1.00	0.00	0.00 60.00
14	Bootlid license lamp garnish X	1.00	0.00	0.00
15	License lamp (LH) X	1.00	0.00	0.00 36.00
16	License lamp (RH) X	1.00	0.00	0.00 36.00
17	Bootlid hinge (LH) X	1.00	0.00	0.00 130.00
18	Bootlid hinge (RH) X	1.00	0.00	0.00 130.00
19	Bootlid key lock X	1.00	0.00	0.00 62.00
20	Bootlid insulator X	1.00	0.00	0.00 105.30
21	Bootlid rubber beading R / CR	1.00	0.00	0.00 112.00
22	Tail lamp (LH) R / CRA	1.00	0.00	0.00 328.90
23	Tail lamp (RH) R / CRA	1.00	0.00	0.00 328.90
24	End panel X / Repair	1.00	0.00	0.00 648.70
25	End panel top garnish R / CRA	1.00	0.00	0.00 121.60

Continue on next page...



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

ESTIMATION REPORT

Vehicle No : SGG7949Y
Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187
Year of Manufacture : 2006
Estimation No. : E18080017
DOA : 07/08/2018

No	Description	Qty	U/P	Amt
26	Spare tyre top board X NN	1.00	0.00	0.00 423.80
27	Front bumper / DERORM	1.00	0.00	0.00 520.00
28	Front bumper retainer (LH) X	1.00	0.00	0.00 27.50
29	Front bumper retainer (RH) X } NN	1.00	0.00	0.00 27.50
30	Front bumper towing cap X	1.00	0.00	0.00
31	Front bumper lower grille / CRA	1.00	0.00	0.00 89.80
32	Front bumper under strip X NN	1.00	0.00	0.00
33	Front bumper reinforcement R / BT	1.00	0.00	0.00 280.00
34	Front bumper sponge R / TORN	1.00	0.00	0.00 160.00
35	Front bumper bracket (LH) X } NN	1.00	0.00	0.00 30.00
36	Front bumper bracket (RH) X	1.00	0.00	0.00 30.00
37	Radiator grille R / CUM	1.00	0.00	0.00 326.30
38	Radiator grille emblem - logo / NBL	1.00	0.00	0.00 42.00
39	Head lamp (LH) R / CRA	1.00	0.00	0.00 436.00
40	Head lamp (RH) X NN	1.00	0.00	0.00 436.00
41	Head lamp bracket (LH) R / NBL	1.00	0.00	0.00 50.00
42	Head lamp bracket (RH) X NN	1.00	0.00	0.00 50.00
43	Bonnet / BT	1.00	0.00	0.00 920.00
44	Bonnet lock X	1.00	0.00	0.00 72.00
45	Bonnet lock catch X	1.00	0.00	0.00
46	Bonnet insulator X } NN	1.00	0.00	0.00
47	Bonnet hinge (LH) X	1.00	0.00	0.00 63.00
48	Bonnet hinge (RH) X	1.00	0.00	0.00 63.00
49	Front support panel R / BT	1.00	0.00	0.00 861.60
50	Support panel top garnish X NN	1.00	0.00	0.00 115.00
51	A/C condenser R / DENT	1.00	0.00	0.00 918.00

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : 5GG7949Y
 Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187
 Year of Manufacture : 2006
 Estimation No. : E18080017
 DOA : 07/08/2018

No	Description	Qty	U/P	Amt
52	Radiator R / Dr.	1.00	0.00	0.00 772.20
				Amt S\$ 0.00 11367.70
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items

53	Reverse sensor set R / SHORT	1.00	250.00	250.00 200
54	Rear number plate and casing X NN	1.00	45.00	45.00
55	Rear bumper clip set / NEL	1.00	40.00	40.00
56	Bootlid insulator clip set / NEL	1.00	40.00	40.00
57	End panel sealant R NN	1.00	50.00	50.00
58	End panel top garnish clip set R / NEL	1.00	30.00	30.00
59	Front bumper clip set / NEL	1.00	40.00	40.00
60	Front number plate and casing / GA	1.00	45.00	45.00
61	Bonnet insulator clip set / NEL	1.00	40.00	40.00
62	Support panel top garnish clip set / NEL	1.00	30.00	30.00
				Amt S\$ 610.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 610.00

Section: Labour Items

63	To remove and refit rear bumper reverse sensor	1.00	60.00	60.00 40
64	To check wiring and lighting system focus tail lamp	1.00	40.00	40.00 30
65	To apply undercoating on affected areas	1.00	80.00	80.00 60
66	To check wiring and lighting system focus head lamp	1.00	40.00	40.00 X
67	To remove and refit rear trims and garnish	1.00	100.00	100.00 60
68	To remove and refit a/c condenser and radiator assy	1.00	150.00	150.00 860
69	To top up a/c gas	1.00	80.00	80.00 840

Continue on next page...

Carb. Off.
 21/8/18.



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGG7949Y

Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187

Year of Manufacture : 2006

Estimation No. : E18080017

DOA : 07/08/2018

No	Description	Qty	U/P	Amt
70	To repair, replace and realign damage areas	1.00	1,600.00	1,600.00
71	To spray painting on affected areas	1.00	1,500.00	1,500.00
72	To check water seepage after repair	1.00	120.00	120.00

Amt S\$ 3,770.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 3,770.00

5 Days.

Lumpsum Repair.

After repair photos.

Gao Qiang

30/8/18.

Parts = 8537.90 - 20% (AQA)
= 6830.32

S/N : 465

Labour : 1890

PT 5+1 = 9185.32 - 20% (Lumpsum)
= 7348.26

Repair Limit 5k

15747.70

List Items Subtotal S\$ 0.00

Special Nett Items Subtotal S\$ 610.00

Labour Items Subtotal S\$ 3,770.00

Total S\$ 4,380.00

PAGE 4 OF 4



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

ESTIMATION REPORT

Vehicle No : SGG7949Y

Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187

Year of Manufacture : 2006

Estimation No. : E18080017

DOA : 07/08/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper / Re .	1.00	0.00	0.00
2	Rear bumper retainer (LH) X	1.00	0.00	0.00
3	Rear bumper retainer (RH) X	1.00	0.00	0.00
4	Rear bumper reinforcement ?	1.00	0.00	0.00
5	Rear bumper sponge ?	1.00	0.00	0.00
6	Rear bumper bracket (LH) X	1.00	0.00	0.00
7	Rear bumper bracket (RH) X	1.00	0.00	0.00
8	Bootlid / BT	1.00	0.00	0.00
9	Bootlid emblem - logo X	1.00	0.00	0.00
10	Bootlid emblem - Verna X	1.00	0.00	0.00
11	Bootlid emblem - M1.4	1.00	0.00	0.00
12	Bootlid lock / BT	1.00	0.00	0.00
13	Bootlid lock catch X	1.00	0.00	0.00
14	Bootlid license lamp garnish X	1.00	0.00	0.00
15	License lamp (LH) X	1.00	0.00	0.00
16	License lamp (RH) X	1.00	0.00	0.00
17	Bootlid hinge (LH) X	1.00	0.00	0.00
18	Bootlid hinge (RH) X	1.00	0.00	0.00
19	Bootlid key lock X	1.00	0.00	0.00
20	Bootlid insulator X	1.00	0.00	0.00
21	Bootlid rubber beading ?	1.00	0.00	0.00
22	Tail lamp (LH) ?	1.00	0.00	0.00
23	Tail lamp (RH) ?	1.00	0.00	0.00
24	End panel ?	1.00	0.00	0.00
25	End panel top garnish ?	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGG7949Y

Estimation No. : E18080017

Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187

DOA : 07/08/2018

Year of : 2006

Manufacture

No	Description	Qty	U/P	Amt
26	Spare tyre top board X <i>nn</i>	1.00	0.00	0.00
27	Front bumper / <i>ee</i>	1.00	0.00	0.00
28	Front bumper retainer (LH) X	1.00	0.00	0.00
29	Front bumper retainer (RH) X <i>nn</i>	1.00	0.00	0.00
30	Front bumper towing cap X	1.00	0.00	0.00
31	Front bumper lower grille ?	1.00	0.00	0.00
32	Front bumper under strip ?	1.00	0.00	0.00
33	Front bumper reinforcement ?	1.00	0.00	0.00
34	Front bumper sponge ?	1.00	0.00	0.00
35	Front bumper bracket (LH) X	1.00	0.00	0.00
36	Front bumper bracket (RH) X	1.00	0.00	0.00
37	Radiator grille X / <i>CPA</i>	1.00	0.00	0.00
38	Radiator grille emblem - logo / <i>ABC</i>	1.00	0.00	0.00
39	Head lamp (LH) ?	1.00	0.00	0.00
40	Head lamp (RH) ?	1.00	0.00	0.00
41	Head lamp bracket (LH) ?	1.00	0.00	0.00
42	Head lamp bracket (RH) ?	1.00	0.00	0.00
43	Bonnet / <i>BT</i>	1.00	0.00	0.00
44	Bonnet lock X	1.00	0.00	0.00
45	Bonnet lock catch X	1.00	0.00	0.00
46	Bonnet insulator X <i>nn</i>	1.00	0.00	0.00
47	Bonnet hinge (LH) X	1.00	0.00	0.00
48	Bonnet hinge (RH) X	1.00	0.00	0.00
49	Front support panel ?	1.00	0.00	0.00
50	Support panel top garnish ?	1.00	0.00	0.00
51	A/C condenser ?	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGG7949Y
Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187
Year of Manufacture : 2006
Estimation No. : E18080017
DOA : 07/08/2018

No	Description	Qty	U/P	Amt
52	Radiator ?	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

53	Reverse sensor set ?	1.00	250.00	250.00	200
54	Rear number plate and casing X NN	1.00	45.00	45.00	
55	Rear bumper clip set - hmc	1.00	40.00	40.00	
56	Bootlid insulator clip set	1.00	40.00	40.00	
57	End panel sealant ?	1.00	50.00	50.00	
58	End panel top garnish clip set ?	1.00	30.00	30.00	
59	Front bumper clip set	1.00	40.00	40.00	
60	Front number plate and casing - hmc	1.00	45.00	45.00	
61	Bonnet insulator clip set	1.00	40.00	40.00	
62	Support panel top garnish clip set	1.00	30.00	30.00	

Amt S\$ 610.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 610.00

Section: Labour Items

63	To remove and refit rear bumper reverse sensor	1.00	60.00	60.00	40
64	To check wiring and lighting system focus tail lamp	1.00	40.00	40.00	30
65	To apply undercoating on affected areas	1.00	80.00	80.00	60
66	To check wiring and lighting system focus head lamp	1.00	40.00	40.00	X NN
67	To remove and refit rear trims and garnish	1.00	100.00	100.00	60
68	To remove and refit a/c condenser and radiator assy	1.00	150.00	150.00	?
69	To top up a/c gas	1.00	80.00	80.00	?

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGG7949Y **Estimation No.** : E18080017
Make & Model : HYUNDAI,VERNA 1.4M,KMHCM41AR6U056187 **DOA** : 07/08/2018
Year of Manufacture : 2006

No	Description	Qty	U/P	Amt
70	To repair, replace and realign damage areas	1.00	1,600.00	1,600.00
71	To spray painting on affected areas	1.00	1,500.00	1,500.00
72	To check water seepage after repair	1.00	120.00	120.00

Amt S\$ 3,770.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,770.00

5 Days.
Lumpsum repair.
After repair photos.
Guo Qiang
30/8/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 610.00
Labour Items Subtotal S\$ 3,770.00
Total S\$ 4,380.00



Service Request Details

Claim

S8M00RDV

Reference

None

Loss Date

7 August 2018

Request Date

28 August 2018

Due Date

4 September 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

29/08/2018 @ 938am
Lucas veh not in.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGG7949Y

Make

TPVD HYUNDAI

Model

VERNA

Service Address

...

Primary Contact/Insured

LIM SIU WAN

5, SIGLAP ROAD, #17-35, 448908, Singapore

MICOL@CENTOURTRAVEL.COM

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

29/8/18 9:12 AM

FROM

TAN Jas

SUBJECT

DS

BODY

hi, please explore DS.





MANDATE REQUEST FOR S8M00RDV

Type

🔗 Question

Message

Liability: Insured involved in 3 vehicle chain collision insured last vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$5,350.00 (w/GST) Loss of Rental: \$800.00 (8days x \$100) GIA: \$31.00 Total: \$6,181.00 Immediate Advice with Mandate and revised marked estimate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (15/10/2018)

Reply



Re:MANDATE REQUEST FOR S8M00RDV

Type

🔗 Question

Message

hi, you may proceed with COR. please offer 5 days for LOR.

Reply



RE: Re:MANDATE REQUEST FOR S8M00RDV

Type

🔔 Question

Message

HI, TP DISAGREED WITH THE LOR AND COUNTER PROPOSE 6DAYS X \$100

Reply



Re:RE: Re:MANDATE REQUEST FOR S8M00RDV

Type

🔗 Question

Message

you may proceed as proposed for COR.

Reply



Re:RE: Re:RE: Re:MANDATE REQUEST FOR S8M00RDV

Type

🔗 Question

Message

Please proceed

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLC 7756Z (Insd veh)	Model:	HYUNDAI VERNA
	SGG 7949Y (TP veh)		
Date of Accident:	07/08/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	16,850.04
Final Repair Cost	:	\$	5,350.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	600.00 6 days
LTA / GIA Search Fee	:	\$	31.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 5,981.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	TORQUE 5 PTE. LTD.	:	\$ 5,981.00

NUR SHAQILAH BTE ABDOL
WAHAB

26/12/2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18015749/Geb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: JAS TAN			Date : 26-12-2018 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLC 7756Z	Veh. Inspected	SGG 7949Y
	Policy No.	VA1/GA354161	Coverage (\$)	0.00
	Claim No.	S8M00RDV	Excess (\$)	0.00
	Assign From	JAS TAN	Assign Date	29/08/2018
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI VERNA	c.c	1399
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	KMHCM41AR6U056187	Colour	BLUE
	Odometer	138083	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55R15	FALKEN	6 mm
	L/H Front Tyre	195/55R15	FALKEN	6 mm
	R/H Rear Tyre	195/55R15	FALKEN	6 mm
	L/H Rear Tyre	195/55R15	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/08/2018	Inspection Date	30/08/2018
	Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 7949Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED	676.00	676.00
1	REAR BUMPER RETAINER (LH) (CONSISTENT)	NOT NECESSARY	53.00	-
1	REAR BUMPER RETAINER (RH) (CONSISTENT)	NOT NECESSARY	53.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	230.00	230.00
1	REAR BUMPER SPONGE (CONSISTENT)	CRACKED	160.00	160.00
1	REAR BUMPER BRACKET (LH) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR BUMPER BRACKET (RH) (CONSISTENT)	NOT NECESSARY	60.00	-
1	BOOTLID (CONSISTENT)	BENT	1,035.60	1,035.60
1	BOOTLID EMBLEM - LOGO (CONSISTENT)	NOT NECESSARY	58.00	-
1	BOOTLID EMBLEM - VERA (CONSISTENT)	NECESSARY	58.00	58.00
1	BOOTLID EMBLEM - M1.4 (CONSISTENT)	NECESSARY	58.00	58.00
1	BOOTLID LOCK (CONSISTENT)	BENT	53.00	53.00
1	BOOTLID LOCK CATCH (CONSISTENT)	NOT NECESSARY	60.00	-
1	BOOTLID LICENSE LAMP GARNISH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	LICENSE LAMP (LH) (CONSISTENT)	NOT NECESSARY	36.00	-
1	LICENSE LAMP (RH) (CONSISTENT)	NOT NECESSARY	36.00	-
1	BOOTLID HINGE (LH) (CONSISTENT)	NOT NECESSARY	130.00	-
1	BOOTLID HINGE (RH) (CONSISTENT)	NOT NECESSARY	130.00	-
1	BOOTLID KEY LOCK (CONSISTENT)	NOT NECESSARY	62.00	-
1	BOOTLID INSULATOR (CONSISTENT)	NOT NECESSARY	105.30	-
1	BOOTLID RUBBER BEARING (CONSISTENT)	CUT	112.00	112.00
1	TAIL LAMP (LH) (CONSISTENT)	CRACKED	328.90	328.90
1	TAIL LAMP (RH) (CONSISTENT)	CRACKED	328.90	328.90
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	648.70	-
1	END PANEL TOP GARNISH (CONSISTENT)	CRACKED	121.60	121.60
1	SPARE TYRE TOP BOARD (CONSISTENT)	NOT NECESSARY	423.80	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	520.00	520.00
1	FRONT BUMPER RETAINER (LH) (CONSISTENT)	NOT NECESSARY	27.50	-
1	FRONT BUMPER RETAINER (RH) (CONSISTENT)	NOT NECESSARY	27.50	-
1	FRONT BUMPER TOWING CAP (NPA) (CONSISTENT)	NOT NECESSARY	-	-

Report Ref No. CC4/ASM18015749/Geb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	CRACKED	89.80	89.80
1	FRONT BUMPER UNDER STRIP (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	280.00	280.00
1	FRONT BUMPER SPONGE (CONSISTENT)	TORN	160.00	160.00
1	FRONT BUMPER BRACKET (LH) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT BUMPER BRACKET (RH) (CONSISTENT)	NOT NECESSARY	30.00	-
1	RADIATOR GRILLE (CONSISTENT)	CUT	326.30	326.30
1	RADIATOR GRILLE EMBLEM - LOGO (CONSISTENT)	NECESSARY	42.00	42.00
1	HEAD LAMP (LH) (CONSISTENT)	CRACKED	436.00	436.00
1	HEAD LAMP (RH) (CONSISTENT)	NOT NECESSARY	436.00	-
1	HEAD LAMP BRACKET (LH) (CONSISTENT)	NECESSARY	50.00	50.00
1	HEAD LAMP BRACKET (RH) (CONSISTENT)	NOT NECESSARY	50.00	-
1	BONNET (CONSISTENT)	DENTED	920.00	920.00
1	BONNET LOCK (CONSISTENT)	NOT NECESSARY	72.00	-
1	BONNET LOCK CATCH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BONNET INSULATOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BONNET HINGE (LH) (CONSISTENT)	NOT NECESSARY	63.00	-
1	BONNET HINGE (RH) (CONSISTENT)	NOT NECESSARY	63.00	-
1	FRONT SUPPORT PANEL (CONSISTENT)	BENT	861.60	861.60
1	SUPPORT PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	115.00	-
1	A/C CONDENSER (CONSISTENT)	DENTED	918.00	918.00
1	RADIATOR (CONSISTENT)	DENTED	772.20	772.20
	LESS 20% DISCOUNT		-	-1,707.58
			11,367.70	6,830.32
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	200.00
1	REAR NUMBER PLATE AND CASING (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	SET BOOTLID INSULATOR CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET END PANEL TOP GARNISH CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00

Report Ref No. CC4/ASM18015749/Geb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE WITH CASING (SN) (CONSISTENT)	CRACKED	45.00	45.00
1	SET BONNET INSULATOR CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	SET SUPPORT PANEL TOP GARNISH CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
			610.00	465.00
	LABOUR			
	TO REMOVE AND REFIT REAR BUMPER REVERSE SENSOR.		60.00	40.00
	TO CHECK WIRING AND LIGHTING SYSTEM FOCUS TAIL LAMP.		40.00	30.00
	TO APPLY UNDERCOATING ON AFFECTED AREAS.		80.00	60.00
	TO CHECK WIRING AND LIGHTING SYSTEM FOCUS HEAD LAMP.	NOT NECESSARY	40.00	-
	TO REMOVE AND REFIT REAR TRIMS AND GARNISH.		100.00	60.00
	TO REMOVE AND REFIT A/C CONDENSER AND RADIATOR ASSY.		150.00	60.00
	TO TOP UP A/C GAS.		80.00	40.00
	TO REPAIR, REPLACE AND REALIGN DAMAGE AREAS. INCLUSIVE OF THE REPAIR OF END PANEL.		1,600.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,500.00	1,000.00
	TO CHECK WATER SEEPAGE AFTER REPAIR.	NOT NECESSARY	120.00	-
			3,770.00	1,890.00
GRAND TOTAL			15,747.70	9,185.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CC4/ASM18015749/Geb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.