

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 / 62717433 FAX: 62745715

Pg 1

ESTIMATE REPAIR

AXA Insurance Pte Ltd

Date: 28.8.2018

Owner's Name : Lau Ying Min

Vehicle No : SLQ7098R

Vehicle Make & Model : Toyota Vellfire 2.5 CVT A

Registration Date : 20 Jul 2017 (YOM 2017) COE Expiry Date 19 July 2027

Claim Type: Third Party Claim

Chassis No: AGH300115371

DOA: 27.8.2018

No	Description	Unit	List (\$)
1	FRONT BONNET	1	\$ PA ✓ 880.60
2	FRONT BONNET HINGE	2	\$ X 210.00
3	FRONT BONNET CHROME	1	\$ CR ✓ 535.90
4	FRONT BONNET STAND	1	\$ X 80.97
5	FRONT BONNET INSULATOR	1	\$ X 265.40
6	FRONT BONNET INSULATOR CLIPS	10	\$ ne ✓ 35.00
7	FRONT BONNET LOCK	1	\$ X 220.90
8	FRONT SPACE LOCK PANEL	1	\$ X 188.90
9	FRONT SUPPORT PANEL	1	\$ repair? 1,550.60
10	FRONT EMBLEM	1	\$ ne ✓ 181.70
11	FRONT GRILLE BASE	1	\$ X 1,125.00
12	FRONT GRILLE CHROME	1	\$ SC ✓ 643.30
13	FRONT LOWER GRILLE	1	\$ DE ✓ 288.70
14	FRONT GRILLE CLIPS/SCREW	SET	\$ ne ✓ 40.00
15	FRONT HEADLAMP LH	1	\$? 2,022.30
16	FRONT HEADLAMP RH	1	\$ CR ✓ 2,022.30
17	FRONT BUMPER	1	\$ DE ✓ 1,614.80
18	FRONT BUMPER SIDE RETAINER	2	\$ ne ✓ 196.00
19	FRONT BUMPER CLIPS	10	\$ ne ✓ 35.00
20	FRONT BUMPER FOGLAMP GARNISH LH	1	\$ X 135.80
21	FRONT BUMPER FOGLAMP GARNISH RH	1	\$ X 135.80
22	FRONT FOGLAMP GARNISH CHROME	2	\$ X 220.00
23	FRONT REINFORCEMENT BAR	1	\$? 580.50
24	FRONT REINFORCEMENT ARM LH	1	\$? 289.80
25	FRONT REINFORCEMENT ARM RH	1	\$? 289.80
26	FRONT BUMPER LOWER COVER	1	\$? 245.90

Total (A) : \$ 14,034.97

Less 25% \$ 3,508.74

Total: \$ 10,526.23

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/62717433 FAX:62745715

Pg 2

ESTIMATE REPAIR

NTUC Income Ins Co-Op Ltd

Date: 26.6.2018

Owner's Name : LJH Holding

Vehicle No : SGQ6198B

Vehicle Make & Model : SGQ6198B

Registration Date : 19 Jan 2007 (YOM 2006) COE Expiry Date 18 Jan 2027

Claim Type: Third Party Claim

Chassis No: GJ11107611

DOA: 29.6.2018

No	Description	Unit	List (\$)
27	FRONT BUMPER LOWER COVER CLIPS	10	\$ <i>ne /</i> 35.00
28	FRONT HEADLAMP LOWER COVER	2	\$ <i>X</i> 200.00
29	FRONT BUMPER TOW COVER	1	\$ <i>X</i> 80.00
30	FRONT BUMPER SPONGE	1	\$ <i>?</i> 170.30
31	FRONT FENDER LH	1	\$ <i>X</i> 735.60
32	FRONT FENDER RH	1	\$ <i>X</i> 735.60
33	FRONT FENDER SHIELD CLIPS	20	\$ <i>X</i> 70.00
34	REAR TAILGATE	1	\$ <i>Puc /</i> 1,809.70
35	REAR TAILGATE ABSORBER	2	\$ <i>X</i> 597.20
36	REAR TAILGATE LAMP LH	1	\$ <i>X</i> 620.40
37	REAR TAILGATE LAMP RH	1	\$ <i>X</i> 620.40
38	REAR TAILGATE CHROME	1	\$ <i>X</i> 890.50
39	REAR TAIL GATE EMBLEM	1	\$ <i>X</i> 150.60
40	REAR TAILGATE "VELLFIRE"	1	\$ <i>ne /</i> 185.60
41	REAR TAILGATE INNER COMPARTMENT	1	\$ <i>CPA /</i> 1,080.00
42	REAR TAILGATE INNER COMPARTMENT CLIPS	18	\$ <i>ne /</i> 81.00
43	REAR TAILGATE LOCK	1	\$ <i>JAN /</i> 870.50
44	REAR TAILGATE STRICK	1	\$ <i>?</i> 102.68
45	REAR TAILGATE WEATHERSHIP	1	\$ <i>ne /</i> 360.50
46	REAR FENDER LH	1	\$ <i>X</i> 1,280.00
47	REAR FENDER RH	1	\$ <i>X</i> 1,280.00
48	REAR SIDE BUMPER LH	1	\$ <i>X</i> 280.80
49	REAR SIDE BUMPER RH	1	\$ <i>X</i> 280.80
50	REAR BUMPER	1	\$ <i>DE /</i> 880.90
51	REAR BUMPER SIDE RETAINER	2	\$ <i>ne /</i> 300.00
52	REAR BUMPER REFLECTOR	2	\$ <i>CPA /</i> 193.60

Total (B) : \$ 13,891.68

Less 25% \$ 3,472.92

Total: \$ 10,418.76

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/ 62717433 FAX:62745715

Pg 3

DOA: 29.6.2018

Total (C) :	\$	5,033.29
Less 25%	\$	1,258.32
Total:	\$	3,774.97

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/62717433 FAX:62745715

Pg 4

DOA: 27.8.2018

[illegible]

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 62717433 FAX: 62745715

Pg 5

ESTIMATE REPAIR

AXA Insurance Pte Ltd

Date: 28.8.2018

Owner's Name : Lau Ying Min

Vehicle No : SLQ7098R

Vehicle Make & Model : Toyota Vellfire 2.5 CVT A

Registration Date : 20 Jul 2017 (YOM 2017) COE Expiry Date 19 July 2027

Claim Type: Third Party Claim

Chassis No: AGH300115371

DOA: 27.8.2018

No	Description	Unit	List (\$)
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 1750 2,800.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 1700 2,600.00
3	Check Wiring System & Light	1	\$ 30 100.00
4	Anti Rust Treatment	1	\$ 100 120.00
5	To Check & Adjust Wheel Aligment	1	\$ X 100.00
6	To Remove/Refix Rear Inner Compartment & Carpet To Facilitate Repair	1	\$ 120 280.00
7	To Remove / Refix / Replace Front Camera	1	\$ 60 180.00
8	To Remove / Replace Front Bumper Sensor	1	\$ 80 180.00
9	To Remove / Replace Rear Reverse Camera	1	\$ 60 180.00
10	To Remove / Replace Rear Reverse Sensor	1	\$ 80 180.00
11	To Check Water Leaking	1	\$ 50 180.00
12	To Remove / Refix / Replace Rear Tail Gate Inner Compartment, Mechemism & Assy To New Tail Gate	1	\$ 100 200.00
13	To Remove/Refix/Replace Exhaust Pipe	1	\$ 80 250.00
14	To Remove / Refix Rear Windscreen To New Tail Gate	1	\$ 120 220.00
15	To Remove/Refix/Replace Seat Belt & Buckle	1	\$ 80 200.00
16	To Remove/Refix/Adjust Rear Chair Roller Bar	1	\$ 80 200.00
17	To Check / Repair / Replace LH & RH Side Sliding Door Auto Open & Close Function	1	\$ 180 350.00
18	Upholstery Details Cleaning	1	\$ X 220.00
19	Computer Diagnostic	1	\$ 150 350.00
I KK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
Total (E) : \$ 8,860.00			
Grand Total: \$ 36,400.64			

Rasul

Hp 90010068

13 days

P/P

29/08/18 @ 1445

Resurvey by part
To check parts price