

Co Reg No : 199405410K

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

ESTIMATE

Invoice Name & Address		GST Reg No : MR-8500111- Owner Name & Vehicle Info			
NG SZE ENG(HUANG SIRONG)	Cust No/Name	LCV05132/Mr Ng Sze Eng (Huang Sirong)			
	Reg No/Reg Date	SLX5352H / 29/03/201			
BLK 17 TECK WHYE LANE #09-155 SINGAPORE 680017 Contact No	Date In/Mileage	0			
	Chassis No	KNAPH81BSJ5411620			
		D4HBHH347448			
	Make/Model	KIA/SORENTO 2.2 A D GT SR 4WDD82			
		DN9 RICH ESPRESSO / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		Marine Na Carana Sans	tational distribution and in the second
CV05132	CROVCH	27/08/2018/ 17:35	TLC	442 / CocoLu		WIP No 34476	
PNT88000		Description of Good	s / Service	S	Qty	Jnit Price Disc9	ն Amoun
REPAIR F	RT BUMPER	, RENEW LOWER COVER					550
PN198000		RT BUMPER					500
SUNDRY Sundry		ici boyii eix					20
90000001							1
PNT88000	DIAGNOSTI	C CHECK FOR THE CAR	SYSTEM				200
REMOVE & SKID PLAT	INSTALL	PARKING SENSOR					.100
9/14/20 7 4/10	TE TREBUIN	TEN.	3	ima	11.00	111.00 00.00	111.
		Francisco	mark [m]		しいい		ļ
nfirm & acc	epted by		-		<u> </u>		
					7% GST on	Neft 1481.00	1,481. 103.
					Total	Payable	1,584.6
thorized si	gnatory ar	id company stamp				-	2,500,861

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.