

INS. CASE OWNER:

Stacy

CC 4 Agm AXA1801

5758

Gebb

LKK:

IDAC:

Surveyor:

XUA

DOI:

ASSIGNMENT

2/18/18

Date / Time:

2/18/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 72764

Name of Insured:

WEE TIAN LIAW

Insured Tel No.:

HP:

84687164

Excess Sec II :SS

D.O.A.:

24/8/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

ANG PET PET 7ENNY

Driver Tel No.:

(V/L ☒ YES / NO)

Claim No.:

8800767 / 66043

Policy No.:

UAH687571

Make / Model:

MONZA

Place of Accident:

PASIR RIS BR 6

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

world

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
no / 8/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	EMAIL 16.10.18
	After call ltr to OI:	
17.9.18 @ 2.33	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒
22/1/19	PRELIMINARY ADVICE	Date/Time: Sent By:
2/19	FINALIZATION	Date/Time: Confirm with:
2/19	Repair Cost:	SS 21,000 (16 days) Reduction: 44%
2/19	FINAL SETTLEMENT	Date/Time: Confirm with:
	Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. 96
	Repair Cost:	SS 22,470.00
	Loss of Rental (LOR):	SS (days)
	Loss of Use (LOU):	SS 1080.00 (560 x 18 days)
	Loss of Income (LOI):	SS (S x days)
	LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]
	GIA/LTA Search	SS 2.00
	Medical:	SS -
	Disbursement:	SS - (e.g. Tow/ Independent)
	Legal Cost	SS -
	Total:	SS 23,552.00 Global Sum SS: 20,000.
	FINAL PAYMENT	Date/Time: Confirm with:
	Payee 1:	SS 20,000.00 Name 1: World Auto Pte Ltd
	Payee 2: (Strike if N.A.)	SS Name 2:
	Payee 3: (Strike if N.A.)	SS Name 3:

Carryover

XPR.

REF: ASM(AXA)

e

ASSIGNMENT

From:

Date: 29082018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLJ 1239C

at Workshop m/s

World Auto

of

No. 1 Kranji Loop

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$70k

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

16

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ1239C

Yr Regn:

29 Nov 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C.

1496

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

080525

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP 710 44174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

29-08-18

Survey held at

w/s

4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

and N/S RT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

repair limit \$21k

(Red - \$16,762.08 / 44.1%)

MV: \$70K

Rebate: \$50,000

NV: \$20,000

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS: SI

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015758/eb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 29-08-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 7226U	Veh. Inspected	SLJ 1239C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/08/2018	Inspection Date		
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD**8 SHENTON WAY #24-01 AXA TOWER****068811****Attention : Motor Claim Department****Contact : 68804888 Fax No. : 880 4838**

the Repairer of the following:

• To resurvey before/after spray painting

• To supply damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate : ES201862**Date : 28/08/2018****Vehicle Num. : SLJ 1239C (LCR)****Make/Model : HONDA SHUTTLE HYBRID****Chassis/Eng# :****Accident Date : 24/08/2018****Claim No. :****Reference :****Policy No. :**

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BONNET / Bue		1,080.00 ✓
2.	2	FRONT BONNET HINGE / BT	98.50	197.00 ✓
3.	1	FRONT BONNET INSULATOR / ee		135.00 ✓
4.	1	FRONT BONNET LOCK / BT		158.00 ✓
5.	1	FRONT BUMPER / ee		1,100.00 ✓
6.	2	FRONT BUMPER SIDE RETAINER / ee	78.00	156.00 ✓
7.	1	FRONT BUMPER REINFORCEMENT / BT		485.80 ✓
8.	1	FRONT BUMPER UNDERDUST COVER / ee		185.00 ✓
9.	1	FRONT BUMPER LOWER GRILLE / CAA		122.00 ✓
10.	1	FRONT BUMPER FOGLAMP COVER LH / mis		75.00 ✓
11.	1	FRONT BUMPER FOGLAMP COVER TOP GARNISH LH / mis		68.00 ✓
12.	2	FRONT FENDER LH / Bue, RH x repair.	489.90 //	979.80 ✓
13.	1	FRONT FENDER TOP BRACKET LH / BT		60.00 ✓
14.	1	FRONT FENDER HYBRID EMBLEM LH / ee		88.60 ✓
15.	1	FRONT FENDER UNDER DUST COVER LH / ee		192.00 ✓
16.	1	FRONT GRILLE BASE / wt		248.00 ✓
17.	1	FRONT GRILLE CHROME MOULDING / wt		228.00 ✓
18.	1	FRONT GRILLE LOWER CHROME MOULDING / CAA		198.00 ✓
19.	1	FRONT GRILLE CENTRE LOCK BRACKET / CAA		118.00 ✓
20.	2	HEAD LAMP / CAA	780.00	1,560.00 ✓
21.	1	HEADLAMP LOWER BRACKET LH / BT		64.00 ✓
22.	1	FRONT SUPPORT PANEL / BT		790.00 ✓
23.	1	FRONT SUPPORT PANEL TOP GARNISH / ee		95.00 ✓
24.	1	RADIATOR / BT		1,311.90 ✓
25.	1	RADIATOR FAN COWLING / CAA		125.00 ✓
26.	1	RADIATOR FAN BLADE / CAA		122.00 ✓
27.	1	RADIATOR FAN MOTOR / CAA		225.00 ✓
28.	2	RADIATOR AIR GUIDE SIDE / CAA	80.00	160.00 ✓
29.	1	RADIATOR SPARE TANK / CAA		92.00 ✓

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES201862

Date : 28/08/2018

Vehicle Num. : SLJ 1239C (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 24/08/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	RADIATOR SPARE TANK CAP <i>mis</i>		20.00 ✓
31.	1	AIRCON CONDENSOR <i>BT</i>		1,160.00 ✓
32.	1	AIRCON CONDENSOR FAN COWLING <i>BT</i>		168.00 ✓
33.	1	AIRCON CONDENSOR FAN BLADE <i>NN</i>		95.00 ✓
34.	1	AIRCON CONDENSOR FAN MOTOR <i>NN</i>		238.00 ✓
35.	1	FRONT WHEELHOUSE INNER PANEL LH <i>BT</i>		198.00 ✓
36.	1	FRONT WHEELHOUSE OUTER PANEL LH <i>BT</i>		188.00 ✓
37.	1	FRONT WHEELHOUSE EXTENSION INNER PANEL LH <i>BT</i>		85.00 ✓
38.	1	FRONT WHEELHOUSE EXTENSION OUTER PANEL LH <i>BT</i>		95.00 ✓
39.	1	FRONT CHASSIS SIDE MEMBER LH <i>NN</i>		850.00 ✓
40.	1	BATTERY TRAY <i>CHA</i>		70.00 ✓
41.	1	BATTERY TRAY BRACKET <i>NN</i>		132.00 ✓
42.	2	BATTERY LOCKING HOOK <i>NN</i>	32.00	64.00 ✓
43.	1	BATTERY LOCKING BRACKET <i>BT</i>		28.00 ✓
44.	1	ENGINE BAY WIRING HARNESS LH <i>NN</i>		1,300.00 ✓
45.	1	AIR FILTER BOX LOWER HOUSING <i>NN</i>		258.00 ✓
46.	1	AIR FILTER BOX TOP COVER <i>NN</i>		98.00 ✓
47.	1	AIR INTAKE RESONANCE <i>CHA</i>		188.00 ✓
48.	1	AIR INTAKE AIR DUCT <i>re</i>		132.00 ✓
49.	1	AIR INTAKE AIR DUCT TUBE <i>re</i>		70.00 ✓
50.	1	TRANSMISSION GEARBOX MOUNTING <i>NN</i>		320.00 ✓
51.	1	DASHBOARD <i>Act</i>		2,152.00 ✓
52.	1	STEERING WHEEL AIRBAG <i>Act</i>		1,850.00 ✓
53.	1	STEERING WHEEL AIR BAG SLIP RING <i>Act</i>		480.00 ✓
54.	1	STEERING ANGLE SENSOR <i>Act</i>		310.00 ✓
55.	1	FRONT PASSENGER AIRBAG <i>Act</i>		2,480.00 ✓
56.	1	AIRBAG CONTROL MODULE <i>Act</i>		1,580.00 ✓
57.	2	FRONT SEATBELT <i>NN</i>	1,298.00	2,596.00 ✓
58.	2	FRONT SEATBELT BUCKLE <i>NN</i>	328.00	656.00 ✓
59.	2	FRONT AIRBAG IMPACT SENSOR <i>Act</i>	185.00	370.00 ✓
60.	1	FRONT WINDSCREEN GLASS <i>CHA</i>		1,850.00 ✓

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES201862

Date : 28/08/2018

Vehicle Num. : SLJ 1239C (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 24/08/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
61.	1SET	FRONT WINDSCREEN MOULDING /		195.00 ✓
62.	1	FRONT WINDSCREEN GLASS OUTER MOULDING LH /		120.00 ✓
63.	1	WIPER AIR GRILLE COWLING /		298.00 ✓
64.	1	WIPER AIR GRILLE COWLING SIDE GARNISH LH /		38.00 ✓
65.	1	RADIATOR TOP HOSE /		78.00 ✓
66.	1	RADIATOR LOWER HOSE /		88.00 ✓
67.	1	AUDIBLE SENSOR /		180.00 ✓
68.	1	ENGINE CROSSMEMBER SUBFRAME /		980.00 ✓
69.	2	ENGINE CROSSMEMBER SUBFRAME BRACKET /	160.00	320.00 ✓
70.	1	FRONT SHOCK ABSORBER - LH /		430.00 ✓
71.	1	FRONT LOWER ARM - LH /		320.00 ✓
72.	1	FRONT KNUCKLE - LH /		360.00 ✓
73.	1	FRONT WHEEL BEARING - LH /		220.00 ✓
74.	1	FRONT STABILIZER LINK LH /		80.00 ✓
75.	1	DRIVE SHAFT FRT / LH /		1,680.00 ✓
76.	1	FRONT WHEEL ABS SENSOR LH /		310.00 ✓
77.	1	FRONT GRILLE EMBLEM /		48.00 ✓
78.	1	STEERING TIE ROD END LH /		120.00 ✓
List Total S\$:				36,365.10
20.00% Discount S\$:				7,273.02
				29,092.08

SPECIAL NETT ITEMS :				
1.	1SET	FRONT BONNET INSULATOR CLIP /		30.00 ✓
2.	1SET	FRONT BUMPER UNDERDUST COVER CLIPS /		30.00 ✓
3.	1SET	FRONT BUMPER CLIP /		30.00 ✓
4.	1SET	FRONT FENDER UNDER DUST COVER CLIPS /		20.00 ✓
5.	1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS /		20.00 ✓
6.	1	BATTERY /		180.00 ✓
				(5%) 90

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES201862

Date : 28/08/2018

Vehicle Num. : SLJ 1239C (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 24/08/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
7.	1	FRONT NUMBER PLATE W/FRAME <i>Mr's</i>		40.00
8.	1	TOWING CHARGE		60.00
9.	1	WINDSCREEN SEALANT		80.00
10.	1	PRIVATE HIRE DECAL <i>abc.</i>		20.00
11.	1	RADIATOR COOLANT		80.00
12.	1	AUTOTRANSMISSION FLUID (HONDA) <i>2 NN</i>		120.00
Special Nett Total S\$:			<i>500</i>	710.00
LABOUR :				
REMOVE AND REPLACE FRONT WINDSCREEN GLASS			<i>120 / 120</i>	180.00
SEND VEHICLE TO INSPECTION CENTRE FOR PRIVATE HIRE DECAL PASTING			<i>NN (400) X</i>	120.00
REMOVE AND REPLACE RADIATOR ASSY INCLUDING PERFORMING ENGINE COOLING SYSTEM PRESSURE TEST AND REFILL COOLANT			<i>800</i>	180.00
REMOVE AND REPLACE AIRCON CONDENSOR ASSY INCLUDING PERFORMING AIRCON SYSTEM PRESSURE LEAK TEST INCLUDING REFILLING AIRCON GAS			<i>80 / 40</i>	180.00
REMOVE FRONT ACCIDENT DAMAGED PARTS INCLUDING FRONT BONNET, FRONT BUMPER, FRONT HEADLAMPS, FRONT FENDERS, CUT OUT AND WELD DAMAGED SUPPORT PANEL AND FRONT LEFT WHEELHOUSE PANEL, FRONT LEFT CHASSIS SIDE MEMBER, AND REPLACE NEW PARTS			<i>1600 2200 2000 1800</i>	2,800.00
HOIST OUT ENGINE ASSY IN ORDER TO FACILITATE REPAIRS TO FRONT ACCIDENT DAMAGED AREAS			<i>300 / 250</i>	480.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES201862

Date : 28/08/2018

Vehicle Num. : SLJ 1239C (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 24/08/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE FRONT UNDERCARRIAGE COMPONENTS IN ORDER TO FACILITATE REPAIRS TO FRONT ACCIDENT DAMAGED AREAS, REFIT BACK AND REPLACE NEW FRONT LEFT UNDERCARRIAGE PARTS	NM80 X	380.00 X
		COMPUTERISED WHEEL ALIGNMENT	60	180.00
		DEACTIVATE VEHICLE HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS TO FRONT ACCIDENT DAMAGED AREAS, REINITIATE HYBRID SYSTEM INCLUDING PERFORMING WHOLE VEHICLE DIAGNOSTIC SCAN AND FAULT CODES ERASING, TEST AND CALIBRATE HYBRID SYSTEM WHERE NECESSARY (HYBRID SYSTEM SAFETY PROCEDURES)	400	600.00
		REMOVE DAMAGED SRS COMPONENTS INCLUDING DASHBOARD, FRONT SEATBELTS AND BUCKLES, FRONT AIRBAGS ASSY, AND REPLACE WITH NEW. TO PERFORM SRS SYSTEM TEST AFTER SRS COMPONENTS REPLACEMENT (SRS SYSTEM SAFETY PROCEDURE)	450	680.00
		REMOVE AND REPLACE DAMAGED ENGINE BAY WIRING HARNESS	NN X	180.00 X
		PUTTY, SANDING, SPRAY PAINT, RUSTPROOFING AND TUFF COATING, AND POLISHING OF REPAIRED AND REPLACED BODY PANELS INCLUDING SUPPLY OF PAINT MATERIALS, AND ETC	1500	2,000.00
		Labour Total S\$:	4790	7,960.00

16 - 18 Days.	E. & O.E.	Total S\$:	37,762.08
---------------	-----------	-------------	-----------

for WORLD AUTO PTE LTD

part by part.

before paint photos.

Gmo Ri ang - 82880282

29/8/18.

26280.56

20% : 21k

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLJ1239C
Vehicle to be Exported:	No
Intended De-registration Date:	30 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	LEB4264149
Chassis No.:	GP71044174
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$20,676.00
Original Registration Date:	29 Nov 2016
First Registration Date:	29 Nov 2016
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,089.00
COE Rebate Amount:	\$46,257.00
Total Rebate Amount:	\$50,007.00

The information contained herein is correct as at 30 Aug 2018

OK



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務

SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: G 10998

Date: 24/8/18

Name/Company World Auto
 Vehicle No. SLJ 1239 C Model Shuttle
 From Pasir Ris Dr 6
 To 1 Kranji loop
 Remarks 83280438

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Time: 19 : 30 - 20 : 00 - 20 : 55

Amount \$ 60

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

YM 51287
 Tow Truck

24 HRS TOWING SERVICE
 6841 0080

www.speedwayrecovery.com
 Email: speedwaytowing@gmail.com

[Signature]
 Received By



Service Request Details

Claim

S8M00TGT

Reference

None 

Loss Date

24 August 2018

Request Date

28 August 2018

Due Date

4 September 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

28/08/2018 @ 9.40am
Ainea veh in
GO

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLJ1239C

Make

TPVD HONDA

Model

SHUTTLE HYBRID-1.5 (A)

Service Address

...

Primary Contact/Insured

WEE TIAN CHUAN (HUANG TIANCHUAN)

BLK 77 MARINE DRIVE, #05-44, 440077, Singapore

84683164

DAVIDWEE1@YAHOO.COM

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



RE: Re:TP MANDATE IA-S8M00TGT

Type

🔗 Question

Message

Dear Stacey, TP reject offer. Counter propose of COR \$21,000 (before GST), LTA search \$2.00, LOU: \$60 x 18days) \$1080.00. Total: \$23,552.00. Final est list marked uploaded. Kindly let us have your approval/instruction. Thanks - Cecilia

Reply

X

WORLD AUTO PTE LTD
47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
S'PORE 577200
Tel No. : 64513933 Fax No. : 64557576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #24-01 AXA TOWER
S'PORE 068811

Attention : Motor Claim Department
Contact : 68804888 Fax No. : 68804838

Tax Invoice : F189452

Date : 19/07/2019
Vehicle Num. : SLJ 1239C
Make/Model : HONDA SHUTTLE HYBRID
Chassis/Eng# :
Accident Date : 24/08/2018
Claim No. : TP/2204/2018
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

GLOBAL SUM				21,000.00
------------	--	--	--	-----------

Total S\$:				21,000.00
-------------	--	--	--	-----------

Total S\$:	21,000.00
GST 7% S\$:	1,470.00
Amount Due S\$:	22,470.00
=====	

WORLD AUTO PTE LTD



Re:RE: Re:TP MANDATE IA-S8M00TGT

Type

🔗 Question

Message

PLEASE OFFER \$20,000 GLOBAL ALL-IN

Reply



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

Tel: 64513933 Fax: 64557576

Date: 19/7/2019

Your ref: SLK 7226U (insured)

Our ref: TP/2204/18

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY EMAIL

Dear Sirs

ACCIDENT INVOLVING SLJ 1239C & SLK 7226U ON 24.8.2018 ALONG PASIR RIS DR 6

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF PTE LTD)

Enclosed herewith are the following documents for your attention:-

- A. Tax Invoice;
- B. Search fee;
- C. Letter of Authority

We are claiming the following:-

1. Final bill	:	\$21,000.00
2. Gst 7%	:	\$ 1,470.00
3. Search fee	:	\$ 2.00
4. PRI (\$60 x 2)	:	\$ 120.00
5. Loss of use (\$60 x 16 days)	:	\$ 960.00
		<u>\$23,552.00</u>

Kindly let us have your clients' mandate to settle.

Yours faithfully,

World Auto Pte Ltd

For: World Auto Pte Ltd

Encls:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015758/Ggb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 07-10-2019		
ATTN: STACEY NG		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 7226U	Veh. Inspected	SLJ 1239C	
Policy No.	GA368152/1	Coverage (\$)	0.00	
Claim No.	S8M00TGT	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GP71044174	Colour	BLACK	
Odometer	080525	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	GITI	5 mm	
L/H Front Tyre	185/60 R15	GITI	5 mm	
R/H Rear Tyre	185/60 R15	GITI	5 mm	
L/H Rear Tyre	185/60 R15	GITI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/08/2018	Inspection Date	29/08/2018	
Survey held at	NO.1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1239C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (CONSISTENT)	BUCKLED	1,080.00	1,080.00
2	FRONT BONNET HINGE @ \$98.50 (CONSISTENT)	BENT	197.00	197.00
1	FRONT BONNET INSULATOR (CONSISTENT)	DEFORMED	135.00	135.00
1	FRONT BONNET LOCK (CONSISTENT)	BENT	158.00	158.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,100.00	1,100.00
2	FRONT BUMPER SIDE RETAINER @ \$78.00 (CONSISTENT)	DEFORMED	156.00	156.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	485.80	485.80
1	FRONT BUMPER UNDERDUST COVER (CONSISTENT)	DEFORMED	185.00	185.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	CRACKED	122.00	122.00
1	FRONT BUMPER FOGLAMP COVER LH (CONSISTENT)	MISSING	75.00	75.00
1	FRONT BUMPER FOGLAMP COVER TOP GARNISH LH (CONSISTENT)	MISSING	68.00	68.00
2	FRONT FENDER @ \$489.90 (CONSISTENT)	N/S BUCKLED / O/S TO REPAIR SEE LABOUR	979.80	489.90
1	FRONT FENDER TOP BRACKET LH (CONSISTENT)	BENT	60.00	60.00
1	FRONT FENDER HYBRID EMBLEM LH (CONSISTENT)	NECESSARY	88.60	88.60
1	FRONT FENDER UNDER DUST COVER LH (CONSISTENT)	DEFORMED	192.00	192.00
1	FRONT GRILLE BASE (CONSISTENT)	CUT	248.00	248.00
1	FRONT GRILLE CHROME MOULDING (CONSISTENT)	CUT	228.00	228.00
1	FRONT GRILLE LOWER CHROME MOULDING (CONSISTENT)	CRACKED	198.00	198.00
1	FRONT GRILLE CENTRE LOCK BRACKET (CONSISTENT)	CRACKED	118.00	118.00
2	HEAD LAMP @ \$780.00 (CONSISTENT)	CRACKED	1,560.00	1,560.00
1	HEAD LAMP LOWER BRACKET LH (CONSISTENT)	BENT	64.00	64.00
1	FRONT SUPPORT PANEL (CONSISTENT)	BENT	790.00	790.00
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	DEFORMED	95.00	95.00
1	RADIATOR (CONSISTENT)	BENT	1,311.90	1,311.90
1	RADIATOR FAN COWLING (CONSISTENT)	NOT NECESSARY	125.00	-
1	RADIATOR FAN BLADE (CONSISTENT)	NOT NECESSARY	122.00	-
1	RADIATOR FAN MOTOR (CONSISTENT)	NOT NECESSARY	225.00	-

Report Ref No. CC4/ASM18015758/Ggb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RADIATOR AIR GUIDE SIDE @ \$80.00 (CONSISTENT)	DEFORMED	160.00	160.00
1	RADIATOR SPARE TANK (CONSISTENT)	CRACKED	92.00	92.00
1	RADIATOR SPARE TANK CAP (CONSISTENT)	MISSING	20.00	20.00
1	AIRCON CONDENSOR (CONSISTENT)	BENT	1,160.00	1,160.00
1	AIRCON CONDENSOR FAN COWLING (CONSISTENT)	NOT NECESSARY	168.00	-
1	AIRCON CONDENSOR FAN BLADE (CONSISTENT)	NOT NECESSARY	95.00	-
1	AIRCON CONDENSOR FAN MOTOR (CONSISTENT)	NOT NECESSARY	238.00	-
1	FRONT WHEELHOUSE INNER PANEL LH (CONSISTENT)	BENT	198.00	198.00
1	FRONT WHEELHOUSE OUTER PANEL LH (CONSISTENT)	BENT	188.00	188.00
1	FRONT WHEELHOUSE EXTENSION INNER PANEL LH (CONSISTENT)	BENT	85.00	85.00
1	FRONT WHEELHOUSE EXTENSION OUTER PANEL LH (CONSISTENT)	BENT	95.00	95.00
1	FRONT CHASSIS SIDE MEMBER LH (CONSISTENT)	NOT NECESSARY	850.00	-
1	BATTERY TRAY (CONSISTENT)	CRACKED	70.00	70.00
1	BATTERY TRAY BRACKET (CONSISTENT)	NOT NECESSARY	132.00	-
2	BATTERY LOCKING HOOK @ \$32.00 (CONSISTENT)	NOT NECESSARY	64.00	-
1	BATTERY LOCKING BRACKET (CONSISTENT)	BENT	28.00	28.00
1	ENGINE BAY WIRING HARNESS LH (CONSISTENT)	NOT NECESSARY	1,300.00	-
1	AIR FILTER BOX LOWER HOUSING (CONSISTENT)	NOT NECESSARY	258.00	-
1	AIR FILTER BOX TOP COVER (CONSISTENT)	NOT NECESSARY	98.00	-
1	AIR INTAKE RESONANCE (CONSISTENT)	CRACKED	188.00	188.00
1	AIR INTAKE AIR DUCT (CONSISTENT)	DEFORMED	132.00	132.00
1	AIR INTAKE AIR DUCT TUBE (CONSISTENT)	DEFORMED	70.00	70.00
1	TRANSMISSION GEARBOX MOUNTING (CONSISTENT)	NOT NECESSARY	320.00	-
1	DASHBOARD (CONSISTENT)	ACTIVATED	2,152.00	2,152.00
1	STEERING WHEEL AIRBAG (CONSISTENT)	ACTIVATED	1,850.00	1,850.00
1	STEERING WHEEL AIR BAG SLIP RING (CONSISTENT)	ACTIVATED	480.00	480.00
1	STEERING ANGLE SENSOR (CONSISTENT)	ACTIVATED	310.00	310.00
1	FRONT PASSENGER AIRBAG (CONSISTENT)	ACTIVATED	2,480.00	2,480.00
1	AIRBAG CONTROL MODULE (CONSISTENT)	ACTIVATED	1,580.00	1,580.00
2	FRONT SEATBELT @ \$1298.00 (CONSISTENT)	ACTIVATED	2,596.00	2,596.00
2	FRONT SEATBELT BUCKLE @ \$328.00 (CONSISTENT)	NOT NECESSARY	656.00	-

Report Ref No. CC4/ASM18015758/Ggb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT AIRBAG IMPACT SENSOR @ \$185.00 (CONSISTENT)	ACTIVATED	370.00	370.00
1	FRONT WINDSCREEN GLASS (CONSISTENT)	CRACKED	1,850.00	1,850.00
1	SET FRONT WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	195.00	195.00
1	FRONT WINDSCREEN GLASS OUTER MOULDING LH (CONSISTENT)	NECESSARY	120.00	120.00
1	WIPER AIR GRILLE COWLING (CONSISTENT)	CRACKED	298.00	298.00
1	WIPER AIR GRILLE COWLING SIDE GARNISH LH (CONSISTENT)	MISSING	38.00	38.00
1	RADIATOR TOP HOSE (CONSISTENT)	NOT NECESSARY	78.00	-
1	RADIATOR LOWER HOSE (CONSISTENT)	NOT NECESSARY	88.00	-
1	AUDIBLE SENSOR (CONSISTENT)	MISSING	180.00	180.00
1	ENGINE CROSSMEMBER SUBFRAME (CONSISTENT)	NOT NECESSARY	980.00	-
2	ENGINE CROSSMEMBER SUBFRAME BRACKET @ \$160.00 (CONSISTENT)	NOT NECESSARY	320.00	-
1	FRONT SHOCK ABSORBER - LH (CONSISTENT)	NOT NECESSARY	430.00	-
1	FRONT LOWER ARM - LH (CONSISTENT)	NOT NECESSARY	320.00	-
1	FRONT KNUCKLE - LH (CONSISTENT)	NOT NECESSARY	360.00	-
1	FRONT WHEEL BEARING - LH (CONSISTENT)	NOT NECESSARY	220.00	-
1	FRONT STABILIZER LINK LH (CONSISTENT)	NOT NECESSARY	80.00	-
1	DRIVE SHAFT FRT / LH (CONSISTENT)	NOT NECESSARY	1,680.00	-
1	FRONT WHEEL ABS SENSOR LH (CONSISTENT)	NOT NECESSARY	310.00	-
1	FRONT GRILLE EMBLEM (CONSISTENT)	NECESSARY	48.00	48.00
1	STEERING TIE ROD END LH (CONSISTENT)	NOT NECESSARY	120.00	-
	LESS 20% DISCOUNT		-7,273.02	-5,247.64
			29,092.08	20,990.56
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BONNET INSULATOR CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER UNDERDUST COVER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT FENDER UNDER DUST COVER CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00

Report Ref No. CC4/ASM18015758/Ggb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	BATTERY (50%) (SN) (CONSISTENT)	DAMAGED	180.00	90.00
1	FRONT NUMBER PLATE W/FRAME (SN) (CONSISTENT)	MISSING	40.00	40.00
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	PRIVATE HIRE DECAL (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	RADIATOR COOLANT (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	AUTOTRANSMISSION FLUID (HONDA) (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
			650.00	440.00
	LABOUR			
	TOWING CHARGE.		60.00	60.00
	REMOVE AND REPLACE FRONT WINDSCREEN GLASS.		180.00	120.00
	SEND VEHICLE TO INSPECTION CENTRE FOR PRIVATE HIRE DECAL PASTING.	NOT NECESSARY	120.00	-
	REMOVE AND REPLACE RADIATOR ASSY INCLUDING PERFORMING ENGINE COOLING SYSTEM PRESSURE TEST AND REFILL COOLANT.		180.00	80.00
	REMOVE AND REPLACE AIRCON CONDENSOR ASSY INCLUDING PERFORMING AIRCON SYSTEM PRESSURE LEAK TEST INCLUDING REFILLING AIRCON GAS.		180.00	80.00
	REMOVE FRONT ACCIDENT DAMAGED PARTS INCLUDING FRONT BONNET, FRONT BUMPER, FRONT HEADLAMPS, FRONT FENDERS, CUT AND WELD DAMAGED SUPPORT PANEL AND FRONT LEFT WHEELHOSE PANEL, FRONT LEFT CHASSIS SIDE MEMBER AND REPLACE NEW PARTS. INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER.		2,800.00	1,800.00
	HOIST OUT ENGINE ASSY IN ORDER TO FACILITATE REPAIRS TO FRONT ACCIDENT DAMAGED AREAS.		480.00	300.00
	REMOVE FRONT UNDERCARRIAGE COMPONENTS IN ORDER TO FACILITATE REPAIRS TO FRONT ACCIDENT DAMAGED AREAS, REFIT BACK AND REPLACE NEW FRONT LEFT UNDERCARRIAGE PARTS.	NOT NECESSARY	380.00	-
	COMPUTERISED WHEEL ALIGNMENT.		180.00	60.00

Report Ref No. CC4/ASM18015758/Ggb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DEACTIVATE VEHICLE HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS TO FRONT ACCIDENT DAMAGED AREAS, REINITIATE HYBRID SYSTEM INCLUDING PERFORMING WHOLE VEHICLE DIAGNOSTIC SCAN AND FAULT CODES ERASING, TEST AND CALIBRATE HYBRID SYSTEM WHERE NECESSARY (HYBRID SYSTEM SAFETY PROCEDURES)		600.00	400.00
	REMOVE DAMAGED SRS COMPONENTS INCLUDING DASHBOARD, FRONT SEATBELTS AND BUCKLES, FRONT AIRBAG ASSY, AND REPLACE WITH NEW. TO PERFORM SRS SYSTEM TEST AFTER SRS COMPONENTS REPLACEMENT (SRS SYSTEM SAFETY PROCEDURE)		680.00	450.00
	REMOVE AND REPLACE DAMAGED ENGINE BAY WIRING HARNESS.	NOT NECESSARY	180.00	-
	PUTTY, SANDING, SPRAY PAINT, RUSTPROOFING AND TUFF COATING, AND POLISHING OF REPAIRED AND REPLACED BODY PANELS INCLUDING SUPPLY OF PAINT MATERIALS, AND ETC.		2,000.00	1,500.00
			8,020.00	4,850.00
GRAND TOTAL			37,762.08	26,280.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				21,000.00

Report Ref No. CC4/ASM18015758/Ggb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.